



HISTORIC PHOTO A-28
1963 AERIAL PHOTO PIT
AND PROCESS AREA
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-29
1963 AERIAL PHOTO
PROCESS AREA
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-30
1963 DUMP LEACH
SURGE POND
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-31
1963 DUMP LEACH SURGE POND IN
FOREGROUND AND SULFIDE TAILINGS
DAM IN BACKGROUND
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-32
1963 LEACHING W-3 WASTE ROCK
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-33
1963 W-3 LEACH POND AND PUMPHOUSE
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-34
1963 LEACH SOLUTIONS
PUMP STATION
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-35
1963 W-3 LEACH POND AND DITCHES
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE




HISTORIC PHOTO A-36
1963 W-3 LEACH SOLUTION
PUMP HOUSE
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-37
1963 W-3 WASTE ROCK AREA
PUMPHOUSE AND SOLUTION TANKS
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-38
1963 PROCESS AREA SOLUTION RECYCLING TANK
IN FOREGROUND, IRON LAUNDERS/CEMENTATION
ON LEFT, COOLING TOWER ON RIGHT, AND
PUMPHOUSE AND SULFIDE PLANT IN BACKGROUND
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-39
1963 IRON LAUNDERS
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-40
1964 EXPANSION OF
FLOTATION PLANT
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE




HISTORIC PHOTO A-41
1963 SUFIDE PLANT
FOLLOWING CONSTRUCTION
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-42
1964 LEACH VATS AND WASH WATER
AND STRONG SOLUTION SUMPS ON LEFT
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE







SOURCE: DALTON, 1998

ES092209222513RDD_A-45 (1/29/10)

HISTORIC PHOTO A-45
1967 AERIAL PHOTO –
YERINGTON MINE
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



SOURCE: BROWN AND CALDWELL, 2008

ES092209222513RDD_A-46 (1/29/10)

HISTORIC PHOTO A-46
1967 AERIAL PHOTO
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

AUG. 23, 1968




SOURCE: BROWN AND CALDWELL, 2008


ES092209222513RDD_A-47 (1/29/10)

HISTORIC PHOTO A-47
1968 AERIAL PHOTO
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE





NOTES
 1. PROJECTION: NEVADA STATE PLANE, WEST ZONE
 2. DATUM: NORTH AMERICAN DATUM 1983
 3. IMAGE PHOTO: TAKEN IN 1977



SOURCE: BROWN AND CALDWELL, 2003b

ES092209222513RDD_A-49 (1/29/10)

HISTORIC PHOTO A-49
1977 AERIAL PHOTO –
YERINGTON MINE
 HISTORICAL SUMMARY REPORT
 ANACONDA-YERINGTON MINE



SOURCE: BROWN AND CALDWELL, 2008

HISTORIC PHOTO A-50
1977 AERIAL PHOTO
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-51
2001 AERIAL PHOTO
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



Photo 1
Looking northeast across surface of Oxide Tailings Area (“mounds” in foreground). (1/23/2002)



Photo 2
Looking southward along west face of Oxide Tailings Area. (7/12/2002)



Photo 3
Looking southwest over Sulfide Tailings with agricultural fields in foreground. (1/23/2002)



Photo 4
Looking southward over VLT-covered surface of Sulfide Tailings Area – saltcedar and other shrub growth. (5/24/2002)



Photo 5
Looking southwest over Process Solution Recycling Ponds. (1/23/2002)




Photo 6
Looking southwest over Unlined Evaporation Ponds to the east and north
of the Phase IV-VLT Heap Leach. (1/23/2002)



Photo 7
Looking west over lined Pumpback Evaporation Ponds, Lined
Evaporation Ponds and the Weed Heights Sewage Lagoons. (1/23/2002)



Photo 8
Looking west at north face of Oxide Tailings and abandoned crusher or
bin support structure. (7/12/2002)



SOURCE: DAVE SCHUMACHER

ES092209222513RDD_A-56 (1/29/10)

HISTORIC PHOTO A-56
2006 AERIAL PHOTO
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE