



### **Notice of Deficiency Response**

Penneco Environmental Solutions, LLC

Underground Injection Control Program
Class IID Injection Well Permit Application

Sedat #3A



September 10, 2016

Mr. Mark Nelson, Hydrologist United States Environmental Protection Agency Region III 1060 Chapline Street Wheeling, West Virginia 26003

RE:

Notice of Deficiency; Penneco Environmental Solutions, LLC Underground Injection Control (UIC) Program Class IID Injection Well Permit Application Sedat #3A

Dear Mr. Nelson,

Penneco Environmental Solutions, LLC is responding to the Notice of Deficiency dated July 8, 2016 for UIC facility ID PAS2D701BALL, for a proposed injection well for the disposal of E&P wastes. We have addressed the items listed in Attachment 1 of the NOD below and are enclosing revised application attachments as needed.

### Item 1. Application Page

We field checked the latitude and longitude of the Sedat #3 A and found the location corresponds to the location shown on the AOR maps.

### Item 2. Area of Review

The topographic map of the AOR has been revised to expand the radius from ¼ mile to ½ mile from the injection well. Two (2) printed copies of the revised map are enclosed. A list of landowners and their address are included with the maps along with water well depths where known. Attachment A, Area of Review Methods, was revised to account for the change in radius from ¼ mile to ½ mile. The additional wells within the enlarged radius were added to the well table in Attachment G.

### Item 3. Attachment E-USDWs

We have expanded the Attachment E narrative giving more detail on USDWs in the AOR. See the revised enclosed Attachment E.

66\_8 ROUTE 22, P.O. BOX 300 DELMONT, PA 15626-0300

PH: (724) 468-8232 FAX: (724) 468-8230

EMAIL: PENNECO@PENNECO.COM

WEB: PENNECO.COM

We are only listing two USWDs as being in the AOR. Pennsylvania Geological Survey Water Resource Reports #35 (Allegheny County) list three (3) and Report #37 (Westmoreland County) list two (2) additional aquifers. The Allegheny County aquifers are the Monongahela Group, Conemaugh Group, and the Allegheny Group. In the AOR there are only two (2) the Conemaugh Group and the Allegheny Group. The surface rocks are predominately of the Conemaugh Group which is roughly 400 to 500 feet thick in the AOR. The Allegheny Group ranges from 200 to 300 feet in thickness and is around 450 feet deep in the AOR and in general any water found below 500 feet in depth is of poor quality (Report #37). The Worthington Sandstone, the lower sandstone unit of the Allegheny Group contains highly concentrated brine where the unit lies below drainage and any formations below the Worthington are not suitable as freshwater aquifers because of either low permeability or contain water high in salt content (page 61 report #35).

Report #37 (Westmoreland County) which covers a geographical area outside the Sedat AOR list an additional two aquifers, the Pottsville Group and the Mauch Chunk formation. The Pottsville lies at a depth of around 900 to 950' in western Westmoreland County and Report #37 on page 42 states that "the rocks of the Pocono Group are generally buried more than 500 feet deep, or more than 100 feet below the level of major streams. Wells drilled into these rocks usually encounter salt water". The Pocono Group is made up of three sandstones, the Homewood sandstone, Upper Connoquenessing sandstone and the Lower Connoquenessing sandstone. The drillers' names for these sands was First Salt sand, Second Salt sand and Maxton also sometimes referred to as the Third Salt sand. The Salt sands were drilled for the brine and the Maxton sand for gas, according to the Topographic and Geologic Atlas of Pennsylvania No. 36 Freeport Quadrangle. The Mauch Chunk is absent in the AOR due to either non deposition or erosion, according to Atlas of Pennsylvania No. 36 Freeport (15") Quadrangle, page 59.

A note about Driller's log reports of water shows on well records. These reports are unreliable and highly inaccurate; the water shows are neither measured for quantity nor sampled for quality analysis. The flow volume is estimated by site, and the quality is just a guess, in addition the water in the bore hole is commingled with waters from any zones left open to the bore hole at the time of sampling. The report of fresh water reported at 1,700 feet was a notational error according to Penneco which illustrates another type of widespread reporting error.

The majority of the conventional wells drilled in Western Pennsylvania were/are drilled by cable tool rigs or rotary air rigs and not logged until after the surface, coal and water strings are run and cemented and the well reaches total depth. Some wells do have a gamma ray log to surface but no electric logs are available.

### Item 4, 5, 6, 7, and 8. Attachment G - Geologic Data

Items 4, 5, 6, 7 and 8 were addressed by revising Attachment G. Item 4 pertained to a typographical error for a permit number, the correct permit number is now shown in the table. Item 5 asked for additional information on the methodology used to determine the frac gradient. HFRAC provides additional information on the frac gradient in supplement 5 at the end of their original report. We have replaced pages 29 through 35 of the HFRAC report with new full size copies to take care of Item 7 asked for justification of the use of 1.8mD for the permeability of the injection zone. HFRAC expands on why this value was chosen in supplement 7 which can be found at the end of

their report. To address Item 8 the geological narrative has been revised so that it now includes an additional structure map contoured on top of the Murrysville Sand, and an additional three (3) cross sections across the AOR showing no sand displacement.

Four seismic maps from the USGS Earthquake Hazards Program were added to the end of Attachment G. Map 1 shows historic seismic activity in Pennsylvania, showing there has been no activity in the AOR. Maps 2, 3 and 4 show the probability of natural or induced seismic activity in different formats. All three show low probability of any activity in the AOR.

### Item 9. Attachment H - Operating Data

Attachment H was revised to provide more detail as to the source of the injection fluid, which is E&P waste, produced water and flow back fluids. Note that Penneco Environmental Solutions, LLC is applying for a commercial license.

### Item 10. Attachment P - Monitoring Program

Attachment P was revised to provide additional information on the monitoring program for both the injection well and the Sedat #1 monitoring well.

Should you need clarification on any other items, please do not hesitate to contact us.

Sincerely,

PENNECO ENVIRONMENTAL SOLUTIONS, LLC

D. Marc Jacobs, Jr. Senior Vice President

### Attachment A Area of Review Methods Sedat #3A Injection Well

### Area of Review Methods:

The size of the area of review was determined by a fixed radius of one quarter mile as required by permit application but expanded to a fixed radius of one half mile at request of permit reviewer. Maps with a one quarter mile, one half mile and one mile radius were prepared. A topographic map extending one (1) mile beyond the well site was prepared by Fox and Fox, Inc. with assistance from Penneco Environmental Solutions, LLC. Maps detailing the area of review are in Attachment B. Research was conducted by:

- 1) Survey by Fox and Fox, Inc. registered professional surveyors
- 2) Conversation with surface landowners by Fox and Fox, representatives of Penneco Environmental Solutions LLC.
- 3) Review of Tax Parcel Maps from the county assessment office.
- 4) Research of Pennsylvania Bureau of Oil and Gas Management's well records
- 5) Research of Pennsylvania Geological Survey publications covering the area of review
- 6) Research of USGS publications covering the area of review.
- 7) Master Thesis (Two) From West Virginia University
- 8) Series of reservoir test by HFrac Consulting Services.

Using the results from the above research, along with topographic and tax maps displaying surface features such as buildings, and streams, maps of the AOR were prepared for and included in Attachment B.

The same research used to map the area of review was used to provide data on the geology of the injection zone and the confining formations described in Attachment G.

As part of larger study to assess its lease acreage in the area of the Sedat lease Penneco ran a series of reservoir tests using HFrac Consulting Services to determine the character of the Murrysville reservoir and the results are included in Attachment H.

### Attachment E

### USDWs for Sedat #3A Injection Well

The Sedat #3A AOR is located in the Pittsburgh Low Plateau Section of the Appalachian Plateau physiographic province (refer to map at the end of this attachment). Underlying rock types are shale, siltstone, sandstone, limestone and coal. Aquifers in the AOR are mainly sandstones of the Conemaugh Group and the Allegheny Group. The Pottsville Group and the Mauch Chunk Formation, identified as USDWs in some areas of Pennsylvania lie at too great a depth to serve as aquifers in the AOR or are absent due to non deposition or erosion as is the case for the Mauch Chunk. See the table on the following pages listing USDWs in Pennsylvania. The thickness of the section from the Conemaugh Group through the Allegheny Group runs in the range of 800 feet depending on surface elevation. A review of the well records shows water production as deep as 1,700 feet. However reports of water production by the driller on their driller's logs are highly unreliable, the quantity and quality of the water is not measured by instrument. The quantity is estimated by site and the water quality which is often measured by taste, is a commingled sample from all formations open to the bore hole at the time of sampling. Additionally, Pennsylvania Geological Survey Water Resource Reports #35 and #37 state water quality is extremely poor beyond 500 feet in depth because of moderate to high mineralization of the waters (high dissolved solids and brine).

### Description of USDWs in AOR

Rock members of the Conemaugh Group predominate at the surface in the AOR: see the section of the geologic map of Pennsylvania at the end of the attachment. The Casselman and Glenshaw Formations make up the Conemaugh Group, and consist of shale, red shale, sandstone and coals.

The Allegheny Group consists of shale, sandstone, thin beds of limestone and coals. The Freeport Formation, Kittanning Formation, Vanport Limestone, and Clarion Formation make up the Allegheny Group.

9-6-2016

Figure 89. The principal aquifers in the Appalachian saus Province in Segment 11 are sandstones in the gic units shown in yellow and limestone shown in Lue. Where fractured, rocks of the Greenbrier, the Catskill, and the Brallier Formations locally yield water. The gray areas represent missing rocks.

System	Pensylvain	Maryland	West Wrginin	Virginia			
Permian	Dunksird Group		Dunland Group				
	Monongahela Group	Mononquinala Formation	Mononcahela Group				
	Conem such Group	Constraugh Permation	Conemauda Group				
8	Allegheny Group	Allegheny Formation	AlleghenyFormation				
8	Potte ville Group	Pottsville Formation					
enegrania			Potentia Group	Harizen Formation			
4				WiseFormation			
				Norton Formation			
				Loo Formation			
				Eluestone Form sison			
		NEARTH CENTRE FORM SELON	Marian Chunk Group	Hirkon Form stion			
20	Nation Chunk Form ation			Bluefield Form tio			
Mesisoippian		Greenbrier Formation <sup>4</sup>	Greenbrier Liss entone	Greathrier Linester			
20				Misserady Shale			
-	Posono Formation			Price Formation			
	Huntley Mountain Formation	Posono Form alson	Posono Giroup				
		Ham pohire Form stion	HampshireFormation				
Se .	Cals-lill Form alion 1		Chem und Formation	Chattanooga Shale			
Devonian	Trim in ## Rock Form #500	Chemung Formation Brailier Formation <sup>1</sup>	Erallier Formation 1				
	Harrel Formation	Harrel Shale	Harrel Shale				

Locally evalue-plotding

Modified from:

tchen, D.G., and others, 1985a, Correlation of stratigraphic units of North America (COSUNA) Project, southern Appalachian region: American Association of Petroleum Geologists, 1 sheet.

1985b, Correlation of stratigraphic units of North America (COSUNA) Project, northern Appalachian region: American Association of Petroleum Geologists, 1 sheet.

### Attachment G\* Geological Data on Injection and Confining Zones SEDAT #3A Injection Well

### Geological Data for Sedat #3A Injection Well

The Sedat #3A injection well will be a repurposed depleted natural gas well located in the Renton Gas Field in Plum Borough, Allegheny County, Pennsylvania. The injection well will target the Murrysville Sand as the injection zone which is water saturated and located very near the axis of the Duquesne-Fairmount syncline, see the copy of a section of Pittsburgh Region Structure Contour Map (Map 1) included with this attachment. Also included is a Geologic Map of the western part of Allegheny County, PA (Map 2). The immediate area around the well has been strip mined for coal (Pittsburgh Seam) and mined by underground methods for coal (Upper Freeport Seam); see the Area of Review map in Attachment B.

There are 15 wells within the 1/2 mile Area of Review (ARO) that penetrate the Murrysville sand, the state permit numbers for the wells are:

Permit #	Permit #	F	Permit #
003-21287	003-21210	003-22200	003-21223
003-21222	003-21644	003-21238	003-21438
003-21228	003-00674	003-21964	003-21317
003-21225	003-20903	003-21868	

All the wells were cased and cemented through the Murrysville, well 003-00674 was plugged, the well records can be found in Attachment B. The Sedat #1A permit # 003-21210 will be converted to an observation well by perforating the cemented casing string at the depth of the Murrysville.

The Murrysville Sand is approximately 128' thick, and lies at a depth of 1,822' to 1,950' in the Sedat #3A AOR. The well had an original TD of 4,309' and was plugged back to 1,940' to just below the injection zone. See Attachment M Construction Details for well schematic and cement data. Fluid will be injected into a 40' section of the Murrysville Sand through a 4" injection string set on a packer at approximately 1,890' in 7" casing perforated with 41 holes from 1896' to 1936'. The confining zones are the Riddlesburg Shale (Sunbury Equivalent) which overlays the Murrysville with the Riceville-Oswayo Shale lying underneath as the lower confining zone.

The upper confining zone lying directly on top of the Murrysville is the Riddlesburg Shale. The Riddlesburg is a dark gray to greenish and grayish black laminated shale and siltstone with occasional sandstone and limestone beds. The Riddlesburg is between 80 to 90 feet thick in the Sedat #3A AOR; see the Riddlesburg Isopach map, Map 3 at the end of Attachment G.

The Murrysville is a greenish-yellow to gray sandstone with occasional conglomeratic lenses, with high porosity and permeability. Because of the Murrysville's thickness, high porosity and permeability the formation serves as a gas storage reservoir to the south of the Sedat. All most all the wells in the AOR including the Sedat #3A were drilled and cased through the Murrysville without running a porosity logs, see the well records in Attachment B. There are two wells for which porosity logs are available that show the average density porosity through the Murrysville Sand to average around 24%, which agrees with published reports of porosity values in the Murrysville. Refer to the log sections and location map at the end of this attachment for wells permit # 129-24721, and well permit #129-25581. Both wells where saturated with brine and did not produce gas.

Penneco conducted several tests to determine the reservoir characteristics of the Murrysville on its leases with the results included at the end of Attachment H. The test provided a breakdown pressure, the pressure needed to initiate a fracture, as 3,115 psi, ISP is estimated as 1,114 psi, with a fracture gradient of 1.23 psi. The reservoir pressure is 232 psi, with an estimated closure pressure of 553 psi. See the supplement to the HFrac report labeled Item 5 for more detail on the methodology used to determine the fracture gradient.

Formation permeability for the Murrysville was reported by Melissa Sager (Petrologic Study of the Murrysville sandstone in SW PA, 2007) as generally high throughout the formation, with a range of 0.005 to 1,000 millidarcies with an average of around 100 millidarcies. The permeability of the Murrysville in the Sedat #3A is estimated to be 1.8 mD and was determined from a series of tests to determine the reservoir characteristics of the Murrysville sand on Penneco leases conducted by HFrac Consulting Services, LLC, see the supplement to the HFrac report labeled Item 7 at the end of this attachment for additional detail. This value falls within the lower range of Sager's study.

The Riceville-Oswayo Shale lying directly beneath the Murrysville serves as the lower confining zone. The Riceville-Oswayo is about 30 feet thick in the AOR; see Map 4, Isopach map of the Oswayo Shale. The Riceville-Oswayo formation consists of dark gray to medium gray shale and siltstones.

Structurally the AOR has a series of northeast-southwest trending anticlines and synclines with the Sedat #3A well lying along the axis of the Duquesne-Fairmount syncline refer to Map 1. While there are some deep seated basement faults associated with the Rome Trough, review of Map 1, Map 2 and an additional structure map contoured on the top of the Murrysville Sand and additional cross sections across the AOR supports the idea that there are no apparent faults at shallower depths in the AOR. The Murrysville structure map along with additional cross sections across the AOR are from McDaniel's <u>Subsurface Stratigraphy and Depositional Controls on Late Devonian-Early Mississippian Sediments in SW PA</u>.

Review of Pennsylvania Geologic Publication, Atlas No. 36, Geology of the Freeport Quad (the Sedat #3A is in the SW corner of the quad) states on page 23 "displacement

faults where not seen in any outcrop. Inquiry among mine operators indicate practically the same thing". Penneco Environmental Solutions, LLC had a related company that at one time mined in the AOR and a search of its records supports the statement found in Atlas No. 36.


The U.S.G.S rates the probability of seismic activity in SW Pennsylvania with sufficient intensity to cause damage as low. A series of four earthquake maps from the U.S.G.S earthquake hazards program website are found at the end of this attachment.


Earthquake Map 1 shows the historical locations of earthquakes in Pennsylvania and nearby areas. Earthquake Map 2 shows the entire US color code to show the chance of a seismic event occurring from lowest to highest. Map 1 shows no seismic events are shown to have occurred in SW PA, and Map 2 shows the AOR lies in an area with the second lowest hazard level.


Earthquake Maps 3 and 4 are from U.S.G.S. open file report 2016 One Year Seismic Hazard Forecast for the Central and Eastern United States from Induced and Natural Earthquakes OFR-2016-1035. Map 3 shows there is a small chance (one percent) that ground shaking greater then IV on the Modified Mercalli Scale will occur. Map 4 indicates the change of damage in the NE from natural or induced seismic activity to be 1% to 2%.

Penneco also contends that the maximum injection pressure is sufficiently below the pressure needed to initiate a fracture or reactive any unknown faults. The injection rate is also not of a sufficient volume to open or extend any fractures or reactive any unknown faults in the area, see the HFRAC report.

9-6-2016







SUPERIOR INACTOR INACTOR IN WELL SERVICES WHOSE, The Whose, The Charleston Way.

GANTA RAY
NEUTRON
DENSITY
DUAL INDUC

1


Dons 7, d 0.3 -0.1 かしる 45 1 E 1200

Run 1 Run 2 Run	The second secon	a contract of the second of th		Market Market Co.		manuscript of the second of th	Authorization desired to the second s	The state of the s	emental mental de la company d	The second secon	man i summa memman man mi si		Territoria de la composition della composition d	The second secon	anne denne den de de la certa de la descripción de la certa de la descripción de la certa del certa de la certa del la certa de la certa del la c	AMERICAN SERVICE SERVI	The second secon	Security of the Contract of th	As parties of the parties of the territories of the	The second of the contract of		The second secon		F. Charles in Charles and Aller and	MART GO CONTRACTOR OF THE PROPERTY OF THE PROP		TRAC	- Company of the Comp
	Schlumberger			manual and a second	NNSXI VANIA	-		The state of the s	KB.	G.L. 1080 R	TOBO R	above Penn. Datum	NSHIP: QUAD:		Const Original	Schlumberger Depth	Top Log Intervel	Casho Schumbarder	OIL OLD	Type Fluid in Hole	HA SOT MILE	(A) RM (B) Meanured Temperati	Ressured 1	Source FIME FIMO	PANE @	pedd	ottom	CHECKER STATE OF THE STATE OF T
	Schlum		A06512		DENZ			H	Herv.:		Elev.:	8.0 #	DWN			-				!				The state of the s				1
	Schlum		DER UNIT #3 WPAC	HEMPELELD TVP		LITHO DENSITY	COMPENSATED NEUTRON / GR	ARRAY INDUCTION / TEMPERATURE	LATITUDE: 40-15-34.2700 EBev.:	LONGITUDE: 79-40-1:3800 117111: S. & 108' W. OF NE ODRINER	GROUNDLEVE	Log Measured From: KB 8.0 ft Orithing Measured From: KB	API Serial No MAP SECTION: TOWNS 97-128-25081-00 8 HEMPT	31 Aug 2005	STATE OF THE PARTY	2135 ft 2137 ft	10	(A)	\$675 m	Ofbrigat	to the destination manufactures and the second seco	The same of the sa	Annual to the state of the stat	AND THE PARTY OF T	RM (8) MRT RMF (8) MRT (4) 70 (4) 70 (8) 70	The second secon		TIM LYON, MIKE KORNACK


DISCLAIMER
STATE MEDICIN MAMEN CAMPANY (AND ANY OF ITS

STIA 1800 Trock Say de Unit #3 129-25521 MURRYSON 000 


### - Permeability vs Depth



### Total Porosity vs Permeability










Map 3. Riddlesburg Shale Isopach Map

McDaniel, Bret, 2006. Subsurface Stratigraphy and Depositional Controls
on Late Devonian-Early Mississippian Sediments in SW PA



Map 4. Riceville-Oswayo Shale Isopach Map McDaniel, Bret, 2006. Subsurface Stratigraphy and Depositional Controls on Late Devonian-Early Mississippian Sediments in SW PA.





Map 5. Structure Map on Top of Murrysville Sand McDaniel, Bret, 2006, Subsurface Stratigraphic and Depositional Controls on Late Devonian-Early Mississippian Sediments in SW PA




Figure 34. Cross section along D-D'. The most dramatic thinning occurs along this line as the Murrysville crosses the Blairsville-Broadtop Lineament (B-BL). Also evident is that there are two thick sequences of Murrysville, one thick and blocky in the southwest and another that lies to the northeast. It is unclear how this northeastern Murrysville relates to the blocky section to the south. One hypothesis may be that the north Murrysville may be nearshore deposits deposited north and south of the main channel the or perhaps these sandstones are abandoned delta lobes. The Weir is thin since it is far to the west of its depositional trend. The Hundred Foot becomes thick to the south, and it is here where the barrier bar sequence is best developed. See Figure 19 for the location of each numbered well.



### Cross Section D-D'

McDaniel, Bret, 2006, Subsurface Stratigraphic and Depositional Controls on Late Devonian-Early Mississippian Sediments in SW PA




Figure 35. Cross-section along E-E'. This is the most erratic section in terms of correlative sand units. The data becomes difficult to interpret within this section, but there is still some evidence that the Blairsville-Broadtop Lineament (B-BL) may have had some influence on deposition of the Murrysville. The Weir sandstone is nearly gone this far west, with only a few intermittent sandstones. See Figure 19 for the location of each numbered well

### Cross Section E-E"

McDaniel, Bret, 2006, Subsurface Stratigraphic and Depositional Controls on Late Devonian-Early Mississippian Sediments in SW PA




Figure 37. Cross section along G-G' section. This section attempts to tie the well log section to the outcrop data along the major Murrysville trend. Three things are evident from the section. (1)The Weir dramatically thins to the west across the proposed basement fault. (2)The Murrysville displays a thickened section to the west of the basement fault. (3)The Hundred Foot thins eastward as it reaches the basement fault. See Figure 19 for the location of each numbered well.

### Cross Section G-G'


McDaniel, Bret, 2006, Subsurface Stratigraphic and Depositional Controls on Late Devonian-Early Mississippian Sediments in SW PA






### Pennsylvania

Seismicity Map - 1973 to March 2012




Share this page: Facebook Twitter Google Email

Earthquake Map 1



Earthquake Map 2

# 2 JSGS Forecast for Ground Shaking Intensi Jom Natural and Induced Earthquakes in




### Modified Mercalli Intensity

3

Earthquake Map

USGS map displaying intensity of potential ground shaking from natural and human-induced earthquakes. There is a small chance (one percent) that ground shaking intensity will occur at this level or higher. There is a greater chance (99 percent) that ground shaking will be lower than what is displayed in these maps.

USGS Forecast for Damage from Natural and Induced Earthquakes in 2016



USGS map displaying potential to experience damage from natural or human-induced participates in 2016. Chances range from less than 1 percent to 12 percent.

USGS map displaying potential to expenence damage from a natural or human-induced earthquake in 2016. Chances range from less than one percent to 12 percent.

### Six States Face the Highest Hazards

The most significant hazards from induced seismicity are in six states, listed in order from highest to lowest potential hazard: Oklahoma, Kansas, Texas, Colorado, New Mexico and Arkansas. Oklahoma and Texas have the largest populations exposed to induced earthquakes.

"In the past five years, the USGS has documented high shaking and damage in areas of these six states, mostly from induced earthquakes," said Petersen. "Furthermore, the USGS Did You Feel It? website has archived tens of thousands of reports from the public who experienced shaking in those states, including about 1,500 reports of strong shaking or damage."

In developing this new product, USGS scientists identified 21 areas with increased rates of induced seismicity. Induced earthquakes have occurred within small areas of Alabama and Ohio but a recent decrease in induced earthquake activity has resulted in a lower hazard forecast in these states for the next events were induced or natural.

People living in areas of higher earthquake hazard should learn how to be prepared for earthquakes, and guidance can be found through FEMA's Ready Campaign.

Marthquake Map 4



**Natural Gas** 


### Seismicity in Pennsylvania and the Pennsylvania State Seismic Network

Dr. Andrew Nyblade, Dept. of Geosciences, Penn State, discusses the research on seismic activity as part of a DCNR and DEP monitoring program

### Time Log:

00:00 Introduction

03:41 Earthquake primer and review of seismicity in PA



www.dcnr.state.pa.us

14:29 Review of building the PA Seismic network

20:56 Seismicity in PA 2013-2014

35:01 More on building PASEIS

42:54 Lawrence County Earthquakes

47:30 Q&A

Seismicity in Pennsylvania and the Pennsylvania State Seismic Network powerpoint

PDF, 5.5 MB

Recorded Webinar - Seismicity in Pennsylvania and the Pennsylvania State Seismic Network

© 2016 Penn State College of Agricultural Sciences [http://agsci.psu.edu]

## Pennsylvania State Seismic Network Seismicity in Pennsylvania and the (PASEIS)

Department of Geosciences, Penn State University Andy Nyblade May 19, 2016









# Introduction

- Earthquake primer
- Review of seismicity in PA
- Review of seismic networks in PA
- (PASEIS) **Building the Pennsylvania State Network**
- Seismicity in Pennsylvania 2013-2014
- More on building PASEIS
- April 25, 2016 Lawrence County earthquakes


### **Body Waves:**




A. P waves generated using a slinky




C. S waves generated using a rope





### Surface Waves:






### Earthquake Location







## Earthquakes in NE United States and Canada 1990 - 2010



June 2010, Won-Young Kim, Lamont-Doherty Earth Observat Earthquake locations by the Lamont Cooperative Seismographic Network, US Geological Survey and the Geological Survey of Canada of Columbia University, <www.ldeo.columbia.edu/LCSN>





#### LANCASTER SEISMIC ZONE

EPICENTERS FROM: STOVER ET AL, 1981 DEWEY & GORDON, 1984 ARMBRUSTER & SEEBER

news/2004/story04-30-04b.html)

Armbruster and Seeber (1987)

### **IRIS Earthquake Browser**

^		- de la companio	A		<u> </u>						
Close	4	2.5	2.1	2	2.2	3.2	2.2	2.2	2.3	4.8	Mag
st 10 q	5	5	5	5	5	18	5	5	5	5	Depth km
Closest 10 quakes shown. Zoom to this vicinity	2011-12-31 20:05:01 41.12 -80.68	2011-09-30 00:52:38 41.14 -80.68	2007-01-03 09:08:31 41.73 -80.17	2005-02-10 04:39:15 41.68 -80.32	2005-04-20 21:36:09	1985-04-14 11:39:49	2010-12-10 21:26:32 41.51 -80.33	2014-02-09 22:34:05 41.48 -80.37	2008-07-21 01:41:30 41.47 -80.37	1998-09-25 19:52:51	Day
1. Zoom to	20:05:01	00:52:38	09:08:31	04:39:15	21:36:09	11:39:49	21:26:32	22:34:05	01:41:30	19:52:51	Time UTC
this vio	41.12	41.14	41.73	41.68	41.62 -80.41	41.33 -80.34	41.51	41.48	41.47	41.44	Lat
inity)	-80.68	-80.68	-80.17	-80.32	-80.41	-80.34	-80.33	-80.37	-80.37	-80.34	Lon
	46	44	34	26	20	13	7	4	ω	0	Dist km
											×
		1	1:3			8	P	5	0		

IRIS=Incorporated
Research Institutions
for Seismology
(www.iris.edu)

Sept. 25, 1998 Pymatuning, PA earthquake (Mag. 5.2)

andusky

Cleveland O

National Fores


Akron Toungstown

Canton

TO ME

Pittsburgh


### **IRIS Earthquake Browser**




Aug. 15, 1991 Centre Hall earthquake (Mag. 3)

### RIS Earthquake Browser

Dillsburg swarm





1.2 2.5

Harrisburg (322) Hershey


and 4.6 mainshock) 1994 Wyomissing (Mag. 4.0 foreshock Hills earthquakes

# Permanent Seismic Stations in PA through 2015


#### 3 Networks:

- **USGS National Network (2 stations)**
- Seismic Network (LCSN) (supported as a regional Lamont Doherty Earth Observatory Cooperative network by the USGS) (6 stations)
- Initial 10 PASEIS stations

### **USGS and LCSN Stations**



### Initial 10 PASEIS stations




# History of building a PA state seismic network

- 2006-2010 Establishment of the first 6 permanent PASEIS stations - DCNR
- 2009 Carbon sequestration technical assessment DCNR
- 25 portable seismic stations
- 2010 Purchase of 4 USArray stations from IRIS DCNR
- 2013 Earthquake monitoring during USArray DCNR
- Support for temporary network to densify the USArray network, develop seismicity catalog
- and provide seismic event information DCNR and DEP 2015 Expand the 10-station permanent network to 30 stations




#### **USArray**





### Stations 2/2013 to 12/2014



Over 100 3component high quality (broadband) stations

Recording continuously

Sample rates of between 40 and 100 samples per second



### (from Kyle Homman's MS thesis) PA seismicity 2/2013 to 12/2014


- Average number of stations used for each event: 10
- Minimum number of stations used was 4
- 1568 events with 1355 located in Pennsylvania

## Picking and Locating Events

- Used Antelope Software package
- Manually picked arrival times
- Filtered with a 1-5 Hz bandpass filter
- using IASP91 velocity model Preliminary locations from Antelope
- Relocated using HYPOELLIPSE and a velocity model for Pennsylvania
- Magnitudes determined using Richter's method for local magnitude


Adap+0d -	5	4	ω	2	1	Layer
Adapted from Katz (1955)	8.1	6.9	6.6	6.3	6.0	P-wave Velocity (km/s)
77)	37.0	30.0	20.0	10.0	0.0	Depth of Interface (km)
	1.74	1.74	1.74	1.74	1.74	Vp/Vs Ratio

Adapted from Katz (1955)



### Magnitudes and Depths


Local magnitudes range from 1.07 to 2.89



Catalog is complete to magnitude 2



Depths




### What are the sources of the seismic events?

### Several possibilities

- tectonic earthquakes
- mine blasts (quarries, coal mines, other mines)
- -induced seismicity from wastewater disposal wells
- induced seismicity from hydraulic fracking

### DISTRIBUTION OF PENNSYLVANIA COALS




## **USGS Event Classification for Blasts**


- Time of event (during working hours)
- (within 5 km) Location of events relative to mines and quarries
- Emergent phase arrivals
- Lack of clear S-wave arrivals
- Excessive low-frequency signal


Presence of a short period surface wave


## Spatial correlation with coal mines



## Spatial correlation with other mines









#### Blasting event

### Waveform characteristics


- Emergent phase arrivals
- Lack of clear S-wave arrivals
- Excessive low-frequency signal
- Presence of a short period surface wave

#### Earthquake





Non-mining events - 11 of them.




### What are the sources of the nonmining seismic events?

### Several possibilities


- tectonic earthquakes
- -induced seismicity from wastewater disposal wells
- induced seismicity from hydraulic fracking

### Induced Seismicity

- Induced events have occurred in several areas of the US
- Both wastewater injection and hydraulic fracturing can induce seismic activity events of both kinds in Ohio
- Pennsylvania has both hydraulic fracture wells and wastewater injection wells




### Are there spatial and temporal correlations with well activity?




 No correlation has been found with either injection wells or fracked wells


11 Non-mining events — they are all probably tectonic earthquakes Summary of findings: 1344 mining related events



## Expanding the Pennsylvania State Seismic Network

30 stations in the PASEIS network by summer 2016





42

40

SP-installed

SP-Needed

## PASEIS Seismic Equipment



Data logger/Digitizer



**GPS** clock



3-component ground motion sensor (vertical, north-south, east-west)

# What does a PASEIS station look like?



### PASEIS data are openly available from the IRIS Data Management Center http://ds.iris.edu/mda/ PENN) or (http://ds.iris.edu/mda/PE)



### IRIS DMC MetaData Aggregator

### **3**

Legend: N N O

### Virtual network summary (1 time span)

Virtual Network \_PENN :: Pennsylvania State Geological Survey :: \_PENN Network Map Start 2004/04/01 00:00:00

Stations for \_PENN virtual network (25 stations) :: Click column title to sort

2599/12/31 23:59:59

THE MARKET PORTS . A ST. TIP.	RIM PE PSAL PSU Altoona Campus, PA, USA	MA PE PASH Shawnee State Park, Schnellsburg, PA	RIM PE PARS Chapman State Park, Clarendon, PA	RIM PE PAMP Mt. Pisgah State Park, Troy, PA	_	RIM PE PALB Little Buffalo State Park, PA, USA	RIM PE PAKC Kettle Creek State Park, Renovo, PA	PAGS PA Geological Survey, Middletown, PA, USA	RIM PE PACH Chapman State Park, Clarendon, PA	⚠ PE NCAT NC A&T Campus	Network AT Station AT Site AT
******	40.543700	40.026000	39.886320	41,805900	41.725095	40,458910	41.374710	40.230000	41.756660	36.078958	Latitude A
22 022000	-78.414500	-78.635690	-80.445220	-76.668890		-77.167830	-77.932530	-76.720000	-79.171430	-79.771183	- Longitude A
Of the State of th	402	393	305	348	537	145	294	120	431	243	Elevation Av
חת מת מת מת המת מת מת מת מת מת בת בת	2004/01/01 00:00:00 2500/12/30 23:59:59	2004/01/01 00:00:00 2500/12/30 23:59:59	2004/01/01 00:00:00 2500/12/30 23:59:59	2004/01/01 00:00:00 2500/12/30 23:59:59	2004/01/01 00:00:00 2500/12/30 23:59:59	2004/01/01 00:00:00 2500/12/30 23:59:59	2004/01/01 00:00:00 2500/12/30 23:59:59	2004/01/01 00:00:00 2500/12/30 23:59:59	2004/01/01 00:00:00 2500/12/30 23:59:59	2004/01/01 00:00:00 2500/12/30 23:59:59	Ynet start Av Ynet end Av



### Station summary (1 time span)

Network	PE :: Penn State Network :: PE Network Map
Station	PACH :: Chapman State Park, Clarendon, PA :: Penn State Network :: PACH Station Map :: RESP :: SAC PZs :: XML
Latitude	41.756660
Longitude	-79.171430
Elevation	431
Start	2016/03/18 (078) 00:00:00
End	2599/12/31 (365) 23:59:59
Epoch	2016/03/18 (078) 00:00:00 - 2599/12/31 (365) 23:59:59
Instrument	Reftek 130 Datalogger
Channels (Hz)	Channels (Hz) Location -:: LOG (0)
Instrument	Nanometrics Trillium Compact/Reftek 130 Datalogger
Channels (Hz)	Channels (Hz) Location -: HHE (100) RA, HHN (100) RA, HHZ (100) RA, LHE (1), LHN (1), LHZ (1)
MetaData Load	MetaData Load 2016/04/15 (106) 14:10:37

### Virtual network affiliations:

Name	Description	Primary DC Secondary	
PENN	Pennsylvania State Geological Survey	PENN	
REALTIME	Stations collected and served in real time at the DMC IRIS DMC	OMC IRIS D	MC
.UNRESTRICTE	UNRESTRICTED All unrestricted stations, generated via cron	IRIS DMC	OMC
US-REGIONAL	US-REGIONAL US Regional Networks	PSU	

Real-time data availability (view Station Monitor)

the data View some of

Information on the data how to request

R 2016/05/06 (127) 00:00:00 2016/05/18 (139) 00:00:00

Archive data availability - Make a batch request for data (breq\_fast) - (data access overview)

### Station Monitor

### Choose a station

Network: PE

Station: WRPS

or choose: List Stations in Network WRPS - PSU, University Park, PA, USA

**Show Station** 

### WRPS - PSU, University Park, PA, USA

Network: PE - Penn State Network


Location: 40.79°N - 77.87°W

### **Daily Data**

Day: 2016-05-14

Location/Channels: O --: HHE/HHN/HHZ \$

Update



# PASEIS web site - coming soon

- Station information
- Station and event maps
- Instructions on obtaining data
- Seismic event information determined from the 42 stations in PA plus open stations in origin time and magnitude neighboring states – event location, depth,

## Minor earthquake measures near


city

Posted: Tuesday, April 19, 2016 12:08 am

By Stella Ruggiero sruggiero@titusvilleherald.com | = 0 comments

Titusville area on Monday, around 6:34 a.m. A small earthquake, which was likely too weak to be noticed by anyone other than geologists, measured in the


no reports of anyone experiencing the quake the scale, and not likely felt by many people, or maybe no one at all. As of late Monday afternoon, Root had received The quake was magnitude 2.2, according to AccuWeather meteorologist Jordan Root. He said it was fairly weak on



# State studying link between fracking, Lawrence County earthquakes


By Laura Legere / Pittsburgh Post-Gazette


April 29, 2016



### Earthquakes Induced by Hydraulic Fracturing in Poland Township, Ohio by Robert J. Skoumal, Michael R. Brudzinski, and Brian S. Currie

- March 4-12, 2014
- 77 events identified
- Magnitudes 1 to 3
- Correlated with fracking of the Utica Shale





magnitude >1

-initial analysis of data indicates >30 events with

earthquakes? Possibly

# Initial Performance of PASEIS network

## 2014 Poland Township events:

Initial event detected was magnitude 3

## 2016 Lawrence County events:

Initial event detected was magnitude 1.9

2 and larger events. PASEIS network is designed for detecting and locating magnitude

# Thanks to DCNR and DEP for promoting open data

access!





distribution! Thanks to IRIS for providing data archiving and





December 7, 2015

Mr. Marc Jacobs, Jr. Senior Vice President Penneco 6608 Route 22 Delmont, PA 15626

Re: Sedat #3A (Murrysville) - Reservoir and Fracture Characterization

Dear Marc,

The following summarizes the reservoir and fracture characterization for the Murrysville formation in the Sedat #3A located in Plum Borough, Allegheny County, Pennsylvania.

A series of tests were designed and conducted at the Sedat #3A to gain a better understanding of the reservoir and fracture characteristics of the Murrysville formation which underlies a sizeable portion of Penneco's proximate lease acreage.

The tests were comprised of (1) formation breakdown, (2) DFIT (diagnostic fluid injection test) to determine closure stress, reservoir pressure, and reservoir transmissibility (kH/mu), (3) Step Rate to determine the fracture extension pressure, and (4) Rate Stepdown to determine the near wellbore friction which includes perforation friction and friction caused by near wellbore tortuosity.

Table 1 shows the timeline of the work performed on the Sedat #3A.

Several high level observations from the work performed was that (1) the well goes on vacuum very quickly after injection stops (i.e., pressure goes to zero on the surface) and (2) the surface treating pressures were excessively high given the depth of the well and the closure stress.

On September 1, 2015 a DFIT was pumped to determine the closure stress, reservoir pressure, and reservoir transmissibility (kH/mu). The DFIT was pumped at 4 bpm for 1500 gals. Bottomhole pressure was recorded with a bottomhole gauge set 1910 ft. The results from the DFIT using the Nolte G function gave a bottomhole closure stress of 553 psi which gives a closure stress gradient of 0.29 psi/ft.

The pressure decline data after closure (ACA) was analyzed with the Nolte FR function to determine reservoir transmissibility. Based on the pressure response it appears that pseudoradial flow was reached. The reservoir transmissibility was 88 mD-ft/cP assuming a reservoir fluid viscosity of 1 cP. The actual results will vary based on the actual reservoir fluid viscosity. The formation capacity (kH) was 88 mD-ft. Assuming a height of 50 ft gives a reservoir permeability of 1.8 mD.

Following the DFIT, an attempt was made on September 29, 2015 to breakdown additional perforations with 500 gals of 15 percent HCL acid and small concentrations of sand pumped in a 20 lb/1000 gal linear gel. The surface pressure was reduced when the acid entered the perforations but quickly increased as low concentration (0.25 lb/gal) of 40/70 sand entered the perforations. The sand was cut and the well flushed.

On October 1, 2015 a Step Rate was pumped to determine the fracture extension pressure. The initial rate was 0.25 bpm and increased to 1.0 bpm in increments of 0.25 bpm. The rate was then increased to 4 bpm in increments of 0.50 bpm. The injection time for each rate was four hours.

The results from the Step Rate gave a fracture extension pressure of 1.70 psi/ft which is abnormally high and cannot be used for formation evaluation. The cause of the excessively high fracture extension pressure was near wellbore friction comprised of perforation friction and friction caused by tortuosity (i.e., a poor connection between the wellbore and the created hydraulic fracture).

Based on the results from the Step Rate another attempt was made to reduce the near wellbore friction with additional acid and higher injection rates. On November 17, 2015 several injections were performed to reduce near wellbore friction. The first injection consisted of 1500 gals 7.5 percent HCl acid and the second injection used 750 gals 15 percent HCl acid. Following the second acid injection the injection rate was 26 bpm and the surface pressure was 2980 psi.

A Stepdown was performed after the second acid injection to quantify the amount of near wellbore friction and break out the perforation friction and friction caused by tortuosity. Perforation friction varies with the flow rate squared and tortuosity varies with the square root of the flow rate. The results from the Stepdown show a total near wellbore friction of 2011 psi at 26 bpm of which 1300 psi is perforation friction and 711 psi is friction caused by tortuosity. The number of open perforations was 5 assuming a discharge coefficient of 0.60.

The perforation efficiency is very low with only 5 out of 41 perforations open.

The ISIP at the end of the last injection was 1446 psi giving a F.G (fracture gradient) of 1.23 psi/ft suggesting a possible horizontal component to the created fracture. The high fracture gradient could also be the result of near to mid-field fracture complexity. As with the other injections the surface pressure quickly fell to zero. This rapid pressure decrease following the rate shutdown is a common response for mid-field fracture complexity (i.e., restriction away from the wellbore).

The results from the tests on the Sedat #3A are shown in Table 2.

In summary the Murrysville formation in the Sedat #3A is characterized by low reservoir pressure, 232 psi, low closure stress, 0.29 psi/ft., and higher than anticipated pumping pressures because of complex near or mid-field fracture complexity. Low perforation efficiency also contributed to the higher than expected pumping pressures.

Thank you for the opportunity to work on the Sedat #3A project with Penneco. If you have any questions or comments let me know.

Sincerely,

Henry Jacot H-Frac Consulting Services, LLC

Table 1 - Timeline

Activity	Date
Perforate	August 7, 2015
Spot Acid and Pull Tubing	August 28, 2015
Break Formation and Pump DFIT	September 1, 2015
Perforation Cleanup	September 29, 2015
Step Rate	October 1, 2015
Perforation Breakdown	November 17, 2015

Table 2 - Results

Parameter	Value	
Breakdown Pressure	3115 psi	
Bottomhole Closure Stress	553 psi	
Closure Stress Gradient	0.29 psi/ft	
Surface ISIP	1446 psi	
Fracture Gradient	1.23 psi/ft	
Reservoir Pressure	232 psi	
Reservoir Transmissibility (kH/mu)	88 mD-ft/cP	
Formation Capacity (kH)	88 mD-ft	
Reservoir Permeability	1.8 mD	
Fracture Extension Pressure	N/A	

PENNECO SEDAT #3A

PLUM BOROUGH ALLEGHENY COUNTY, PA

December 7, 2015



### **TEST OBJECTIVES**

- ✓ Formation Breakdown Pressure
- ✓ Closure Stress
- ✓ Fracture Gradient (F.G.)
- ✓ Reservoir Pressure
- Reservoir Transmissibility (kH/mu)
- x Fracture Extension Pressure



### TIME LINE


Activity	Date
Perforate	August 7, 2015
Spot Acid and Pull Tubing	August 28, 2015
Break Formation/Pump DFIT	September 1, 2015
Perforation Cleanup	September 29, 2015
Step Rate	October 1, 2015
Perforation Breakdown	November 17, 2015



### **TEST RESULTS**

Parameter	Value	
Breakdown Pressure	3115 psi	
Closure Stress	553 psi	
Closure Stress Gradient	0.29 psi/ft	
ISIP	1446 psi	
Fracture Gradient	1.23 psi/ft	
Reservoir Pressure	232 psi	
Reservoir Transmissibility (kH/mu)	88 mD-ft/cP	
Formation Capacity (kH)	88 mD-ft	
Reservoir Permeability	1.8 mD	
Fracture Extension Pressure	N/A	






Murrysville type logs.

### SEDAT #3A WELLBORE SCHEMATIC \*\*\*Particle W. State of Market Mark


HFRAC

### PERFORATION DATA Value Description 0.58" **Entry Hole Diameter** 60 degree Phasing EHC Type 25 grams Charge 1896 ft to 1939 ft Depth 41 ea Perforations HFRAC

The Sedat #3A was perforated in the Murrysville from 1896 ft to 1939 ft with 41 0.58 in entry hole perforations. Perforation phasing was 60 degrees and the charge was 25 grams.




The Murrysville formation in the Sedat #3A was broke down on September 1, 2015. The breakdown pressure was 3115 psi. Following the breakdown the acid was displaced at 4 bpm. The well was on vacuum after shutdown with the pressure decreasing to zero in less than two minutes.



Following the formation breakdown a DFIT (diagnostic fluid injection test) was pumped in the Murrysville to determine closure stress, reservoir pressure, and reservoir transmissibility (kh/mu). Prior to starting the DFIT the whole was loaded with water. After the hole was loaded 1500 gals of water was pumped at 4.1 bpm. The average surface treating pressure was 2902 psi and the average bottomhole treating pressure was 3816 psi.

During the injection the surface pressure increased from 2700 psi to 3100 psi with a constant rate indication some type of restriction.

After the rate went to zero the surface pressure declined rapidly and went to zero. The bottomhole pressure was recorded with a bottomhole pressure gauge at 1910 ft.




The bottomhole pressure from the DFIT was analyzed with the Nolte G function to determine the closure pressure and closure stress gradient.

Following the injection the pressure declined rapidly. The rapid pressure decline is most likely caused by fracture complexity and low closure stress and not leakoff into the formation.


The estimated bottomhole ISIP is 960 psi resulting in a fracture gradient of 0.50 psi/ft.

Closure occurred at a Nolte G time of 7.2 giving a bottomhole closure of 553 psi. The closure stress gradient is 0.29 psi. The net pressure was 407 psi and the fluid efficiency was 79 percent.



The bottomhole pressure after closure was analyzed using the Nolte FR function. If the late time data reaches pseudoradial flow estimates of reservoir transmissibility (kh/mu) and reservoir pressure can be determined.

The results from the Nolte FR function show that pseudoradial flow was reached. P\* was 232 psi. The formation capacity (kH) was 88 mD-ft assuming a reservoir fluid viscosity of 1 cP. Using a formation height of 50 ft the reservoir permeability is 1.8 mD.




On September 29, 2015 an attempt was made to remove excess friction seen on the DFIT. 500 gals of 15% HCL was pumped. A decrease on the surface treating pressure was seen when the acid was on the perforations. The surface pressure decreased and the injection rate was increased to 12 bpm. The surface pressure continued to decrease to 2500 psi.

Low concentration (0.25 lb/gal) of 40/70 sand was pumped in an effort to remove the excess friction. The surface pressure initially decreased with the 40/70 sand on the perforations but increased rapidly to over 3000 psi on the surface. The maximum pressure on the packer was 4000 psi so the injection was decreased to 11 bpm then to 7 bpm.

The calculated bottomhole pressure remained close to 4000 psi and was erratic.


The rate was reduced and the pressure declined to zero in less than two minutes.



A Step Rate Test was pumped on October 1, 2015 to determine the fracture extension pressure. The initial rate was 0.25 bpm and increased in 0.25 bpm increments until 1 bpm where it was increased to 4 bpm in 0.5 bpm increments. Injection period for each rate stage was 4 hours.


Following the rate increases the rate was decreased from 4 bpm in 1 bpm increments until the rate reached zero.

Total injected volume was 4292 bbls.



Analysis of the Step Rate gave a fracture extension pressure of 3255 psi and fracture extension gradient of 1.70 psi/ft. This high of extension pressure gradient is unrealistic and cannot be used.

The high fracture extension pressure gradient is a result of excess near wellbore friction as evidenced by the sudden pressure increase with each rate increase (slide 13).




On November 17, 2015 additional acid was pumped in an attempt to breakdown additional perforations and remove excess near wellbore friction to establish better communication between the wellbore and created hydraulic fracture.

The first acid injection consisted of 1500 gals 7.5% HCl and the second acid injection was 750 gals 15% HCl acid.


Following the acid injections the maximum rate was 26 bpm at an average surface pressure of 2980 psi.

A rate stepdown was performed at the end of the acid breakown. An additional injection was pumped at 15 bpm to establish an ISIP.

The ISIP was 1441 psi.




This plot shows the calculated bottomhole pressure from the acid breakdown.



This plot zooms in on the rate stepdown and final injection. The final rate on the stepdown was 4.4 bpm and the pressure was 1118 psi. The final ISIP was 1446 psi giving a fracture gradient of 1.23 psi/ft


This high of fracture gradient may be caused by either a horizontal fracture or excess fracture complexity.



A Stepdown Analysis was conducted to determine the cause of the excess near wellbore friction.

STE											
N Masta	Chipelation	Bhoarent/P	har Lamban	g Persona (a Sin 4	goladedin	andownounds	sc - (Anarysis W	and Ethel 59	include AP Fr	ul disconnection	
Mil See	Clats Analysis P	ing Gutter	men. Inosi	Morocan Davi							
Regent	ya Santaya Nobel G	Too Regen	erors traffects for	gt Didta fesse	Step Coloni No.	18:4					
W 11 W	0.00							Ann arrangement of the		MENTAL SALE	100000000000000000000000000000000000000
			Value								
	6, 94	,		24/4							
and the same	in county of which										
1 1	or a peaking town.										
I market	Main Southwest -	cette art									
	adout ingrested			1.00							material Co.
											Apparent 1000
-			September	0.624	1000	att tree.		ar retaining	on ment life at	38 fear Conse	Page of San Page
	Simen (moits)	kate tom	STEP HAND	freduit.	Date.	21)	All tear	t-	200		183
8	(man)							- 9			1 \$8400
8 0	78 (7.087)		1146.00	274.00	A. SALES	THE STREET	p.08760	766.862	341 (39	229 709	2 21401
	1/ 1571	1000	10/24 ( )	145 51			10 35 F4 62 7689		30).714	742.mtc	2.54942
	77.2667	14.00	2999 53	1510 64	54 1/4/7	District of the last of the la	64 6490	1241 80	0.04 404	141 49	3 5014
	25 Mar./	19.16	2502.78			STREET,	99.50	1911 84	364.963 1245.00	723.6	+ 010-49
-	6 20.45	20.78	2159.93	1141,141	114 /14		5.64 245 COUNTRY WEST SE				
M 1008	Yes and the same										
1 1984											
\$ 1800											
1	te Cesunghor										General Assaulten
9 2 10	and the second									and the same and	APPENDICT NEWSFILM

Stepdown Table showing the point selection and friction values.



The Stepdown Analysis gives a total near wellbore friction of 2011 psi at 26 bpm. Of which 1300 psi is perforation friction and 711 is near wellbore tortuosity. The resulting number of perforations is 5 assuming a discharge coefficient of 0.60.

### SEDAT #3A SUMMARY

- A series of injections were pumped on the Sedar #3A to determine closure stress, fracture gradient, reservoir pressure, reservoir transmissibility (permeability), and breakdown pressure.
- During the injection tests excess friction existed either because of limited number of perforations open or near wellbore fracture complexity.
- Attempts were made to reduce the excess friction with acid, higher rates, and low concentrations of 40/70 sand. Acid and higher injection rates removed some of the excess friction but the high excess pressures still existed.
- The rate stepdown analysis showed total near wellbore friction of 2000 psi comprised of 1300 psi of perforation friction and 700 psi of near wellbore tortuosity of fracture complexity.



### SEDAT #3A SUMMARY (CONT.)

- The rate stepdown shows only 5 perforations open out of 41 perforations.
- After each injection the pressure quickly fell to zero at the surface because
  of the low closure stress of the Murrysville.
- The closure stress determined from the DFIT was 553 psi giving a closure stress gradient of 0.29 psi/ft. The Murrysville in the Sedat #3A cannot support a column of water.
- The DFIT reached pseudoradial flow. The After Closure Analysis with the Nolte FR function gave a reservoir transmissibility (kH/mu) of 88 mD-ft/cP assuming a reservoir fluid viscosity of 1 cP. Assuming a height of 50 ft the reservoir permeability is 1.76 mD.




### SEDAT #3A SUMMARY (CONT.)

 The ISIP at the end of the last injection was 1446 psi giving a fracture gradient of 1.23 psi/ft suggesting a possible horizontal fracture. The high fracture gradient could also be the result of near or mid-field fracture complexity.



APPENDI	ıx		The second of th
			AND DESCRIPTION OF THE PERSON
HERAC			



## AFTER CLOSURE ANALYSIS

- The reservoir transmissibility (kh/μ) can be calculated by analyzing the pressure decline data after closure; if the late time pressure data reaches pseudo-radial flow.
- Similar to a Horner analysis with the reservoir transmissibility calculated from the slope of the late time data.
- The pressure data when plotted on log-log scale will exhibit a slope of unity when pseudo-radial flow has developed.



## RADIAL FLOW TIME FUNCTION

$$F_R(t, t_c) = \frac{1}{4} \ln \left( 1 + \frac{\chi t_c}{t - t_c} \right)$$

ts nere

y = 16 T

t = time to closure, min

f time, mr

 $F_3$  - radial flow function

e ig 190 fe - 505 (86 fe



## AFTER CLOSURE ANALYSIS

$$kh/\mu = 251,000 \left(\frac{V_t}{m_R t_c}\right)$$

n here

k = reservoir permeability, mD

h = net pay. ft

u≈reservoir fluid viscosity, cP

I'-volume injected, bbl

m<sub>2</sub> - slope

t time to closure, min

e G No. ne - SAE 38676



API Permit #: 37-003-21223 Customer: PENNECO

Lease and Well Name: SEDAT #3A

A.F.E #: N/A



**Cement Slurry Information** 

Job Type: MISC. PUMP PTA

Cement Operator: LANCE SHIREY

Date Cemented: 8/28/2015

Drilling Contractor: SERVICE RIG

No. of Sacks		Cement Blend Co.						Yield (ft³/sk)	MixWater (gal/sk)	Density (lb/gal)	(bbl) Mix Water	(ft3) Of Slurry	(bbl) Of Slurry
			Amount										
	A-tone									Totals			
					W	/ellbore l	nformati	on					
		New/Used	Diameter (In)	Weight	Тор	Bottom					Request	ed TOC (ft)	SURFAC
Cas	sing	Used	4 1/2	(lb/ft) 10.5	SURFACE	(ft) (psi)				-	5 (0)		
Previou	s Casing						1,041				10	D (ft)	N/A
	r Drillpipe	Used	1 1/2	4.6	SURFACE	1,930	ļ				Displacem	ent Depth (ft)	
	n Hole n Hole												-
										1	Displace	ement (bbl)	
	Pun	ping Ret	urns		Cemei	nt Slurry	Tempera	ture Rec	ord (°F)		Fluid Inf	formation	1
		Return Seen A			Cement	Reading 1	Reading 2	Reading 3	Average		x Water Temp		
		s Seen at Surf ent Returns (B		-	Blend 1 Blend 2	-	-	-	-		lacement Flui cement Fluid		Brine
	iount or out	one reading (a	- C	1	Blend 3						nent Fluid De		8.3
Ti	me	Rate	(bpm)	Volun	ne (bbl)	Pressu	ıre (psi)		Ever	nt or Sta	ge Descr	iption	
12	2:15											Run Casing	
Manufacture Control		-						-			s, Hold JSEA ety Meeting	١,	
										Load Line	s, Test Lines		
	3:00	The same of the sa	2		1 4.8	0-25 25			DI		WATER	AEI/	
	3:02 3:04		2	<u> </u>	4.8	25				.5%IRON CH WATER	1EK		
	3:06								SI	HUT DOWN	PULL TUB	NG	
15:00	9-15:27	-	-4		6	0.	3000	DI	JMP WATER		5 W/ RIG	IN ECONAL	ION
	5:27	1			0	0-	3000	-	DIVIP WATER		DOWN	IN FORMAT	ION
											CK UP		
16	5:00					-		-		LEAVE	OCATION		
		<del>                                     </del>						<b>+</b>		-			
		-						-					
											1000		
		-		-		-							
		-				-							***************************************
		-		-		-		-					
Com	ments:			Ц	EDAC	Dono	v+ F	2000	20				
				П	FRAC	veho	71 L - F	age 4	25				
										-	hank You fo	r your Busir	1888
											nann rou fo	your busin	1633
LIMS Con	ment Operato	r Slanature					Customer	Representati	ve Signature:				
0.10 001	operatu	g.,m.=10:		LANCE	E SHIREY								
													100

		T	REATM	ENT SI	JMMARY			
Customer Name:	Penneco			DFI		Date	9/29/1	5
Well Name:	Sedat #3A			4100				
	PRESSURES IN P	SI			CI	LEAN VOL	UMES IN GAL	
BREAKDOWN	0 TOP PERF MD_		1896		TOP PERF TVD_	1896	PAD	70
AVERAGE 2341	BTM PERF MD		1936		BTM PERF TVD	1936	DISPL	30
SHUT IN: INSTANT	1251 5-MIN _	0	10-MIN	na	TREATMENT_	247	TTL VOL	100
	HYDRAULIC HORSEP	OWER				RATES	IN B.P.M.	
USED	671		~		AVG TREATING _	11.7	MAXIMUM	11.9
DESCRIPTION OF JO	В				DFIT			

ESCRIPTION OF	JOB		DFIT	
Time	Rate (bpm)	Slurry Volume (gal)	Pressure (psi)	Description of Stage or Event
8:45	na	na	na	Hold Safety Meeting
9:11	na	na	na	Prime Pumps
9:17	na	na	4752	Pressure Test Lines
9:20	na	na	na	Fix Leak
9:28	na	na	na	Prime Pumps
9:29	na	na	5132	Pressure Test Lines
9:33	0.0	0	0	Load Hole
9:37	0.0	21	45	Pump Pad
9:41	na	na	na	Prime Acid
9:44	0.0	40	68	Pump Acid
9:50	0.1	40	1328	Displace Acid/Pump Pad
10:00	4.0	64	2900	Break Formation
10:05	11.9	107	2700	Establish Rate
10:05	11.9	110	2693	Start Sand @ 0.25 40/70
10:12	11.6	175	2852	Start Sand @ 0.30 40/70
10:12	11.7	193	2885	Cut Sand/Flush
10:22	5.0	273	2640	Establish 5.0 bpm
10:23	3.2	275	2031	Establish 3.0 bpm
10:25	2.4	280	1755	Establish 2.0 bpm
10:26	1.4	284	1624	Establish 1.0 bpm
10:28	0.0	287	1251	Shutdown
		Totals		
Sand	40/70	9	Sks	
Chemicals	Unislick ST-50	5	Gals	
	Unigel 5F	175	Lbs	Attorn
	LEB 10X Breaker	0.4375	Gals	
				UNIVERSAL WELL SERVICES, INC.
	15% HCL	495	Gals	

API Permit #: 3700321223

Customer: PENNECO OIL COMPANY

Lease and Well Name: SEDAT 3A

A.F.F. N/A



Job Type: DFIT

Coment Operator: JAMES CAMPBELL

Date Comented: 10/1/2015

No. of									Density	(bbl)			
Sacks	Cement Blend Composition				Yleid (ft³/sk)	MixWater (gal/sk)	(lb/gai)	Mix Water	(ft3) Of Sturry	(bbi) Of Siu			
				1A	fellbore l	nformatio			Totals		. 7		
		Diameter	Weight	Тор	Bottom		pse/Burst Pres	SUITES		T	4 700 (11)		
	New/Used	(in)	(lb/ft)	(ft)	(R)	Colle	(psi)	20149		Requeste	d TOC (ft)		
Casing			10.5	SURFACE	1,930					TVI	(ff) C		
Previous Casi Tubing or Drillp										Displaceme	ent Depth (ft)		
Open Hole										Displacemo	ur paper (it)		
Open Hole							***************************************	<u> </u>		Displaces	ment (bbl)		
	Pumping Reti	ıms		Ceme	nt Slurry	Tempera	ture Reco	rd (°F)	1 W== 1	40 9 0	ormation		
	Sweep Return Seen A			Cement	Reading 1	Reading 2	Reading 3	Average		x Water Temp			
	Cement Returns Seen at Surface Amount of Cement Returns (BBL)		Blend 1 Blend 2							Displacement Fluid Type Haplacement Fluid Temp (°F)			
Amount	or comercine to	32,		Blend 3						nent Fluid Den			
Time	Rate	(bpm)	Volun	ne (bbi)	Pressu	re (psi)	<u> </u>	Ever	t or Sta	ge Descri	ption		
0730		(								ATION, HOLD			
0745								SPOT TRUC	KS, MAKE	HOOKUPS, V	WAIT ON RIC		
					0.0	200		1	HOLD SAFETY MEETING LOAD LINES, PSI TEST				
0927 0932		-1 -2	. 1			100	PUMP WATER TO LOAD HOLE						
0944		25	2.7		0-450		PUMP WATER TO START DFIT						
0955		0		0		0			NN, RELEASE PRESSURE, UNHOOK				
1006		25		80	0.	700	WELL HEAD FLANGE NEEDS TIGHTENED PUMP WATER TO START DFIT						
1005		5		20	0-700 450-825		RATE CHANGE TO .5 BBL/MIN						
1805		75		80	825-1075		RATE CHANGE			GE TO .75 BBL/MIN			
2206		1		240	1075-1330					CHANGE TO 1 BBL/MIN			
0205		.5		360	1330-1770					ANGE TO 1.5 BBL/MIN HANGE TO 2 BBL/MIN			
0605 1005		.5		800	1770-2004 2004-2162			RATE CHANGE RATE CHANGE					
1406		3		20		-2400		RA	TE CHANG	E TO 3 BBL/	MIN		
1806	3	.5		140		-2600				TO 3.5 BBL			
2205		4		12		-2500		RATE CHANGE TO RATE CHANGE TO					
0011		3		90		-2250 -2050				E TO 2 BBL/			
0111		1		30		-1450				E TO 1 BBL/		-	
0141		)		0		27-0		SHUTDOV	VN, MONIT	OR PRESSU	RE 10 MIN.		
0155								REL		SSURE, UNH	OOK		
0200 0230								JOBC		LEAVE LOC	ATION		
0230													
	1						ERE SHUT					_	

Customer Representative Signature:

			TF	REATME	NT S	UMMARY			
Customer Name:	Penr	neco Oil Co		Acid Breakdown			Date	e: 11/17	115
Well Name:	Se	edat #3A							
	PRESS	URES IN P	SI			CI	LEAN VO	LUMES IN GAL	
BREAKDOWN 311	4 TOP F	PERF MD		1896		TOP PERF TVD	1896	PAD	
AVERAGE 2506	BTM F	PERF MD		1936		BTM PERF TVD	1936	DISPL	1270
INSTANT	1401	5-MIN	0	10-MIN	0	TREATMENT	27888	TTL VOL	36750
	HYDRAULI	CHORSEP	OWER				RATES	S IN B.P.M.	
USED		1130	)			AVG TREATING	18.4	MAXIMUM	26.3
DESCRIPTION OF JO	OB				S	lickwater Fracture			

ESCRIPTION OF	- JOR	3	lickwater Fracture	·
Time	Rate (bpm)	Slurry Volume (bbl)	Pressure (psi)	Description of Stage or Event
5:00				Arrive on location, rig up
7:06				Hold Safety Meeting
7:31			4160	Test Lines
7:33				Fix Leak
7:37			4665	Re-Test Lines, Good Test
8:09				Open Well
8:17	2.7	0	1766	Pump Water
8:19				Shutdown, Re-Prime Pump
8:21	2.7			Pump Water
8:23			1	Shutdown, Replace Hose
8:27				Re-Prime Pump, Inspect Pump
8:52	5	32	2320	Pump Water
8:55	7.2	40	3114	Break Formation
8:57	10.7	55	3058	Pump Tripped Out, Resume Pumping
8:58	14.1	68	3031	Establish Rate
8:59	4.0	75	1815	Pump Acid
9:07	6.4	110	2167	Displace Acid
9:09	14.1	126	2733	Acid to Perfs
9:12	20.1	171	2802	Establish Rate
9:13	16.0	183	2236	Stepdown Rate
9:14	5.1	198	1279	Stepdown Rate
9:15	0.0	203	261	Shut Down
9:21	3.7	204	1401	Pump Water
9:21	4.0	204	1520	Pump Acid
9:25	4.0	239	1385	Displace Acid
9:28	26.0	284	3005	Establish Rate
9:41	20.8	609	2541	Stepdown Rate - 20 BPM
9:41	16.1	620	2164	Stepdown Rate - 15 BPM
9:42	14.2	636	2006	Stepdown Rate - 14 BPM
9:43	8.6	650	1387	Stepdown Rate - 10 BPM
9:45	4.4	656	1117	Stepdown Rate - 5 BPM
9:46	0.0	664	0	Shut Down
5.40		Totals		
Chemicals	Unigel 5F	0	Lbs	
	LEB 10X Breaker	0	Qts	
	FRP 121	110	Lbs	7_\
				WELL SERVICES, INC.
Acid	15% HCL	750	Gals	
	7.5% HCL	1,500	Gals	



#### **CWM** Environmental

101 Parkview Drive Ext. Kittanning, Pennsylvania 16201 724-543-3011 Lab # 03-457

#### Lab Analysis Report

Sample Number: 07163702

Customer: Penneco Oil Co., Inc.

Collection Date:

07/29/16 13:00

Site: Gas Well

Received Date:

07/29/16 15:43

Monitoring Pt:

DeSimone #3

Matrix: Non Potable Water (NPW)

Source Type:

Discharge

**Collection Method:** 

Grab

07163702	Result	Reporting Limit	Method	Analysis Date	Analyst
Specific Gravity	1.1027 grams/ml	grams/ml	ASTM D1429	8/3/16 0:00	33-325
Total Dissolved Solids	140958 mg/L	5 mg/L	SM 2540 C	8/3/16 8:12	PLP
pH	5.78 SU	SU	SM4500 H+B	8/1/16 13:00	EJK

#### Sample Comments:

pH: The pH result measured @ temperature of 25 deg C pH: The pH was analyzed outside of the 15 minutes holding time.

Degen C Stole

Ryan C Shafer, Vice President of Operations

\nalyst Reference: 33-325 - G & C Laboratory

HFRAC Report - Page 33

9:51:16AM Confidential Page 1 of 1 Printed: 8/26/2016



#### **CWM** Environmental

11931 State Route 85
Kittanning, Pennsylvania 16201
724-543-3011
Lab # 03-457

#### Lab Analysis Report

Sample Number: 09150657

Customer: Penneco Oil Co., Inc.

Collection Date:

08/28/15 08:00

Site: Sedat #3A

Received Date:

09/04/15 16:17

Monitoring Pt:

Tank Water Matrix

Matrix: Non Potable Water (NPW)

Source Type:

Discharge

Collection Method:

Grab

09150657	Result	Reporting Limit	Method	Analysis Date	Analyst
Specific Gravity	11084 gr/ml	0 gr/ml	ASTM D-1298	9/9/15 0:00	33-325
pH	4.69 SU	SU	SM4500 H+B	9/9/15 13:30	JRD
Total Dissolved Solids	155476 mg/L	5 mg/L	SM 2540 C	9/8/15 16:03	ARB

#### Sample Comments:

pH: The pH result measured @ temperature of 25 deg C pH: The pH was analyzed outside of the 15 minutes holding time.

Degen C Stob

Ryan C Shafer, Vice President of Operations

HFRAC Report - Page 34

Analyst Reference: 33-325 - G & C Laboratory

Analyte names in bold are listed under the laboratory's current NELAP scope of accreditation.

Printed: 9/14/2015 1:07:25PM **Confidential** Page 1 of 1

Universal Well Services, Inc. Chemical Technology 13549 S. Mosiertown Road Meadville, PA 814-373-3107



## **Laboratory Water Analysis**

## Sample Information

Penneco
Sedat 3a
Frac Water
Tide Water
9/23/2015
9/23/2015
Bilich

## **Analysis Results**

#### Sample 1 Sample 2

pH	4.90	5.10	
Temperature	74.4	74.3	
Specific Gravity	1.110	1.132	
Fluid Density	9.26	THE RESERVE OF THE PARTY OF THE	lb/gal
Chlorides (titrated)	100,000	120,000	
Total Dissolved Solids	159,500	191,400	
Total Suspended Solids	N/A	THE RESERVE OF THE PERSON NAMED IN	mg/L
Approximate Salt Percentage	14.4	16.9	-
Total Hardness	67,000	70,000	
Ca Hardness	63,000	60,000	
Ca <sup>2+</sup>	25,200	24,000	-
Mg Hardness	4,000	10,000	
$Mg^{2+}$	971	2,428	THE REAL PROPERTY AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IN COLUM
Total Iron (titrated)	437	THE RESERVE AND ADDRESS OF THE PARTY OF THE	mg/L
Sulfates	39		mg/L
Hydroxide Alkalinity as CaCO <sub>3</sub>	0	The second secon	mg/L
Carbonate Alkalinity as CaCO <sub>3</sub>	0		mg/L
Bicarbonate Alkalinity as CaCO <sub>3</sub>	0		mg/L
Total Alkalinity as CaCO3	0		ng/L
fannin/ Lignin	N/A	N/A	
Barium/ Strontium PS	< 1	< 1	white the same of
pecific Conductance	172,500	193,200	the same of the sa

HFrac Report Supplement Items 5 and 7

#### Item 5 Attachment Geologic Data

The Fracture Gradient (F.G.) 1.23 psi/ft was calculated using the ISIP (instantaneous shut-in pressure) of 1446 psi and fluid S.G. of 1.10 psi/ft. The mid-perforation depth was 1917.5 ft (1896 ft - 1939 ft).

$$F.G. = \frac{ISIP + HydrostaticHead}{Depth}$$

$$F.G = \frac{1446 + 913}{1917.5} = 1.23$$




Figure 1 - Sedat 3A Injection Test pumped on November 17, 2015. ISIP 1446 psi.




Figure 2 - Sedat #3A Injection Test pumped on November 17, 2015 (zoomed). ISIP 1446 psi

#### Item 7 Attachment Geologic Data

The reservoir permeability of 1.80 mD was an average permeability using a formation height of 50 ft. Using a reservoir permeability of 1.8 mD and formation height of 50 ft the formation capacity (k/H) was 90 mD/ft.

The bottomhole pressure after closure was analyzed using the Nolte FR function. If the late time data reaches pseudoradial flow estimates of reservoir transmissibility (kh/mu) and reservoir pressure can be determined.

The results from the Nolte FR function show that pseudoradial flow was reached. P\* was 232 psi. The formation capacity (kH) was 90 mD-ft assuming a reservoir fluid viscosity of 1 cP. Using a formation height of 50 ft the reservoir permeability is 1.8 mD.




Figure 3 - Sedat #3A After Closure Analysis (ACA)

$$kh/\mu = 251,000 \left(\frac{V_i}{m_R t_c}\right)$$

where

k = reservoir permeability, mD

h = net pay, ft

 $\mu$ =reservoir fluid viscosity, cP

 $V_i$ =volume injected, bbl

 $m_R = \text{slope}$ 

 $t_c$  = time to closure, min

# Attachment H Operating Data Sedat #3A Injection Well

#### Injection Rates and Volumes

1) The proposed average injection rate is 1,800 BBLs of water per day and the maximum rate should be no greater than 2,000 BBLs of water per day or 54,000 BBLs per month.

#### **Injection Pressures**

2) Injection pressure is expected to be below 1,420 psi, the calculated maximum injection pressure at the well head, without accounting for any friction through the perforations through the 7" casing and the pipe friction through the 4 ½" injection string. The bottom hole pressure/reservoir pressure as measured with a bottom hole pressure gage is 232 psi.

The maximum injection pressure of 1,420 psi, was calculated using the formula published in 40 CFR 147.1953, Pm = [(FG - (0.433)(Sg)]D, for a column of water. The fracture gradient of 1.23 from the Reservoir and Characterization study found at the end of Attachment G was used. The Sg used was 1.11, the Sg of the produced brine water used in the formation study and a depth of 1,896' the top perforation in the Sedat #3A. [Pm = (1.23 - 0.433 (1.11))1896]; Pm = 1,420#.

#### **Annulus Fluid**

3) Fresh water will be in placed in the 4 ½" by 7" annulus, mixed with a chemical such as ALPHA 3207 which acts as a corrosion inhibitor and bacteria growth preventer. One (1) gallon of ALPHA 3207 will be mixed with approximately every 1,000 gallons of fresh water placed in the annulus. The MSD sheet for the chemical mixture ALPHA 3201 listing ingredients and physical data is included in this section. Positive pressure will be maintained on the annulus to monitor mechanical integrity.

#### Source and Analysis of Injection Fluid

4) The source of the injection fluid will be E&P wastes, produced water from oil and gas wells and flow back fluid from oil and gas well stimulation activities. Penneco Environmental Solutions, LLC will accept fluid generated by other drilling and production companies (filing a commercial application) The geographic area from which fluids will be generated is Western Pennsylvania and possibly a small amount of the fluids may originate in the shale gas fields of North Eastern Pennsylvania. Representative sample analyses from two wells are included with this attachment. Before injection the produced fluid will be analyzed for the parameters required by the permit. The produced fluid and flow back water will be subjected to treatment and passed through a filter to remove

large particles and suspended solids from the fluid before injection. The solids removed will be transported to an appropriate waste disposal site.

8-24-16

## Attachment P Monitoring Program Sedat #3A Injection Well

#### Monitoring Program for Sedat #3A Injection Well

The Sedat #3A injection well will be monitored for the well's entire life in compliance with all EPA monitoring guidelines and reporting requirements.

The injection site is located so that the facilities cannot be seen from public roads or public or private properties adjacent to the site. The access road is gated and will be locked when the site is not operating. The injection site and surface facilities will be fenced and lighted at night with the fenced gate locked when the site is not operating.


There will be one (1) monitoring well, identified by its Pennsylvania issued permit number, 003-21210. This is a depleted gas well that will be adapted for use as an observation well and is 1,010' to the south west of the Sedat #3A, see well plat map at end of Attachment. The well has satisfactory spacing and placement to provide adequate sampling area without having to drill a well or wells for the specific propose of sampling. A monitoring string set on a packer immediately above the Murrysville Sand will be installed to isolate the Murrysville injection zone. Penneco will sample, monitor and record quarterly, or more often if required by permit, the fluid level in the Sedat #1 monitoring well, either by slick line or service rig. The company will monitor the pressure at the well head and as well as the 7" – isolation string annulus. The results will be reported as required by permit or according to EPA guidelines. Any change in fluid level or fluid makeup will be investigated as to its cause. Quarterly mechanical integrity testing will also be conducted.

Pressure and rate monitoring will be at the well site (wellhead); both injection pressure and the pressure on the 7" by 4 ½" annulus will be monitored. The company will also conduct quarterly mechanical integrity testing as required by Pennsylvania Oil and Gas regulations. Pressure will be measured by use of a continuously recording pressure gage and the injection rate by a continuously recording flow meter. Results will be reported to the EPA as required by the injection permit or according to EPA guidelines, but not less than annually.

The specific gravity of each truck load will be measured to ensure the specific gravity of the fluid to be injected does not exceed the allowed value.

Injection fluids will be sampled and analyzed quarterly with the sample taken at the injection site (wellhead). The results will be reported as required by the permit or according to EPA guidelines.

The company will also be prepared to conduct any other monitoring or sampling as required by the permit.



Phone (903) 234-8443 Fax (903) 234-1641

September 28, 2016

Longview, Texas 75606-4029

Mr. Marc Jacobs Penneco Environmental Solutions, LLC 6608 Route 22 Delmont, Pa 15626-2408

RE: Proposal for a Surface Facility for your proposed Sedat #3 SWD

Dear Mr. Jacobs,

Titanium Environmental Services, LLC (TES) is pleased to present the draft drawings and process flow for Penneco Environmental Solutions, LLC (PES) Sedat #3 Salt Water Disposal (SWD) well surface facility. As previously discussed, PES and TES agree that safe and environmentally sound design and operations are paramount to meeting PES's expectations for their operation.

In that vein, TES has proposed a facility that would be acceptable for Resource Conservation and Recovery Act (RCRA) waste operations. TES believes that ultimately the requirements for wells and surface facilities that manage class II waste related to exploration and production will be raised to match those presently applicable to class 1 non-hazardous well and facility operations. Some of these requirements will be very expensive or even impossible to incorporate into existing wells and surface structures. As the cost to construct the well(s) and surface equipment with the safeguards that will be regulatory mandates is not significant, if incorporated with the construction design, we recommend and have incorporated these protective components into our plans.

The entire surface facility will be built atop a multilayered secondary containment system/structure. The facility will begin with a base layer of clay, felt liner, 60 mil High Density Polyethylene (HDPE) liner, and another felt liner, perforated liquid collection pipe system covered by pea gravel, concrete containment floor and walls. The edge of the HDPE liner will be folded up against the containment walls to keep rainwater from entering the system. The liquid collection system piping will be extended from under the containment to allow for inspection or liquid (condensation) removal and as the last mechanical containment to intercept a leak.

Notice the truck unloading pad is built to prevent rainwater run on and all rainwater or truck leakage will be collected by the truck bay collection system which empties into the solids settling tank containment which can hold all the trucks that could be in the truck bays. All sump pumps automatically empty the sumps without human intervention. If the receiving tanks can't hold the trucks trying to unload (Level transmitters) the system closes all unloading lines until there is sufficient room to


continue unloading. Further if there is insufficient room in the storage tanks, the system will not let the transfer pumps move fluid from the receiving/settling tanks to the storage tanks. Thus the unloading valves won't open nor will the transfer pumps transfer fluid into tanks that are already full. The water filtering pumps will transfer filtered water into the pre-injection tanks (Filtered Water) as long as the fluid level in the filtered water tanks does not exceed the upper limit established by the operator. The injection pumps will inject water into the well as long as there is sufficient filtered water to inject and all control parameters for the well are within preset value ranges.

All liquid unloading at the facility will enter tanks that are equipped with internal piping that allows fluids to be introduced under the liquid level in the tanks (submerged loading). Submerged loading is a recognized method of reducing emissions. All liquid transfer systems are connected together by a vent header to vapor balance the exchange between the receiving and transferring tanks. All used filters and tank cleanout solids are collected and disposed of to a permitted facility.

TES suggest Standard Operating Procedures (SOP) and daily facility inspections which would not be addendums to the Permit as they will have to be modified over time and could be "Permit Modifications" if they were addendums. All waste should have an approved profile to be accepted at the facility. All trucks would be unloaded through Mass Flow Meters recording density and volume. Likewise Mass Flow Meters would be used for injection measurement for reporting of density and volume.

Simplicity in design with many passive controls that don't require human attention or maintenance is TES's design goal. The design also reduces the number of incidents/accidents caused by operator error or inattention. Tanks that might fail, can be valved out of operation and bypassed with no effect on the operation. There is one transfer pump (plus one standby), one filter pump (plus one standby), one charge pump (plus one standby) and one injection pump (plus one standby). Three unloading bays and only one or two required. Since the PLC logic instructs the continuous filtration and injection of water, the only operator interaction is changing the filters when required and making sure inbound trucks/loads are approved into the facility and then enabling the specific unloading valve. All sump pumps activate automatically and are freeze protected as is the transfer pump. All containments have a fluid level alarm to detect leaks and have reduced height walls between them that together can contain 110% of any of the tank systems plus a twenty-five year 24 hour rainfall event.

If you have any questions about this letter or any of the drawings or process flow diagram please call TES' Special Projects Manager, Lynn Goldston – 903-235-1477.



	<u>WATER SUPPLY SURVEY</u>												
MUNICIPALITY	COUNTY	STATE	OWNER	Address	City, State, Zip	PIN	Water	Well Details	Mailed Assessment	Called	Notes		
um	Allegheny	PA	James D & Suzanne Pattock	2029 Old Leechburg Rd	New Kensington, PA 15068	1233-P-00003	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
um	Allegheny	PA	Nancy Rosenberg	2032 Old Leechburg Rd	New Kensington, Pa 15068-8324	1233-P-00036	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	Mark M & Judith Ann Sweeny	2024 Old Leechburg Rd	New Kensington, Pa 15068-8324	1233-P-00109	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
lum	Allegheny	PA	Kirt E & Lisa M Pattock	4059 7Th Street Rd	New Kensington, Pa 15068	1234-A-00160	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
lum	Allegheny	PA	David V & Teresa D Kvortek	864 Hill St	New Kensington, Pa 15068	1234-B-00322	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	Benjamin F. Buchholz	1924 Old Leechburg Rd.	New Kensington, Pa 15068	1234-F-00085	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	Daniel S Cooper	1855 Old Leechburg Rd	New Kensington, Pa 15068	1234-F-00159	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	Lewis R Giacco	P.O. Box 327	West Sunbury, PA 16061	1234-F-00242	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
lum	Allegheny	PA	Janet Ann & Russell William Mitchell	504 Clarendon St	Pittsburgh, Pa 15238	1234-G-00026	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	Herman E & Irene B Vanhorn	1920 Drennen Rd.	New Kensington, PA 15068	1234-G-00086	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	Shirley Ann & Eddie Lion Sprouse	1927 Drennen Rd	New Kensington, Pa 15068-1804	1234-G-00148	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	James & Shirley Smith	1933 Drennen Rd	New Kensington, Pa 15068	1234-G-00155	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	Romaine E Kozuch	229 5Th Ave	New Kensington, Pa 15068	1234-G-00219 & 00230	No Response		7/28/2016	Mailed Tax assessment address.			
Plum	Allegheny	PA	Joshua Hipple	1958 Greensburg Rd.	New Kensington, Pa 15068	1234-H-00270	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	Robert J & Mary Lee Dziuban	Po Box 961252	Fort Worth, Tx 76161	1234-L-00142	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Plum	Allegheny	PA	Harry L & Patricia L. Burkey	1942 Drennen Rd	New Kensington, Pa 15068	1234-L-00184	No Response		7/28/2016	Called 9-8-16 and 9-9-			
Jpper Burrell	Westmoreland	PA	Walter T Menhart	109 Myers Dr	New Kensington Pa 15068	62-07-00-0-013	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
Jpper Burrell	Westmoreland	PA	Gerald L & Joy Greiner	134 W Pittsburgh St	Delmont Pa 15626	62-08-00-0-006	No Response		7/28/2016	Voicemail Message on or before 9-8-16			
lpper Burrell	Westmoreland	PA	David & Edna Kasmoch	1509 Big Bend Rd.	Emlenton, PA 16373	62-08-00-0-008	No Response		7/28/2016	Voicemail Message on or before 9-8-16			

Upper Burrell	Westmoreland	PA	Jessalin M. Callender	1920 Greensburg Rd	New Kensington Pa 15068	62-80-00-0-001	No Response		7/28/2016	Voicemail Message on or before 9-8-16	
Plum	Allegheny	PA	Andrew Palombo	430 Donald Rd	Pittsburgh, Pa 15235	1097-S-00395	None		7/28/2016		Message left 8-25-16
Plum	Allegheny	PA	Mable Harris	Undeliverable	Undeliverable	1096-M-00016	None		7/28/2016		
Plum	Allegheny	PA	Palombo-Aiello Maria Palombo Ferdinand	433 Donald Rd	Pittsburgh, Pa 15235	1097-S-00301	None		7/28/2016		
Plum	Allegheny	PA	Alvin R Iii & Diane Elizabeth Miller	Undeliverable	Undeliverable	1098-D-00128	None		7/28/2016		
Plum	Allegheny	PA	Anna Louise & Kathleen Costa Miller	2240 Freeport Rd 622 Frank Dr	New Kensington, Pa 15068	1233-J-00342 & 1233-N-00346	None		7/28/2016		
Plum	Allegheny	PA	Klint L & Jennifer S Macro	1814 Greensburg Rd	New Kensington, Pa 15068	1233-P-00044	None	Vacant	7/28/2016		
Plum	Allegheny	PA	Lucille Christina & Raymond Armoul Logan Frere	1206 5Th Ave	New Kensington, Pa 15068	1234-C-00347	None		7/28/2016		
Plum	Allegheny	PA	Joseph & Ilde Pasquarelli	693 Harrogate Rd	Pittsburgh, Pa 15241	1234-C-00377	None		7/28/2016		
Plum	Allegheny	PA	Sedat Inc	6608 Route 22	Delmont, Pa 15626-2408	1234-F-00206	None		7/28/2016		
Plum	Allegheny	PA	Ttmar Inc	Undeliverable	Undeliverable	1234-G-00077	None		7/28/2016		
Plum	Allegheny	PA PA	Joseph & Michelle Vaglia Theodore & Virginia Smolenski	418 Willowbrook Rd 14 Tenby Chase Dr	Apollo, Pa 15613 Newark, De 19711	1234-G-00126 1234-K-00134	None		7/28/2016 7/28/2016		
Plum Plum	Allegheny Allegheny	PA	Allegheny Valley Habitat For Humanity	Po Box 147	Natrona Heights, Pa 15065	1234-K-00134 1234-K-00154	None None	n/a	7/28/2016	8/23/2016	
Plum	Allegheny	PA	Ben Dziuban	520 Walnut St BAD	Pittsburgh, Pa 15238	1234-L-00106	None	n/a	7/28/2016	0/23/2010	
		2		204 Ohara Woods Dr. NEW		1005 11 005			= (0.0 / ·		
Plum	Allegheny	PA	Donna Jean Haas	4130 7Th Street Rd	New Kensington, Pa 15068	1096-M-00261	None		7/28/2016		
Plum	Allegheny	PA	Clarence Chambers	1609 Greensburg Rd	New Kensington, Pa 15068	1096-H-00355	None	- /-	7/28/2016	0/22/2016	
Plum	Allegheny Allegheny	PA PA	A William Visnansky & Susan M Balazik & Jean A Milko Benedict & Ferdinand & Andrew Palombo	9517 Ferry Harbour Ct 370 Hamilton Dr Ext	Alexandria, Va 22309 Pittsburgh, Pa 15235	1096-M-00010 1097-M-00126	Public Public	n/a	7/28/2016	8/23/2016	
Plum Plum	Allegheny	PA	Antoinette Cardinale	360 Hamilton Dr Ext	Pittsburgh, Pa 15235	1097-R-00100	Public		7/28/2016 7/28/2016		
Plum	Allegheny	PA	Benedict & Kathy Ann Palombo	1778 Old Leechburg Rd	New Kensington, Pa 15068	1097-S-00348	Public		7/28/2016		
Plum	Allegheny	PA	Ladonna H Fuge	1730 Old Leechburg Rd	New Kensington, Pa 15068	1098-D-00299 & 00277	Public		7/28/2016		
Plum	Allegheny	PA	Rosalyn Christopherson			1233-N-00269	Public		7/28/2016		
Plum	Allegheny	PA	Robert W & Barbara L Matt				Public		7/28/2016		
Plum	Allegheny	PA	Annie Rebecca Cook NEW OWNER	732 Tradewinds Dr 1746 Faulk Rd. (Tax)	Brandon, FI 33511 New Kensington, PA 15068 (Tax)	1233-N-00303	Public		7/28/2016		
Plum	Allegheny	PA	Phillip Jr & Allene C Otlano	5137 Butler St	Pittsburgh, Pa 15201	1233-N-00326	Public		7/28/2016		
Plum	Allegheny	PA	Andrew & Anna Daugherty	1823 Greensburg Rd 1755 Greensburg Rd (Tax)	New Kensington, PA 15068	1233-N-00354	Public		7/28/2016		
Plum	Allegheny	PA	Marvin H Williams	431 Markle Rd	Apollo, Pa 15613	1233-N-00362	Public		7/28/2016		
Plum	Allegheny	PA	Andrew R & Linda E Strano	516 Farneth Rd	New Kensington, Pa 15068	1233-N-00375	Public		7/28/2016		
Plum	Allegheny	PA	Jennie E & Louis R Daugherty	1769 Greensburg Rd	New Kensington, Pa 15068	1233-N-00384	Public		7/28/2016		
Plum	Allegheny	PA	Lottie E Park & Arthur D Phillips & Anna Phillips	1804 Greensburg Rd	New Kensington, Pa 15068	1233-P-00069	Public		7/28/2016		
Plum	Allegheny	PA	Matthew W Podobnik	1932 Old Leechburg Rd	New Kensington, Pa 15068	1234-B-00160	Public		7/28/2016		
Plum	Allegheny	PA	John R & Margaret J Labella	77 S Main St	Washington, Pa 15301	1234-B-00293	Public		7/28/2016		
Plum Plum	Allegheny Allegheny	PA PA	Ralph & Ethely Nankrom  Beverly J & William E Siskos	38 Terrace Rd 103 Rock Springs Rd	Carnegie, Pa 15106-1053  Delmont, Pa 15626-1114	1234-G-00071 1234-G-00098	Public Public		7/28/2016 7/28/2016		
Plum	Allegheny	PA	Thomas W Scheetz	1730 Old Leechburg Rd	New Kensington, Pa 15068	1234-J-00010	Public		7/28/2016		
Plum	Allegheny	PA	James J & Donna J Hoey	Po Box 8469	Canton, Oh 44711	1234-L-00165	Public		7/28/2016		
Plum	Allegheny	PA	Michael A & Linda S. Baleno	2701 Renton Rd	Pittsburgh, Pa 15239	1235-K-00276	Public		7/28/2016		
Plum	Allegheny	PA	Martha J Slack	2008 Old Leechburg Rd	New Kensington, Pa 15068-8324	1234-B-00217 & 00227	Public		7/28/2016		
Plum	Allegheny	PA	William C & Gail Z Powell	1724 Greensburg Rd	New Kensington, Pa 15068-1718	1096-M-00062	Public		7/28/2016		
Plum	Allegheny	PA	John L Pater	2016 Old Leechburg Rd	New Kensington, Pa 15068	1233-P-00129	Public		7/28/2016		
Upper Burrell	Westmoreland	PA	Dwight E & Kenna Householder	101 Myers Dr	New Kensington Pa 15068	62-07-00-0-014	Residentual	Has an old well that does not work and has no pump	7/28/2016		
Plum	Allegheny	PA	Anna Aspden	1781 Old Leechburg Rd	New Kensington, Pa 15068	1097-M-00142	Spring	located 144' East	7/28/2016		
					,			of the house			

Plum	Allegheny	PA	Frank T & Marcia Marie Smolenski	1900 Old Leechburg Rd	New Kensington, Pa 15068	1234-K-00185	Spring	Middle of	7/28/2016	
								property		
Upper Burrell	Westmoreland	PA	Louis Cynthia Louise Trzeciak	1500 Menk Rd	New Kensington Pa 15068	62-08-00-0-086	Well	40' from house,	7/28/2016	Via Mail
								75' deep		
Plum	Allegheny	PA	Robert M Teorsky	1 Home Campus	Des Moines, la 50328	1233-N-00241	Well	Geo Thermal heat	7/28/2016	
								supply well		
Plum	Allegheny	PA	Klint L & Jennifer S Macro	Po Box 961252	Fort Worth, Tx 76161	1233-P-00086	Well	2 Directly next to	7/28/2016	
								the house		
Plum	Allegheny	PA	Leonard J & Nina E Hasson			1233-P-00198	Well	not provided	7/28/2016	
Plum	Allegheny	PA	Richard A & Mary Jane Martin	1819 Greensburg Rd	New Kensington, Pa 15068	1233-P-00215	Well	not provided	7/28/2016	
Plum	Allegheny	PA	Louis R Daugherty	1815 Greensburg Rd	New Kensington, Pa 15068	1233-P-00245 & 00227	Well	back corner of	7/28/2016	
								house		
Plum	Allegheny	PA	David R Daugherty	1801 Greensburg Rd	New Kensington, Pa 15068	1233-P-00258 & 00262	Well		7/28/2016	
Plum	Allegheny	PA	Mary C Schwartz	4198 Brittany Dr	Ellicott City, Md 21043	1234-B-00198	Well	Not working at	7/28/2016	
								this time.		
Plum	Allegheny	PA	Wildon E & Gracie E Barker (deceased)	1123 Park View Dr	Covina, Ca 91724	1234-G-00164	Well	house is in	7/28/2016	
								foreclosure		
Plum	Allegheny	PA	Donald J & Florence M (W) Anuskiewicz	1938 Greensburg Rd	New Kensington, Pa 15068	1234-G-00204	Well		7/28/2016	
Plum	Allegheny	PA	Frank Choltko Iii	1820 Old Leechburg Rd	New Kensington, Pa 15068	1234-J-00087	Well	Front yard	7/28/2016	
Plum	Allegheny	PA	Theodore & Virginia Smolenski	1835 Old Leechburg Rd	New Kensington, Pa 15068	1234-K-00222	Well	At House	7/28/2016	
Upper Burrell	Westmoreland	PA	Louis Anthony & Sandy Lombardo	1550 Menk Rd	New Kensington Pa 15068	62-07-00-0-015	Well	115' deep, 70' of	7/28/2016	
								water, 6 feet		
								south of house		
Plum	Allegheny	PA	David A & Stephanie Plance	2013 Old Leechburg Rd	New Kensington, Pa 15068	1234-B-00254 & 00258	Well		7/28/2016	

X & Fox Inc.

8 Timber Bridge Rd., Suit 10 Jarion, PA 16214

POSTAL SERVICE®

USPS TRACKING #

Label 400 Jan. 2013 7690-16-000-7948

Harry L & Patricia L. Burkey 1942 Drennen Rd New Kensington, Pa 15068 English

**Customer Service** 

USPS Mobile

Register / Sign In

#### **■USPS.COM®**

### USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs >



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433073

Updated Delivery Day: Friday, July 29, 2016

#### **Product & Tracking Information**

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 2:56 pm

Delivered, In/At Mailbox

**KENSINGTON, PA 15068** 

Your item was delivered in or at the mailbox at 2:56 pm on July 29, 2016 in NEW KENSINGTON, PA 15068

July 29, 2016, 7:50 am

Out for Delivery

NEW KENSINGTON, PA 15068

July 29, 2016, 7:40 am

Sorting Complete

Departed USPS Facility

KENSINGTON, PA 15068 PITTSBURGH, PA 15290

July 29, 2016, 7:30 am July 29, 2016, 7:22 am

Arrived at Post Office

Arrived at USPS Origin

KENSINGTON, PA 15068

July 29, 2016, 5:08 am

Facility

PITTSBURGH, PA 15290

July 29, 2016, 4:30 am

Departed USPS Facility

WARRENDALE, PA 15095

July 29, 2016, 4:17 am

Arrived at USPS Origin Facility

WARRENDALE, PA 15095

July 29, 2016, 2:27 am

Departed USPS Facility

Departed Post Office

WARRENDALE, PA 15086

Arrived at USPS Origin

WARRENDALE, PA 15086

July 28, 2016, 11:57 pm

Facility

July 28, 2016, 5:02 pm July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

CLARION, PA 16214

#### Track Another Package

Tracking (or receipt) number

Track It

#### Manage Incoming Packages

Track all your packages from a dashboard No tracking numbers necessary

Sign up for My USPS >



UNITED STATES POSTAL SERVICE

Apply Priority Mail Postage Here

VISIT US AT USPS

8 Timber Bridge Rd., Suite 20 Clarion, PA 16214 ox & Fox Inc.

POSTAL SERVICE •

New Kensington Pa 15068 Jessalin M. Callender 1920 Greensburg Rd

English

Customer Service

USPS Mobile

Register / Sign In

#### **■USPS.COM®**

## USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs >



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433196

Updated Delivery Day: Friday, July 29, 2016

#### **Product & Tracking Information**

Postal Product:

eatures:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 11:41 am

Delivered, In/At Mailbox

NEW

KENSINGTON, PA 15068

Your item was delivered in or at the mailbox at 11:41 am on July 29, 2016 in NEW KENSINGTON, PA 15068.

July 29, 2016, 7:50 am

Out for Delivery

NEW

KENSINGTON, PA 15068

July 29, 2016, 7:40 am

Sorting Complete

NEW KENSINGTON, PA 15068

NE

July 29, 2016 , 7:22 am

Arrived at Post Office

KENSINGTON, PA 15068

July 29, 2016, 4:30 am

Departed USPS Facility

WARRENDALE, PA 15095

July 29, 2016 , 3:03 am

Arrived at USPS Origin Facility WARRENDALE, PA 15095

July 29, 2016, 2:27 am

Departed USPS Facility

WARRENDALE, PA 15086

July 28, 2016, 11:56 pm

Arrived at USPS Origin Facility WARRENDALE, PA 15086

July 28, 2016 , 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

#### Track Another Package

Tracking (or receipt) number

Track It

#### Manage Incoming Packages

Track all your packages from a dashboard. No tracking numbers necessary.

Sign up for My USPS >





Flat Rate Mailing Envelope Apply Priority Mail Postage Here

> Fox & Fox Inc. 58 Timber Bridge Rd., Suite 20 Clarion, PA 16214

Daniel S Cooper 1855 Old Leechburg Rd New Kensington, Pa 15068

	# 5		4338 7	
ATES RVICE®	<b>USPS TRACKING #</b>		9114 9999 4431 3758 4338 7	
UNITED STATES POSTAL SERVICE®	. SASN	ing valende	1 8999 4	
A			9116	

Label 400 Jan. 2013 7690-16-000-7948 English

Customer Service

USPS Mobile

Register / Sign In

#### **■USPS.COM**°

## USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs >



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433875

Updated Delivery Day: Friday, July 29, 2016

#### Product & Tracking Information

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 12:58 pm

Delivered, In/At Mailbox

NEW KENSINGTON, PA 15068

Your item was delivered in or at the mailbox at 12:58 pm on July 29, 2016 in NEW KENSINGTON, PA 15068

15068.

July 29, 2016, 7:50 am

Out for Delivery

NEW

KENSINGTON, PA 15068

July 29, 2016, 7:40 am

Sorting Complete

NEW KENSINGTON, PA 15068

NEW

July 29, 2016, 7:22 am

Arrived at Post Office

KENSINGTON, PA 15068

July 28, 2016 , 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

#### Track Another Package

Tracking (or receipt) number

Track It

#### Manage Incoming Packages

Track all your packages from a dashboard No tracking numbers necessary.

Sign up for My USPS >





Flat Rate Mailing Envelope

Apply Priority Mail Postage Here

Timber Briuge Rd., Suite 20 rion, PA 16214 & Fox Inc



Label 400 Jan 2013 7690-16-000-7948

Robert J & Mary Lee Dziuban Fort Worth, Tx 76161 Po Box 961252

English

Customer Service

**USPS Mobile** 

Register / Sign In

#### **■USPS.COM®**

## USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758419947

Updated Delivery Day: Saturday, July 30, 2016

#### Product & Tracking Information

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 30, 2016, 5:19 am

Delivered, PO Box

FORT WORTH, TX 76161

Your item has been delivered and is available at a PO Box at 5:19 am on July 30, 2016 in FORT WORTH, TX 76161.

July 30, 2016, 5:17 am

Arrived at Post Office

FORT WORTH, TX 76161

July 30, 2016, 4:35 am

Departed USPS Facility

FORT WORTH, TX 76161

July 30, 2016 , 12:17 am

Arrived at USPS Facility

Departed USPS Origin

FORT WORTH, TX 76161

July 28, 2016 , 11:51 pm

Facility

WARRENDALE, PA 15086

July 28, 2016, 11:50 pm

Arrived at USPS Origin Facility

WARRENDALE, PA 15086

July 28, 2016, 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

#### Track Another Package

Tracking (or receipt) number

Track It

Manage Incoming Packages

Track all your packages from a dashboard. No tracking numbers necessary.

Sign up for My USPS >



58 Timber Bridge Rd., Suite 20 Clarion, PA 16214

UNITED STATES
POSTAL SERVICE®

3758 4334 17 **USPS TRACKING #** 

9114 9999 4431

Label 400 Jan. 2013 7690-16-000-7948

West Sunbury, Pa 16061 Lewis R Giacco Po Box 327

**Customer Service** 

USPS Mobile

Register / Sign In

### **■USPS.COM®**

# USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs >



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433417

Updated Delivery Day: Friday, July 29, 2016

### **Product & Tracking Information**

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016 , 9:19 am

Delivered, PO Box

WEST

SUNBURY, PA 16061

Your item has been delivered and is available at a PO Box at 9:19 am on July 29, 2016 in WEST SUNBURY, PA 16061.

July 29, 2016, 9:03 am

Arrived at Post Office

WEST

SUNBURY, PA 16061

July 29, 2016, 4:30 am

Departed USPS Facility

WARRENDALE, PA 15095

July 29, 2016, 3:27 am

Arrived at USPS Origin Facility

WARRENDALE, PA 15095

July 28, 2016, 11:45 pm

Arrived at USPS Origin Facility WARRENDALE, PA 15086

July 28, 2016, 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

## Track Another Package

Tracking (or receipt) number

Track It

Manage Incoming Packages

Track all your packages from a dashboard. No tracking numbers necessary.



UNITED STATES
POSTAL SERVICE®

Gerald L & Joy Greiner 134 W Pittsburgh St Delmont Pa 15626

**USPS TRACKING #** 

Label 400 Jan. 2013 7690-16-000-7948

**Customer Service** 

USPS Mobile

Register / Sign In

### **■USPS.COM**®

## USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs >



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433059

### **Product & Tracking Information**

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 30, 2016, 11:43 am

Delivered, In/At Mailbox

DELMONT, PA 15626

Your item was delivered in or at the mailbox at 11:43 am on July 30, 2016 in DELMONT, PA 15626

July 30, 2016, 9:49 am

Arrived at Post Office

DELMONT, PA 15626

July 30, 2016, 6:47 am

Departed USPS Facility

PITTSBURGH, PA 15290

July 30, 2016, 4:36 am

Arrived at USPS Origin Facility

PITTSBURGH, PA 15290

July 30, 2016, 3:15 am

Departed USPS Origin Facility

WARRENDALE, PA 15095

July 29, 2016, 3:27 am

Arrived at USPS Origin Facility

WARRENDALE, PA 15095

July 28, 2016 , 11:47 pm

Departed USPS Origin Facility

.

WARRENDALE, PA 15086

July 28, 2016, 11:43 pm

Arrived at USPS Origin Facility WARRENDALE, PA 15086

July 28, 2016 , 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

## Track Another Package

Tracking (or receipt) number

Track It

#### Manage Incoming Packages

Track all your packages from a dashboard. No tracking numbers necessary.



POSTAL SERVICE®

**USPS TRACKING #** 

New Kensington, Pa 15068

Romaine E Kozuch

229 5Th Ave

Label 400 Jan. 2013 7690-16-000-7948

8762-000-91-0692

Customer Service

**USPS** Mobile

Register / Sign In

#### **■USPS.COM®**

## USPS Tracking®

Still Have Questions?

Available Actions



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758419961

Updated Delivery Day: Friday, July 29, 2016

#### Product & Tracking Information

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 10:50 am

Delivered, In/At Mailbox

NEW KENSINGTON, PA 15068

Your item was delivered in or at the mailbox at 10:50 am on July 29, 2016 in NEW KENSINGTON, PA 15068.

July 29, 2016, 7:50 am

Out for Delivery

Sorting Complete

NEW KENSINGTON, PA 15068

NEW

July 29, 2016, 7:40 am

July 29, 2016, 7:22 am

Arrived at Post Office

KENSINGTON, PA 15068

July 29, 2016, 4:30 am

Departed USPS Facility

WARRENDALE, PA 15095

KENSINGTON, PA 15068

July 29, 2016, 3:05 am

Arrived at USPS Origin

Facility

WARRENDALE, PA 15095

July 29, 2016 , 2:27 am

Departed USPS Facility

WARRENDALE, PA 15086

July 28, 2016, 11:53 pm

Arrived at USPS Origin Facility

WARRENDALE, PA 15086

July 28, 2016, 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

## Track Another Package

Tracking (or receipt) number

Track It

### Manage Incoming Packages

Track all your packages from a dashboard. No tracking numbers necessary.



Gr al 58 Timber Bridge Ku., --Clarion, PA 16214 Fox & Couline

9114 9999 4431 3758 4335 92 **USPS TRACKING #** POSTAL SERVICE® UNITED STATES

Zabel 400 Jan. 2013 7690-16-000-7948

David V & Teresa D Kvortek New Kensington, Pa 15068 864 Hill St

ING PACINALES (FOR DOWESTIC ONLY)

Up to 70 pounds for Priority Mail and Priority Mail Express Packages WEIGHT: Up to 13 ounces for First-Class Mail Parcels

it USPS.com<sup>es</sup> and Domestic Mail Manual and International Mail Manual at http://pe.usps.com for details.

Customer Service

**USPS Mobile** 

Register / Sign In

### **■USPS.COM**°

# USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs >



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433592

Updated Delivery Day: Friday, July 29, 2016

#### **Product & Tracking Information**

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 11:48 am

Delivered, In/At Mailbox

NEW

KENSINGTON, PA 15068

Your item was delivered in or at the mailbox at 11:48 am on July 29, 2016 in NEW KENSINGTON, PA 15068.

July 29, 2016, 7:50 am

Out for Delivery

NEW

KENSINGTON, PA 15068

July 29, 2016, 7:40 am

Sorting Complete

NEW KENSINGTON, PA 15068

July 29, 2016, 7:22 am

Arrived at Post Office

NEW KENSINGTON, PA 15068

July 29, 2016 , 4:30 am

Departed USPS Facility

WARRENDALE, PA 15095

July 29, 2016, 3:04 am

Arrived at USPS Origin Facility WARRENDALE, PA 15095

July 29, 2016 , 2:27 am

Departed USPS Facility

Arrived at USPS Origin

WARRENDALE, PA 15086

July 28, 2016 , 11:58 pm

Facility

WARRENDALE, PA 15086

July 28, 2016 , 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016 , 10:57 am

Acceptance

CLARION, PA 16214

## Track Another Package

Tracking (or receipt) number

Track It

#### Manage Incoming Packages

Track all your packages from a dashboard No tracking numbers necessary.





Flat Rate Mailing Envelope

Apply Priority Mail Postage Here

Fox & Fox Inc. 58 Timber Bridge Rd., Suite 20 Clarion, PA 16214 Walter T Menhart 109 Myers Dr New Kensington Pa 15068



USPS TRACKING #

Label 400 Jan. 2013 7690-16-000-7948

**Customer Service** 

USPS Mobile

Register / Sign In

### **■USPS.COM®**

# USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433912

Updated Delivery Day: Friday, July 29, 2016

#### Product & Tracking Information

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 12:52 pm

Delivered, In/At Mailbox

NEW

KENSINGTON, PA 15068

Your item was delivered in or at the mailbox at 12:52 pm on July 29, 2016 in NEW KENSINGTON, PA 15068

July 29, 2016, 7:50 am

Out for Delivery

NEW

KENSINGTON, PA 15068

July 29, 2016, 7:40 am

Sorting Complete

NEW KENSINGTON, PA 15068

.....

July 29, 2016, 7:22 am

Arrived at Post Office

KENSINGTON, PA 15068

July 29, 2016, 4:30 am

Departed USPS Facility

WARRENDALE, PA 15095

July 29, 2016, 3:06 am

Arrived at USPS Origin Facility

WARRENDALE, PA 15095

July 29, 2016, 2:27 am

Departed USPS Facility

WARRENDALE, PA 15086

July 28, 2016 , 11:53 pm

Arrived at USPS Origin Facility WARRENDALE, PA 15086

July 28, 2016 , 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016 , 10:57 am

Acceptance

CLARION, PA 16214

## Track Another Package

Tracking (or receipt) number

Track It

### Manage Incoming Packages

Track all your packages from a dashboard No tracking numbers necessary.





Flat Rate Mailing Envelope

Apply Priority Mail Postage Here

Fox & Fox Inc. 58 Timber Bridge Rd., Svite 20 Clarion, PA 16214 Janet Ann & Russell William Mitchell 504 Clarendon St Pittsburgh, Pa 15238



USPS TRACKING #

9114.9999 4431.3758 4331.72

Zabel 400 Jan 2013 7690-16-000-848

**Customer Service** 

USPS Mobile

Register / Sign In

### **■USPS.COM®**

# USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433172

Updated Delivery Day: Friday, July 29, 2016

### Product & Tracking Information

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 11:22 am

Delivered, In/At Mailbox

PITTSBURGH, PA 15238

Your item was delivered in or at the mailbox at 11:22 am on July 29, 2016 in PITTSBURGH, PA 15238.

July 29, 2016, 8:13 am

Out for Delivery

PITTSBURGH, PA 15238

July 29, 2016, 8:03 am

Sorting Complete

Arrived at Post Office

PITTSBURGH, PA 15238

July 29, 2016, 7:52 am July 29, 2016, 7:30 am

Departed USPS Facility

PITTSBURGH, PA 15238 PITTSBURGH, PA 15290

July 29, 2016 , 5:22 am

Arrived at USPS Origin Facility

.....

July 29, 2016, 4:30 am

Departed USPS Facility

PITTSBURGH, PA 15290

WARRENDALE, PA 15095

July 29, 2016 , 3:05 am

Arrived at USPS Origin Facility

WARRENDALE, PA 15095

July 28, 2016, 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

## Track Another Package

Tracking (or receipt) number

Track It

#### Manage Incoming Packages

Track all your packages from a dashboard No tracking numbers necessary.



Apply Priority Mail Postage Here

UNITED STATES POSTAL SERVICE

ED STATES 31. SERVICE

Fox & Fox Inc. 58 Timber Bridge Rd., Suite 20 Clarion, PA 16214 Kirt E & Lisa M Pattock 4059 7Th Street Rd New Kensington, Pa 15068

POSTAL SERVICE®

USPS TRACKING #

Zabel 400 Jan. 2013 7690-16-000-7948

Customer Service

USPS Mobile

Register / Sign In

### **■USPS.COM®**

# USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433233

Updated Delivery Day: Friday, July 29, 2016

#### Product & Tracking Information

Postal Product:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 12:38 pm

Delivered, In/At Mailbox

KENSINGTON, PA 15068

Your item was delivered in or at the mailbox at 12:38 pm on July 29, 2016 in NEW KENSINGTON, PA 15068

July 29, 2016, 7:50 am

Out for Delivery

NEW

KENSINGTON, PA 15068

July 29, 2016, 7:40 am

Sorting Complete

NEW KENSINGTON, PA 15068

July 29, 2016, 7:22 am

Arrived at Post Office

KENSINGTON, PA 15068

July 29, 2016, 4:30 am

Departed USPS Facility

July 29, 2016, 4:10 am

Arrived at USPS Origin

WARRENDALE, PA 15095

July 29, 2016, 2:27 am

Departed USPS Facility

WARRENDALE, PA 15095

Arrived at USPS Origin

Departed Post Office

WARRENDALE, PA 15086

July 28, 2016, 11:58 pm

Facility

Facility

WARRENDALE, PA 15086

July 28, 2016, 5:02 pm

Acceptance

CLARION, PA 16214 CLARION, PA 16214

July 28, 2016, 10:57 am

## Track Another Package

Tracking (or receipt) number

Track It

#### Manage Incoming Packages

Track all your packages from a dashboard No tracking numbers necessary



Sh2'Colta

Fox & Fox Inc. 58 Timber Bridge Rd., Suite 20 Clarion, PA 16214

WINITED STATES
POSTAL SERVICE®

Label 400 Jan. 2013 7690-16-000-7948

Nancy Rosenberg 2032 Old Leechburg Rd New Kensington, Pa 15068-8324

**Customer Service** 

**USPS** Mobile

Register / Sign In

## **■USPS.COM**°

# USPS Tracking®

Still Have Questions?

**Available Actions** 

Browse our FAQs



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758419824

Updated Delivery Day: Friday, July 29, 2016

## Product & Tracking Information

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016 , 12:55 pm

Delivered, In/At Mailbox

NEW

KENSINGTON, PA 15068

Your item was delivered in or at the mailbox at 12:55 pm on July 29, 2016 in NEW KENSINGTON, PA 15068.

July 29, 2016, 7:50 am

Out for Delivery

NEW

KENSINGTON, PA 15068

July 29, 2016, 7:40 am

Sorting Complete

KENSINGTON, PA 15068

July 29, 2016, 7:22 am

Arrived at Post Office

KENSINGTON, PA 15068

July 29, 2016, 4:30 am

Departed USPS Facility

WARRENDALE, PA 15095

July 29, 2016, 3:05 am

Arrived at USPS Origin Facility

WARRENDALE, PA 15095

Departed USPS Facility

July 29, 2016, 2:27 am

Arrived at USPS Origin

WARRENDALE, PA 15086

July 28, 2016, 11:51 pm

Facility

WARRENDALE, PA 15086

July 28, 2016, 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

## Track Another Package

Tracking (or receipt) number

Track It

#### Manage Incoming Packages

Track all your packages from a dashboard No tracking numbers necessary



UNITED STATES POSTAL SERVICE

58 Timber Bridge Rd., Suite 20 Clarion, PA 16214 Fox & Fox Inc.

VINITED STATES
POSTAL SERVICE®

USPS TRACKING #

Label 400 Jan. 2013 7690-16-000-7948

New Kensington, Pa 15068 James & Shirley Smith 1933 Drennen Rd

**Customer Service** 

**USPS Mobile** 

Register / Sign In

## **■USPS.COM**°

# USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758433110

Updated Delivery Day: Friday, July 29, 2016

### Product & Tracking Information

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 2:55 pm

Delivered, In/At Mailbox

NEW KENSINGTON, PA 15068

Your item was delivered in or at the mailbox at 2:55 pm on July 29, 2016 in NEW KENSINGTON, PA 15068.

July 29, 2016 , 7:50 am

Out for Delivery

NEW KENSINGTON, PA 15068

NFW

July 29, 2016, 7:40 am

Sorting Complete

KENSINGTON, PA 15068

July 29, 2016, 7:22 am

Arrived at Post Office

NEW KENSINGTON, PA 15068

July 29, 2016, 4:30 am

Departed USPS Facility

WARRENDALE, PA 15095

July 29, 2016, 3:05 am

Arrived at USPS Origin Facility WARRENDALE, PA 15095

July 29, 2016 , 2:27 am

Departed USPS Facility

WARRENDALE, PA 15086

July 28, 2016, 11:57 pm

Arrived at USPS Origin Facility

WARRENDALE, PA 15086

July 28, 2016, 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016, 10:57 am

Acceptance

CLARION, PA 16214

## Track Another Package

Tracking (or receipt) number

Track It

### Manage Incoming Packages

Track all your packages from a dashboard No tracking numbers necessary.





58 Timber Bridge Rd., Suite 20

OX & FOX INC.

Clarion, PA 16214

Flat Rate Mailing Envelope

Apply Priority Mail Postage Here

VINITED STATES
POSTAL SERVICE

Mark M & Judith Ann Sweeny

2024 Old Leechburg Rd

**USPS TRACKING #** 

Label 400 Jan. 2013 7690-16-000-7948

New Kensington, Pa 15068-8324

**Customer Service** 

**USPS Mobile** 

Register / Sign In

### **■USPS.COM®**

## USPS Tracking®

Still Have Questions?

Available Actions

Browse our FAQs



Get Easy Tracking Updates > Sign up for My USPS.

Tracking Number: 9114999944313758419749

Updated Delivery Day: Friday, July 29, 2016

#### **Product & Tracking Information**

Postal Product:

Features:

USPS Tracking®

DATE & TIME

STATUS OF ITEM

LOCATION

July 29, 2016, 12:56 pm

Delivered, In/At Mailbox

KENSINGTON, PA 15068

Your item was delivered in or at the mailbox at 12:56 pm on July 29, 2016 in NEW KENSINGTON, PA 15068

July 29, 2016, 7:50 am

Out for Delivery

VEW

KENSINGTON, PA 15068

July 29, 2016, 7:40 am

Sorting Complete

NEW KENSINGTON, PA 15068

July 29, 2016, 7:22 am Arrived at Post Office

NEW KENSINGTON, PA 15068

July 29, 2016, 4:30 am

Departed USPS Facility

WARRENDALE, PA 15095

July 29, 2016, 3:07 am

Arrived at USPS Origin Facility WARRENDALE, PA 15095

July 29, 2016 , 2:27 am

Departed USPS Facility

WARRENDALE, PA 15086

July 28, 2016, 11:50 pm

Arrived at USPS Origin Facility

WARRENDALE, PA 15086

July 28, 2016 , 5:02 pm

Departed Post Office

CLARION, PA 16214

July 28, 2016 , 10:57 am

Acceptance

CLARION, PA 16214

## Track Another Package

Tracking (or receipt) number

Track It

## Manage Incoming Packages

Track all your packages from a dashboard. No tracking numbers necessary.

