

FIGURE 6-11

TRICHLOROETHENE DETECTED IN FILL

DES MOINES SOUTH AREA
SOURCE CONTROL PROJECT
DES MOINES, IOWA

ECKENFELDER INC.

Nashville, Tennessee
Mahwah, New Jersey
Rochester, New York



FIGURE 6-12

TRICHLOROETHENE DETECTED IN NATURAL SOIL

DES MOINES SOUTH AREA SOURCE CONTROL PROJECT
DES MOINES, IOWA

ECKENFELDER INC.
Nashville, Tennessee
Mahwah, New Jersey
Rochester, New York