

## RECEIVED UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region 1, 5 Post Office Square, Suite 100 Boston, Massachusetts 02109-3912

**EXPEDITED SETTLEMENT AGREEMENT** Docket Number: CWA-01-2011-0019

Gallo Construction ("Respondent") is a "person," within the enforcement action against Respondent for any other past, meaning of Section 502(5) of the Clean Water Act ("Act"), 33 U.S.C. § 1362(5), and 40 C.F.R. § 122.2.

Attached is an "Expedited Settlement Offer Deficiencies Form" ("Form"), which is incorporated by reference. By its signature, Complainant ("EPA") finds that Respondent is responsible for the deficiencies specified in the Form.

Respondent had an unauthorized discharge of storm water in violation of Section 301(a) of the Clean Water Act, 33 U.S.C. § 1311, and/or failed to comply with its National Pollutant Discharge Elimination System ("NPDES") storm water permit issued under Section 402 of the Act, 33 U.S.C. § 1342.

EPA finds, and Respondent admits, that Respondent is subject to Section 301(a) of the Act, 33 U.S.C. § 1311, and that EPA has jurisdiction over any "person" who "discharges pollutants" from a "point source" to "waters of the United States." Respondent neither admits nor denies the deficiencies specified in the Form.

EPA is authorized to enter into this Consent Agreement and Final Order ("Agreement") under the authority vested in the Administrator of EPA by Section 309(g)(2)(A) of the Act, 33 U.S.C. § 1319(g)(2)(A), and by 40 C.F.R. § 22.13(b). The parties enter into this Agreement in order to settle the civil violation(s) alleged in this Agreement for a penalty of \$1,250. Respondent consents to the assessment of this penalty, and waives the right to: (1) contest the finding(s) specified in the Form; (2) a hearing pursuant to Section 309(g)(2) of the Act, 33 U.S.C. § 1319(g)(2); and (3) appeal pursuant to Section 309(g)(8), 33 U.S.C. § 1319(g)(8).

Within 10 days of the effective date of this Agreement, IT IS SO ORDERED: Respondent shall submit a bank, cashiers, or certified check, with case name and docket number noted, for the amount specified above, payable to the "Treasurer, United States of Jill T. Metcalf America," via certified mail, to: U.S. EPA, Fines and Penalties, In the Matter of: Gallo Construction, Docket No. CWA-01-2011-0019, Cincinnati Finance Center, P.O. Box 979077, St. Louis, MO 63197-9000

This Agreement settles EPA's civil penalty claims against Respondent for the Clean Water Act violation(s) specified in this Agreement. EPA does not waive its rights to take any

present, or future civil or criminal violation of the Act or of any other federal statute or regulation. EPA does not waive its right to issue a compliance order for any uncorrected deficiencies or violation(s) described in the Form. EPA has determined this Agreement to be appropriate.

Office of Regional Hearing Clerk EPA ORC

This Agreement is binding on the parties signing below and effective thirty (30) days from the date it is signed by the Presiding Officer unless a petition to set aside the Order is filed by a commenter pursuant to Section 309(g)(4)(C) of the Act, 33 U.S.C. § 1319(g)(4)(C), and 40 C.F.R. Part 22.

APPROVED BY EPA:

Simu Stigher \_ Date: 03/11/11 Susan Studlien

Director Office of Environmental Stewardship

APPROVED BY RESPONDENT:

Name (print): STEVEN A. GALLO Title: (print): POE STORM


Signature: 100 The Date: 2/18/11

More than 40 days have elapsed since the issuance of public notice pursuant to Section 309(g)(4)(A) of the Act, 33 U.S.C. § 1319(g)(4)(A), and EPA has received no comments concerning this matter.

Having determined that this Agreement is authorized by law,

Date:

Acting Regional Judicial Officer



## Expedited Settlement Offer Worksheet

Deficiencies Form Consult instructions regarding eligibility criteria and procedures prior to use

version 10.3.4



	LEGAL NAME AND MAILING ADDRESS OF OPERATOR	<b>Telephone Number</b>	NPDES Pe	rmit Numbe	r	
1	Gallo Construction	Construction of the	11		A DECEMBER OF THE PARTY OF THE	
	31 Gallair Circle Holden, MA 01520	Inspector Name:	Andrew Spejewski			
	and the second se	Inspector Agency: Entrance Interview Co	US EPA		1	
		Exit Interview Conduc		10	1	
	LOCATION AND ADDRESS OF SITE	Exit Interview given to	i since i la		1 A A A A	
2	Bryn Mawr Estates Briarcliff Drive	Exit Interview time:	-199	Date:	10/21/2010	
-	Aubum MA					

FACILITY DESCRIPTION / CONTACT NAMES	
Name of Site Contact (ESO Worksheet recipient):	
Name of Authorized Official (40 CFR 122.22):	Steven Gallo
Inspection Date:	10/21/2010
Start Construction Date:	C. I. C. Balancian C. Para Series and Series and Series and Series
Estimated Completion Construction Date:	the second
If Unpermitted, Number of Months Unpermitted:	CANA AND THE ALL OF PARADOX LAND A MALE OF PRO
Name of Receiving Water Body (Indicate whether 303(d) listed):	
Acres Currently Disturbed   Acres to be Disturbed in Whole Common Plan:	
Has Operator Requested Rainfall Erosivity or TMDL Waiver per 44 CFR 122.26(b)(15)?	No

		PERMIT COVERAGE	Findings	Citation Reference**	R C A*	No. of Deficien- cies	Dollar Amount	Total
3		Operator unpermitted formonths (# months unpermitted equals number of violations)		CWA 301	11.1	19. 191	\$500.00 =	
		SWPPP REVIEW	the second second	and the second s				
4		SWPPP not prepared (If no SWPPP, leave elements 5 - 30 blank)	Mar Star	CGP 3.1.A		$x_{1}=T_{0}^{-1}+\widetilde{y_{1}^{-1}}$	\$5,000.00 =	
5		SWPPP prepared but prepared after construction start (# of months = # of violations)		CGP 3.1.A	1		\$75.00 =	
6		SWPPP does not identify all potential sources of pollution to include: porta-pottys, fuel tanks, staging areas, waste containers, chemical storage areas, concrete cure, paints, solvents, etc		CGP 3.1.B	1.000		\$250.00 =	
7		SWPPP does not identify all operators for the project site and the areas of the site over which each operator has control		CGP 3.3.A		a de la constance de la	\$500.00 =	
8		SWPPP does not have site description, as follows:	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1					
		Nature of activity in description		CGP 3.3.B.1	100	6.	\$100.00 =	
		Intended sequence of major activities	Add and a state of the state of the	CGP 3.3.B.2	1.1.1	and be as the state	\$100.00 =	
	_	Total disturbed acreage	1944	CGP 3.3.B.3	-		\$100.00 =	
		General location map	The second second second second	CGP 3.3.B.4	0		\$100.00 =	
		Site map		CGP 3.3.C	1		\$500.00 =	
	F	Site map does not show drainage patterns, slopes, areas of disturbance, locations of major controls, structural practices shown, stabilization practices, offsite materials, waste, borrow or equipment storage ageas, surface waters, discharge points, areas of final stabilization (count each omission under 8F as 1 violation)		CGP 3.3.C.1-8			\$50.00 =	
	G	Location/description industrial activities, like concrete or asphalt batch plants		CGP 3.3.D	134	1 (m 4 19	\$500.00 =	
9	-	SWPPP does not:	A CHARTER AND A CONTRACT OF SERVICE	A CALL PROPERTY AND		22.24		
	A	Describe all pollution control measures (e.g. BMPs)		CGP 3.4.A	11		\$750.00 =	

	B	Describe sequence for implementation	ALC: STATE OF THE STATE	CGP 3.4.A		\$250.00 =	
ł	C	Detail operator(s) responsible for implementation	1945年1月1日日日	CGP 3.4.A	ANT SEAR	\$250.00 =	
10	16	SWPPP does not describe interim stabilization practices		CGP 3.4.B	4 0.78 12.88	\$250.00 =	
11		SWPPP does not describe permanent stabilization practices		CGP 3.4.B		\$250.00 =	
12		SWPPP does not describe a schedule to implement stabilization practices	and a second	CGP 3.4.B	are the	\$250.00 =	
13	「二、二、二、	Following dates are not recorded: major grading activities; construction temporarily or permanently ceased; stabilization measures initiated (count each omission under 13 as 1 violation)		CGP 3.4.C.1-3		\$250.00 =	
14	-71/	SWPPP does not have description of structural practices to divert flows from exposed soils, retain	and the second	CGP 3.4.D		\$500.00 =	
15		flows, or limit runoff from exposed areas SWPPP does not have a description of measures that will be installed during the construction process to control pollutants in storm water discharges that will occur AFTER construction operations have been completed		CGP 3.4.E		\$500.00 =	
16	20	SWPPP does not describe measures to prevent discharge of solid materials to waters of the US, except as authorized by 404 permit		CGP 3.4.F		\$500.00 =	
17		SWPPP does not describe measures to minimize off-site vehicle tracking and generation of dust		CGP 3.4.G		\$500.00 =	
18	1.15	SWPPP does not include description of construction or wasta materials expected to be stored on site w/updates re: controls used to reduce pollutants from these materials		CGP 3.4.H		\$250.00 =	·
19		SWPPP does not have description of pollutant sources from areas other than construction (asphalt or concrete plants) w/ updates re: controls to reduce pollutants from these materials		CGP 3.4.1		\$500.00 =	
20		SWPPP does not identify allowable sources of non-storm water discharges listed in subpart 1.3.B of the CGP		CGP 3.5		\$500.00 =	
21	「ころ」	SWPPP does not identify/ensure implementation of pollution prevention measures for non-storm water discharges	and the second secon	CGP 3.5		\$500.00 =	
22	が行	Endangered Species Act documentation is not in SWPPP		CGP 3.7		\$500.00 =	
23	3	Historic Properties (Reserved)			Li		- min
24	-	Copy of permit and/or NOI not in SWPPP (count each omission under 24 as 1 violation)	a man a her water and the second and a second	CGP 3.8	x	\$250.00 =	
25	1 1 a 1	SWPPP is not consistent with requirements specified in applicable sediment and erosion site plans or site permits, or storm water management plans or site permits approved by State, Tribal or local officials (e.g., MS4 requirements)		CGP 3.9		\$750.00 =	
26	20	SWPPP has not been updated to remain consistent with changes applicable to protecting surface waters in State, Tribal or local erosion plans		CGP 3.9		\$250.00 =	
27		Copies of inspection reports have not been retained as part of the SWPPP for 3 years from date permit coverage terminates		CGP 3.10.G		\$500.00 =	
28	1	SWPPP has not been updated/modified to reflect change at site effecting discharge, or where inspections identify SWPPP/BMPs as ineffective, updates to SWPPP regarding modifications to BMPs not made within 7 days of such inspection (count each omission under under 28 as 1 violation)	antal Nga dia amin'ny desira dia mampina dia ma	CGP 3.11.C		\$50.00 =	
29		Copy of SWPPP not retained on site A SWPPP not made available upon request		CGP 3.12.A CGP 3.12.C	1 1 - 1 - 2	\$500.00 = \$500.00 =	
30		SWPPP not signed/certified	and the state of the	CGP 3.12.D	100	\$500.00 =	

	INSPECTIONS						
31	Inspections not performed and documented either once every 7 days, or once every 14 days and within 24 hours after storm event greater than 0.5 inches or greater (not required if: temp stabilization; runoff unlikely due to winter conditions; construction during and periods in and areas) (Count each failure to inspect and document as one violation).		CGP 3.10.A, 3.10.B			\$250.00	-
	No inspections conducted and documented (if	A BAT A CARD ALAS	-	AL DE RUA	的 一個 一個	True or	
-	True, then leave elements 32-39 blank) Number of Inspections expected if performed	5781		1.21	四世的 私 法利	False	and and the second
	every 7 days:		En No	a carta		J. Mary	den in ser
-	Number of Inspections expected if performed bi- weekly:	2890				and the second	10
1	If known, number of days of rainfall of >0.5"	·····································	- The second sec	and a state of the			
32	Inspections not conducted by qualified personnel		CGP 3.10.D	1		\$50.00	=
33	All areas disturbed by construction activity or used for storage of materials and which exposed to precipitation not inspected		CGP 3.10.E.			\$50.00	=
34	All pollution control measures not inspected to ensure proper operation		CGP 3.10.E.	A	1997 - 1997 -	\$50.00	=
35	Discharge locations are not observed and inspected		CGP 3.10.E.	th.	-100 - 1	\$50.00	=
36	For discharge locations that are not accessible, nearby locations are not inspected	alle and the second a	CGP 3.10.E.	1 24 1 24	for the second sec	\$50.00	
37	Entrance/exit not inspected for off-site tracking	9 	CGP 3.10.E.	ora.	1977 - (2)	\$50.00	=
38	Site inspection report does not include: date, name and qualifications of inspector, weather information, location of sediment/pollutant discharge, BMP(s) requiring maintenance, BMP(s) that have failed, BMP(s) that are needed, corrective action required including changes/updates to SWPPP and schedule/dates (count each omission under 38 as 1 violation)		CGP 3.10.G	a to a second		\$50.00	=
39	Inspection reports not properly signed/certified (count each failure to to sign/certify as 1 violation)		CGP 3.10.G	- 1.P.	an ta shi a ta shi	\$50.00	=
-	·	1	Sul	ototal	Inspectio	ns Deficiencie	\$ \$0
	AVAILABILITY OF RECORDS			_			
40	Sign/notice not posted A Does not contain copy of complete NOI		CGP 3.12.B CGP 3.12.B			\$250.00	
	B Location of SWPPP or contact person for scheduling viewing times where on-site location		CGP 3.12.B	1. 2.4	n for a start	\$50.00	and the second se
	for SWPPP unavailable not noted on sign	and the second		1. 2.00	, HEAT ?		
				Subt	otal Recor	ds Deficiencies	s \$0
41	BEST MANAGEMENT PRACTICES No velocity dissipation devices located at discharge locations or outfall channels to ensure		CGP 3.13.F		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	\$500.00	=
42	non-erosive flow to receiving water Control measures are not properly:	Flocculation not installed to control fine	And the second second	-			and the second second
	A Selected, installed and maintained	clays; gravel site entrance not maintained; detention basin not	CGP 3.13.A	-	2	× \$500.00	\$1,000
E	B Maintenance not performed prior to next anticipated storm event	maintained	CGP 3.6.B		1	× \$250.00	\$250
	(count each failure to select, install, maintain each BMP as one violation						1 1 1
43	When sediment escapes the site, it is not removed at a frequency necessary to minimize off-site impacts		CGP 3.13.B	1		\$500.00	=
44	Litter, construction debris, and construction chemicals exposed to storm water are not prevented from becoming a pollutant source (e.g. screening outfalls, pickup daily, etc.)		CGP 3.13.C			\$500.00	-

. . .

45 Stabilization measures are not practible on portions of the site activities have temporarily or p	where construction armanently ceased		CGP 3.13.D	\$500.00 =	
within 14 days after such cess	ation		3/11 2	12 - 4	
*Exceptions:	ist. C	- 1	F ALTO POT P		S Barris Barris
(a) Snow or frozen ground	conditions		ATTICK STORE STREET BAL	A COLOR NO AND	
(b) Activities will be resume		al and an			
(c) Arid or Semi-arid areas	(<20 inches per		A A A A A A A A A A A A A A A A A A A	Anna Alt Alland March 1	
46 Common Drainage of 10+ acre		1	CGP 3.13.E.1	\$1,000.00 =	
sedimentation basin for the 2 y or 3600 cubic ft. storage per ad	ear, 24 hour storm,		12		
A Where sedimentation basin no sediment basins, sediment trap controls not implemented for d	s, or erosion	and the	CGP 3.13.E.2	\$1,000.00 =	
B Sadiment not removed from se traps when design capacity rec more	diment basin or		CGP 3.6.C	\$500.00 =	
47 Common Drainage less than 1 have sediment traps, silt fence strips, or equivalent sediment of slope boundaries (not required sediment basin meeting criteria	s, vegetative buffer controls for all down if sedimentation		CGP 3.13.E.3	\$500.00 ⊨	
A Sediment not removed from se design capacity reduced by 50			CGP 3.6.C	\$500.00 =	
1 Jucaigh capacity reduced by co				Subtotal BMP Deficiencies	\$1,2
SMALL BUSINESS EVALUAT	ION				
48 Is the Owner/Operator a Small	Business?	10		Yes	
A small business is defined Business Compliance Policy corporation, partnership, or employs 100 or fewer indivit facilities and operations own business)." The number of	as: "a person, other entity that dals (across all ed by the small employees should				
be considered as full-time ed annual basis, including contr 40 CFR 372.3). A full time e 2000 hours worked per year	act employees (see mployee unit is		Carlo I		
and the second s	and the local data and the second			al Expedited Settlement:	\$1,2

4

\* Requires Corrective Action \*\* NPDES General Permit, 68 FR 39087, issued by EPA on July 1, 2003, http://cfpub.epa.gov/npdes/stormwater/cgp.cfm