## **Expedited Settlement Offer Worksheet** Findings and Alleged Violations Consult instructions regarding eligibility criteria

and procedures prior to use

Version: 2021 Washington State Construction Stormwater General Permit

August 25, 2025

August 25, 2025
24:49 P.M. PST
35. EPA REGION 10
HEARING CLERK HEARING CLERK

								GCLLINN		
	LEGAL NAME AND MAILING ADDRESS OF OPERATOR		Telephone Number				NPDES Permit Number			
1	Rob Hinton, Site Owner Contact		Inspector Name: Inspector Agency: Entrance Interview Conducted: Exit Interview Conducted: Exit Interview given to:			WAR305872				
	Granite Three, LLC					Jon Klemesrud EPA				
L	14010A NE 3rd Court, Suite 106									
L	Vancouver, WA 98685					Yes				
						Yes Tim Ritola				
	LOCATION AND ADDRESS OF SITE									
2	Granite Highlands Subdivision		Exit Interview d	late / time	e:	1/14/2025 approx. 12:00PM				
_	Parcels 130541-000 and 130545-000 (N 6th Street and N 10th Street)					_				
F	Washougal, Washington 98671									
F										
	EAGULITY RECORDED ON A CONTACT MANGE									
	FACILITY DESCRIPTION / CONTACT NAMES	Name of Site Contact (ESO Worksheet recipient):								
3										
<u> </u>		Name of Authorized Official (40 CFR 122.22):								
<u> </u>		Inspection Date:								
		Start Construction Date:								
F		Estimated Completion Construction Date:								
L		If Unpermitted, Number of Months Unpermitted:								
		Name of Receiving Water Body (Indicate whether 303(d) listed):			Washa	ugal Pi	vor			
_ <u> </u>	Acres Disturbed   Acres for Whole Common Plan:									
	Operator Requested Rainfall Erosivity or TMDL Waiver (44 CFR 122.2	ī	40.0							
	Operator Requested Raillan Erosivity of ThibE Waiver (44 of R 122.2	(b)(13))	No. of							
	PERMIT COVERAGE	Findings	CGP Citation	RCA*	Deficien-	Mult-	Penalty	Total		
					cies	iply	Amount			
26	Site inspection report does not include all information required by the	15 site inspection reports reviewed did not include implementation schedule	S4.B.4.a-m		15	Х	\$60.00	\$900		
	Permit. (Count each omission as one violation.)	for remedial actions and BMP observations.								
<del></del>	BEST MANAGEMENT PRACTICES									
	General Maintenance Requirements:					1 1				
28 /	A Failure to ensure that all stormwater controls are maintained and remain	(1) Check-dams installed along eastern drainage channel (along	S3.C.2;		3	X	\$300.00	\$900		
	in effective operating condition (i.e., all routine maintenance-and	easternmost area of N LeBrun Blvd) were full and needed maintenance -	S9.D.11				***************************************	,,,,		
	corrective actions are-performed within the timeframes required by the	Jan 14, 2025. (2) drainage channel in need of maintenance along N Z Circle								
	Permit). (Count each failure to timely maintain each control as one	Jan 14, 2025; (3) construction road maintenance (need for BMPs) on								
	violation.)	eastern half of the site - Jan 14, 2025. Corrective actions for BMPs and								
		eastern half of the site - Jan 14, 2025. Corrective actions for BMPs and controls not conducted within timeframes required by the Permit. 3 counts								
		eastern half of the site - Jan 14, 2025. Corrective actions for BMPs and								
		eastern half of the site - Jan 14, 2025. Corrective actions for BMPs and controls not conducted within timeframes required by the Permit. 3 counts								
42	violation.)  Failure to initiate and complete stabilization measures within the	eastern half of the site - Jan 14, 2025. Corrective actions for BMPs and controls not conducted within timeframes required by the Permit. 3 counts	S9.D.8.b;		2	Х	\$600.00	\$1,200		
42	violation.)	eastern half of the site - Jan 14, 2025. Corrective actions for BMPs and controls not conducted within timeframes required by the Permit. 3 counts total	S9.D.5;		2	Х	\$600.00	\$1,200		
42	violation.)  Failure to initiate and complete stabilization measures within the	eastern half of the site - Jan 14, 2025. Corrective actions for BMPs and controls not conducted within timeframes required by the Permit. 3 counts total  Observed areas were unstabilized – along NY Street and along the ecology			2	Х	\$600.00	\$1,200		
42	violation.)  Failure to initiate and complete stabilization measures within the	eastern half of the site - Jan 14, 2025. Corrective actions for BMPs and controls not conducted within timeframes required by the Permit. 3 counts total  Observed areas were unstabilized – along NY Street and along the ecology	S9.D.5;		2	Х	\$600.00	\$1,200		

	SMALL BUSINESS EVALUATION							
52	Is the Owner/Operator a Small Business?						Yes or No	
	A <i>small business</i> is defined by EPA's Small Business Compliance Policy as: "a person, corporation, partnership, or other entity that employs 100 or fewer individuals (across all facilities and operations owned by the small business)." The number of employees should be considered as fulltime equivalents on an annual basis, including contract employees (see 40 CFR 372.3). A full time employee unit is 2000 hours worked per year.						Yes	
Total Expedited Settlement:								\$3,000
	ADJUSTMENT FOR REPEAT VIOLATOR:							
54	For Repeat Violators, the Expedited Settlement Amount should be adjusted upward using the appropriate Escalation Factor. Enter either 0.25 (1st time Repeat Violator) or 0.5 (2nd or more times) into Column G. Leave this row blank if this is not a Repeat Violator.	Adjustment for Repeat Violator:				Х	\$3,000.00	\$0

## **Total Expedited Settlement Amount**

\$3,000

\*RCA: Requires Corrective Action