

FIGURE TA5-2
Degradation Pathways
for Chlorinated Compounds
Remedial Investigation
San Gabriel Valley Area 3 Superfund Site

Source: Interstate Technology Regulatory Cooperation (ITRC), 1999, Technical/Regulatory Guidelines, Natural Attenuation of Chlorinated Solvents in Groundwater: Principles and Practices, September.

CH2MHILL