# APPENDIX A
# CHAIN-OF-CUSTODY FORMS

IT CORPORATION
INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 201 31b

Page 1 of 1

Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 65554
Required Report Date: See PAM

Samples Shipment Date: 9/1/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

**ONE CONTAINER PER LINE**

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| NOT COLLECTED | A-PUF | SAMPLE STATION A | 8/31/00 | 0.00 | Jar & Envelope | ICE | TO-4 & TO-13 full suite | | |
| NOT COLLECTED | B-PUF | SAMPLE STATION B | 8/31/00 | 0.00 | " | " | TO-4 & TO-13 full suite | | |
| NOT COLLECTED | C-PUF | SAMPLE STATION C | 8/31/00 | 0.00 | " | " | TO-4 & TO-13 full suite | | |
| NOT COLLECTED | D-PUF | SAMPLE STATION D | 8/31/00 | 0.00 | " | " | TO-4 & TO-13 full suite | | |
| 00831-LFFPUF-2403 | E-PUF | PARCEL E | 8/31/00 | 332.99 | " | " | TO-4 & TO-13 full suite | 27255 | |
| NOT COLLECTED | F-PUF | SAMPLE STATION F | 8/31/00 | 0.00 | " | " | TO-4 & TO-13 full suite | | |
| NOT COLLECTED | BLANK-PUF | PUF Blank | 8/31/00 | NA | " | " | TO-4 & TO-13 full suite | | |
| NOT COLLECTED | A-VOC | SAMPLE STATION A | 8/31/00 | 0.00 | SUMMA | None | TO-14 full suite, see NOTE | | |
| 00831-LFFVOC-A701 | B-VOC | PARCEL E | 8/31/00 | 19.50 | " | " | TO-14 | 27256 | |
| NOT COLLECTED | C-VOC | SAMPLE STATION C | 8/31/00 | 0.00 | " | " | TO-14 | | |
| NOT COLLECTED | D-VOC | SAMPLE STATION D | 8/31/00 | 0.00 | " | " | TO-14 | | |
| NOT COLLECTED | E-VOC | SAMPLE STATION E | 8/31/00 | 0.00 | " | " | TO-14 | | |
| NOT COLLECTED | F-VOC | SAMPLE STATION F | 8/31/00 | 0.00 | " | " | TO-14 | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 8/31/00 | NA | " | " | TO-14 | | |
| NOT COLLECTED | A-TSP | SAMPLE STATION A | 8/31/00 | 0.00 | Envelope | " | Metals full suite | | |
| NOT COLLECTED | B-TSP | SAMPLE STATION B | 8/31/00 | 0.00 | " | " | Metals full suite | | |
| NOT COLLECTED | C-TSP | SAMPLE STATION C | 8/31/00 | 0.00 | " | " | Metals full suite | | |
| NOT COLLECTED | D-TSP | SAMPLE STATION D | 8/31/00 | 0.00 | " | " | Metals full suite | | |
| 00831-LFFTSP-7168 | E-TSP | PARCEL E | 8/31/00 | 1853.36 | " | " | Metals full suite | 27257 | |
| NOT COLLECTED | F-TSP | SAMPLE STATION F | 8/31/00 | 0.00 | " | " | Metals full suite | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 8/31/00 | NA | " | " | Metals full suite | | |

Special Instructions: Check pressure on AVOCS sample.
Possible Hazard ID: none
Sample Disposal: By Lab
Turnaround Time Required: Standard
QC Level: See PAM

Relinquished by (Signature/Affiliation): [signature] Date: 9/1/00 Time: 1305
Received by 1. (Signature/Affiliation): [signature] Date: 9/1/00 Time: 1:06 pm

Relinquished by (Signature/Affiliation): [signature] Date: 9/1/00 Time: 4:30pm
Received by 2. (Signature/Affiliation): Charlotte Moon Date: 09/01/00 Time: 4:30

Relinquished by (Signature/Affiliation): Date: Time:
Received by 3. (Signature/Affiliation): Date: Time:

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)



SEP-11-2000 MON 04:28 PM K PRIME INC FAX NO. 707 527 7879 P. 09/09

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 00090809



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L. Leet, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/10/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00090809-PUFAE-2406 | A-PUF | SAMPLE STATION AE | 9/8/00 | 298.66 | Jar & Envelope | ICE | TO-4 & TO-13 | | 27304 |
| 00090809-PUFBE-2407 | B-PUF | SAMPLE STATION BE | 9/8/00 | 305.90 | " | " | TO-4 & TO-13 | | 27305 |
| 00090809-PUFCE-2408 | C-PUF | SAMPLE STATION CE | 9/8/00 | 313.15 | " | " | TO-4 & TO-13 | | 27306 |
| 00090809-PUFDE-2409 | D-PUF | SAMPLE STATION DE | 9/8/00 | 301.99 | " | " | TO-4 & TO-13 | | 27307 |
| 00090809-PUFEE-2411 | E-PUF | SAMPLE STATION EE | 9/8/00 | 193.36 | " | " | TO-4 & TO-13 | | 27308 |
| 00090809-PUFFE-2410 | F-PUF | SAMPLE STATION FE | 9/8/00 | 288.84 | " | " | TO-4 & TO-13 | | 27309 |
| Not Collected | BLANK-PUF | PUF Blank | 9/8/00 | NA | " | " | TO-4 & TO-13 | | |
| Not Collected | A-VOC | SAMPLE STATION A | 9/8/00 | 0.00 psi | SUMMA | None | TO-14 See Note | | |
| Not Collected | B-VOC | SAMPLE STATION B | 9/8/00 | 0.00 | " | " | TO-14 | | |
| Not Collected | C-VOC | SAMPLE STATION C | 9/8/00 | 0.00 | " | " | TO-14 | | |
| Not Collected | D-VOC | SAMPLE STATION D | 9/8/00 | 0.00 | " | " | TO-14 | | |
| Not Collected | E-VOC | SAMPLE STATION E | 9/8/00 | 0.00 | " | " | TO-14 | | |
| Not Collected | F-VOC | SAMPLE STATION F | 9/8/00 | 0.00 | " | " | TO-14 | | |
| Not Collected | VOC-BLANK | VOC-BLANK | 9/8/00 | NA | " | " | TO-14 | | |
| Not Collected | A-TSP | SAMPLE STATION A | 9/8/00 | 0.00 | Envelope | " | Full Suite Metals | | |
| Not Collected | B-TSP | SAMPLE STATION B | 9/8/00 | 0.00 | " | " | Full Suite Metals | | |
| Not Collected | C-TSP | SAMPLE STATION C | 9/8/00 | 0.00 | " | " | Full Suite Metals | | |
| Not Collected | D-TSP | SAMPLE STATION D | 9/8/00 | 0.00 | " | " | Full Suite Metals | | |
| Not Collected | E-TSP | SAMPLE STATION E | 9/8/00 | 0.00 | " | " | Full Suite Metals | | |
| Not Collected | F-TSP | SAMPLE STATION F | 9/8/00 | 0.00 | " | " | Full Suite Metals | | |
| Not Collected | TSP-BLANK | TSP-BLANK | 9/8/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Sample for full suite in reference methods. Additonally, include analyses per conversations with IT for low res. dioxins and furans and chlorine components.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: Standard | QC Level: See PAM

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) C. Foreman, L. Leet (VTC) | Date: 9-10-00 Time: 1002 | 1. Received by (Signature/Affiliation) L. Leet (VTC) | Date: 9/10/00 Time: 1002 |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: 9-10-00 Time: 11:30 |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

BW

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-090910



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L. Leet, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/11/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00090910-PUFAE-2412 | A-PUF | SAMPLE STATION A | 9/9/00 | 315.81 | Jar & Envelope | ICE | TO-4&TO-13&TO9m | | |
| 00090910-PUFBE-2413 | B-PUF | SAMPLE STATION B | 9/9/00 | 325.93 | " | " | TO-4&TO-13&TO9m | | |
| 00090910-PUFCE-2414 | C-PUF | SAMPLE STATION C | 9/9/00 | 337.09 | " | " | TO-4&TO-13&TO9m | | |
| 00090910-PUFDE-2415 | D-PUF | SAMPLE STATION D | 9/9/00 | 338.01 | " | " | TO-4&TO-13&TO9m | | |
| 00090910-PUFEE-2416 | E-PUF | SAMPLE STATION E | 9/9/00 | 335.60 | " | " | TO-4&TO-13&TO9m | | |
| 00090910-PUFFE-2417 | F-PUF | SAMPLE STATION F | 9/9/00 | 324.04 | " | " | TO-4&TO-13&TO9m | | |
| NOT COLLECTED | BLANK-PUF | PUF Blank | 9/9/00 | NA | " | " | TO-4&TO-13&TO9m | | |
| 00090910-VOCAE-A420 | A-VOC | SAMPLE STATION A | 9/9/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00090910-VOCBE-A433 | B-VOC | SAMPLE STATION B | 9/9/00 | 1.50 | " | " | TO-14a | | |
| 0090910-VOCCE-A425 | C-VOC | SAMPLE STATION C | 9/9/00 | 4.00 | " | " | TO-14a | | |
| 0090910-VOCDE-A426 | D-VOC | SAMPLE STATION D | 9/9/00 | 1.90 | " | " | TO-14a | | |
| 00090910-VOCEE-A914 | E-VOC | SAMPLE STATION E | 9/9/00 | 0.00 | " | " | TO-14a | | |
| 00090910-VOCFE-A301 | F-VOC | SAMPLE STATION F | 9/9/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/9/00 | NA | " | " | TO-14a | | |
| 00090910-TSPAE-7170 | A-TSP | SAMPLE STATION A | 9/9/00 | 1773.37 | Envelope | " | Full Suite Metals | | |
| 00090910-TSPBE-7171 | B-TSP | SAMPLE STATION B | 9/9/00 | 1846.55 | " | " | Full Suite Metals | | |
| 00090910-TSPCE-7172 | C-TSP | SAMPLE STATION C | 9/9/00 | 1878.76 | " | " | Full Suite Metals | | |
| 00090910-TSPDE-7173 | D-TSP | SAMPLE STATION D | 9/9/00 | 1838.74 | " | " | Full Suite Metals | | |
| 00090910-TSPEE-7180 | E-TSP | SAMPLE STATION E | 9/9/00 | 1835.95 | " | " | Full Suite Metals | | |
| 00090910-TSPFE-7174 | F-TSP | SAMPLE STATION F | 9/9/00 | 1881.87 | " | " | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/9/00 | NA | " | " | Full Suite Metals | | |
| --- | --- | --- | --- | --- | --- | --- | --- | | |
| --- | --- | --- | --- | --- | --- | --- | --- | | |
| --- | --- | --- | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze for full suite in reference methods. Additonally,include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: Standard | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091011



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L. Leet, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/12/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091011-PUFAE-2425 | A-PUF | SAMPLE STATION A | 9/10/00 | 338.18 | Jar & Envelope | ICE | TO-4 & TO-13&TO-9m | | |
| 00091011-PUFBE-2424 | B-PUF | SAMPLE STATION B | 9/10/00 | 344.14 | " | " | TO-4 & TO-13&TO-9m | | |
| 00091011-PUFCE-2423 | C-PUF | SAMPLE STATION C | 9/10/00 | 332.05 | " | " | TO-4 & TO-13&TO-9m | | |
| 00091011-PUFDE-2422 | D-PUF | SAMPLE STATION D | 9/10/00 | 341.10 | " | " | TO-4 & TO-13&TO-9m | | |
| 00091011-PUFEE-2421 | E-PUF | SAMPLE STATION E | 9/10/00 | 332.79 | " | " | TO-4 & TO-13&TO-9m | | |
| 00091011-PUFFE-2420 | F-PUF | SAMPLE STATION F | 9/10/00 | 332.61 | " | " | TO-4 & TO-13&TO-9m | | |
| 00091011-FBEPUF-2419 | BLANK-PUF | PUF Blank | 9/10/00 | NA | " | " | TO-4 & TO-13&TO-9m | | |
| 00091011-VOCAE-A102 | A-VOC | SAMPLE STATION A | 9/10/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00091011-VOCBE-A508 | B-VOC | SAMPLE STATION B | 9/10/00 | 0.00 | " | " | TO-14a | | |
| 00091011-VOCCE-A803 | C-VOC | SAMPLE STATION C | 9/10/00 | 0.00 | " | " | TO-14a | | |
| 00091011-VOCDE-A201 | D-VOC | SAMPLE STATION D | 9/10/00 | 0.00 | " | " | TO-14a | | |
| 00091011-VOCEE-A306 | E-VOC | SAMPLE STATION E | 9/10/00 | 0.00 | " | " | TO-14a | | |
| 00091011-VOCEF-A802 | F-VOC | SAMPLE STATION F | 9/10/00 | 0.00 | " | " | TO-14a | | |
| 00091011-FBEVOC-A513 | VOC-BLANK | VOC-BLANK | 9/10/00 | NA | " | " | TO-14a | | |
| 00091011-TSPAE-7176 | A-TSP | SAMPLE STATION A | 9/10/00 | 1910.18 | Envelope | " | Full Suite Metals | | |
| 00091011-TSPBE-7177 | B-TSP | SAMPLE STATION B | 9/10/00 | 1965.62 | " | " | Full Suite Metals | | |
| 00091011-TSPCE-7178 | C-TSP | SAMPLE STATION C | 9/10/00 | 1883.92 | " | " | Full Suite Metals | | |
| 00091011-TSPDE-7179 | D-TSP | SAMPLE STATION D | 9/10/00 | 1923.28 | " | " | Full Suite Metals | | |
| 00091011-TSPEE-7182 | E-TSP | SAMPLE STATION E | 9/10/00 | 1850.32 | " | " | Full Suite Metals | | |
| 00091011-TSPFE-7181 | F-TSP | SAMPLE STATION F | 9/10/00 | 1872.52 | " | " | Full Suite Metals | | |
| 00091011-FBETSP-7183 | TSP-BLANK | TSP-BLANK | 9/10/00 | NA | " | " | Full Suite Metals | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. Dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: Standard | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809 Sample No. 00091011-TSPBE-7177 ran slightly over 25 hours.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091112



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/13/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091112-PUFAE-2432 | A-PUF | SAMPLE STATION A | 9/11/00 | 334.10 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00091112-PUFBE-2433 | B-PUF | SAMPLE STATION B | 9/11/00 | 335.68 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091112-PUFCE-2434 | C-PUF | SAMPLE STATION C | 9/11/00 | 336.34 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091112-PUFDE-2435 | D-PUF | SAMPLE STATION D | 9/11/00 | 323.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091112-PUFEE-2436 | E-PUF | SAMPLE STATION E | 9/11/00 | 321.52 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091112-PUFFE-2437 | F-PUF | SAMPLE STATION F | 9/11/00 | 326.30 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | BLANK-PUF | PUF Blank | 9/11/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091112-VOCAE-A507 | A-VOC | SAMPLE STATION A | 9/11/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00091112-VOCBE-A809 | B-VOC | SAMPLE STATION B | 9/11/00 | 0.00 | " | " | TO-14a | | |
| 00091112-VOCCE-A105 | C-VOC | SAMPLE STATION C | 9/11/00 | 8.00 | " | " | TO-14a | | |
| 00091112-VOCDE-A807 | D-VOC | SAMPLE STATION D | 9/11/00 | 4.00 | " | " | TO-14a | | |
| 00091112-VOCEE-A705 | E-VOC | SAMPLE STATION E | 9/11/00 | 0.00 | " | " | TO-14a | | |
| 00091112-VOCFE-A204 | F-VOC | SAMPLE STATION F | 9/11/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/11/00 | NA | " | " | TO-14a | | |
| 00091112-TSPAE-7184 | A-TSP | SAMPLE STATION A | 9/11/00 | 1817.19 | Envelope | " | Full Suite Metals | | |
| 00091112-TSPBE-7185 | B-TSP | SAMPLE STATION B | 9/11/00 | 1942.01 | " | " | Full Suite Metals | | |
| 00091112-TSPCE-7193 | C-TSP | SAMPLE STATION C | 9/11/00 | 1855.57 | " | " | Full Suite Metals | | |
| 00091112-TSPDE-7194 | D-TSP | SAMPLE STATION D | 9/11/00 | 1800.05 | " | " | Full Suite Metals | | |
| 00091112-TSPEE-7197 | E-TSP | SAMPLE STATION E | 9/11/00 | 1806.22 | " | " | Full Suite Metals | | |
| 00091112-TSPFE-7195 | F-TSP | SAMPLE STATION F | 9/11/00 | 1815.32 | " | " | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/11/00 | NA | " | " | Full Suite Metals | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Spare PUF glass included.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnaround | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809). Sample 00091112-TSPBE-7185 ran slightly in excess of 25 hours.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091213



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/14/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091213-PUFAE-2427 | A-PUF | SAMPLE STATION A | 9/12/00 | 321.37 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| VOID | B-PUF | SAMPLE STATION B | 9/12/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091213-PUFCE-2429 | C-PUF | SAMPLE STATION C | 9/12/00 | 335.09 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091213-PUFDE-2430 | D-PUF | SAMPLE STATION D | 9/12/00 | 335.43 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091213-PUFEE-2431 | E-PUF | SAMPLE STATION E | 9/12/00 | 337.32 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091213-PUFFE-2438 | F-PUF | SAMPLE STATION F | 9/12/00 | 328.44 | " | " | TO-4 & TO-13 & TO-9m | | |
| 0091213-FBEPUF-2426 | BLANK-PUF | PUF Blank | 9/12/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091213-VOCAE-A502 | A-VOC | SAMPLE STATION A | 9/12/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00091213-VOCBE-A806 | B-VOC | SAMPLE STATION B | 9/12/00 | 0.00 | " | " | TO-14a | | |
| 00091213-VOCCE-A702 | C-VOC | SAMPLE STATION C | 9/12/00 | 0.00 | " | " | TO-14a | | |
| 00091213-VOCDE-A607 | D-VOC | SAMPLE STATION D | 9/12/00 | 2.00 | " | " | TO-14a | | |
| 00091213-VOCEE-A805 | E-VOC | SAMPLE STATION E | 9/12/00 | 0.00 | " | " | TO-14a | | |
| 00091213-VOCFE-A423 | F-VOC | SAMPLE STATION F | 9/12/00 | 0.00 | " | " | TO-14a | | |
| 00091213-FBEVOC-A808 | VOC-BLANK | VOC-BLANK | 9/12/00 | NA | " | " | TO-14a | | |
| 00091213-TSPAE-7198 | A-TSP | SAMPLE STATION A | 9/12/00 | 1799.93 | Envelope | " | Full Suite Metals | | |
| VOID | B-TSP | SAMPLE STATION B | 9/12/00 | 0.00 | " | " | Full Suite Metals | | |
| 00091213-TSPCE-7200 | C-TSP | SAMPLE STATION C | 9/12/00 | 1871.45 | " | " | Full Suite Metals | | |
| 00091213-TSPDE-7201 | D-TSP | SAMPLE STATION D | 9/12/00 | 1847.54 | " | " | Full Suite Metals | | |
| 00091213-TSPEE-7202 | E-TSP | SAMPLE STATION E | 9/12/00 | 1849.09 | " | " | Full Suite Metals | | |
| 00091213-TSPFE-7203 | F-TSP | SAMPLE STATION F | 9/12/00 | 1869.08 | " | " | Full Suite Metals | | |
| 0091213-FBETSP-7196 | TSP-BLANK | TSP-BLANK | 9/12/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Void PUF sample included.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnaround | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-280Sample 00091213-VOCBE-A806 ran until 0820 Thursday 8/14/00.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091314



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/15/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091314-PUFAE-2439 | A-PUF | SAMPLE STATION A | 9/13/00 | 326.50 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00091314-PUFBE-2440 | B-PUF | SAMPLE STATION B | 9/13/00 | 348.14 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | C-PUF | SAMPLE STATION C | 9/13/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091314-PUFDE-2442 | D-PUF | SAMPLE STATION D | 9/13/00 | 342.06 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091314-PUFEE-2443 | E-PUF | SAMPLE STATION E | 9/13/00 | 334.80 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091314-PUFFE-2444 | F-PUF | SAMPLE STATION F | 9/13/00 | 313.92 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | BLANK-PUF | PUF Blank | 9/13/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091314-VOCAE-A414 | A-VOC | SAMPLE STATION A | 9/13/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| NOT COLLECTED | B-VOC | SAMPLE STATION B | 9/13/00 | 0.00 | " | " | TO-14a | | |
| 0091314-VOCCE-A432 | C-VOC | SAMPLE STATION C | 9/13/00 | 9.00 | " | " | TO-14a | | |
| 0091314-VOCDE-A112 | D-VOC | SAMPLE STATION D | 9/13/00 | 3.00 | " | " | TO-14a | | |
| 00091314-VOCEE-A804 | E-VOC | SAMPLE STATION E | 9/13/00 | 0.00 | " | " | TO-14a | | |
| 00091314-VOCFE-A303 | F-VOC | SAMPLE STATION F | 9/13/00 | 2.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/13/00 | NA | " | " | TO-14a | | |
| 00091314-TSPAE-7204 | A-TSP | SAMPLE STATION A | 9/13/00 | 1780.16 | Envelope | " | Full Suite Metals | | |
| 00091314-TSPBE-7205 | B-TSP | SAMPLE STATION B | 9/13/00 | 1900.17 | " | " | Full Suite Metals | | |
| 00091314-TSPCE-7207 | C-TSP | SAMPLE STATION C | 9/13/00 | 1917.11 | " | " | Full Suite Metals | | |
| 00091314-TSPDE-7208 | D-TSP | SAMPLE STATION D | 9/13/00 | 1847.76 | " | " | Full Suite Metals | | |
| 00091314-TSPEE-7209 | E-TSP | SAMPLE STATION E | 9/13/00 | 1836.26 | " | " | Full Suite Metals | | |
| 00091314-TSPFE-7210 | F-TSP | SAMPLE STATION F | 9/13/00 | 1850.89 | " | " | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/13/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnaround | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091415



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/16/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091415-PUFAE-2446 | A-PUF | SAMPLE STATION A | 9/14/00 | 320.83 | Jar & Envelope | ICE | O-4 & TO-13 & TO-9m | | |
| 00091415-PUFBE-2447 | B-PUF | SAMPLE STATION B | 9/14/00 | 341.27 | " | " | O-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | C-PUF | SAMPLE STATION C | 9/14/00 | 0.00 | " | " | O-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | D-PUF | SAMPLE STATION D | 9/14/00 | 0.00 | " | " | O-4 & TO-13 & TO-9m | | |
| 00091415-PUFEE-2449 | E-PUF | SAMPLE STATION E | 9/14/00 | 331.59 | " | " | O-4 & TO-13 & TO-9m | | |
| 00091415-PUFFE-2450 | F-PUF | SAMPLE STATION F | 9/14/00 | 333.07 | " | " | O-4 & TO-13 & TO-9m | | |
| 0091415-FBEPUF-2445 | BLANK-PUF | PUF Blank | 9/14/00 | NA | " | " | O-4 & TO-13 & TO-9m | | |
| VOID | A-VOC | SAMPLE STATION A | 9/14/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00091415-VOCBE-A201 | B-VOC | SAMPLE STATION B | 9/14/00 | 2.00 | " | " | TO-14a | | |
| 00091415-VOCCE-A301 | C-VOC | SAMPLE STATION C | 9/14/00 | 10.00 | " | " | TO-14a | | |
| 00091415-VOCDE-A102 | D-VOC | SAMPLE STATION D | 9/14/00 | 4.50 | " | " | TO-14a | | |
| 00091415-VOCEE-A914 | E-VOC | SAMPLE STATION E | 9/14/00 | 0.00 | " | " | TO-14a | | |
| 00091415-VOCFE-A602 | F-VOC | SAMPLE STATION F | 9/14/00 | 3.00 | " | " | TO-14a | | |
| 0091415-FBEVOC-A701 | VOC-BLANK | VOC-BLANK | 9/14/00 | NA | " | " | TO-14a | | |
| 00091415-TSPAE-7211 | A-TSP | SAMPLE STATION A | 9/14/00 | 1793.84 | Envelope | " | Full Suite Metals | | |
| 00091415-TSPBE-7213 | B-TSP | SAMPLE STATION B | 9/14/00 | 1877.75 | " | " | Full Suite Metals | | |
| 00091415-TSPCE-7214 | C-TSP | SAMPLE STATION C | 9/14/00 | 1892.32 | " | " | Full Suite Metals | | |
| 00091415-TSPDE-7215 | D-TSP | SAMPLE STATION D | 9/14/00 | 1838.42 | " | " | Full Suite Metals | | |
| 00091415-TSPEE-7216 | E-TSP | SAMPLE STATION E | 9/14/00 | 1849.29 | " | " | Full Suite Metals | | |
| 00091415-TSPFE-7217 | F-TSP | SAMPLE STATION F | 9/14/00 | 1853.73 | " | " | Full Suite Metals | | |
| 0091415-FBETSP-7212 | TSP-BLANK | TSP-BLANK | 9/14/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnaroun | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |
| Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | |

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091516



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L. Leet, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/17/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091516-PUFAE-2451 | A-PUF | SAMPLE STATION A | 9/15/00 | 342.34 | Jar & Envelope | ICE | O-4 & TO-13 & TO-9m | | |
| 00091516-PUFBE-2452 | B-PUF | SAMPLE STATION B | 9/15/00 | 340.68 | " | " | O-4 & TO-13 & TO-9m | | |
| 00091516-PUFCE-2441 | C-PUF | SAMPLE STATION C | 9/15/00 | 344.12 | " | " | O-4 & TO-13 & TO-9m | | |
| 00091516-PUFDE-2448 | D-PUF | SAMPLE STATION D | 9/15/00 | 333.03 | " | " | O-4 & TO-13 & TO-9m | | |
| VOID | E-PUF | SAMPLE STATION E | 9/15/00 | 0.00 | " | " | O-4 & TO-13 & TO-9m | | |
| 00091516-PUFFE-2454 | F-PUF | SAMPLE STATION F | 9/15/00 | 327.16 | " | " | O-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | BLANK-PUF | PUF Blank | 9/15/00 | NA | " | " | O-4 & TO-13 & TO-9m | | |
| 00091516-VOCAE-A428 | A-VOC | SAMPLE STATION A | 9/15/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00091516-VOCBE-A603 | B-VOC | SAMPLE STATION B | 9/15/00 | 0.00 | " | " | TO-14a | | |
| 00091516-VOCCE-A202 | C-VOC | SAMPLE STATION C | 9/15/00 | 8.00 | " | " | TO-14a | | |
| 00091516-VOCDE-A704 | D-VOC | SAMPLE STATION D | 9/15/00 | 0.00 | " | " | TO-14a | | |
| 00091516-VOCEE-A306 | E-VOC | SAMPLE STATION E | 9/15/00 | 0.00 | " | " | TO-14a | | |
| 00091516-VOCFE-A433 | F-VOC | SAMPLE STATION F | 9/15/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/15/00 | NA | " | " | TO-14a | | |
| 00091516-TSPAE-7218 | A-TSP | SAMPLE STATION A | 9/15/00 | 1974.76 | Envelope | " | Full Suite Metals | | |
| 00091516-TSPBE-7219 | B-TSP | SAMPLE STATION B | 9/15/00 | 2044.38 | " | " | Full Suite Metals | | |
| 00091516-TSPCE-7220 | C-TSP | SAMPLE STATION C | 9/15/00 | 2021.47 | " | " | Full Suite Metals | | |
| 00091516-TSPDE-7221 | D-TSP | SAMPLE STATION D | 9/15/00 | 1960.55 | " | " | Full Suite Metals | | |
| 00091516-TSPEE-7222 | E-TSP | SAMPLE STATION E | 9/15/00 | 1944.38 | " | " | Full Suite Metals | | |
| 00091516-TSPFE-7223 | F-TSP | SAMPLE STATION F | 9/15/00 | 1970.65 | " | " | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/15/00 | NA | " | " | Full Suite Metals | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res.dioxins and furans. Returning VOID PUF sample.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnaroun | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |
| Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | |

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091617



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L. Leet, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/18/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091617-PUFAE-2456 | A-PUF | SAMPLE STATION A | 9/16/00 | 330.99 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00091617-PUFBE-2457 | B-PUF | SAMPLE STATION B | 9/16/00 | 328.14 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091617-PUFCE-2458 | C-PUF | SAMPLE STATION C | 9/16/00 | 335.67 | " | " | TO-4 & TO-13 & TO-9m | | |
| VOID | D-PUF | SAMPLE STATION D | 9/16/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091617-PUFEE-2460 | E-PUF | SAMPLE STATION E | 9/16/00 | 334.52 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091617-PUFFE-2461 | F-PUF | SAMPLE STATION F | 9/16/00 | 320.58 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 9/16/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091617-FBEPUF-2455 | PUF BLANK | PUF-BLANK | 9/16/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091617-VOCAE-A801 | A-VOC | SAMPLE STATION A | 9/16/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00091617-VOCBE-A513 | B-VOC | SAMPLE STATION B | 9/16/00 | 0.00 | " | " | TO-14a | | |
| 00091617-VOCCE-A506 | C-VOC | SAMPLE STATION C | 9/16/00 | 0.00 | " | " | TO-14a | | |
| 00091617-VOCDE-A606 | D-VOC | SAMPLE STATION D | 9/16/00 | 1.00 | " | " | TO-14a | | |
| 00091617-VOCEE-A810 | E-VOC | SAMPLE STATION E | 9/16/00 | 0.00 | " | " | TO-14a | | |
| 00091617-VOCFE-A508 | F-VOC | SAMPLE STATION F | 9/16/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 9/16/00 | 0.00 | " | " | TO-14a | | |
| 00091617-FBEVOC-A429 | VOC-BLANK | VOC-BLANK | 9/16/00 | NA | " | " | TO-14a | | |
| 00091617-TSPAE-7224 | A-TSP | SAMPLE STATION A | 9/16/00 | 1801.34 | Envelope | " | Full Suite Metals | | |
| 00091617-TSPBE-7239 | B-TSP | SAMPLE STATION B | 9/16/00 | 1892.15 | " | " | Full Suite Metals | | |
| NOT COLLECTED | C-TSP | SAMPLE STATION C | 9/16/00 | 0.00 | " | " | Full Suite Metals | | |
| 00091617-TSPDE-7241 | D-TSP | SAMPLE STATION D | 9/16/00 | 1838.33 | " | " | Full Suite Metals | | |
| 00091617-TSPEE-7242 | E-TSP | SAMPLE STATION E | 9/16/00 | 1839.10 | " | " | Full Suite Metals | | |
| 00091617-TSPFE-7243 | F-TSP | SAMPLE STATION F | 9/16/00 | 1855.79 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/16/00 | 0.00 | | | Full Suite Metals | | |
| 00091617-FBETSP-7244 | TSP-BLANK | TSP-BLANK | 9/16/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning VOID PUF sample and SUMMA canister.

| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour | QC Level: | See PAM |
|---|---|---|---|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | | Date: Time: | |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | | Date: Time: | |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | | Date: Time: | |
| Comments: | Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | | | | |

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-09161700HR



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L. Leet, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/18/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091617-PUFHRA-2000 | A-PUF | SAMPLE STATION A | 9/16/00 | 341.05 | Jar | ICE | TO-9m | | |
| 00091617-PUFHRB-2001 | B-PUF | SAMPLE STATION B | 9/16/00 | 347.85 | " | " | TO-9m | | |
| NOT COLLECTED | C-PUF | SAMPLE STATION C | 9/16/00 | 0.00 | " | " | TO-9m | | |
| 00091617-PUFHRD-2003 | D-PUF | SAMPLE STATION D | 9/16/00 | 344.13 | " | " | TO-9m | | |
| 00091617-PUFHRE-2004 | E-PUF | SAMPLE STATION E | 9/16/00 | 339.37 | " | " | TO-9m | | |
| 00091617-PUFHRF-2005 | F-PUF | SAMPLE STATION F | 9/16/00 | 327.40 | " | " | TO-9m | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 9/16/00 | 0.00 | " | " | TO-9m | | |
| 00091617-HRFBPUF-2006 | PUF BLANK | PUF-BLANK | 9/16/00 | NA | " | " | TO-9m | | |
| NOT COLLECTED | A-VOC | SAMPLE STATION A | 9/16/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| NOT COLLECTED | B-VOC | SAMPLE STATION B | 9/16/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | C-VOC | SAMPLE STATION C | 9/16/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | D-VOC | SAMPLE STATION D | 9/16/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | E-VOC | SAMPLE STATION E | 9/16/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | F-VOC | SAMPLE STATION F | 9/16/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 9/16/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/16/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | A-TSP | SAMPLE STATION A | 9/16/00 | 0.00 | Envelope | " | Full Suite Metals | | |
| NOT COLLECTED | B-TSP | SAMPLE STATION B | 9/16/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | C-TSP | SAMPLE STATION C | 9/16/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | D-TSP | SAMPLE STATION D | 9/16/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | E-TSP | SAMPLE STATION E | 9/16/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | F-TSP | SAMPLE STATION F | 9/16/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/16/00 | 0.00 | | | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/16/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for Hi resolution dioxins and furans per conversations with IT.

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 5 day turnarour |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091718



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/19/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091718-PUFAE-2462 | A-PUF | SAMPLE STATION A | 9/17/00 | 331.76 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00091718-PUFBE-2463 | B-PUF | SAMPLE STATION B | 9/17/00 | 352.31 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091718-PUFCE-2464 | C-PUF | SAMPLE STATION C | 9/17/00 | 333.88 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091718-PUFDE-2465 | D-PUF | SAMPLE STATION D | 9/17/00 | 344.05 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091718-PUFEE-2467 | E-PUF | SAMPLE STATION E | 9/17/00 | 336.55 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091718-PUFFE-2466 | F-PUF | SAMPLE STATION F | 9/17/00 | 328.08 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091718-PUFGE-2468 | G-PUF | SAMPLE STATION G | 9/17/00 | 341.40 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | PUF BLANK | PUF-BLANK | 9/17/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091718-VOCAE-A507 | A-VOC | SAMPLE STATION A | 9/17/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00091718-VOCBE-A803 | B-VOC | SAMPLE STATION B | 9/17/00 | 1.50 | " | " | TO-14a | | |
| 0091718-VOCCE-A105 | C-VOC | SAMPLE STATION C | 9/17/00 | 12.50 | " | " | TO-14a | | |
| 0091718-VOCDE-A811 | D-VOC | SAMPLE STATION D | 9/17/00 | 1.50 | " | " | TO-14a | | |
| 00091718-VOCEE-A807 | E-VOC | SAMPLE STATION E | 9/17/00 | 0.00 | " | " | TO-14a | | |
| 00091718-VOCFE-A802 | F-VOC | SAMPLE STATION F | 9/17/00 | 0.00 | " | " | TO-14a | | |
| 0091718-VOCGE-A809 | G-VOC | SAMPLE STATION G | 9/17/00 | 28.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/17/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | A-TSP | SAMPLE STATION A | 9/17/00 | 0.00 | Envelope | " | Full Suite Metals | | |
| NOT COLLECTED | B-TSP | SAMPLE STATION B | 9/17/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | C-TSP | SAMPLE STATION C | 9/17/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | D-TSP | SAMPLE STATION D | 9/17/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | E-TSP | SAMPLE STATION E | 9/17/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | F-TSP | SAMPLE STATION F | 9/17/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/17/00 | 0.00 | | | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/17/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| | | | |
|---|---|---|---|
| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

09171800.COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091718RAD



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/19/00
Lab Destination: Barringer Laboratories
Lab Contact: Sample Receiving
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Fed Ex: 802454546034

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091718-TSPAE-7228 | A-TSP | SAMPLE STATION A | 9/17/00 | 1863.40 | Envelope | " | **Methods 900.0m&901.1m** | | |
| 00091718-TSPBE-7229 | B-TSP | SAMPLE STATION B | 9/17/00 | 1987.43 | " | " | **Methods 900.0m&901.1m** | | |
| 00091718-TSPCE-7240 | C-TSP | SAMPLE STATION C | 9/17/00 | 1988.48 | " | " | **Methods 900.0m&901.1m** | | |
| 00091718-TSPDE-7230 | D-TSP | SAMPLE STATION D | 9/17/00 | 1937.72 | " | " | **Methods 900.0m&901.1m** | | |
| 00091718-TSPEE-7231 | E-TSP | SAMPLE STATION E | 9/17/00 | 1920.89 | " | " | **Methods 900.0m&901.1m** | | |
| 00091718-TSPFE-7232 | F-TSP | SAMPLE STATION F | 9/17/00 | 1927.06 | " | " | **Methods 900.0m&901.1m** | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/17/00 | 0.00 | | | **Methods 900.0m&901.1m** | | |
| 0091718-FBETSP-7252 | TSP-BLANK | TSP-BLANK | 9/17/00 | NA | " | " | **Methods 900.0m&901.1m** | | |
| | | | | psi | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | psi | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Gross Alpha/Beta, trigger additional analyses with gross alpha/beta-call with results (925)288-2061. Gamma-maximum number of isotopes, identify all peaks.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 7 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091819



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/20/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00091819-PUFAE-2469 | A-PUF | SAMPLE STATION A | 9/18/00 | 323.39 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00091819-PUFBE-2470 | B-PUF | SAMPLE STATION B | 9/18/00 | 345.04 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091819-PUFCE-2478 | C-PUF | SAMPLE STATION C | 9/18/00 | 320.81 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091819-PUFDE-2479 | D-PUF | SAMPLE STATION D | 9/18/00 | 326.84 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091819-PUFEE-2480 | E-PUF | SAMPLE STATION E | 9/18/00 | 314.85 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091819-PUFFE-2481 | F-PUF | SAMPLE STATION F | 9/18/00 | 325.35 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 9/18/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091819-FBEPUF-2482 | PUF BLANK | PUF-BLANK | 9/18/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091819-VOCAE-A805 | A-VOC | SAMPLE STATION A | 9/18/00 | 1.00 psi | SUMMA | None | TO-14a See Note | | |
| 00091819-VOCBE-A806 | B-VOC | SAMPLE STATION B | 9/18/00 | 1.50 | " | " | TO-14a | | |
| 0091819-VOCCE-A502 | C-VOC | SAMPLE STATION C | 9/18/00 | 16.50 | " | " | TO-14a | | |
| 0091819-VOCDE-A420 | D-VOC | SAMPLE STATION D | 9/18/00 | 2.50 | " | " | TO-14a | | |
| 00091819-VOCEE-A705 | E-VOC | SAMPLE STATION E | 9/18/00 | 0.00 | " | " | TO-14a | | |
| 00091819-VOCFE-A204 | F-VOC | SAMPLE STATION F | 9/18/00 | 1.50 | " | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 9/18/00 | 0.00 | " | " | TO-14a | | |
| 00091819-FBEVOC-A423 | VOC-BLANK | VOC-BLANK | 9/18/00 | NA | " | " | TO-14a | | |
| 00091819-TSPAE-7226 | A-TSP | SAMPLE STATION A | 9/18/00 | 1793.06 | Envelope | " | Full Suite Metals | | |
| 00091819-TSPBE-7227 | B-TSP | SAMPLE STATION B | 9/18/00 | 1889.79 | " | " | Full Suite Metals | | |
| 00091819-TSPCE-7234 | C-TSP | SAMPLE STATION C | 9/18/00 | 1868.28 | " | " | Full Suite Metals | | |
| 00091819-TSPDE-7235 | D-TSP | SAMPLE STATION D | 9/18/00 | 1818.66 | " | " | Full Suite Metals | | |
| 00091819-TSPEE-7236 | E-TSP | SAMPLE STATION E | 9/18/00 | 1798.52 | " | " | Full Suite Metals | | |
| 00091819-TSPFE-7237 | F-TSP | SAMPLE STATION F | 9/18/00 | 1829.84 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/18/00 | 0.00 | | | Full Suite Metals | | |
| 00091819-FBETSP-7238 | TSP-BLANK | TSP-BLANK | 9/18/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

09181900 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091920



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/21/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| VOID | A-PUF | SAMPLE STATION A | 9/19/00 | 0.00 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00091920-PUFBE-2484 | B-PUF | SAMPLE STATION B | 9/19/00 | 341.02 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091920-PUFCE-2471 | C-PUF | SAMPLE STATION C | 9/19/00 | 342.81 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091920-PUFDE-2472 | D-PUF | SAMPLE STATION D | 9/19/00 | 332.72 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091920-PUFEE-2473 | E-PUF | SAMPLE STATION E | 9/19/00 | 308.47 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091920-PUFFE-2474 | F-PUF | SAMPLE STATION F | 9/19/00 | 334.94 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091920-PUFGE-2475 | G-PUF | SAMPLE STATION G | 9/19/00 | 345.77 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | PUF BLANK | PUF-BLANK | 9/19/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00091920-VOCAE-A112 | A-VOC | SAMPLE STATION A | 9/19/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00091920-VOCBE-A804 | B-VOC | SAMPLE STATION B | 9/19/00 | 1.50 | " | " | TO-14a | | |
| 0091920-VOCCE-A428 | C-VOC | SAMPLE STATION C | 9/19/00 | 18.00 | " | " | TO-14a | | |
| 0091920-VOCDE-A425 | D-VOC | SAMPLE STATION D | 9/19/00 | 2.00 | " | " | TO-14a | | |
| 00091920-VOCEE-A914 | E-VOC | SAMPLE STATION E | 9/19/00 | 0.00 | " | " | TO-14a | | |
| 00091920-VOCFE-A102 | F-VOC | SAMPLE STATION F | 9/19/00 | 3.50 | " | " | TO-14a | | |
| 0091920-VOCGE-A701 | G-VOC | SAMPLE STATION G | 9/19/00 | 30.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/19/00 | NA | " | " | TO-14a | | |
| VOID | A-TSP | SAMPLE STATION A | 9/19/00 | 0.00 | Envelope | " | Full Suite Metals | | |
| 00091920-TSPBE-7253 | B-TSP | SAMPLE STATION B | 9/19/00 | 1943.48 | " | " | Full Suite Metals | | |
| 00091920-TSPCE-7254 | C-TSP | SAMPLE STATION C | 9/19/00 | 1929.66 | " | " | Full Suite Metals | | |
| 00091920-TSPDE-7255 | D-TSP | SAMPLE STATION D | 9/19/00 | 1888.01 | " | " | Full Suite Metals | | |
| 00091920-TSPEE-7256 | E-TSP | SAMPLE STATION E | 9/19/00 | 1918.83 | " | " | Full Suite Metals | | |
| 00091920-TSPFE-7257 | F-TSP | SAMPLE STATION F | 9/19/00 | 1904.18 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/19/00 | 0.00 | | | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/19/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning 1 SUMMA regulator for analysis. Returning VOID PUF sample.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarou | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

09192000 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-091920hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L. Leet, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/21/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (liters) | Container Type | Preservative | Requested Testing Program | RPL # Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| VOID | A-Hcl | SAMPLE STATION A | 9/19/00 | 338.47 | 3 viles | None | TO-0051m See Note 1 | — | |
| 00091920-HCLBE-2001 | B-Hcl | SAMPLE STATION B | 9/19/00 | 0.00 | " | " | TO-0051m | 27622 | |
| 00091920-HCLCE-2002 | C-Hcl | SAMPLE STATION C | 9/19/00 | 2733.04 | " | " | TO-0051m | 27623 | |
| 00091920-HCLDE-2003 | D-Hcl | SAMPLE STATION D | 9/19/00 | 3030.24 | " | " | TO-0051m | 27624 | |
| 00091920-HCLEE-2004 | E-Hcl | SAMPLE STATION E | 9/19/00 | 695.27 | " | " | TO-0051m | 27625 | |
| 00091920-HCLFE-2005 | F-Hcl | SAMPLE STATION F | 9/19/00 | 2732.94 | " | " | TO-0051m | 27626 | |
| Not collected | G-Hcl | Not Collected | 9/19/00 | 0.00 | " | " | TO-0051m | — | |

Special Instructions: Note 1:All volumes are approximate and may be used for indication only.

| | | | |
|---|---|---|---|
| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnaroun | QC Level: See PAM |
| 1. Relinquished by (Signature/Affiliation) | Date: 9/21/00 Time: 1319 | 1. Received by (Signature/Affiliation) | Date: 9/21/00 Time: 1:15 |
| 2. Relinquished by (Signature/Affiliation) Cindi (UTC) | Date: 9/21/00 Time: 3:30 | 2. Received by (Signature/Affiliation) Charlotte Moon | Date: 09/21/00 Time: 3:30 |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |
| Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | |

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092021



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/22/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092021-PUFAE-2476 | A-PUF | SAMPLE STATION A | 9/20/00 | 343.51 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00092021-PUFBE-2477 | B-PUF | SAMPLE STATION B | 9/20/00 | 345.23 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092021-PUFCE-2485 | C-PUF | SAMPLE STATION C | 9/20/00 | 342.96 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092021-PUFDE-2486 | D-PUF | SAMPLE STATION D | 9/20/00 | 345.60 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092021-PUFEE-2487 | E-PUF | SAMPLE STATION E | 9/20/00 | 330.64 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092021-PUFFE-2488 | F-PUF | SAMPLE STATION F | 9/20/00 | 341.59 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 9/20/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092021-FBEPUF-2489 | PUF BLANK | PUF-BLANK | 9/20/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092021-VOCAE-A426 | A-VOC | SAMPLE STATION A | 9/20/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00092021-VOCBE-A306 | B-VOC | SAMPLE STATION B | 9/20/00 | 1.50 | " | " | TO-14a | | |
| VOID | C-VOC | SAMPLE STATION C | 9/20/00 | 0.00 | " | " | TO-14a | | |
| 0092021-VOCDE-A704 | D-VOC | SAMPLE STATION D | 9/20/00 | 2.00 | " | " | TO-14a | | |
| 00092021-VOCEE-A301 | E-VOC | SAMPLE STATION E | 9/20/00 | 0.00 | " | " | TO-14a | | |
| 00092021-VOCFE-A202 | F-VOC | SAMPLE STATION F | 9/20/00 | 4.90 | " | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 9/20/00 | 0.00 | " | " | TO-14a | | |
| 00092021-FBEVOC-A808 | VOC-BLANK | VOC-BLANK | 9/20/00 | NA | " | " | TO-14a | | |
| 00092021-TSPAE-7206 | A-TSP | SAMPLE STATION A | 9/20/00 | 1904.06 | Envelope | " | Full Suite Metals | | |
| 00092021-TSPBE-7245 | B-TSP | SAMPLE STATION B | 9/20/00 | 1947.90 | " | " | Full Suite Metals | | |
| 00092021-TSPCE-7246 | C-TSP | SAMPLE STATION C | 9/20/00 | 1962.58 | " | " | Full Suite Metals | | |
| 00092021-TSPDE-7247 | D-TSP | SAMPLE STATION D | 9/20/00 | 1933.33 | " | " | Full Suite Metals | | |
| 00092021-TSPEE-7248 | E-TSP | SAMPLE STATION E | 9/20/00 | 1926.40 | " | " | Full Suite Metals | | |
| 00092021-TSPFE-7249 | F-TSP | SAMPLE STATION F | 9/20/00 | 1934.92 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/20/00 | 0.00 | | | Full Suite Metals | | |
| 00092021-FBETSP-7251 | TSP-BLANK | TSP-BLANK | 9/20/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning 1 void SUMMA canister and regulator for analysis/maintenance.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

09202100.COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000 .021hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/22/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | KPI # Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092021-HCLAE-2006 | A-Chlorine | SAMPLE STATION A | 9/20/00 | 1541.40 | 3 vials | None | TO-0051m | 27651 | |
| 00092021-HCLBE-2007 | B-Chlorine | SAMPLE STATION B | 9/20/00 | 732.72 | " | " | TO-0051m | 27652 | |
| 00092021-HCLCE-2008 | C- Chlorine | SAMPLE STATION C | 9/20/00 | 1420.09 | " | " | TO-0051m | 27653 | |
| 00092021-HCLDE-2009 | D-Chlorine | SAMPLE STATION D | 9/20/00 | 1515.00 | " | " | TO-0051m | 27654 | |
| 00092021-HCLEE-2010 | E-Chlorine | SAMPLE STATION E | 9/20/00 | 1099.22 | " | " | TO-0051m | 27655 | |
| 00092021-HCLFE-2011 | F-Chlorine | SAMPLE STATION F | 9/20/00 | 1505.00 | " | " | TO-0051m | 27656 | |
| Not collected | G-Chlorine | SAMPLE STATION G | 9/20/00 | 0.00 | " | " | TO-0051m | — | |
| Not collected | Chlorine Blank | Blank | 9/20/00 | NA | " | " | TO-0051m | — | |
| 000921-PHAE-2000AM | A-PH | SAMPLE STATION A | 9/20/00 | 54.99 | 1 Vial | Ice | TO-6m | 27657 | |
| 000921-PHBE-2001AM | B-PH | SAMPLE STATION B | 9/20/00 | 48.50 | 1 Vial | Ice | TO-6m | 27658 | |
| 000921-PHCE-2002AM | C-PH | SAMPLE STATION C | 9/20/00 | 60.06 | 1 Vial | Ice | TO-6m | 25659 | |
| 000921-PHDE-2003AM | D-PH | SAMPLE STATION D | 9/20/00 | 50.34 | 1 Vial | Ice | TO-6m | 25660 | |
| 000921-PHEE-2004AM | E-PH | SAMPLE STATION E | 9/20/00 | 75.41 | 1 Vial | Ice | TO-6m | 25661 | |
| 000921-PHFE-2005AM | F-PH | SAMPLE STATION F | 9/20/00 | 60.64 | 1 Vial | Ice | TO-6m | 25662 | |
| Not collected | G-PH | SAMPLE STATION G | 9/20/00 | 0.00 | 1 Vial | Ice | TO-6m | — | |
| 000921-PHAE-2009PM | A-PH | SAMPLE STATION A | 9/20/00 | 46.70 | 1 Vial | Ice | TO-6m | 25663 | |
| 000921-PHBE-2008PM | B-PH | SAMPLE STATION B | 9/20/00 | 52.05 | 1 Vial | Ice | TO-6m | 25664 | |
| 000921-PHCE-2012PM | C-PH | SAMPLE STATION C | 9/20/00 | 52.02 | 1 Vial | Ice | TO-6m | 25665 | |
| 000921-PHDE-2007PM | D-PH | SAMPLE STATION D | 9/20/00 | 48.10 | 1 Vial | Ice | TO-6m | 25666 | |
| 000921-PHEE-2010PM | E-PH | SAMPLE STATION E | 9/20/00 | 53.00 | 1 Vial | Ice | TO-6m | 25667 | |
| 000921-PHFE-2011PM | F-PH | SAMPLE STATION F | 9/20/00 | 52.79 | 1 Vial | Ice | TO-6m | 25668 | |
| Not collected | G-PH | SAMPLE STATION G | 9/20/00 | 0.00 | 1 Vial | Ice | TO-6m | — | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |

Special Instructions:

| | | | |
|---|---|---|---|
| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnaround | QC Level: See PAM |
| 1. Relinquished by (Signature/Affiliation) | Date: 9/22/00 Time: 1308 | 1. Received by (Signature/Affiliation) MARK Lindgren | Date: 9-22 Time: 1:10 |
| 2. Relinquished by (Signature/Affiliation) | Date: 9-22 Time: 3:51 | 2. Received by (Signature/Affiliation) Charlotte Moon | Date: 09/22/00 Time: 3:51 |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092122



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/23/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092122-PUFAE-2490 | A-PUF | SAMPLE STATION A | 9/21/00 | 320.56 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00092122-PUFBE-2491 | B-PUF | SAMPLE STATION B | 9/21/00 | 343.55 | Jar & Envelope | " | TO-4 & TO-13 & TO-9m | | |
| 00092122-PUFCE-2499 | C-PUF | SAMPLE STATION C | 9/21/00 | 336.64 | Jar & Envelope | " | TO-4 & TO-13 & TO-9m | | |
| 00092122-PUFDE-2500 | D-PUF | SAMPLE STATION D | 9/21/00 | 336.31 | Jar & Envelope | " | TO-4 & TO-13 & TO-9m | | |
| 00092122-PUFEE-2501 | E-PUF | SAMPLE STATION E | 9/21/00 | 323.27 | Jar & Envelope | " | TO-4 & TO-13 & TO-9m | | |
| 00092122-PUFFE-2502 | F-PUF | SAMPLE STATION F | 9/21/00 | 322.06 | Jar & Envelope | " | TO-4 & TO-13 & TO-9m | | |
| 00092122-PUFGE-2503 | G-PUF | SAMPLE STATION G | 9/21/00 | 326.27 | Jar & Envelope | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | PUF BLANK | PUF-BLANK | 9/21/00 | NA | Jar & Envelope | " | TO-4 & TO-13 & TO-9m | | |
| 0092122-VOCAE-A201 | A-VOC | SAMPLE STATION A | 9/21/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 0092122-VOCBE-A801 | B-VOC | SAMPLE STATION B | 9/21/00 | 0.50 | SUMMA | " | TO-14a | | |
| NOT COLLECTED | C-VOC | SAMPLE STATION C | 9/21/00 | 0.00 | SUMMA | " | TO-14a | | |
| 0092122-VOCDE-A506 | D-VOC | SAMPLE STATION D | 9/21/00 | 5.50 | SUMMA | " | TO-14a | | |
| 0092122-VOCEE-A429 | E-VOC | SAMPLE STATION E | 9/21/00 | 0.00 | SUMMA | " | TO-14a | | |
| 0092122-VOCFE-A507 | F-VOC | SAMPLE STATION F | 9/21/00 | 5.00 | SUMMA | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 9/21/00 | 0.00 | SUMMA | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/21/00 | NA | SUMMA | " | TO-14a | | |
| 00092122-TSPAE-7250 | A-TSP | SAMPLE STATION A | 9/21/00 | 1811.02 | Envelope | " | Full Suite Metals | | |
| 00092122-TSPBE-7258 | B-TSP | SAMPLE STATION B | 9/21/00 | 1893.56 | Envelope | " | Full Suite Metals | | |
| 00092122-TSPCE-7259 | C-TSP | SAMPLE STATION C | 9/21/00 | 1851.88 | Envelope | " | Full Suite Metals | | |
| 00092122-TSPDE-7260 | D-TSP | SAMPLE STATION D | 9/21/00 | 1781.17 | Envelope | " | Full Suite Metals | | |
| 00092122-TSPEE-7261 | E-TSP | SAMPLE STATION E | 9/21/00 | 1836.53 | Envelope | " | Full Suite Metals | | |
| 00092122-TSPFE-7262 | F-TSP | SAMPLE STATION F | 9/21/00 | 1836.39 | Envelope | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/21/00 | 0.00 | Envelope | | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/21/00 | NA | Envelope | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| | | | |
|---|---|---|---|
| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See Contract |
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

09212200 COC
H. Bowles, Excel 5/7-Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/9/00 10:00 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092122hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/23/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00092122-HCLAE-2012 | A-Chlorine | SAMPLE STATION A | 9/21/00 | Unknown | 3 vials | None | TO-0051m | | | |
| 00092122-HCLBE-2013 | B-Chlorine | SAMPLE STATION B | 9/21/00 | 1490.03 | 3 vials | None | TO-0051m | | | |
| 00092122-HCLCE-2014 | C- Chlorine | SAMPLE STATION C | 9/21/00 | 1396.83 | 3 vials | None | TO-0051m | | | |
| 00092122-HCLDE-2015 | D-Chlorine | SAMPLE STATION D | 9/21/00 | 1372.83 | 3 vials | None | TO-0051m | | | |
| 00092122-HCLEE-2016 | E-Chlorine | SAMPLE STATION E | 9/21/00 | Unknown | 3 vials | None | TO-0051m | | | |
| Not Collected | F-Chlorine | SAMPLE STATION F | 9/21/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 9/21/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | hlorine Blank | Blank | 9/21/00 | NA | 3 vials | None | TO-0051m | | | |
| Not Collected | A-PH | SAMPLE STATION A | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | B-PH | SAMPLE STATION B | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | C-PH | SAMPLE STATION C | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | D-PH | SAMPLE STATION D | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | E-PH | SAMPLE STATION E | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | F-PH | SAMPLE STATION F | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION G | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | A-PH | SAMPLE STATION A | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | B-PH | SAMPLE STATION B | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | C-PH | SAMPLE STATION C | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | D-PH | SAMPLE STATION D | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | E-PH | SAMPLE STATION E | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not Collected | F-PH | SAMPLE STATION F | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION G | 1/0/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions: Analytical results for samples collected from Stations 'A' and 'E' should be considered representative because volumes are unknown due to the pump shutting off prematurely.

| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaroun | QC Level: | See PAM |
|---|---|---|---|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | | Date: Time: | |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | | Date: Time: | |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | | Date: Time: | |
| Comments: | Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | | | | |

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092223



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/24/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092223-PUFAE-2492 | A-PUF | SAMPLE STATION A | 9/22/00 | 325.15 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00092223-PUFBE-2493 | B-PUF | SAMPLE STATION B | 9/22/00 | 330.14 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092223-PUFCE-2494 | C-PUF | SAMPLE STATION C | 9/22/00 | 324.66 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092223-PUFDE-2495 | D-PUF | SAMPLE STATION D | 9/22/00 | 333.40 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092223-PUFEE-2496 | E-PUF | SAMPLE STATION E | 9/22/00 | 317.55 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092223-PUFFE-2497 | F-PUF | SAMPLE STATION F | 9/22/00 | 332.66 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 9/22/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092223-FBEPUF-2498 | PUF BLANK | PUF-BLANK | 9/22/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092223-VOCAE-A513 | A-VOC | SAMPLE STATION A | 9/22/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00092223-VOCBE-A420 | B-VOC | SAMPLE STATION B | 9/22/00 | 1.50 | " | " | TO-14a | | |
| NOT COLLECTED | C-VOC | SAMPLE STATION C | 9/22/00 | 0.00 | " | " | TO-14a | | |
| 0092223-VOCDE-A606 | D-VOC | SAMPLE STATION D | 9/22/00 | 5.00 | " | " | TO-14a | | |
| 00092223-VOCEE-A803 | E-VOC | SAMPLE STATION E | 9/22/00 | 0.00 | " | " | TO-14a | | |
| 00092223-VOCFE-A502 | F-VOC | SAMPLE STATION F | 9/22/00 | 6.00 | " | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 9/22/00 | 0.00 | " | " | TO-14a | | |
| 00092223-FBEVOC-A705 | VOC-BLANK | VOC-BLANK | 9/22/00 | NA | " | " | TO-14a | | |
| 00092223-TSPAE-7263 | A-TSP | SAMPLE STATION A | 9/22/00 | 1806.95 | Envelope | " | Full Suite Metals | | |
| 00092223-TSPBE-7264 | B-TSP | SAMPLE STATION B | 9/22/00 | 1836.18 | " | " | Full Suite Metals | | |
| 00092223-TSPCE-7272 | C-TSP | SAMPLE STATION C | 9/22/00 | 1788.29 | " | " | Full Suite Metals | | |
| 00092223-TSPDE-7273 | D-TSP | SAMPLE STATION D | 9/22/00 | 1840.75 | " | " | Full Suite Metals | | |
| 00092223-TSPEE-7274 | E-TSP | SAMPLE STATION E | 9/22/00 | 1843.84 | " | " | Full Suite Metals | | |
| 00092223-TSPFE-7275 | F-TSP | SAMPLE STATION F | 9/22/00 | 1826.70 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/22/00 | 0.00 | | | Full Suite Metals | | |
| 00092223-FBETSP-7276 | TSP-BLANK | TSP-BLANK | 9/22/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

09222300 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092425



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/26/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092425-PUFAE-2504 | A-PUF | SAMPLE STATION A | 9/24/00 | 323.84 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| VOID | B-PUF | SAMPLE STATION B | 9/24/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092425-PUFCE-2506 | C-PUF | SAMPLE STATION C | 9/24/00 | 331.92 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092425-PUFDE-2507 | D-PUF | SAMPLE STATION D | 9/24/00 | 330.27 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092425-PUFEE-2508 | E-PUF | SAMPLE STATION E | 9/24/00 | 316.65 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092425-PUFFE-2509 | F-PUF | SAMPLE STATION F | 9/24/00 | 332.23 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092425-PUFGE-2510 | G-PUF | SAMPLE STATION G | 9/24/00 | 317.97 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | PUF BLANK | PUF-BLANK | 9/24/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092425-VOCAE-A807 | A-VOC | SAMPLE STATION A | 9/24/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00092425-VOCBE-A432 | B-VOC | SAMPLE STATION B | 9/24/00 | 1.00 | " | " | TO-14a | | |
| 0092425-VOCCE-A101 | C-VOC | SAMPLE STATION C | 9/24/00 | 0.00 | " | " | TO-14a | | |
| 0092425-VOCDE-A806 | D-VOC | SAMPLE STATION D | 9/24/00 | 4.50 | " | " | TO-14a | | |
| 00092425-VOCEE-A607 | E-VOC | SAMPLE STATION E | 9/24/00 | 0.00 | " | " | TO-14a | | |
| 00092425-VOCFE-A636 | F-VOC | SAMPLE STATION F | 9/24/00 | 6.00 | " | " | TO-14a | | |
| 0092425-VOCGE-A423 | G-VOC | SAMPLE STATION G | 9/24/00 | 10.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/24/00 | NA | " | " | TO-14a | | |
| 00092425-TSPAE-7265 | A-TSP | SAMPLE STATION A | 9/24/00 | 1775.52 | Envelope | " | Full Suite Metals | | |
| 00092425-TSPBE-7266 | B-TSP | SAMPLE STATION B | 9/24/00 | 1816.77 | " | " | Full Suite Metals | | |
| 00092425-TSPCE-7270 | C-TSP | SAMPLE STATION C | 9/24/00 | 1802.09 | " | " | Full Suite Metals | | |
| 00092425-TSPDE-7271 | D-TSP | SAMPLE STATION D | 9/24/00 | 1827.54 | " | " | Full Suite Metals | | |
| 00092425-TSPEE-7277 | E-TSP | SAMPLE STATION E | 9/24/00 | 1847.23 | " | " | Full Suite Metals | | |
| 00092425-TSPFE-7278 | F-TSP | SAMPLE STATION F | 9/24/00 | 1848.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/24/00 | 0.00 | | | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/24/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-280 Note: Returning void PUF sample. 11/9/00 10:00 AM

09242500 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092425HR



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/26/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092425-PUFHRA-2007 | A-PUF | SAMPLE STATION A | 9/24/00 | 334.24 | Jar | ICE | TO-9 | | |
| 00092425-PUFHRB-2008 | B-PUF | SAMPLE STATION B | 9/24/00 | 342.70 | " | " | TO-9 | | |
| 00092425-PUFHRC-2002 | C-PUF | SAMPLE STATION C | 9/24/00 | 341.27 | " | " | TO-9 | | |
| 00092425-PUFHRD-2009 | D-PUF | SAMPLE STATION D | 9/24/00 | 322.02 | " | " | TO-9 | | |
| 00092425-PUFHRE-2010 | E-PUF | SAMPLE STATION E | 9/24/00 | 342.99 | " | " | TO-9 | | |
| 00092425-PUFHRF-2011 | F-PUF | SAMPLE STATION F | 9/24/00 | 332.72 | " | " | TO-9 | | |
| 00092425-PUFHRG-2012 | G-PUF | SAMPLE STATION G | 9/24/00 | 328.88 | " | " | TO-9 | | |
| NOT COLLECTED | PUF BLANK | PUF-BLANK | 9/24/00 | NA | " | " | TO-9 | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for Hi resolution dioxins and furans per conversations with IT.

| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 5 day turnarour | QC Level: | See PAM |
|---|---|---|---|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | | Date: Time: | |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | | Date: Time: | |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | | Date: Time: | |
| Comments: | Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | | | | |

09242500HR COC
H. Bowles, Excel 5/7-Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/7/00 11:17 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092526



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/27/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092526-PUFAE-2511 | A-PUF | SAMPLE STATION A | 9/25/00 | 321.17 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00092526-PUFBE-2512 | B-PUF | SAMPLE STATION B | 9/25/00 | 330.02 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092526-PUFCE-2520 | C-PUF | SAMPLE STATION C | 9/25/00 | 326.67 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092526-PUFDE-2521 | D-PUF | SAMPLE STATION D | 9/25/00 | 317.99 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092526-PUFEE-2522 | E-PUF | SAMPLE STATION E | 9/25/00 | 313.23 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092526-PUFFE-2523 | F-PUF | SAMPLE STATION F | 9/25/00 | 318.62 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 9/25/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092526-FBEPUF-2524 | PUF BLANK | PUF-BLANK | 9/25/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092526-VOCAE-A306 | A-VOC | SAMPLE STATION A | 9/25/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00092526-VOCBE-A704 | B-VOC | SAMPLE STATION B | 9/25/00 | 0.00 | " | " | TO-14a | | |
| 0092526-VOCCE-A808 | C-VOC | SAMPLE STATION C | 9/25/00 | 0.00 | " | " | TO-14a | | |
| 0092526-VOCDE-A602 | D-VOC | SAMPLE STATION D | 9/25/00 | 6.00 | " | " | TO-14a | | |
| 00092526-VOCEE-A508 | E-VOC | SAMPLE STATION E | 9/25/00 | 0.00 | " | " | TO-14a | | |
| 00092526-VOCFE-A105 | F-VOC | SAMPLE STATION F | 9/25/00 | 8.00 | " | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 9/25/00 | 0.00 | " | " | TO-14a | | |
| 00092526-FBEVOC-A426 | VOC-BLANK | VOC-BLANK | 9/25/00 | NA | " | " | TO-14a | | |
| 00092526-TSPAE-7267 | A-TSP | SAMPLE STATION A | 9/25/00 | 1758.41 | Envelope | " | Full Suite Metals | | |
| 00092526-TSPBE-7268 | B-TSP | SAMPLE STATION B | 9/25/00 | 1826.53 | " | " | Full Suite Metals | | |
| 00092526-TSPCE-7269 | C-TSP | SAMPLE STATION C | 9/25/00 | 1804.60 | " | " | Full Suite Metals | | |
| 00092526-TSPDE-7279 | D-TSP | SAMPLE STATION D | 9/25/00 | 1747.28 | " | " | Full Suite Metals | | |
| 00092526-TSPEE-7280 | E-TSP | SAMPLE STATION E | 9/25/00 | 1753.22 | " | " | Full Suite Metals | | |
| 00092526-TSPFE-7281 | F-TSP | SAMPLE STATION F | 9/25/00 | 1755.64 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/25/00 | 0.00 | | | Full Suite Metals | | |
| 00092526-FBETSP-7282 | TSP-BLANK | TSP-BLANK | 9/25/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

09252600 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-0925hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. Gildersleeve
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/26/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| Not Collected | A-Chlorine | SAMPLE STATION A | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | B-Chlorine | SAMPLE STATION B | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | C- Chlorine | SAMPLE STATION C | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | D-Chlorine | SAMPLE STATION D | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | E-Chlorine | SAMPLE STATION E | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | F-Chlorine | SAMPLE STATION F | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | hlorine Blank | Blank | 1/0/00 | NA | 3 vials | None | **TO-0051m** | | | |
| 000925-PHAE-2018 a.m | A-PH | SAMPLE STATION A | 9/25/00 | 64.20 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHBE-2019 a.m | B-PH | SAMPLE STATION B | 9/25/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHCE-2020 a.m | C-PH | SAMPLE STATION C | 9/25/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHDE-2021 a.m | D-PH | SAMPLE STATION D | 9/25/00 | 52.50 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHEE-2022 a.m | E-PH | SAMPLE STATION E | 9/25/00 | 49.50 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHFE-2023 a.m | F-PH | SAMPLE STATION F | 9/25/00 | 49.00 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/25/00 | NA | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHAE-2024PM | A-PH | SAMPLE STATION A | 9/25/00 | 62.54 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHBE-2025PM | B-PH | SAMPLE STATION B | 9/25/00 | 49.00 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHCE-2026PM | C-PH | SAMPLE STATION C | 9/25/00 | 65.10 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHDE-2027PM | D-PH | SAMPLE STATION D | 9/25/00 | 53.35 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHEE-2028PM | E-PH | SAMPLE STATION E | 9/25/00 | 52.47 | 1 vial | Ice | **TO-6m** | | | |
| 000925-PHFE-2029PM | F-PH | SAMPLE STATION F | 9/25/00 | 46.56 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/25/00 | NA | 1 vial | Ice | **TO-6m** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

11/16/00 9:21 AM

092500HCL COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092627



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. Gildersleeve
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/28/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092627-PUFAE-2525 | A-PUF | SAMPLE STATION A | 9/26/00 | 341.09 | Jar & Envelope | ICE | O-4 & TO-13 & TO-9m | | |
| 00092627-PUFBE-2526 | B-PUF | SAMPLE STATION B | 9/26/00 | 352.21 | " | " | O-4 & TO-13 & TO-9m | | |
| 00092627-PUFCE-2513 | C-PUF | SAMPLE STATION C | 9/26/00 | 346.79 | " | " | O-4 & TO-13 & TO-9m | | |
| 00092627-PUFDE-2514 | D-PUF | SAMPLE STATION D | 9/26/00 | 346.04 | " | " | O-4 & TO-13 & TO-9m | | |
| 00092627-PUFEE-2515 | E-PUF | SAMPLE STATION E | 9/26/00 | 341.56 | " | " | O-4 & TO-13 & TO-9m | | |
| 00092627-PUFFE-2516 | F-PUF | SAMPLE STATION F | 9/26/00 | 326.91 | " | " | O-4 & TO-13 & TO-9m | | |
| 00092627-PUFGE-2517 | G-PUF | SAMPLE STATION G | 9/26/00 | 333.72 | " | " | O-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | PUF BLANK | PUF-BLANK | 9/26/00 | NA | " | " | O-4 & TO-13 & TO-9m | | |
| 00092627-VOCAE-A303 | A-VOC | SAMPLE STATION A | 9/26/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00092627-VOCBE-A202 | B-VOC | SAMPLE STATION B | 9/26/00 | 1.00 | " | " | TO-14a | | |
| 00092627-VOCCE-A301 | C-VOC | SAMPLE STATION C | 9/26/00 | 0.00 | " | " | TO-14a | | |
| 00092627-VOCDE-A810 | D-VOC | SAMPLE STATION D | 9/26/00 | 4.50 | " | " | TO-14a | | |
| 00092627-VOCEE-A805 | E-VOC | SAMPLE STATION E | 9/26/00 | 0.00 | " | " | TO-14a | | |
| 00092627-VOCFE-A112 | F-VOC | SAMPLE STATION F | 9/26/00 | 3.50 | " | " | TO-14a | | |
| 00092627-VOCGE-A914 | G-VOC | SAMPLE STATION G | 9/26/00 | 10.50 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/26/00 | NA | " | " | TO-14a | | |
| 00092627-TSPAE-7290 | A-TSP | SAMPLE STATION A | 9/26/00 | 1854.15 | Envelope | " | Full Suite Metals | | |
| 00092627-TSPBE-7284 | B-TSP | SAMPLE STATION B | 9/26/00 | 1901.71 | " | " | Full Suite Metals | | |
| 00092627-TSPCE-7285 | C-TSP | SAMPLE STATION C | 9/26/00 | 1907.17 | " | " | Full Suite Metals | | |
| 00092627-TSPDE-7286 | D-TSP | SAMPLE STATION D | 9/26/00 | 1872.38 | " | " | Full Suite Metals | | |
| 00092627-TSPEE-7287 | E-TSP | SAMPLE STATION E | 9/26/00 | 1869.33 | " | " | Full Suite Metals | | |
| 00092627-TSPFE-7288 | F-TSP | SAMPLE STATION F | 9/26/00 | 1876.84 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/26/00 | 0.00 | | | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/26/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning SUMMA regulator for maintenance.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |
| Comments: Fax Preliminary results to Cliff Foreman (1-415-671-280 Samples 00092627-TSPBE-7284 and 00092627-TSPCE-7285 ran slightly over 25 hours. | | | |

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092627hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. Gildersleeve
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/27/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00092627-HCLAE-2030 | A-Chlorine | SAMPLE STATION A | 9/26/00 | 1532.24 | 3 vials | None | TO-0051m | | | |
| 00092627-HCLBE-2031 | B-Chlorine | SAMPLE STATION B | 9/26/00 | 1514.10 | 3 vials | None | TO-0051m | | | |
| 00092627-HCLCE-2032 | C- Chlorine | SAMPLE STATION C | 9/26/00 | 1382.39 | 3 vials | None | TO-0051m | | | |
| 00092627-HCLDE-2033 | D-Chlorine | SAMPLE STATION D | 9/26/00 | 1506.96 | 3 vials | None | TO-0051m | | | |
| 00092627-HCLEE-2034 | E-Chlorine | SAMPLE STATION E | 9/26/00 | 1518.30 | 3 vials | None | TO-0051m | | | |
| 00092627-HCLFE-2035 | F-Chlorine | SAMPLE STATION F | 9/26/00 | 1393.70 | 3 vials | None | TO-0051m | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 9/26/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | hlorine Blank | Blank | 9/26/00 | NA | 3 vials | None | TO-0051m | | | |
| 000926-PHAE-2031 a.m | A-PH | SAMPLE STATION A | 9/26/00 | 59.92 | 1 vial | Ice | TO-6m | | | |
| 000926-PHBE-2032 a.m | B-PH | SAMPLE STATION B | 9/26/00 | 52.10 | 1 vial | Ice | TO-6m | | | |
| 000926-PHCE-2033 a.m | C-PH | SAMPLE STATION C | 9/26/00 | 53.04 | 1 vial | Ice | TO-6m | | | |
| 000926-PHDE-2034 a.m | D-PH | SAMPLE STATION D | 9/26/00 | 54.08 | 1 vial | Ice | TO-6m | | | |
| 000926-PHEE-2035 a.m | E-PH | SAMPLE STATION E | 9/26/00 | 55.12 | 1 vial | Ice | TO-6m | | | |
| 000926-PHFE-2036 a.m | F-PH | SAMPLE STATION F | 9/26/00 | 50.40 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/26/00 | #REF! | 1 vial | Ice | TO-6m | | | |
| 000926-PHAE-2037 p.m | A-PH | SAMPLE STATION A | 9/26/00 | 55.62 | 1 vial | Ice | TO-6m | | | |
| 000926-PHBE-2038 p.m | B-PH | SAMPLE STATION B | 9/26/00 | 47.53 | 1 vial | Ice | TO-6m | | | |
| 000926-PHCE-2039 p.m | C-PH | SAMPLE STATION C | 9/26/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| 000926-PHDE-2040 p.m | D-PH | SAMPLE STATION D | 9/26/00 | 51.00 | 1 vial | Ice | TO-6m | | | |
| 000926-PHEE-2041 p.m | E-PH | SAMPLE STATION E | 9/26/00 | 49.50 | 1 vial | Ice | TO-6m | | | |
| 000926-PHFE-2042 p.m | F-PH | SAMPLE STATION F | 9/26/00 | 50.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/26/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaroun |
| QC Level: | See PAM | | | | |
| 1. Relinquished by (Signature/Affiliation) | | Date: / Time: | | 1. Received by (Signature/Affiliation) | Date: / Time: |
| 2. Relinquished by (Signature/Affiliation) | | Date: / Time: | | 2. Received by (Signature/Affiliation) | Date: / Time: |
| 3. Relinquished by (Signature/Affiliation) | | Date: / Time: | | 3. Received by (Signature/Affiliation) | Date: / Time: |
| Comments: | Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | | |

09262700HCL COC
H. Bowles, Excel 5/7-Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/16/00 9:21 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092728hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S.Gildersleeve
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/28/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092728-HCLAE-2043 | A-Chlorine | SAMPLE STATION A | 9/27/00 | 1504.70 | 3 vials | None | TO-0051m | | 27856 |
| 00092728-HCLBE-2044 | B-Chlorine | SAMPLE STATION B | 9/27/00 | 1538.25 | 3 vials | None | TO-0051m | | 27857 |
| 00092728-HCLCE-2045 | C- Chlorine | SAMPLE STATION C | 9/27/00 | 1494.80 | 3 vials | None | TO-0051m | | 27858 |
| 00092728-HCLDE-2046 | D-Chlorine | SAMPLE STATION D | 9/27/00 | 1539.29 | 3 vials | None | TO-0051m | | 27859 |
| 00092728-HCLEE-2047 | E-Chlorine | SAMPLE STATION E | 9/27/00 | 1430.80 | 3 vials | None | TO-0051m | | 27860 |
| 00092728-HCLFE-2048 | F-Chlorine | SAMPLE STATION F | 9/27/00 | 1551.71 | 3 vials | None | TO-0051m | | 27861 |
| Not Collected | G-Chlorine | SAMPLE STATION G | 9/27/00 | 0.00 | 3 vials | None | TO-0051m | | — |
| Not Collected | Chlorine Blank | Blank | 9/27/00 | NA | 3 vials | None | TO-0051m | | — |
| 000926-PHAE-2037p.m | A-PH | SAMPLE STATION A | 9/26/00 | 55.62 | 1 vial | Ice | TO-6m | | 27862 |
| 000926-PHBE-2038 p.m | B-PH | SAMPLE STATION B | 9/26/00 | 47.53 | 1 vial | Ice | TO-6m | | 27863 |
| 000926-PHCE-2039 p.m | C-PH | SAMPLE STATION C | 9/26/00 | 51.50 | 1 vial | Ice | TO-6m | | 27864 |
| 000926-PHDE-2040 p.m | D-PH | SAMPLE STATION D | 9/26/00 | 51.00 | 1 vial | Ice | TO-6m | | 27865 |
| 000926-PHEE-2041 p.m | E-PH | SAMPLE STATION E | 9/26/00 | 49.50 | 1 vial | Ice | TO-6m | | 27866 |
| 000926-PHFE-2042 p.m | F-PH | SAMPLE STATION F | 9/26/00 | 50.00 | 1 vial | Ice | TO-6m | | 27867 |
| Not collected | G-PH | SAMPLE STATION G | 9/26/00 | #REF! | 1 vial | Ice | TO-6m | | — |
| 000927-PHAE-2055 p.m | A-PH | SAMPLE STATION A | 9/27/00 | 50.50 | 1 vial | Ice | TO-6m | | 27868 |
| 000927-PHBE-2056 p.m | B-PH | SAMPLE STATION B | 9/27/00 | 56.84 | 1 vial | Ice | TO-6m | | 27869 |
| 000927-PHCE-2057 p.m | C-PH | SAMPLE STATION C | 9/27/00 | 61.20 | 1 vial | Ice | TO-6m | | 27870 |
| 000927-PHDE-2058 p.m | D-PH | SAMPLE STATION D | 9/27/00 | 57.57 | 1 vial | Ice | TO-6m | | 27871 |
| 000927-PHEE-2059 p.m | E-PH | SAMPLE STATION E | 9/27/00 | 51.50 | 1 vial | Ice | TO-6m | | 27872 |
| 000927-PHFE-2060 p.m | F-PH | SAMPLE STATION F | 9/27/00 | 51.50 | 1 vial | Ice | TO-6m | | 27873 |
| Not collected | G-PH | SAMPLE STATION G | 9/27/00 | 0.00 | 1 vial | Ice | TO-6m | | — |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaroun |
| 1. Relinquished by (Signature/Affiliation) | | Date: 9/28/00 Time: 1424 | | 1. Received by (Signature/Affiliation) | |
| 2. Relinquished by (Signature/Affiliation) | | Date: 9/28/00 Time: 2:48 | | 2. Received by (Signature/Affiliation) | C Saulnier |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | |

QC Level: See PAM

1. Received by: Date: 9/28/00 Time: 2:24
2. Received by: Date: 9/28/00 Time: 4:55
3. Received by: Date: Time:

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092728



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. Gildersleeve
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/29/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092728-PUFAE-2518 | A-PUF | SAMPLE STATION A | 9/27/00 | 333.67 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00092728-PUFBE-2519 | B-PUF | SAMPLE STATION B | 9/27/00 | 353.41 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092728-PUFCE-2527 | C-PUF | SAMPLE STATION C | 9/27/00 | 339.18 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092728-PUFDE-2528 | D-PUF | SAMPLE STATION D | 9/27/00 | 348.93 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092728-PUFEE-2529 | E-PUF | SAMPLE STATION E | 9/27/00 | 347.19 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092728-PUFFE-2530 | F-PUF | SAMPLE STATION F | 9/27/00 | 332.06 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 9/27/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092728-FBEPUF-2531 | PUF BLANK | PUF-BLANK | 9/27/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092728-VOCAE-A204 | A-VOC | SAMPLE STATION A | 9/27/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00092728-VOCBE-A433 | B-VOC | SAMPLE STATION B | 9/27/00 | 1.00 | " | " | TO-14a | | |
| 0092728-VOCCE-A603 | C-VOC | SAMPLE STATION C | 9/27/00 | 0.00 | " | " | TO-14a | | |
| 0092728-VOCDE-A702 | D-VOC | SAMPLE STATION D | 9/27/00 | 4.50 | " | " | TO-14a | | |
| 00092728-VOCEE-A804 | E-VOC | SAMPLE STATION E | 9/27/00 | 0.00 | " | " | TO-14a | | |
| 00092728-VOCFE-A705 | F-VOC | SAMPLE STATION F | 9/27/00 | 5.00 | " | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 9/27/00 | 0.00 | " | " | TO-14a | | |
| 00092728-FBEVOC-A428 | VOC-BLANK | VOC-BLANK | 9/27/00 | NA | " | " | TO-14a | | |
| 00092728-TSPAE-7291 | A-TSP | SAMPLE STATION A | 9/27/00 | 1919.87 | Envelope | " | Full Suite Metals | | |
| 00092728-TSPBE-7292 | B-TSP | SAMPLE STATION B | 9/27/00 | 1980.50 | " | " | Full Suite Metals | | |
| VOID | C-TSP | SAMPLE STATION C | 9/27/00 | 0.00 | " | " | Full Suite Metals | | |
| 00092728-TSPDE-7294 | D-TSP | SAMPLE STATION D | 9/27/00 | 1894.79 | " | " | Full Suite Metals | | |
| 00092728-TSPEE-7295 | E-TSP | SAMPLE STATION E | 9/27/00 | 1895.55 | " | " | Full Suite Metals | | |
| 00092728-TSPFE-7296 | F-TSP | SAMPLE STATION F | 9/27/00 | 1838.42 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/27/00 | 0.00 | | | Full Suite Metals | | |
| 00092728-FBETSP-7289 | TSP-BLANK | TSP-BLANK | 9/27/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-285 Samples from stations A, B and C - elapsed timers are in question. 11/9/00 10:00 AM

09272800 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092829



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. McNerny
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/30/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092829-PUFAE-2532 | A-PUF | SAMPLE STATION A | 9/28/00 | 324.25 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00092829-PUFBE-2533 | B-PUF | SAMPLE STATION B | 9/28/00 | 327.91 | " | " | TO-4 & TO-13 & TO-9m | | |
| VOID | C-PUF | SAMPLE STATION C | 9/28/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092829-PUFDE-2535 | D-PUF | SAMPLE STATION D | 9/28/00 | 325.82 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092829-PUFEE-2536 | E-PUF | SAMPLE STATION E | 9/28/00 | 311.94 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092829-PUFFE-2537 | F-PUF | SAMPLE STATION F | 9/28/00 | 320.13 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092829-PUFGE-2538 | G-PUF | SAMPLE STATION G | 9/28/00 | 330.96 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | PUF BLANK | PUF-BLANK | 9/28/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092829-VOCAE-A502 | A-VOC | SAMPLE STATION A | 9/28/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00092829-VOCBE-A811 | B-VOC | SAMPLE STATION B | 9/28/00 | 2.50 | " | " | TO-14a | | |
| 0092829-VOCCE-A606 | C-VOC | SAMPLE STATION C | 9/28/00 | 0.00 | " | " | TO-14a | | |
| 0092829-VOCDE-A420 | D-VOC | SAMPLE STATION D | 9/28/00 | 4.20 | " | " | TO-14a | | |
| 00092829-VOCEE-A425 | E-VOC | SAMPLE STATION E | 9/28/00 | 0.00 | " | " | TO-14a | | |
| 00092829-VOCFE-A809 | F-VOC | SAMPLE STATION F | 9/28/00 | 7.00 | " | " | TO-14a | | |
| 0092829-VOCGE-A803 | G-VOC | SAMPLE STATION G | 9/28/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 9/28/00 | NA | " | " | TO-14a | | |
| 00092829-TSPAE-7298 | A-TSP | SAMPLE STATION A | 9/28/00 | 1754.06 | Envelope | " | Full Suite Metals | | |
| 00092829-TSPBE-7299 | B-TSP | SAMPLE STATION B | 9/28/00 | 1908.78 | " | " | Full Suite Metals | | |
| VOID | C-TSP | SAMPLE STATION C | 9/28/00 | 0.00 | " | " | Full Suite Metals | | |
| 00092829-TSPDE-7301 | D-TSP | SAMPLE STATION D | 9/28/00 | 1801.15 | " | " | Full Suite Metals | | |
| 00092829-TSPEE-7302 | E-TSP | SAMPLE STATION E | 9/28/00 | 1809.28 | " | " | Full Suite Metals | | |
| 00092829-TSPFE-7303 | F-TSP | SAMPLE STATION F | 9/28/00 | 1788.19 | " | " | Full Suite Metals | | |
| 00092829-TSPGE-7233 | G-TSP | SAMPLE STATION G | 9/28/00 | 1882.23 | | | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 9/28/00 | NA | " | " | Full Suite Metals | | |
| --- | --- | --- | --- | --- | --- | --- | --- | | |
| --- | --- | --- | --- | --- | --- | --- | --- | | |
| --- | --- | --- | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning 1 SUMMA regulator for maintenance. Returning VOID PUF sample.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-280 Sample 0092829-VOCCE-A606 ran slightly over 25 hours. 11/9/00 10:00 AM

09282900 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

IT INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092728ahcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. Gildersleeve
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/29/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00000 | A-Chlorine | SAMPLE STATION A | 9/28/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | B-Chlorine | SAMPLE STATION B | 9/28/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | C- Chlorine | SAMPLE STATION C | 9/28/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | D-Chlorine | SAMPLE STATION D | 9/28/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | E-Chlorine | SAMPLE STATION E | 9/28/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | F-Chlorine | SAMPLE STATION F | 9/28/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | G-Chlorine | SAMPLE STATION G | 9/28/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | hlorine Blank | Blank | 9/28/00 | NA | 3 vials | None | TO-0051m | | | |
| 000928-PHAE-2067a.m | A-PH | SAMPLE STATION A | 9/28/00 | 66.96 | 1 vial | Ice | TO-6m | | | |
| 000928-PHBE-2068 a.m | B-PH | SAMPLE STATION B | 9/28/00 | 52.92 | 1 vial | Ice | TO-6m | | | |
| 000928-PHCE-2069 a.m | C-PH | SAMPLE STATION C | 9/28/00 | 53.00 | 1 vial | Ice | TO-6m | | | |
| 000928-PHDE-2070 a.m | D-PH | SAMPLE STATION D | 9/28/00 | 52.50 | 1 vial | Ice | TO-6m | | | |
| 000928-PHEE-2071 a.m | E-PH | SAMPLE STATION E | 9/28/00 | 60.00 | 1 vial | Ice | TO-6m | | | |
| 000928-PHFE-2072 a.m | F-PH | SAMPLE STATION F | 9/28/00 | 60.77 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/28/00 | #REF! | 1 vial | Ice | TO-6m | | | |
| 000928-PHAE-2073 p.m | A-PH | SAMPLE STATION A | 9/28/00 | 51.94 | 1 vial | Ice | TO-6m | | | |
| 000928-PHBE-2074 p.m | B-PH | SAMPLE STATION B | 9/28/00 | 51.36 | 1 vial | Ice | TO-6m | | | |
| 000928-PHCE-2075 p.m | C-PH | SAMPLE STATION C | 9/28/00 | 47.94 | 1 vial | Ice | TO-6m | | | |
| 000928-PHDE-2076 p.m | D-PH | SAMPLE STATION D | 9/28/00 | 50.47 | 1 vial | Ice | TO-6m | | | |
| 000928-PHEE-2077 p.m | E-PH | SAMPLE STATION E | 9/28/00 | 52.02 | 1 vial | Ice | TO-6m | | | |
| 000928-PHFE-2078 p.m | F-PH | SAMPLE STATION F | 9/28/00 | 50.96 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/28/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaroun | QC Level: | See PAM |
|---|---|---|---|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | | Date: Time: | |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | | Date: Time: | |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | | Date: Time: | |
| Comments: | Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | | | | |

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092930



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, L. Leet, S. McNerny
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/1/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00092930-PUFAE-2540 | A-PUF | SAMPLE STATION A | 9/29/00 | 318.96 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00092930-PUFBE-2541 | B-PUF | SAMPLE STATION B | 9/29/00 | 315.21 | " | " | TO-4 & TO-13 & TO-9m | | |
| VOID | C-PUF | SAMPLE STATION C | 9/29/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092930-PUFDE-2543 | D-PUF | SAMPLE STATION D | 9/29/00 | 316.88 | " | " | TO-4 & TO-13 & TO-9m | | |
| VOID | E-PUF | SAMPLE STATION E | 9/29/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092930-PUFFE-2545 | F-PUF | SAMPLE STATION F | 9/29/00 | 311.19 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 9/29/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00092930-FBEPUF-2539 | PUF BLANK | PUF-BLANK | 9/29/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | A-VOC | SAMPLE STATION A | 9/29/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00092930-VOCBE-A414 | B-VOC | SAMPLE STATION B | 9/29/00 | 1.50 | " | " | TO-14a | | |
| 0092930-VOCCE-A513 | C-VOC | SAMPLE STATION C | 9/29/00 | 0.00 | " | " | TO-14a | | |
| 0092930-VOCDE-A101 | D-VOC | SAMPLE STATION D | 9/29/00 | 5.20 | " | " | TO-14a | | |
| 00092930-VOCEE-A432 | E-VOC | SAMPLE STATION E | 9/29/00 | 0.00 | " | " | TO-14a | | |
| 00092930-VOCFE-A636 | F-VOC | SAMPLE STATION F | 9/29/00 | 9.80 | " | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 9/29/00 | 0.00 | " | " | TO-14a | | |
| 00092930-FBEVOC-A808 | VOC-BLANK | VOC-BLANK | 9/29/00 | NA | " | " | TO-14a | | |
| 00092930-TSPAE-7304 | A-TSP | SAMPLE STATION A | 9/29/00 | 1751.02 | Envelope | " | Full Suite Metals | | |
| 00092930-TSPBE-7305 | B-TSP | SAMPLE STATION B | 9/29/00 | 1821.95 | " | " | Full Suite Metals | | |
| VOID | C-TSP | SAMPLE STATION C | 9/29/00 | 0.00 | " | " | Full Suite Metals | | |
| 00092930-TSPDE-7307 | D-TSP | SAMPLE STATION D | 9/29/00 | 1804.45 | " | " | Full Suite Metals | | |
| VOID | E-TSP | SAMPLE STATION E | 9/29/00 | 0.00 | " | " | Full Suite Metals | | |
| 00092930-TSPFE-7309 | F-TSP | SAMPLE STATION F | 9/29/00 | 1757.23 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 9/29/00 | 0.00 | | | Full Suite Metals | | |
| 00092930-FBETSP-7297 | TSP-BLANK | TSP-BLANK | 9/29/00 | NA | " | " | Full Suite Metals | | |
| --- | --- | --- | --- | --- | --- | --- | --- | | |
| --- | --- | --- | --- | --- | --- | --- | --- | | |
| --- | --- | --- | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning 2 VOID PUF samples.

| | | | |
|---|---|---|---|
| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

09293000 COC
T. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092829hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/30/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00092829-HCLAE-2061 | A-Chlorine | SAMPLE STATION AE | 9/29/00 | 1531.92 | 3 vials | None | TO-0051m | | | |
| 00092829-HCLBE-2062 | B-Chlorine | SAMPLE STATION BE | 9/29/00 | 995.31 | 3 vials | None | TO-0051m | | | |
| 00092829-HCLCE-2063 | C- Chlorine | SAMPLE STATION CE | 9/29/00 | ~1320 | 3 vials | None | TO-0051m | | | |
| 00092829-HCLDE-2064 | D-Chlorine | SAMPLE STATION DE | 9/29/00 | ~1346.4 | 3 vials | None | TO-0051m | | | |
| Not Collected | E-Chlorine | SAMPLE STATION EE | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | F-Chlorine | SAMPLE STATION FE | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | G-Chlorine | SAMPLE STATION GE | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | hlorine Blank | Blank | 1/0/00 | NA | 3 vials | None | TO-0051m | | | |
| 000929-PHAE-2079AM | A-PH | SAMPLE STATION AE | 9/29/00 | 59.16 | 1 vial | Ice | TO-6m | | | |
| 000929-PHBE-2080AM | B-PH | SAMPLE STATION BE | 9/29/00 | 49.50 | 1 vial | Ice | TO-6m | | | |
| 000929-PHCE-2081AM | C-PH | SAMPLE STATION CE | 9/29/00 | 52.92 | 1 vial | Ice | TO-6m | | | |
| 000929-PHDE-2082AM | D-PH | SAMPLE STATION DE | 9/29/00 | 48.48 | 1 vial | Ice | TO-6m | | | |
| 000929-PHEE-2083AM | E-PH | SAMPLE STATION EE | 9/29/00 | 52.00 | 1 vial | Ice | TO-6m | | | |
| 000929-PHFE-2084AM | F-PH | SAMPLE STATION FE | 9/29/00 | 53.04 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION GE | 9/29/00 | NA | 1 vial | Ice | TO-6m | | | |
| 000929-PHAE-2085PM | A-PH | SAMPLE STATION AE | 9/29/00 | 51.00 | 1 vial | Ice | TO-6m | | | |
| 000929-PHBE-2086PM | B-PH | SAMPLE STATION BE | 9/29/00 | 54.00 | 1 vial | Ice | TO-6m | | | |
| 000929-PHCE-2087PM | C-PH | SAMPLE STATION CE | 9/29/00 | 52.00 | 1 vial | Ice | TO-6m | | | |
| 000929-PHDE-2088PM | D-PH | SAMPLE STATION DE | 9/29/00 | 52.00 | 1 vial | Ice | TO-6m | | | |
| 000929-PHEE-2089PM | E-PH | SAMPLE STATION EE | 9/29/00 | 50.00 | 1 vial | Ice | TO-6m | | | |
| 000929-PHFE-2090PM | F-PH | SAMPLE STATION FE | 9/29/00 | 53.50 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION GE | 9/29/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaroun | QC Level: | See PAM |
|---|---|---|---|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | | Date: Time: | |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | | Date: Time: | |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | | Date: Time: | |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

BU

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-092930hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 9/30/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00092930-HclAE-2065 | A-Chlorine | SAMPLE STATION A | 9/29/00 | 1508.80 | 3 vials | None | TO-0051m | | | |
| 00092930-HclBE-2066 | B-Chlorine | SAMPLE STATION B | 9/29/00 | 1446.20 | 3 vials | None | TO-0051m | | | |
| 00092930-HclCE-2067 | C- Chlorine | SAMPLE STATION C | 9/29/00 | 1472.93 | 3 vials | None | TO-0051m | | | |
| 00092930-HclDE-2068 | D-Chlorine | SAMPLE STATION D | 9/29/00 | 1431.15 | 3 vials | None | TO-0051m | | | |
| 00092930-HclEE-2069 | E-Chlorine | SAMPLE STATION E | 9/29/00 | 1476.60 | 3 vials | None | TO-0051m | | | |
| 00092930-HclFE-2070 | F-Chlorine | SAMPLE STATION F | 9/29/00 | 1883.70 | 3 vials | None | TO-0051m | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 9/29/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | hlorine Blank | Blank | 9/29/00 | NA | 3 vials | None | TO-0051m | | | |
| Not collected | A-PH | SAMPLE STATION A | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | B-PH | SAMPLE STATION B | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | C-PH | SAMPLE STATION C | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | D-PH | SAMPLE STATION D | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | E-PH | SAMPLE STATION E | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | F-PH | SAMPLE STATION F | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/30/00 | #REF! | 1 vial | Ice | TO-6m | | | |
| Not collected | A-PH | SAMPLE STATION A | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | B-PH | SAMPLE STATION B | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | C-PH | SAMPLE STATION C | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | D-PH | SAMPLE STATION D | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | E-PH | SAMPLE STATION E | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | F-PH | SAMPLE STATION F | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/30/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour |
| QC Level: | See PAM | | | | |
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | Date: Time: |
| Comments: | Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | | |

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-0930hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L.Leet, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/1/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| Not Collected | A-Chlorine | SAMPLE STATION A | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | B-Chlorine | SAMPLE STATION B | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | C- Chlorine | SAMPLE STATION C | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | D-Chlorine | SAMPLE STATION D | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | E-Chlorine | SAMPLE STATION E | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | F-Chlorine | SAMPLE STATION F | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 1/0/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | hlorine Blank | Blank | 1/0/00 | NA | 3 vials | None | **TO-0051m** | | | |
| 000930-PHAE-2091AM | A-PH | SAMPLE STATION A | 9/30/00 | 56.00 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHBE-2092AM | B-PH | SAMPLE STATION B | 9/30/00 | 52.50 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHCE-2093AM | C-PH | SAMPLE STATION C | 9/30/00 | 54.50 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHDE-2094AM | D-PH | SAMPLE STATION D | 9/30/00 | 50.50 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHEE-2095AM | E-PH | SAMPLE STATION E | 9/30/00 | 10.10 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHFE-2096AM | F-PH | SAMPLE STATION F | 9/30/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/30/00 | #REF! | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHAE-2097PM | A-PH | SAMPLE STATION A | 9/30/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHBE-2098PM | B-PH | SAMPLE STATION B | 9/30/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHCE-2099PM | C-PH | SAMPLE STATION C | 9/30/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHDE-2100PM | D-PH | SAMPLE STATION D | 9/30/00 | 49.00 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHEE-2101PM | E-PH | SAMPLE STATION E | 9/30/00 | 49.00 | 1 vial | Ice | **TO-6m** | | | |
| 000930-PHFE-2102PM | F-PH | SAMPLE STATION F | 9/30/00 | 58.50 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 9/30/00 | 0.00 | 1 vial | Ice | **TO-6m** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

093000hcl.COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/16/00 9:21 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1001



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L. Leet, A. Cortez, S. McNerny
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/3/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001001-PUFAE-2546 | A-PUF | SAMPLE STATION A | 10/1/00 | 5.92 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001001-PUFBE-2547 | B-PUF | SAMPLE STATION B | 10/1/00 | 5.77 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001001-PUFCE-2548 | C-PUF | SAMPLE STATION C | 10/1/00 | 6.19 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001001-PUFDE-2549 | D-PUF | SAMPLE STATION D | 10/1/00 | 5.81 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001001-PUFEE-2550 | E-PUF | SAMPLE STATION E | 10/1/00 | 5.48 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001001-PUFFE-2551 | F-PUF | SAMPLE STATION F | 10/1/00 | 5.73 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001001-PUFGE-2552 | G-PUF | SAMPLE STATION G | 10/1/00 | 5.89 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | PUF BLANK | PUF-BLANK | 10/1/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001001-VOCAE-A914 | A-VOC | SAMPLE STATION A | 10/1/00 | 3.00 psi | SUMMA | None | TO-14a See Note | | |
| 001001-VOCBE-A508 | B-VOC | SAMPLE STATION B | 10/1/00 | 0.00 | " | " | TO-14a | | |
| 001001-VOCCE-A704 | C-VOC | SAMPLE STATION C | 10/1/00 | 3.00 | " | " | TO-14a | | |
| 001001-VOCDE-A306 | D-VOC | SAMPLE STATION D | 10/1/00 | 4.00 | " | " | TO-14a | | |
| 001001-VOCEE-A602 | E-VOC | SAMPLE STATION E | 10/1/00 | 0.00 | " | " | TO-14a | | |
| 001001-VOCFE-A105 | F-VOC | SAMPLE STATION F | 10/1/00 | 1.50 | " | " | TO-14a | | |
| 001001-VOCGE-A423 | G-VOC | SAMPLE STATION G | 10/1/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 10/1/00 | NA | " | " | TO-14a | | |
| 001001-TSPAE-7310 | A-TSP | SAMPLE STATION A | 10/1/00 | 1863.21 | Envelope | " | Full Suite Metals | | |
| 001001-TSPBE-7311 | B-TSP | SAMPLE STATION B | 10/1/00 | 2078.02 | " | " | Full Suite Metals | | |
| 001001-TSPCE-7312 | C-TSP | SAMPLE STATION C | 10/1/00 | 2029.24 | " | " | Full Suite Metals | | |
| 001001-TSPDE-7313 | D-TSP | SAMPLE STATION D | 10/1/00 | 1952.85 | " | " | Full Suite Metals | | |
| 001001-TSPEE-7318 | E-TSP | SAMPLE STATION E | 10/1/00 | 1829.50 | " | " | Full Suite Metals | | |
| 001001-TSPFE-7319 | F-TSP | SAMPLE STATION F | 10/1/00 | 2109.55 | " | " | Full Suite Metals | | |
| 001001-TSPGE-7320 | G-TSP | SAMPLE STATION G | 10/1/00 | 1849.44 | | | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 10/1/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning 7 PUF samples which are missing labels.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarou | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

100100.COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-280 Samples 001001-TSPBE-7311 and 001001-TSPCE-7312 ran slightly over 25 hours. 11/9/00 10:00 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1001hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/2/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 001001-HCLAE-2071 | A-Chlorine | SAMPLE STATION A | 10/1/00 | 1598.40 | 3 vials | None | **TO-0051m** | | | |
| 001001-HCLBE-2072 | B-Chlorine | SAMPLE STATION B | 10/1/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| 001001-HCLCE-2073 | C- Chlorine | SAMPLE STATION C | 10/1/00 | 1432.53 | 3 vials | None | **TO-0051m** | | | |
| 001001-HCLDE-2074 | D-Chlorine | SAMPLE STATION D | 10/1/00 | 1515.25 | 3 vials | None | **TO-0051m** | | | |
| 001001-HCLEE-2075 | E-Chlorine | SAMPLE STATION E | 10/1/00 | 1572.48 | 3 vials | None | **TO-0051m** | | | |
| 001001-HCLFE-2076 | F-Chlorine | SAMPLE STATION F | 10/1/00 | 1744.70 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 10/1/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | hlorine Blank | Blank | 10/1/00 | NA | 3 vials | None | **TO-0051m** | | | |
| 001001-PHAE-2103AM | A-PH | SAMPLE STATION A | 10/1/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHBE-2104AM | B-PH | SAMPLE STATION B | 10/1/00 | 54.50 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHCE-2105AM | C-PH | SAMPLE STATION C | 10/1/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHDE-2106AM | D-PH | SAMPLE STATION D | 10/1/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHEE-2107AM | E-PH | SAMPLE STATION E | 10/1/00 | 51.50 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHFE-2108AM | F-PH | SAMPLE STATION F | 10/1/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/1/00 | #REF! | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHAE-2109PM | A-PH | SAMPLE STATION A | 10/1/00 | 52.50 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHBE-2110PM | B-PH | SAMPLE STATION B | 10/1/00 | 54.00 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHCE-2111PM | C-PH | SAMPLE STATION C | 10/1/00 | 51.50 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHDE-2112PM | D-PH | SAMPLE STATION D | 10/1/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHEE-2113PM | E-PH | SAMPLE STATION E | 10/1/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001001-PHFE-2114PM | F-PH | SAMPLE STATION F | 10/1/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/1/00 | 0.00 | 1 vial | Ice | **TO-6m** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

11/16/00 9:21 AM

100100 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1002



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, B. Womack
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/4/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001002-PUFAE--2553 | A-PUF | SAMPLE STATION A | 10/2/00 | 338.83 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001002-PUFBE-2554 | B-PUF | SAMPLE STATION B | 10/2/00 | 335.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001002-PUFCE-2555 | C-PUF | SAMPLE STATION C | 10/2/00 | 373.27 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001002-PUFDE-2556 | D-PUF | SAMPLE STATION D | 10/2/00 | 313.36 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001002-PUFEE-2557 | E-PUF | SAMPLE STATION E | 10/2/00 | 320.17 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001002-PUFFE-2558 | F-PUF | SAMPLE STATION F | 10/2/00 | 322.80 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 10/2/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001002-FBEPUF-2559 | PUF BLANK | PUF-BLANK | 10/2/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001002-VOCAE-A810 | A-VOC | SAMPLE STATION A | 10/2/00 | 1.50 psi | SUMMA | None | TO-14a See Note | | |
| 001002-VOCBE-A301 | B-VOC | SAMPLE STATION B | 10/2/00 | 0.00 | " | " | TO-14a | | |
| 001002-VOCCE-A303 | C-VOC | SAMPLE STATION C | 10/2/00 | 2.00 | " | " | TO-14a | | |
| 001002-VOCDE-A202 | D-VOC | SAMPLE STATION D | 10/2/00 | 7.50 | " | " | TO-14a | | |
| 001002-VOCEE-A805 | E-VOC | SAMPLE STATION E | 10/2/00 | 0.00 | " | " | TO-14a | | |
| 001002-VOCFE-A426 | F-VOC | SAMPLE STATION F | 10/2/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | G-VOC | SAMPLE STATION G | 10/2/00 | 0.00 | " | " | TO-14a | | |
| 001002-FBEVOC-A112 | VOC-BLANK | VOC-BLANK | 10/2/00 | NA | " | " | TO-14a | | |
| 001002-TSPAE-7314 | A-TSP | SAMPLE STATION A | 10/2/00 | 1881.45 | Envelope | " | Full Suite Metals | | |
| 001002-TSPBE-7315 | B-TSP | SAMPLE STATION B | 10/2/00 | 1886.81 | " | " | Full Suite Metals | | |
| 001002-TSPCE-7306 | C-TSP | SAMPLE STATION C | 10/2/00 | 1961.93 | " | " | Full Suite Metals | | |
| 001002-TSPDE-7316 | D-TSP | SAMPLE STATION D | 10/2/00 | 1931.31 | " | " | Full Suite Metals | | |
| 001002-TSPEE-7317 | E-TSP | SAMPLE STATION E | 10/2/00 | 1839.22 | " | " | Full Suite Metals | | |
| 001002-TSPFE-7326 | F-TSP | SAMPLE STATION F | 10/2/00 | 1912.13 | " | " | Full Suite Metals | | |
| NOT COLLECTED | G-TSP | SAMPLE STATION G | 10/2/00 | 0.00 | | | Full Suite Metals | | |
| 001002-FBEPUF-7327 | TSP-BLANK | TSP-BLANK | 10/2/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarou | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-280 Samples 001002-PUFCE-2555, 001002-TSPCE-7306 and 001002-TSPDE-7316 ran slightly over 25 hours. 11/9/00 10:00 AM

100200 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1002HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, L. Leet, A. Cortez, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/3/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 001002-HCLAE-2077 | A-Chlorine | SAMPLE STATION A | 10/2/00 | 1634.40 | 3 vials | None | **TO-0051m** | | | |
| 001002-HCLBE-2078 | B-Chlorine | SAMPLE STATION B | 10/2/00 | 1504.80 | 3 vials | None | **TO-0051m** | | | |
| 001002-HCLCE-2079 | C- Chlorine | SAMPLE STATION C | 10/2/00 | 1605.60 | 3 vials | None | **TO-0051m** | | | |
| 001002-HCLDE-2080 | D-Chlorine | SAMPLE STATION D | 10/2/00 | 1483.20 | 3 vials | None | **TO-0051m** | | | |
| 001002-HCLEE-2081 | E-Chlorine | SAMPLE STATION E | 10/2/00 | 1576.80 | 3 vials | None | **TO-0051m** | | | |
| 001002-HCLFE-2082 | F-Chlorine | SAMPLE STATION F | 10/2/00 | 1656.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 10/2/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | hlorine Blank | Blank | 10/2/00 | NA | 3 vials | None | **TO-0051m** | | | |
| 001002-PHAE-2115AM | A-PH | SAMPLE STATION A | 10/2/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHBE-2116AM | B-PH | SAMPLE STATION B | 10/2/00 | 56.00 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHCE-2117AM | C-PH | SAMPLE STATION C | 10/2/00 | 51.50 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHDE-2118AM | D-PH | SAMPLE STATION D | 10/2/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHEE-2119AM | E-PH | SAMPLE STATION E | 10/2/00 | 56.00 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHFE-2120AM | F-PH | SAMPLE STATION F | 10/2/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/2/00 | #REF! | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHAE-2121PM | A-PH | SAMPLE STATION A | 10/2/00 | 50.00 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHBE-2122PM | B-PH | SAMPLE STATION B | 10/2/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHCE-2123PM | C-PH | SAMPLE STATION C | 10/2/00 | 52.50 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHDE-2124PM | D-PH | SAMPLE STATION D | 10/2/00 | 52.50 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHEE-2125PM | E-PH | SAMPLE STATION E | 10/2/00 | 55.50 | 1 vial | Ice | **TO-6m** | | | |
| 001002-PHFE-2126PM | F-PH | SAMPLE STATION F | 10/2/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/2/00 | 0.00 | 1 vial | Ice | **TO-6m** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaroun |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

100200 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

11/16/00 9:21 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1002HR



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, E. Diaz, S. McNerny
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/4/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001002-PUFHRA-2013 | A-PUF | SAMPLE STATION A | 10/2/00 | 317.51 | Jar | ICE | TO-9 | | |
| 001002-PUFHRB-2014 | B-PUF | SAMPLE STATION B | 10/2/00 | 335.31 | " | " | TO-9 | | |
| 001002-PUFHRC-2015 | C-PUF | SAMPLE STATION C | 10/2/00 | 326.70 | " | " | TO-9 | | |
| 001002-PUFHRD-2016 | D-PUF | SAMPLE STATION D | 10/2/00 | 340.57 | " | " | TO-9 | | |
| 001002-PUFHRE-2017 | E-PUF | SAMPLE STATION E | 10/2/00 | 315.27 | " | " | TO-9 | | |
| 001002-PUFHRF-2018 | F-PUF | SAMPLE STATION F | 10/2/00 | 334.46 | " | " | TO-9 | | |
| NOT COLLECTED | G-PUF | SAMPLE STATION G | 10/2/00 | 0.00 | " | " | TO-9 | | |
| 001002-HRFBPUF-2019 | PUF BLANK | PUF-BLANK | 10/2/00 | NA | " | " | TO-9 | | |
| | | | | psi | | | | | |

Special Instructions: Analyze for Hi resolution dioxins and furans per conversations with IT.

| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 5 day turnarour | QC Level: | See PAM |
|---|---|---|---|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | | Date: Time: | |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | | Date: Time: | |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | | Date: Time: | |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

100200hr COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/7/00 11:16 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1003



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/5/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001003-PUFAE-2560 | A-PUF | SAMPLE STATION A | 10/3/00 | 332.74 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001003-PUFBE-2561 | B-PUF | SAMPLE STATION B | 10/3/00 | 338.56 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001003-PUFCE-2562 | C-PUF | SAMPLE STATION C | 10/3/00 | 337.74 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001003-PUFDE-2563 | D-PUF | SAMPLE STATION D | 10/3/00 | 303.44 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001003-PUFEE-2564 | E-PUF | SAMPLE STATION E | 10/3/00 | 311.84 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001003-PUFFE-2565 | F-PUF | SAMPLE STATION F | 10/3/00 | 298.29 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001003-PUFGE-2566 | G-PUF | SAMPLE STATION G | 10/3/00 | 306.01 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | PUF BLANK | PUF-BLANK | 10/3/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001003-VOCAE-A425 | A-VOC | SAMPLE STATION A | 10/3/00 | 5.50 psi | SUMMA | None | TO-14a See Note | | |
| 001003-VOCBE-A433 | B-VOC | SAMPLE STATION B | 10/3/00 | 0.00 | " | " | TO-14a | | |
| 001003-VOCCE-A421 | C-VOC | SAMPLE STATION C | 10/3/00 | 6.00 | " | " | TO-14a | | |
| 001003-VOCDE-A705 | D-VOC | SAMPLE STATION D | 10/3/00 | 10.50 | " | " | TO-14a | | |
| 001003-VOCEE-A603 | E-VOC | SAMPLE STATION E | 10/3/00 | 0.00 | " | " | TO-14a | | |
| 001003-VOCFE-A604 | F-VOC | SAMPLE STATION F | 10/3/00 | 1.50 | " | " | TO-14a | | |
| 001003-VOCGE-A503 | G-VOC | SAMPLE STATION G | 10/3/00 | 2.00 | " | " | TO-14a | | |
| NOT COLLECTED | VOC-BLANK | VOC-BLANK | 10/3/00 | NA | " | " | TO-14a | | |
| 001003-TSPAE-7321 | A-TSP | SAMPLE STATION A | 10/3/00 | 1798.78 | Envelope | " | Full Suite Metals | | |
| 001003-TSPBE-7322 | B-TSP | SAMPLE STATION B | 10/3/00 | 1863.10 | " | " | Full Suite Metals | | |
| 001003-TSPCE-7323 | C-TSP | SAMPLE STATION C | 10/3/00 | 1786.52 | " | " | Full Suite Metals | | |
| 001003-TSPDE-7324 | D-TSP | SAMPLE STATION D | 10/3/00 | 1764.84 | " | " | Full Suite Metals | | |
| 001003-TSPEE-7325 | E-TSP | SAMPLE STATION E | 10/3/00 | 1808.60 | " | " | Full Suite Metals | | |
| 001003-TSPFE-7328 | F-TSP | SAMPLE STATION F | 10/3/00 | 1672.14 | " | " | Full Suite Metals | | |
| 001003-TSPGE-7329 | G-TSP | SAMPLE STATION G | 10/3/00 | 1759.58 | | | Full Suite Metals | | |
| NOT COLLECTED | TSP-BLANK | TSP-BLANK | 10/3/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |
| Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | 11/9/00 10:00 AM |

100300.COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1003HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S.McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/4/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 001003-HCLAE-2083 | A-Chlorine | SAMPLE STATION A | 10/3/00 | 1667.50 | 3 vials | None | **TO-0051m** | | | |
| 001003-HCLBE-2084 | B-Chlorine | SAMPLE STATION B | 10/3/00 | 1537.00 | 3 vials | None | **TO-0051m** | | | |
| 001003-HCLCE-2085 | C- Chlorine | SAMPLE STATION C | 10/3/00 | 1624.00 | 3 vials | None | **TO-0051m** | | | |
| 001003-HCLDE-2086 | D-Chlorine | SAMPLE STATION D | 10/3/00 | #VALUE! | 3 vials | None | **TO-0051m** | | | |
| 001003-HCLEE-2087 | E-Chlorine | SAMPLE STATION E | 10/3/00 | 1515.25 | 3 vials | None | **TO-0051m** | | | |
| 001003-HCLFE-2088 | F-Chlorine | SAMPLE STATION F | 10/3/00 | 1747.25 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 10/3/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | hlorine Blank | Blank | 10/3/00 | NA | 3 vials | None | **TO-0051m** | | | |
| 001003-PHAE-2127AM | A-PH | SAMPLE STATION A | 10/3/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHBE-2128AM | B-PH | SAMPLE STATION B | 10/3/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHCE-2129AM | C-PH | SAMPLE STATION C | 10/3/00 | 55.00 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHDE-2130AM | D-PH | SAMPLE STATION D | 10/3/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHEE-2131AM | E-PH | SAMPLE STATION E | 10/3/00 | 55.00 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHFE-2132AM | F-PH | SAMPLE STATION F | 10/3/00 | 51.50 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/3/00 | #REF! | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHAE-2133PM | A-PH | SAMPLE STATION A | 10/3/00 | 51.50 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHBE-2134PM | B-PH | SAMPLE STATION B | 10/3/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHCE-2135PM | C-PH | SAMPLE STATION C | 10/3/00 | 56.50 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHDE-2136PM | D-PH | SAMPLE STATION D | 10/3/00 | 50.50 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHEE-2137PM | E-PH | SAMPLE STATION E | 10/3/00 | 54.50 | 1 vial | Ice | **TO-6m** | | | |
| 001003-PHFE-2138PM | F-PH | SAMPLE STATION F | 10/3/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/3/00 | 0.00 | 1 vial | Ice | **TO-6m** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour | QC Level: | See PAM |
|---|---|---|---|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | | Date: Time: | |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | | Date: Time: | |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | | Date: Time: | |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/16/00 9:21 AM

100300 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1004



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, E. Diaz, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/6/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001004-PUFAE-2567 | AC, ED | PARCEL E, STATION A | 10/4/00 | 320.55 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001004-PUFBE-2568 | AC, ED | PARCEL E, STATION B | 10/4/00 | 322.45 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001004-PUFCE-2569 | AC, ED | PARCEL E, STATION C. | 10/4/00 | 324.10 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001004-PUFDE-2570 | AC, ED | PARCEL E, STATION D | 10/4/00 | 328.32 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001004-PUFEE-2571 | AC, ED | PARCEL E, STATION E | 10/4/00 | 320.93 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001004-PUFFE-2572 | AC, ED | PARCEL E, STATION F | 10/4/00 | 314.72 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/4/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001004-FBEPUF-2573 | AC, ED | PARCEL E, PUF-BLANK | 10/4/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001004-VOCAE-A801 | AC, ED | PARCEL E, STATION A | 10/4/00 | 5.50 psi | SUMMA | None | TO-14a See Note | | |
| 001004-VOCBE-A420 | AC, ED | PARCEL E, STATION B | 10/4/00 | 0.00 | " | " | TO-14a | | |
| 001004-VOCCE-A417 | AC, ED | PARCEL E, STATION C | 10/4/00 | 8.00 | " | " | TO-14a | | |
| 001004-VOCDE-A809 | AC, ED | PARCEL E, STATION D | 10/4/00 | 11.50 | " | " | TO-14a | | |
| 001004-VOCEE-A428 | AC, ED | PARCEL E, STATION E | 10/4/00 | 0.00 | " | " | TO-14a | | |
| 001004-VOCFE-A430 | AC, ED | PARCEL E, STATION F | 10/4/00 | 2.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/4/00 | 0.00 | " | " | TO-14a | | |
| 001004-FBEVOC-A803 | AC, ED | PARCEL E, VOC-BLANK | 10/4/00 | NA | " | " | TO-14a | | |
| 001004-TSPAE-7336 | AC, ED | PARCEL E, STATION A | 10/4/00 | 1770.18 | Envelope | " | Full Suite Metals | | |
| 001004-TSPBE-7335 | AC, ED | PARCEL E, STATION B | 10/4/00 | 1776.73 | " | " | Full Suite Metals | | |
| 001004-TSPCE-7334 | AC, ED | PARCEL E, STATION C | 10/4/00 | 1773.87 | " | " | Full Suite Metals | | |
| 001004-TSPDE-7333 | AC, ED | PARCEL E, STATION D | 10/4/00 | 1778.98 | " | " | Full Suite Metals | | |
| 001004-TSPEE-7332 | AC, ED | PARCEL E, STATION E | 10/4/00 | 1746.01 | " | " | Full Suite Metals | | |
| 001004-TSPFE-7331 | AC, ED | PARCEL E, STATION F | 10/4/00 | 1725.42 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/4/00 | 0.00 | | | Full Suite Metals | | |
| 001004-FBEPUF-7330 | AC, ED | PARCEL E, TSP-BLANK | 10/4/00 | NA | " | " | Full Suite Metals | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

100400 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1004HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/5/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 001004-HCLAE-2089 | A-Chlorine | SAMPLE STATION A | 10/4/00 | 1663.20 | 3 vials | None | **TO-0051m** | | | |
| 001004-HCLBE-2090 | B-Chlorine | SAMPLE STATION B | 10/4/00 | 1468.80 | 3 vials | None | **TO-0051m** | | | |
| 001004-HCLCE-2091 | C- Chlorine | SAMPLE STATION C | 10/4/00 | 1605.60 | 3 vials | None | **TO-0051m** | | | |
| 001004-HCLDE-2092 | D-Chlorine | SAMPLE STATION D | 10/4/00 | 1497.60 | 3 vials | None | **TO-0051m** | | | |
| 001004-HCLEE-2093 | E-Chlorine | SAMPLE STATION E | 10/4/00 | 1512.00 | 3 vials | None | **TO-0051m** | | | |
| 001004-HCLFE-2094 | F-Chlorine | SAMPLE STATION F | 10/4/00 | 1792.80 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 10/4/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | hlorine Blank | Blank | 10/4/00 | NA | 3 vials | None | **TO-0051m** | | | |
| 001004-PHAE-2139AM | A-PH | SAMPLE STATION A | 10/4/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHBE-2140AM | B-PH | SAMPLE STATION B | 10/4/00 | 54.50 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHCE-2141AM | C-PH | SAMPLE STATION C | 10/4/00 | 56.00 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHDE-2142AM | D-PH | SAMPLE STATION D | 10/4/00 | 52.50 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHEE-2143AM | E-PH | SAMPLE STATION E | 10/4/00 | 55.00 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHFE-2144AM | F-PH | SAMPLE STATION F | 10/4/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/4/00 | #REF! | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHAE-2145PM | A-PH | SAMPLE STATION A | 10/4/00 | 51.50 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHBE-2146PM | B-PH | SAMPLE STATION B | 10/4/00 | 54.00 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHCE-2147PM | C-PH | SAMPLE STATION C | 10/4/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHDE-2148PM | D-PH | SAMPLE STATION D | 10/4/00 | 51.00 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHEE-2149PM | E-PH | SAMPLE STATION E | 10/4/00 | 56.00 | 1 vial | Ice | **TO-6m** | | | |
| 001004-PHFE-2150PM | F-PH | SAMPLE STATION F | 10/4/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/4/00 | 0.00 | 1 vial | Ice | **TO-6m** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |
| Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | 11/16/00 9:22 AM |

100400 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1005E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, E. Diaz, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/7/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001005-PUFAE-2574 | AC, ED | PARCEL E, STATION A | 10/5/00 | 324.62 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001005-PUFBE-2575 | AC, ED | PARCEL E, STATION B | 10/5/00 | 322.10 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001005-PUFCE-2576 | AC, ED | PARCEL E, STATION C. | 10/5/00 | 328.24 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001005-PUFDE-2577 | AC, ED | PARCEL E, STATION D | 10/5/00 | 328.70 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001005-PUFEE-2578 | AC, ED | PARCEL E, STATION E | 10/5/00 | 327.23 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001005-PUFFE-2579 | AC, ED | PARCEL E, STATION F | 10/5/00 | 324.85 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001005-PUFGE-2580 | AC, ED | PARCEL E, STATION G | 10/5/00 | 326.62 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | AC, ED | PARCEL E, PUF-BLANK | 10/5/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001005-VOCAE-A702 | AC, ED | PARCEL E, STATION A | 10/5/00 | 6.00 psi | SUMMA | None | TO-14a See Note | | |
| 001005-VOCBE-A804 | AC, ED | PARCEL E, STATION B | 10/5/00 | 0.00 | " | " | TO-14a | | |
| 001005-VOCCE-A502 | AC, ED | PARCEL E, STATION C | 10/5/00 | 9.00 | " | " | TO-14a | | |
| 001005-VOCDE-A811 | AC, ED | PARCEL E, STATION D | 10/5/00 | 14.00 | " | " | TO-14a | | |
| 001005-VOCEE-A204 | AC, ED | PARCEL E, STATION E | 10/5/00 | 0.00 | " | " | TO-14a | | |
| 001005-VOCFE-A509 | AC, ED | PARCEL E, STATION F | 10/5/00 | 1.50 | " | " | TO-14a | | |
| 001005-VOCGE-A606 | AC, ED | PARCEL E, STATION G | 10/5/00 | 3.50 | " | " | TO-14a | | |
| NOT COLLECTED | AC, ED | PARCEL E, VOC-BLANK | 10/5/00 | NA | " | " | TO-14a | | |
| 001005-TSPAE-7337 | AC, ED | PARCEL E, STATION A | 10/5/00 | 1772.73 | Envelope | " | Full Suite Metals | | |
| 001005-TSPBE-7338 | AC, ED | PARCEL E, STATION B | 10/5/00 | 1778.16 | " | " | Full Suite Metals | | |
| 001005-TSPCE-7339 | AC, ED | PARCEL E, STATION C | 10/5/00 | 1776.11 | " | " | Full Suite Metals | | |
| 001005-TSPDE-7340 | AC, ED | PARCEL E, STATION D | 10/5/00 | 1784.11 | " | " | Full Suite Metals | | |
| 001005-TSPEE-7341 | AC, ED | PARCEL E, STATION E | 10/5/00 | 1783.14 | " | " | Full Suite Metals | | |
| 001005-TSPFE-7342 | AC, ED | PARCEL E, STATION F | 10/5/00 | 1785.23 | " | " | Full Suite Metals | | |
| 001005-TSPGE-7343 | AC, ED | PARCEL E, STATION G | 10/5/00 | 1781.39 | | | Full Suite Metals | | |
| NOT COLLECTED | AC, ED | PARCEL E, TSP-BLANK | 10/5/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

100500.COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1005hcl



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/6/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 001005-HCLAE-2095 | A-Chlorine | SAMPLE STATION A | 10/5/00 | 1648.80 | 3 vials | None | **TO-0051m** | | | |
| 001005-HCLBE-2096 | B-Chlorine | SAMPLE STATION B | 10/5/00 | 1447.20 | 3 vials | None | **TO-0051m** | | | |
| 001005-HCLCE-2097 | C- Chlorine | SAMPLE STATION C | 10/5/00 | 1555.20 | 3 vials | None | **TO-0051m** | | | |
| 001005-HCLDE-2098 | D-Chlorine | SAMPLE STATION D | 10/5/00 | 1447.20 | 3 vials | None | **TO-0051m** | | | |
| 001005-HCLEE-2099 | E-Chlorine | SAMPLE STATION E | 10/5/00 | 1497.60 | 3 vials | None | **TO-0051m** | | | |
| 001005-HCLFE-2100 | F-Chlorine | SAMPLE STATION F | 10/5/00 | 1548.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 10/5/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | hlorine Blank | Blank | 10/5/00 | NA | 3 vials | None | **TO-0051m** | | | |
| 001005-PHAE-2151AM | A-PH | SAMPLE STATION A | 10/5/00 | 52.50 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHBE-2152AM | B-PH | SAMPLE STATION B | 10/5/00 | 54.00 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHCE-2153AM | C-PH | SAMPLE STATION C | 10/5/00 | 50.50 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHDE-2154AM | D-PH | SAMPLE STATION D | 10/5/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHEE-2155AM | E-PH | SAMPLE STATION E | 10/5/00 | 51.00 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHFE-2156AM | F-PH | SAMPLE STATION F | 10/5/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/5/00 | #REF! | 1 vial | Ice | **TO-6m** | | | |
| 001005PHAE-2157PM | A-PH | SAMPLE STATION A | 10/5/00 | 52.50 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHBE-2158PM | B-PH | SAMPLE STATION B | 10/5/00 | 55.50 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHCE-2159PM | C-PH | SAMPLE STATION C | 10/5/00 | 51.00 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHDE-2160PM | D-PH | SAMPLE STATION D | 10/5/00 | 51.50 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHEE-2161PM | E-PH | SAMPLE STATION E | 10/5/00 | 50.50 | 1 vial | Ice | **TO-6m** | | | |
| 001005-PHFE-2162PM | F-PH | SAMPLE STATION F | 10/5/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/5/00 | 0.00 | 1 vial | Ice | **TO-6m** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |
| Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) | Formulas Verified 10/16/97 | | 11/16/00 9:22 AM |

100500 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1006



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Womack, A. Cortez, E. Diaz, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/8/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001006-PUFAE-2587 | AC, ED | PARCEL E, STATION A | 10/6/00 | 319.65 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001006-PUFBE-2588 | AC, ED | PARCEL E, STATION B | 10/6/00 | 320.59 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001006-PUFCE-2589 | AC, ED | PARCEL E, STATION C. | 10/6/00 | 325.44 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001006-PUFDE-2590 | AC, ED | PARCEL E, STATION D | 10/6/00 | 325.68 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001006-PUFEE-2591 | AC, ED | PARCEL E, STATION E | 10/6/00 | 320.25 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001006-PUFFE-2592 | AC, ED | PARCEL E, STATION F | 10/6/00 | 323.12 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | AC, ED | PARCEL E, STATION G | 10/6/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001006-FBEPUF-2593 | AC, ED | PARCEL E, PUF-BLANK | 10/6/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001006-VOCAE-A105 | AC, ED | PARCEL E, STATION A | 10/6/00 | 6.00 psi | SUMMA | None | TO-14a See Note | | |
| 001006-VOCBE-A704 | AC, ED | PARCEL E, STATION B | 10/6/00 | 0.00 | " | " | TO-14a | | |
| 001006-VOCCE-A432 | AC, ED | PARCEL E, STATION C | 10/6/00 | 5.00 | " | " | TO-14a | | |
| 001006-VOCDE-A602 | AC, ED | PARCEL E, STATION D | 10/6/00 | 2.00 | " | " | TO-14a | | |
| 001006-VOCEE-A508 | AC, ED | PARCEL E, STATION E | 10/6/00 | 0.00 | " | " | TO-14a | | |
| 001006-VOCFE-A306 | AC, ED | PARCEL E, STATION F | 10/6/00 | 1.80 | " | " | TO-14a | | |
| NOT COLLECTED | AC, ED | PARCEL E, STATION G | 10/6/00 | 0.00 | " | " | TO-14a | | |
| 001006-FBEVOC-A102 | AC, ED | PARCEL E, VOC-BLANK | 10/6/00 | NA | " | " | TO-14a | | |
| 001006-TSPAE-7350 | AC, ED | PARCEL E, STATION A | 10/6/00 | 1765.43 | Envelope | " | Full Suite Metals | | |
| 001006-TSPBE-7351 | AC, ED | PARCEL E, STATION B | 10/6/00 | 1765.72 | " | " | Full Suite Metals | | |
| 001006-TSPCE-7352 | AC, ED | PARCEL E, STATION C | 10/6/00 | 1762.88 | " | " | Full Suite Metals | | |
| 001006-TSPDE-7353 | AC, ED | PARCEL E, STATION D | 10/6/00 | 1772.11 | " | " | Full Suite Metals | | |
| 001006-TSPEE-7354 | AC, ED | PARCEL E, STATION E | 10/6/00 | 1774.52 | " | " | Full Suite Metals | | |
| 001006-TSPFE-7355 | AC, ED | PARCEL E, STATION F | 10/6/00 | 1778.35 | " | " | Full Suite Metals | | |
| NOT COLLECTED | AC, ED | PARCEL E, STATION G | 10/6/00 | 0.00 | | | Full Suite Metals | | |
| 001006-FBETSP-7356 | AC, ED | PARCEL E, TSP-BLANK | 10/6/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

100600 COC
H. Bowles, Excel 5/7 Win 95
ISP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1006HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/7/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 001006-HCLAE-2101 | A-Chlorine | SAMPLE STATION A | 10/6/00 | 1641.60 | 3 vials | None | **TO-0051m** | | | |
| 001006-HCLBE-2102 | B-Chlorine | SAMPLE STATION B | 10/6/00 | 1468.80 | 3 vials | None | **TO-0051m** | | | |
| 001006-HCLCE-2103 | C- Chlorine | SAMPLE STATION C | 10/6/00 | 1454.40 | 3 vials | None | **TO-0051m** | | | |
| 001006-HCLDE-2104 | D-Chlorine | SAMPLE STATION D | 10/6/00 | 1490.40 | 3 vials | None | **TO-0051m** | | | |
| 001006-HCLEE-2105 | E-Chlorine | SAMPLE STATION E | 10/6/00 | 1562.40 | 3 vials | None | **TO-0051m** | | | |
| 001006-HCLFE-2106 | F-Chlorine | SAMPLE STATION F | 10/6/00 | 1598.40 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | G-Chlorine | SAMPLE STATION G | 10/6/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | hlorine Blank | Blank | 10/6/00 | NA | 3 vials | None | **TO-0051m** | | | |
| 001006-PHAE-2163AM | A-PH | SAMPLE STATION A | 10/6/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHBE-2164AM | B-PH | SAMPLE STATION B | 10/6/00 | 55.50 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHCE-2165AM | C-PH | SAMPLE STATION C | 10/6/00 | 51.00 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHDE-2166AM | D-PH | SAMPLE STATION D | 10/6/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHEE-2167AM | E-PH | SAMPLE STATION E | 10/6/00 | 51.50 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHFE-2168AM | F-PH | SAMPLE STATION F | 10/6/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/6/00 | #REF! | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHAE-2169PM | A-PH | SAMPLE STATION A | 10/6/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHBE-2170PM | B-PH | SAMPLE STATION B | 10/6/00 | 55.50 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHCE-2171PM | C-PH | SAMPLE STATION C | 10/6/00 | 51.50 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHDE-2172PM | D-PH | SAMPLE STATION D | 10/6/00 | 51.00 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHEE-2173PM | E-PH | SAMPLE STATION E | 10/6/00 | 51.00 | 1 vial | Ice | **TO-6m** | | | |
| 001006-PHFE-2174PM | F-PH | SAMPLE STATION F | 10/6/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | G-PH | SAMPLE STATION G | 10/6/00 | 0.00 | 1 vial | Ice | **TO-6m** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

100600.COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

11/16/00 9:22 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1007



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Womack, A. Cortez, E. Diaz, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/9/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001007-PUFAE-2594 | AC, ED | PARCEL E, STATION A | 10/7/00 | 319.54 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001007-PUFBE-2595 | AC, ED | PARCEL E, STATION B | 10/7/00 | 320.72 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001007-PUFCE-2596 | AC, ED | PARCEL E, STATION C. | 10/7/00 | 325.58 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001007-PUFDE-2597 | AC, ED | PARCEL E, STATION D | 10/7/00 | 324.88 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001007-PUFEE-2598 | AC, ED | PARCEL E, STATION E | 10/7/00 | 328.32 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001007-PUFFE-2599 | AC, ED | PARCEL E, STATION F | 10/7/00 | 321.62 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001007-PUFGE-2600 | AC, ED | PARCEL E, STATION G | 10/7/00 | 322.72 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | AC, ED | PARCEL E, PUF-BLANK | 10/7/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001007-VOCAE-A112 | AC, ED | PARCEL E, STATION A | 10/7/00 | 6.10 psi | SUMMA | None | TO-14a See Note | | |
| 001007-VOCBE-A636 | AC, ED | PARCEL E, STATION B | 10/7/00 | 0.00 | " | " | TO-14a | | |
| 001007-VOCCE-A810 | AC, ED | PARCEL E, STATION C | 10/7/00 | 6.50 | " | " | TO-14a | | |
| 001007-VOCDE-A101 | AC, ED | PARCEL E, STATION D | 10/7/00 | 0.00 | " | " | TO-14a | | |
| 001007-VOCEE-A414 | AC, ED | PARCEL E, STATION E | 10/7/00 | 0.00 | " | " | TO-14a | | |
| 001007-VOCFE-A202 | AC, ED | PARCEL E, STATION F | 10/7/00 | 1.50 | " | " | TO-14a | | |
| 001007-VOCGE-A914 | AC, ED | PARCEL E, STATION G | 10/7/00 | 4.00 | " | " | TO-14a | | |
| NOT COLLECTED | AC, ED | PARCEL E, VOC-BLANK | 10/7/00 | NA | " | " | TO-14a | | |
| 001007-TSPAE-7357 | AC, ED | PARCEL E, STATION A | 10/7/00 | 1762.89 | Envelope | " | Full Suite Metals | | |
| 001007-TSPBE-7358 | AC, ED | PARCEL E, STATION B | 10/7/00 | 1769.70 | " | " | Full Suite Metals | | |
| 001007-TSPCE-7359 | AC, ED | PARCEL E, STATION C | 10/7/00 | 1761.47 | " | " | Full Suite Metals | | |
| 001007-TSPDE-7360 | AC, ED | PARCEL E, STATION D | 10/7/00 | 1765.58 | " | " | Full Suite Metals | | |
| 001007-TSPEE-7361 | AC, ED | PARCEL E, STATION E | 10/7/00 | 1758.05 | " | " | Full Suite Metals | | |
| 001007-TSPFE-7362 | AC, ED | PARCEL E, STATION F | 10/7/00 | 1761.61 | " | " | Full Suite Metals | | |
| 001007-TSPGE-7363 | AC, ED | PARCEL E, STATION G | 10/7/00 | 1761.61 | | | Full Suite Metals | | |
| NOT COLLECTED | AC, ED | PARCEL E, TSP-BLANK | 10/7/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

100700 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-285 Sample 001007-TSPEE-7361 ran slightly less than 23 hours. 11/9/00 10:00 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1007-HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, S. McNerney, B. Womack, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/8/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00000 | | SAMPLE STATION A | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | | SAMPLE STATION B | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | | SAMPLE STATION C | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | | SAMPLE STATION D | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | | SAMPLE STATION E | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| 0000000 | | SAMPLE STATION F | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | | SAMPLE STATION G | 1/0/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | | Blank | 1/0/00 | NA | 3 vials | None | TO-0051m | | | |
| 001007-PHAE-2175 | SM | SAMPLE STATION A | 10/7/00 | 53.50 | 1 vial | Ice | TO-6m | | | |
| 001007-PHBE-2176 | SM | SAMPLE STATION B | 10/7/00 | 54.50 | 1 vial | Ice | TO-6m | | | |
| 001007-PHCE-2177 | SM | SAMPLE STATION C | 10/7/00 | 52.50 | 1 vial | Ice | TO-6m | | | |
| 001007-PHDE-2178 | SM | SAMPLE STATION D | 10/7/00 | 52.50 | 1 vial | Ice | TO-6m | | | |
| 001007-PHEE-2179 | SM | SAMPLE STATION E | 10/7/00 | 51.00 | 1 vial | Ice | TO-6m | | | |
| 001007-PHFE-2180 | SM | SAMPLE STATION F | 10/7/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/7/00 | #REF! | 1 vial | Ice | TO-6m | | | |
| 001007-PHAE-2181 | SM | SAMPLE STATION A | 10/7/00 | 53.00 | 1 vial | Ice | TO-6m | | | |
| 001007-PHBE-2182 | SM | SAMPLE STATION B | 10/7/00 | 54.50 | 1 vial | Ice | TO-6m | | | |
| 001007-PHCE-2183 | SM | SAMPLE STATION C | 10/7/00 | 50.50 | 1 vial | Ice | TO-6m | | | |
| 001007-PHDE-2184 | SM | SAMPLE STATION D | 10/7/00 | 51.00 | 1 vial | Ice | TO-6m | | | |
| 001007-PHEE-2185 | SM | SAMPLE STATION E | 10/7/00 | 50.00 | 1 vial | Ice | TO-6m | | | |
| 001007-PHFE-2186 | SM | SAMPLE STATION F | 10/7/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/7/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaroun |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1008



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Womack, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/10/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001008-PUFAE-2601 | BW, ED | PARCEL E, STATION A | 10/8/00 | 323.04 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001008-PUFBE-2602 | BW, ED | PARCEL E, STATION B | 10/8/00 | 322.37 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001008-PUFCE-2603 | BW, ED | PARCEL E, STATION C. | 10/8/00 | 328.18 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001008-PUFDE-2604 | BW, ED | PARCEL E, STATION D | 10/8/00 | 323.33 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001008-PUFEE-2605 | BW, ED | PARCEL E, STATION E | 10/8/00 | 325.61 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001008-PUFFE-2606 | BW, ED | PARCEL E, STATION F | 10/8/00 | 320.07 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | NA | NA | NA | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001008-FBEPUF-2607 | BW, ED | PARCEL E, PUF-BLANK | 10/8/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001008-VOCAE-A-805 | BW, ED | PARCEL E, STATION A | 10/8/00 | 6.50 psi | SUMMA | None | TO-14a See Note | | |
| 001008-VOCBE-A-301 | BW, ED | PARCEL E, STATION B | 10/8/00 | 0.00 | " | " | TO-14a | | |
| 001008-VOCCE-A-604 | BW, ED | PARCEL E, STATION C | 10/8/00 | 6.00 | " | " | TO-14a | | |
| 001008-VOCDE-A-603 | BW, ED | PARCEL E, STATION D | 10/8/00 | 2.50 | " | " | TO-14a | | |
| 001008-VOCEE-A-303 | BW, ED | PARCEL E, STATION E | 10/8/00 | 0.00 | " | " | TO-14a | | |
| 001008-VOCFE-A-426 | BW, ED | PARCEL E, STATION F | 10/8/00 | 12.00 | " | " | TO-14a | | |
| NOT COLLECTED | NA | NA | NA | NA | " | " | TO-14a | | |
| 001008-FBEVOC-A-703 | BW, ED | PARCEL E, VOC-BLANK | 10/8/00 | NA | " | " | TO-14a | | |
| 001008-TSPAE-7364 | BW, ED | PARCEL E, STATION A | 10/8/00 | 1761.97 | Envelope | " | Full Suite Metals | | |
| 001008-TSPBE-7365 | BW, ED | PARCEL E, STATION B | 10/8/00 | 1767.35 | " | " | Full Suite Metals | | |
| 001008-TSPCE-7366 | BW, ED | PARCEL E, STATION C | 10/8/00 | 1759.43 | " | " | Full Suite Metals | | |
| 001008-TSPDE-7367 | BW, ED | PARCEL E, STATION D | 10/8/00 | 1758.43 | " | " | Full Suite Metals | | |
| 001008-TSPEE-7370 | BW, ED | PARCEL E, STATION E | 10/8/00 | 1758.43 | " | " | Full Suite Metals | | |
| 001008-TSPFE-7371 | BW, ED | PARCEL E, STATION F | 10/8/00 | 1755.61 | " | " | Full Suite Metals | | |
| NOT COLLECTED | NA | NA | NA | NA | | | Full Suite Metals | | |
| 001008-FBETSP-7372 | BW, ED | PARCEL E, TSP-BLANK | 10/8/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

100800 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

11/9/00 10:00 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1009



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Womack, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/11/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001009-PUFAE-2608 | BW, ED | PARCEL E, STATION A | 10/9/00 | 319.71 | Jar & Envelope | ICE | O-4 & TO-13 & TO-9m | | |
| 001009-PUFBE-2609 | BW, ED | PARCEL E, STATION B | 10/9/00 | 321.31 | " | " | O-4 & TO-13 & TO-9m | | |
| 001009-PUFCE-2610 | BW, ED | PARCEL E, STATION C. | 10/9/00 | 331.97 | " | " | O-4 & TO-13 & TO-9m | | |
| 001009-PUFDE-2611 | BW, ED | PARCEL E, STATION D | 10/9/00 | 315.20 | " | " | O-4 & TO-13 & TO-9m | | |
| 001009-PUFEE-2612 | BW, ED | PARCEL E, STATION E | 10/9/00 | 322.25 | " | " | O-4 & TO-13 & TO-9m | | |
| 001009-PUFFE-2613 | BW, ED | PARCEL E, STATION F | 10/9/00 | 322.24 | " | " | O-4 & TO-13 & TO-9m | | |
| 001009-PUFGE-2614 | BW, ED | PARCEL E, STATION G | 10/9/00 | 315.96 | " | " | O-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | NA | NA | NA | NA | " | " | O-4 & TO-13 & TO-9m | | |
| 001009-VOCAE-A809 | BW, ED | PARCEL E, STATION A | 10/9/00 | 7.00 psi | SUMMA | None | TO-14a See Note | | |
| 001009-VOCBE-A420 | BW, ED | PARCEL E, STATION B | 10/9/00 | 22.00 | " | " | TO-14a | | |
| VOID | BW, ED | PARCEL E, STATION C | 10/9/00 | 0.00 | " | " | TO-14a | | |
| 001009-VOCDE-A637 | BW, ED | PARCEL E, STATION D | 10/9/00 | 2.00 | " | " | TO-14a | | |
| VOID | BW, ED | PARCEL E, STATION E | 10/9/00 | 0.00 | " | " | TO-14a | | |
| VOID | BW, ED | PARCEL E, STATION F | 10/9/00 | 0.00 | " | " | TO-14a | | |
| VOID | BW, ED | PARCEL E, STATION G | 10/9/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | NA | NA | NA | NA | " | " | TO-14a | | |
| 001009-TSPAE-7373 | BW, ED | PARCEL E, STATION A | 10/9/00 | 1762.08 | Envelope | " | Full Suite Metals | | |
| 001009-TSPBE-7374 | BW, ED | PARCEL E, STATION B | 10/9/00 | 1770.15 | " | " | Full Suite Metals | | |
| 001009-TSPCE-7375 | BW, ED | PARCEL E, STATION C | 10/9/00 | 1777.34 | " | " | Full Suite Metals | | |
| 001009-TSPDE-7376 | BW, ED | PARCEL E, STATION D | 10/9/00 | 1785.30 | " | " | Full Suite Metals | | |
| 001009-TSPEE-7377 | BW, ED | PARCEL E, STATION E | 10/9/00 | 1777.65 | " | " | Full Suite Metals | | |
| 001009-TSPFE-7378 | BW, ED | PARCEL E, STATION F | 10/9/00 | 1766.04 | " | " | Full Suite Metals | | |
| 001009-TSPGE-7379 | BW, ED | PARCEL E, STATION G | 10/9/00 | 1785.14 | | | Full Suite Metals | | |
| NOT COLLECTED | NA | NA | NA | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning 4 VOID SUMMA canisters and 7 SUMMA regulators for maintenance.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarou | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1009-HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, L. Leet
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/10/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 001009-HCLAE-2107 | SMC | SAMPLE STATION A | 10/9/00 | 1684.80 | 3 vials | None | TO-0051m | | | |
| 001009-HCLBE-2108 | SMC | SAMPLE STATION B | 10/9/00 | 1540.80 | 3 vials | None | TO-0051m | | | |
| 001009-HCLCE-2109 | SMC | SAMPLE STATION C | 10/9/00 | 1483.20 | 3 vials | None | TO-0051m | | | |
| 001009-HCLDE-2110 | SMC | SAMPLE STATION D | 10/9/00 | 1533.60 | 3 vials | None | TO-0051m | | | |
| 001009-HCLEE-2111 | SMC | SAMPLE STATION E | 10/9/00 | 1569.60 | 3 vials | None | TO-0051m | | | |
| 001009-HCLFE-2112 | SMC | SAMPLE STATION F | 10/9/00 | 1548.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | | SAMPLE STATION G | 10/9/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | | Blank | 10/9/00 | NA | 3 vials | None | TO-0051m | | | |
| 001009-PHAE-2187 | SMC | SAMPLE STATION A | 10/9/00 | 52.50 | 1 vial | Ice | TO-6m | | | |
| 001009-PHBE-2188 | SMC | SAMPLE STATION B | 10/9/00 | 54.00 | 1 vial | Ice | TO-6m | | | |
| 001009-PHCE-2189 | SMC | SAMPLE STATION C | 10/9/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| 001009-PHDE-2190 | SMC | SAMPLE STATION D | 10/9/00 | 53.00 | 1 vial | Ice | TO-6m | | | |
| 001009-PHEE-2191 | SMC | SAMPLE STATION E | 10/9/00 | 51.00 | 1 vial | Ice | TO-6m | | | |
| 001009-PHFE-2192 | SMC | SAMPLE STATION F | 10/9/00 | 53.50 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/9/00 | #REF! | 1 vial | Ice | TO-6m | | | |
| 001009-PHAE-2193 | SMC | SAMPLE STATION A | 10/9/00 | 52.50 | 1 vial | Ice | TO-6m | | | |
| 001009-PHBE-2194 | SMC | SAMPLE STATION B | 10/9/00 | 53.50 | 1 vial | Ice | TO-6m | | | |
| 001009-PHCE-2195 | SMC | SAMPLE STATION C | 10/9/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| 001009-PHDE-2196 | SMC | SAMPLE STATION D | 10/9/00 | 53.00 | 1 vial | Ice | TO-6m | | | |
| 001009-PHEE-2197 | SMC | SAMPLE STATION E | 10/9/00 | 50.00 | 1 vial | Ice | TO-6m | | | |
| 001009-PHFE-2198 | SMC | SAMPLE STATION F | 10/9/00 | 52.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/9/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaroun |
| QC Level: | See PAM | | | | |
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101011



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Womack, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/12/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001010-PUFAE-2615 | BW, ED | PARCEL E, STATION A | 10/10/00 | 335.72 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001010-PUFBE-2616 | BW, ED | PARCEL E, STATION B | 10/10/00 | 331.91 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001010-PUFCE-2617 | BW, ED | PARCEL E, STATION C. | 10/10/00 | 348.18 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001010-PUFDE-2618 | BW, ED | PARCEL E, STATION D | 10/10/00 | 320.63 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001010-PUFEE-2619 | BW, ED | PARCEL E, STATION E | 10/10/00 | 313.18 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001010-PUFFE-2620 | BW, ED | PARCEL E, STATION F | 10/10/00 | 324.89 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | BW, ED | PARCEL E, STATION G | 10/10/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001010-FBEPUF-2621 | BW, ED | PARCEL E, PUF-BLANK | 10/10/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001010-VOCAE-A804 | BW, ED | PARCEL E, STATION A | 10/10/00 | 5.50 psi | SUMMA | None | TO-14a See Note | | |
| VOID | BW, ED | PARCEL E, STATION B | 10/10/00 | 0.00 | " | " | TO-14a | | |
| 001010-VOCCE-A705 | BW, ED | PARCEL E, STATION C | 10/10/00 | 20.00 | " | " | TO-14a | | |
| 001010-VOCDE-A503 | BW, ED | PARCEL E, STATION D | 10/10/00 | 1.00 | " | " | TO-14a | | |
| VOID | BW, ED | PARCEL E, STATION E | 10/10/00 | 0.00 | " | " | TO-14a | | |
| VOID | BW, ED | PARCEL E, STATION F | 10/10/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | BW, ED | PARCEL E, STATION G | 10/10/00 | 0.00 | " | " | TO-14a | | |
| 001010-FBEVOC-A425 | BW, ED | PARCEL E, VOC-BLANK | 10/10/00 | NA | " | " | TO-14a | | |
| 001010-TSPAE-7380 | BW, ED | PARCEL E, STATION A | 10/10/00 | 1842.35 | Envelope | " | Full Suite Metals | | |
| 001010-TSPBE-7381 | BW, ED | PARCEL E, STATION B | 10/10/00 | 1844.05 | " | " | Full Suite Metals | | |
| 001010-TSPCE-7382 | BW, ED | PARCEL E, STATION C | 10/10/00 | 1839.80 | " | " | Full Suite Metals | | |
| 001010-TSPDE-7383 | BW, ED | PARCEL E, STATION D | 10/10/00 | 1837.45 | " | " | Full Suite Metals | | |
| 001010-TSPEE-7384 | BW, ED | PARCEL E, STATION E | 10/10/00 | 1831.25 | " | " | Full Suite Metals | | |
| 001010-TSPFE-7385 | BW, ED | PARCEL E, STATION F | 10/10/00 | 1829.57 | " | " | Full Suite Metals | | |
| NOT COLLECTED | BW, ED | PARCEL E, STATION G | 10/10/00 | 0.00 | | | Full Suite Metals | | |
| 001010-FBETSP-7386 | BW, ED | PARCEL E, TSP-BLANK | 10/10/00 | NA | " | " | Full Suite Metals | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | ---------- | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning 3 VOID SUMMA canisters and empty base & acid containers.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarou | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

10101100 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/9/00 10:00 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101011HR



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Womack, A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/12/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001010-PUFHRA-2020 | BW, ED | PARCEL E, STATION A | 10/10/00 | 336.13 | Jar | ICE | TO-9 | | |
| 001010-PUFHRB-2021 | BW, ED | PARCEL E, STATION B | 10/10/00 | 330.58 | " | " | TO-9 | | |
| 001010-PUFHRC-2022 | BW, ED | PARCEL E, STATION C. | 10/10/00 | 326.65 | " | " | TO-9 | | |
| 001010-PUFHRD-2023 | BW, ED | PARCEL E, STATION D | 10/10/00 | 317.61 | " | " | TO-9 | | |
| 001010-PUFHRE-2024 | BW, ED | PARCEL E, STATION E | 10/10/00 | 322.35 | " | " | TO-9 | | |
| 001010-PUFHRF-2025 | BW, ED | PARCEL E, STATION F | 10/10/00 | 318.12 | " | " | TO-9 | | |
| 001010-PUFHRG-2026 | BW, ED | PARCEL E, STATION G | 10/10/00 | 322.42 | " | " | TO-9 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 10/10/00 | NA | " | " | TO-9 | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour | QC Level: | See PAM |
|---|---|---|---|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | | Date: Time: | |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | | Date: Time: | |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | | Date: Time: | |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101112



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/13/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 001011-PUFAE-2622 | AC, ED | PARCEL E, STATION A | 10/11/00 | 338.38 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 001011-PUFBE-2623 | AC, ED | PARCEL E, STATION B | 10/11/00 | 335.55 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001011-PUFCE-2624 | AC, ED | PARCEL E, STATION C. | 10/11/00 | 357.31 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001011-PUFDE-2625 | AC, ED | PARCEL E, STATION D | 10/11/00 | 329.32 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001011-PUFEE-2626 | AC, ED | PARCEL E, STATION E | 10/11/00 | 330.14 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001011-PUFFE-2627 | AC, ED | PARCEL E, STATION F | 10/11/00 | 337.42 | " | " | TO-4 & TO-13 & TO-9m | | |
| 001011-PUFGE-2628 | AC, ED | PARCEL E, STATION G | 10/11/00 | 333.80 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 10/11/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 001011-VOCAE-A602 | AC, ED | PARCEL E, STATION A | 10/11/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 001011-VOCBE-A513 | AC, ED | PARCEL E, STATION B | 10/11/00 | 3.00 | " | " | TO-14a | | |
| 001011-VOCCE-A429 | AC, ED | PARCEL E, STATION C | 10/11/00 | 6.00 | " | " | TO-14a | | |
| 001011-VOCDE-A704 | AC, ED | PARCEL E, STATION D | 10/11/00 | 0.00 | " | " | TO-14a | | |
| 001011-VOCEE-A802 | AC, ED | PARCEL E, STATION E | 10/11/00 | 3.00 | " | " | TO-14a | | |
| 001011-VOCFE-A808 | AC, ED | PARCEL E, STATION F | 10/11/00 | 7.00 | " | " | TO-14a | | |
| 001011-VOCGE-A605 | AC, ED | PARCEL E, STATION G | 10/11/00 | 8.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 10/11/00 | NA | " | " | TO-14a | | |
| 001011-TSPAE-7387 | AC, ED | PARCEL E, STATION A | 10/11/00 | 1865.12 | Envelope | " | Full Suite Metals | | |
| 001011-TSPBE-7388 | AC, ED | PARCEL E, STATION B | 10/11/00 | 1878.62 | " | " | Full Suite Metals | | |
| VOID | | PARCEL E, STATION C | 10/11/00 | 0.00 | " | " | Full Suite Metals | | |
| 001011-TSPDE-7390 | AC, ED | PARCEL E, STATION D | 10/11/00 | 1886.55 | " | " | Full Suite Metals | | |
| 001011-TSPEE-7391 | AC, ED | PARCEL E, STATION E | 10/11/00 | 1900.68 | " | " | Full Suite Metals | | |
| 001011-TSPFE-7392 | AC, ED | PARCEL E, STATION F | 10/11/00 | 1907.88 | " | " | Full Suite Metals | | |
| 001011-TSPGE-7393 | AC, ED | PARCEL E, STATION G | 10/11/00 | 1917.63 | | | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 10/11/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) 11/9/00 10:00 AM

10111200 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 1011HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, L. Leet
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/12/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00101112-HCLAE-2113 | SMC | SAMPLE STATION A | 10/11/00 | 1512.00 | 3 vials | None | **TO-0051m** | | | |
| 00101112-HCLBE-2114 | SMC | SAMPLE STATION B | 10/11/00 | 1548.00 | 3 vials | None | **TO-0051m** | | | |
| 00101112-HCLCE-2115 | SMC | SAMPLE STATION C | 10/11/00 | 1476.00 | 3 vials | None | **TO-0051m** | | | |
| 00101112-HCLDE-2116 | SMC | SAMPLE STATION D | 10/11/00 | 1526.40 | 3 vials | None | **TO-0051m** | | | |
| 00101112-HCLEE-2117 | SMC | SAMPLE STATION E | 10/11/00 | 1548.00 | 3 vials | None | **TO-0051m** | | | |
| 00101112-HCLFE-2118 | SMC | SAMPLE STATION F | 10/11/00 | 1598.40 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | | SAMPLE STATION G | 10/11/00 | 0.00 | 3 vials | None | **TO-0051m** | | | |
| Not Collected | | Blank | 10/11/00 | NA | 3 vials | None | **TO-0051m** | | | |
| 001011-PHAE-2199 | SMC | SAMPLE STATION A | 10/11/00 | 53.00 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHBE-2200 | SMC | SAMPLE STATION B | 10/11/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHCE-2201 | SMC | SAMPLE STATION C | 10/11/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHDE-2202 | SMC | SAMPLE STATION D | 10/11/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHEE-2203 | SMC | SAMPLE STATION E | 10/11/00 | 50.50 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHFE-2204 | SMC | SAMPLE STATION F | 10/11/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | | SAMPLE STATION G | 10/11/00 | #REF! | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHAE-2205 | SMC | SAMPLE STATION A | 10/11/00 | 52.00 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHBE-2206 | SMC | SAMPLE STATION B | 10/11/00 | 53.50 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHCE-2207 | SMC | SAMPLE STATION C | 10/11/00 | 51.00 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHDE-2208 | SMC | SAMPLE STATION D | 10/11/00 | 50.50 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHEE-2209 | SMC | SAMPLE STATION E | 10/11/00 | 50.50 | 1 vial | Ice | **TO-6m** | | | |
| 001011-PHFE-2210 | SMC | SAMPLE STATION F | 10/11/00 | 54.00 | 1 vial | Ice | **TO-6m** | | | |
| Not collected | | SAMPLE STATION G | 10/11/00 | 0.00 | 1 vial | Ice | **TO-6m** | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnaroun | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809) Formulas Verified 10/16/97

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101213



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/14/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00101213-PUFAE-2634 | | PARCEL E, STATION A | 10/12/00 | 329.81 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00101213-PUFBE-2635 | | PARCEL E, STATION B | 10/12/00 | 328.74 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101213-PUFCE-2636 | | PARCEL E, STATION C. | 10/12/00 | 338.99 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101213-PUFDE-2637 | | PARCEL E, STATION D | 10/12/00 | 323.37 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101213-PUFEE-2638 | | PARCEL E, STATION E | 10/12/00 | 327.27 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101213-PUFFE-2668 | | PARCEL E, STATION F | 10/12/00 | 323.02 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/12/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101213-FBEPUF-2669 | | PARCEL E, PUF-BLANK | 10/12/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101213-VOCAE-A508 | | PARCEL E, STATION A | 10/12/00 | 2.00 psi | SUMMA | None | TO-14a See Note | | |
| 00101213-VOCBE-A112 | | PARCEL E, STATION B | 10/12/00 | 0.00 | " | " | TO-14a | | |
| 0101213-VOCCE-A636 | | PARCEL E, STATION C | 10/12/00 | 5.00 | " | " | TO-14a | | |
| 0101213-VOCDE-A105 | | PARCEL E, STATION D | 10/12/00 | 3.00 | " | " | TO-14a | | |
| 00101213-VOCEE-A432 | | PARCEL E, STATION E | 10/12/00 | 3.00 | " | " | TO-14a | | |
| 00101213-VOCFE-A507 | | PARCEL E, STATION F | 10/12/00 | 17.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/12/00 | 0.00 | " | " | TO-14a | | |
| 00101213-FBEVOC-A306 | | PARCEL E, VOC-BLANK | 10/12/00 | NA | " | " | TO-14a | | |
| 00101213-TSPAE-7400 | | PARCEL E, STATION A | 10/12/00 | 1810.48 | Envelope | " | Full Suite Metals | | |
| 00101213-TSPBE-7401 | | PARCEL E, STATION B | 10/12/00 | 1805.66 | " | " | Full Suite Metals | | |
| 00101213-TSPCE-7406 | | PARCEL E, STATION C | 10/12/00 | 1796.31 | " | " | Full Suite Metals | | |
| 00101213-TSPDE-7407 | | PARCEL E, STATION D | 10/12/00 | 1787.59 | " | " | Full Suite Metals | | |
| 00101213-TSPEE-7408 | | PARCEL E, STATION E | 10/12/00 | 1786.45 | " | " | Full Suite Metals | | |
| 00101213-TSPFE-7409 | | PARCEL E, STATION F | 10/12/00 | 1778.41 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/12/00 | 0.00 | | | Full Suite Metals | | |
| 00101213-FBETSP-7410 | | PARCEL E, TSP-BLANK | 10/12/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

10121300 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/9/00 10:00 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101314



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz, B. Womack
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/15/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00101314-PUFAE-2670 | | PARCEL E, STATION A | 10/13/00 | 320.08 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00101314-PUFBE-2671 | | PARCEL E, STATION B | 10/13/00 | 339.38 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101314-PUFCE-2672 | | PARCEL E, STATION C. | 10/13/00 | 342.03 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101314-PUFDE-2673 | | PARCEL E, STATION D | 10/13/00 | 345.27 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101314-PUFEE-2674 | | PARCEL E, STATION E | 10/13/00 | 344.44 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101314-PUFFE-2682 | | PARCEL E, STATION F | 10/13/00 | 330.62 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101314-PUFGE-2683 | | PARCEL E, STATION G | 10/13/00 | 348.51 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 10/13/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101314-VOCAE-202 | | PARCEL E, STATION A | 10/13/00 | 1.00 psi | SUMMA | None | TO-14a See Note | | |
| 00101314-VOCBE-430 | | PARCEL E, STATION B | 10/13/00 | 0.00 | " | " | TO-14a | | |
| 00101314-VOCCE-601 | | PARCEL E, STATION C | 10/13/00 | 4.50 | " | " | TO-14a | | |
| 00101314-VOCDE-703 | | PARCEL E, STATION D | 10/13/00 | 2.50 | " | " | TO-14a | | |
| 00101314-VOCEE-428 | | PARCEL E, STATION E | 10/13/00 | 3.00 | " | " | TO-14a | | |
| 00101314-VOCFE-810 | | PARCEL E, STATION F | 10/13/00 | 23.00 | " | " | TO-14a | | |
| 00101314-VOCGE-102 | | PARCEL E, STATION G | 10/13/00 | 4.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 10/13/00 | NA | " | " | TO-14a | | |
| 00101314-TSPAE-7411 | | PARCEL E, STATION A | 10/13/00 | 1866.42 | Envelope | " | Full Suite Metals | | |
| 00101314-TSPBE-7412 | | PARCEL E, STATION B | 10/13/00 | 1865.56 | " | " | Full Suite Metals | | |
| 00101314-TSPCE-7413 | | PARCEL E, STATION C | 10/13/00 | 1855.89 | " | " | Full Suite Metals | | |
| 00101314-TSPDE-7414 | | PARCEL E, STATION D | 10/13/00 | 1858.90 | " | " | Full Suite Metals | | |
| 00101314-TSPEE-7415 | | PARCEL E, STATION E | 10/13/00 | 1853.44 | " | " | Full Suite Metals | | |
| 00101314-TSPFE-7416 | | PARCEL E, STATION F | 10/13/00 | 1841.41 | " | " | Full Suite Metals | | |
| 00101314-TSPGE-7417 | | PARCEL E, STATION G | 10/13/00 | 1850.47 | | | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 10/13/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| | | | |
|---|---|---|---|
| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

10131400 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

11/9/00 10:01 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101314-HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, L. Leet
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/14/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00101314-HCLAE-2119 | SMC | SAMPLE STATION A | 10/13/00 | 1468.80 | 3 vials | None | TO-0051m | | | |
| 00101314-HCLBE-2120 | SMC | SAMPLE STATION B | 10/13/00 | 1454.40 | 3 vials | None | TO-0051m | | | |
| 00101314-HCLCE-2121 | SMC | SAMPLE STATION C | 10/13/00 | 1447.20 | 3 vials | None | TO-0051m | | | |
| 00101314-HCLDE-2122 | SMC | SAMPLE STATION D | 10/13/00 | 1490.40 | 3 vials | None | TO-0051m | | | |
| 00101314-HCLEE-2123 | SMC | SAMPLE STATION E | 10/13/00 | 1526.40 | 3 vials | None | TO-0051m | | | |
| 00101314-HCLFE-2124 | SMC | SAMPLE STATION F | 10/13/00 | 1692.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | | SAMPLE STATION G | 10/13/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | | Blank | 10/13/00 | NA | 3 vials | None | TO-0051m | | | |
| 001013-PHAE-2211 | SMC | SAMPLE STATION A | 10/13/00 | 54.50 | 1 vial | Ice | TO-6m | | | |
| 001013-PHBE-2212 | SMC | SAMPLE STATION B | 10/13/00 | 50.50 | 1 vial | Ice | TO-6m | | | |
| 001013-PHCE-2213 | SMC | SAMPLE STATION C | 10/13/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| 001013-PHDE-2214 | SMC | SAMPLE STATION D | 10/13/00 | 52.50 | 1 vial | Ice | TO-6m | | | |
| 001013-PHEE-2215 | SMC | SAMPLE STATION E | 10/13/00 | 50.00 | 1 vial | Ice | TO-6m | | | |
| 001013-PHFE-2216 | SMC | SAMPLE STATION F | 10/13/00 | 53.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/13/00 | #REF! | 1 vial | Ice | TO-6m | | | |
| 001013-PHAE-2217 | SMC | SAMPLE STATION A | 10/13/00 | 50.00 | 1 vial | Ice | TO-6m | | | |
| 001013-PHBE-2218 | SMC | SAMPLE STATION B | 10/13/00 | 52.00 | 1 vial | Ice | TO-6m | | | |
| 001013-PHCE-2219 | SMC | SAMPLE STATION C | 10/13/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| 001013-PHDE-2220 | SMC | SAMPLE STATION D | 10/13/00 | 52.50 | 1 vial | Ice | TO-6m | | | |
| 001013-PHEE-2221 | SMC | SAMPLE STATION E | 10/13/00 | 51.00 | 1 vial | Ice | TO-6m | | | |
| 001013-PHFE-2222 | SMC | SAMPLE STATION F | 10/13/00 | 54.50 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/13/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaround |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101415



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: S. McNerney, B. Womack
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/16/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00101415-PUFAE-2684 | BW, SM | PARCEL E, STATION A | 10/14/00 | 340.15 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00101415-PUFBE-2685 | BW, SM | PARCEL E, STATION B | 10/14/00 | 340.60 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101415-PUFCE-2686 | BW, SM | PARCEL E, STATION C. | 10/14/00 | 352.16 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101415-PUFDE-2687 | BW, SM | PARCEL E, STATION D | 10/14/00 | 332.05 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101415-PUFEE-2688 | BW, SM | PARCEL E, STATION E | 10/14/00 | 346.55 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101415-PUFFE-2675 | BW, SM | PARCEL E, STATION F | 10/14/00 | 333.84 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/14/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101415-FBEPUF-2676 | BW, SM | PARCEL E, PUF-BLANK | 10/14/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101415-VOCAE-A914 | BW, SM | PARCEL E, STATION A | 10/14/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00101415-VOCBE-A421 | BW, SM | PARCEL E, STATION B | 10/14/00 | 0.00 | " | " | TO-14a | | |
| 0101415-VOCCE-A805 | BW, SM | PARCEL E, STATION C | 10/14/00 | 5.00 | " | " | TO-14a | | |
| 0101415-VOCDE-A433 | BW, SM | PARCEL E, STATION D | 10/14/00 | 1.00 | " | " | TO-14a | | |
| 00101415-VOCEE-A426 | BW, SM | PARCEL E, STATION E | 10/14/00 | 1.00 | " | " | TO-14a | | |
| 00101415-VOCFE-A603 | BW, SM | PARCEL E, STATION F | 10/14/00 | 18.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/14/00 | 0.00 | " | " | TO-14a | | |
| 00101415-FBEVOC-A604 | BW, SM | PARCEL E, VOC-BLANK | 10/14/00 | NA | " | " | TO-14a | | |
| 00101415-TSPAE-7418 | BW, SM | PARCEL E, STATION A | 10/14/00 | 1879.80 | Envelope | " | Full Suite Metals | | |
| 00101415-TSPBE-7419 | BW, SM | PARCEL E, STATION B | 10/14/00 | 1876.40 | " | " | Full Suite Metals | | |
| 00101415-TSPCE-7420 | BW, SM | PARCEL E, STATION C | 10/14/00 | 1874.67 | " | " | Full Suite Metals | | |
| 00101415-TSPDE-7421 | BW, SM | PARCEL E, STATION D | 10/14/00 | 1876.40 | " | " | Full Suite Metals | | |
| 00101415-TSPEE-7422 | BW, SM | PARCEL E, STATION E | 10/14/00 | 1891.80 | " | " | Full Suite Metals | | |
| 00101415-TSPFE-7423 | BW, SM | PARCEL E, STATION F | 10/14/00 | 1892.13 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/14/00 | 0.00 | | | Full Suite Metals | | |
| 00101415-FBETSP-7424 | BW, SM | PARCEL E, TSP-BLANK | 10/14/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning 1 SUMMA regulator for maintenance.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarou | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

10141500 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/9/00 9:59 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101516



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. Diaz, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/17/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00101516-PUFAE-2677 | AC, ED | PARCEL E, STATION A | 10/15/00 | 330.61 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00101516-PUFBE-2678 | AC, ED | PARCEL E, STATION B | 10/15/00 | 337.46 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101516-PUFCE-2679 | AC, ED | PARCEL E, STATION C. | 10/15/00 | 352.40 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101516-PUFDE-2680 | AC, ED | PARCEL E, STATION D | 10/15/00 | 332.43 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101516-PUFEE-2681 | AC, ED | PARCEL E, STATION E | 10/15/00 | 342.06 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101516-PUFFE-2689 | AC, ED | PARCEL E, STATION F | 10/15/00 | 311.22 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101516-PUFGE-2690 | AC, ED | PARCEL E, STATION G | 10/15/00 | 335.56 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 10/15/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101516-VOCAE-A503 | AC, ED | PARCEL E, STATION A | 10/15/00 | 1.00 psi | SUMMA | None | TO-14a See Note | | |
| 00101516-VOCBE-A637 | AC, ED | PARCEL E, STATION B | 10/15/00 | 0.00 | " | " | TO-14a | | |
| 0101516-VOCCE-A425 | AC, ED | PARCEL E, STATION C | 10/15/00 | 4.00 | " | " | TO-14a | | |
| 0101516-VOCDE-A705 | AC, ED | PARCEL E, STATION D | 10/15/00 | 2.00 | " | " | TO-14a | | |
| 00101516-VOCEE-A101 | AC, ED | PARCEL E, STATION E | 10/15/00 | 1.00 | " | " | TO-14a | | |
| 00101516-VOCFE-A303 | AC, ED | PARCEL E, STATION F | 10/15/00 | 17.00 | " | " | TO-14a | | |
| 0101516-VOCGE-A803 | AC, ED | PARCEL E, STATION G | 10/15/00 | 2.90 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 10/15/00 | NA | " | " | TO-14a | | |
| 00101516-TSPAE-7425 | AC, ED | PARCEL E, STATION A | 10/15/00 | 1862.85 | Envelope | " | Full Suite Metals | | |
| 00101516-TSPBE-7426 | AC, ED | PARCEL E, STATION B | 10/15/00 | 1868.95 | " | " | Full Suite Metals | | |
| 00101516-TSPCE-7427 | AC, ED | PARCEL E, STATION C | 10/15/00 | 1874.08 | " | " | Full Suite Metals | | |
| 00101516-TSPDE-7428 | AC, ED | PARCEL E, STATION D | 10/15/00 | 1875.37 | " | " | Full Suite Metals | | |
| 00101516-TSPEE-7429 | AC, ED | PARCEL E, STATION E | 10/15/00 | 1870.23 | " | " | Full Suite Metals | | |
| 00101516-TSPFE-7430 | AC, ED | PARCEL E, STATION F | 10/15/00 | 1871.30 | " | " | Full Suite Metals | | |
| 00101516-TSPGE-7431 | AC, ED | PARCEL E, STATION G | 10/15/00 | 1864.88 | | | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 10/15/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| | | | |
|---|---|---|---|
| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

10151600 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

11/9/00 10:01 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101617E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. Diaz, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/18/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00101617-PUF-2691 | AC, ED | PARCEL E, STATION A | 10/16/00 | 350.49 | Jar & Envelope | ICE | O-4 & TO-13 & TO-9m | | |
| 00101617-PUF-2692 | AC, ED | PARCEL E, STATION B | 10/16/00 | 347.84 | " | " | O-4 & TO-13 & TO-9m | | |
| 00101617-PUF-2693 | AC, ED | PARCEL E, STATION C. | 10/16/00 | 357.80 | " | " | O-4 & TO-13 & TO-9m | | |
| 00101617-PUF-2694 | AC, ED | PARCEL E, STATION D | 10/16/00 | 347.71 | " | " | O-4 & TO-13 & TO-9m | | |
| VOID | | PARCEL E, STATION E | 10/16/00 | 0.00 | " | " | O-4 & TO-13 & TO-9m | | |
| 00101617-PUF-2696 | AC, ED | PARCEL E, STATION F | 10/16/00 | 342.30 | " | " | O-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/16/00 | 0.00 | " | " | O-4 & TO-13 & TO-9m | | |
| 00101617-PUF-2697 | AC, ED | PARCEL E, PUF-BLANK | 10/16/00 | NA | " | " | O-4 & TO-13 & TO-9m | | |
| 00101617-VOC-A301 | AC, ED | PARCEL E, STATION A | 10/16/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| 00101617-VOC-A429 | AC, ED | PARCEL E, STATION B | 10/16/00 | 0.00 | " | " | TO-14a | | |
| 00101617-VOC-A704 | AC, ED | PARCEL E, STATION C | 10/16/00 | 1.00 | " | " | TO-14a | | |
| 00101617-VOC-A804 | AC, ED | PARCEL E, STATION D | 10/16/00 | 1.00 | " | " | TO-14a | | |
| 00101617-VOC-A420 | AC, ED | PARCEL E, STATION E | 10/16/00 | 1.00 | " | " | TO-14a | | |
| 00101617-VOC-A513 | AC, ED | PARCEL E, STATION F | 10/16/00 | 3.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/16/00 | 0.00 | " | " | TO-14a | | |
| 00101617-VOC-A809 | AC, ED | PARCEL E, VOC-BLANK | 10/16/00 | NA | " | " | TO-14a | | |
| 00101617-TSP-7432 | AC, ED | PARCEL E, STATION A | 10/16/00 | 1902.54 | Envelope | " | Full Suite Metals | | |
| 00101617-TSP-7433 | AC, ED | PARCEL E, STATION B | 10/16/00 | 1902.02 | " | " | Full Suite Metals | | |
| 00101617-TSP-7434 | AC, ED | PARCEL E, STATION C | 10/16/00 | 1893.83 | " | " | Full Suite Metals | | |
| 00101617-TSP-7435 | AC, ED | PARCEL E, STATION D | 10/16/00 | 1895.59 | " | " | Full Suite Metals | | |
| 00101617-TSP-7436 | AC, ED | PARCEL E, STATION E | 10/16/00 | 1907.40 | " | " | Full Suite Metals | | |
| 00101617-TSP-7437 | AC, ED | PARCEL E, STATION F | 10/16/00 | 1904.87 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/16/00 | 0.00 | | | Full Suite Metals | | |
| 00101617-TSP-7438 | AC, ED | PARCEL E, TSP-BLANK | 10/16/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans. Returning VOID PUF sample.

| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaroun | QC Level: | See PAM |
|---|---|---|---|---|---|---|---|

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

10161700 COC
H. Bowles, Excel 5/7-Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/9/00 10:01 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101617-HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: C. Foreman, A. Cortez, L. Leet
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/17/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00101617-HCLAE-2125 | SMC | SAMPLE STATION A | 10/16/00 | 1591.20 | 3 vials | None | TO-0051m | | | |
| 00101617-HCLBE-2126 | SMC | SAMPLE STATION B | 10/16/00 | 1490.40 | 3 vials | None | TO-0051m | | | |
| 00101617-HCLCE-2127 | SMC | SAMPLE STATION C | 10/16/00 | 1584.00 | 3 vials | None | TO-0051m | | | |
| 00101617-HCLDE-2128 | SMC | SAMPLE STATION D | 10/16/00 | 1490.40 | 3 vials | None | TO-0051m | | | |
| 00101617-HCLEE-2129 | SMC | SAMPLE STATION E | 10/16/00 | 1555.20 | 3 vials | None | TO-0051m | | | |
| 00101617-HCLFE-2130 | SMC | SAMPLE STATION F | 10/16/00 | 1677.60 | 3 vials | None | TO-0051m | | | |
| Not Collected | | SAMPLE STATION G | 10/16/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | | Blank | 10/16/00 | NA | 3 vials | None | TO-0051m | | | |
| 001016-PHAE-2223 | SMC | SAMPLE STATION A | 10/16/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| 001016-PHBE-2224 | SMC | SAMPLE STATION B | 10/16/00 | 53.50 | 1 vial | Ice | TO-6m | | | |
| 001016-PHCE-2225 | SMC | SAMPLE STATION C | 10/16/00 | 52.50 | 1 vial | Ice | TO-6m | | | |
| 001016-PHDE-2226 | SMC | SAMPLE STATION D | 10/16/00 | 52.00 | 1 vial | Ice | TO-6m | | | |
| 001016-PHEE-2227 | SMC | SAMPLE STATION E | 10/16/00 | 54.00 | 1 vial | Ice | TO-6m | | | |
| 001016-PHFE-2228 | SMC | SAMPLE STATION F | 10/16/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/16/00 | #REF! | 1 vial | Ice | TO-6m | | | |
| 001016-PHAE-2229 | SMC | SAMPLE STATION A | 10/16/00 | 50.00 | 1 vial | Ice | TO-6m | | | |
| 001016-PHBE-2230 | SMC | SAMPLE STATION B | 10/16/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| 001016-PHCE-2231 | SMC | SAMPLE STATION C | 10/16/00 | 50.00 | 1 vial | Ice | TO-6m | | | |
| 001016-PHDE-2232 | SMC | SAMPLE STATION D | 10/16/00 | 50.50 | 1 vial | Ice | TO-6m | | | |
| 001016-PHEE-2233 | SMC | SAMPLE STATION E | 10/16/00 | 50.50 | 1 vial | Ice | TO-6m | | | |
| 001016-PHFE-2234 | SMC | SAMPLE STATION F | 10/16/00 | 55.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/16/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions:

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnaround |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101718



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/19/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00101718-PUF-2698 | AC, ED | PARCEL E, STATION A | 10/17/00 | 330.34 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| 00101718-PUF-2699 | AC, ED | PARCEL E, STATION B | 10/17/00 | 299.84 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101718-PUF-2700 | AC, ED | PARCEL E, STATION C. | 10/17/00 | 341.66 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101718-PUF-2701 | AC, ED | PARCEL E, STATION D | 10/17/00 | 341.37 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101718-PUF-2702 | AC, ED | PARCEL E, STATION E | 10/17/00 | 326.30 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101718-PUF-2703 | AC, ED | PARCEL E, STATION F | 10/17/00 | 332.84 | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101718-PUF-2704 | AC, ED | PARCEL E, STATION G | 10/17/00 | 338.66 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 10/17/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101718-VOC-A605 | AC, ED | PARCEL E, STATION A | 10/17/00 | 3.00 psi | SUMMA | None | TO-14a See Note | | |
| 00101718-VOC-A802 | AC, ED | PARCEL E, STATION B | 10/17/00 | 0.00 | " | " | TO-14a | | |
| 00101718-VOC-A417 | AC, ED | PARCEL E, STATION C | 10/17/00 | 5.00 | " | " | TO-14a | | |
| 00101718-VOC-A808 | AC, ED | PARCEL E, STATION D | 10/17/00 | 2.00 | " | " | TO-14a | | |
| 00101718-VOC-A621 | AC, ED | PARCEL E, STATION E | 10/17/00 | 4.00 | " | " | TO-14a | | |
| 00101718-VOC-A638 | AC, ED | PARCEL E, STATION F | 10/17/00 | 1.00 | " | " | TO-14a | | |
| 00101718-VOC-A512 | AC, ED | PARCEL E, STATION G | 10/17/00 | 5.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 10/17/00 | NA | " | " | TO-14a | | |
| 00101718-TSP-7439 | AC, ED | PARCEL E, STATION A | 10/17/00 | 1806.91 | Envelope | " | Full Suite Metals | | |
| 00101718-TSP-7440 | AC, ED | PARCEL E, STATION B | 10/17/00 | 1849.50 | " | " | Full Suite Metals | | |
| 00101718-TSP-7441 | AC, ED | PARCEL E, STATION C | 10/17/00 | 1852.93 | " | " | Full Suite Metals | | |
| 00101718-TSP-7442 | AC, ED | PARCEL E, STATION D | 10/17/00 | 1850.15 | " | " | Full Suite Metals | | |
| 00101718-TSP-7443 | AC, ED | PARCEL E, STATION E | 10/17/00 | 1843.07 | " | " | Full Suite Metals | | |
| 00101718-TSP-7444 | AC, ED | PARCEL E, STATION F | 10/17/00 | 1848.86 | " | " | Full Suite Metals | | |
| 00101718-TSP-7445 | AC, ED | PARCEL E, STATION G | 10/17/00 | 1848.33 | | | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 10/17/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

10171800 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/9/00 10:01 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101819



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. Diaz, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/19/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| NOT COLLECTED | | PARCEL E, STATION A | 10/18/00 | 0.00 | Jar & Envelope | ICE | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION B | 10/18/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION C. | 10/18/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION D | 10/18/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION E | 10/18/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION F | 10/18/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/18/00 | 0.00 | " | " | TO-4 & TO-13 & TO-9m | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 10/18/00 | NA | " | " | TO-4 & TO-13 & TO-9m | | |
| 00101819-VOC-A430 | AC, ED | PARCEL E, STATION A | 10/18/00 | 2.00 psi | SUMMA | None | TO-14a See Note | | |
| 00101819-VOC-A601 | AC, ED | PARCEL E, STATION B | 10/18/00 | 0.00 | " | " | TO-14a | | |
| 00101819-VOC-A112 | AC, ED | PARCEL E, STATION C | 10/18/00 | 6.00 | " | " | TO-14a | | |
| 00101819-VOC-A636 | AC, ED | PARCEL E, STATION D | 10/18/00 | 4.00 | " | " | TO-14a | | |
| 00101819-VOC-A202 | AC, ED | PARCEL E, STATION E | 10/18/00 | 4.00 | " | " | TO-14a | | |
| 00101819-VOC-A602 | AC, ED | PARCEL E, STATION F | 10/18/00 | 6.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/18/00 | 0.00 | " | " | TO-14a | | |
| 00101819-VOC-A508 | AC, ED | PARCEL E, VOC-BLANK | 10/18/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | 10/18/00 | 0.00 | Envelope | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION B | 10/18/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION C | 10/18/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION D | 10/18/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION E | 10/18/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION F | 10/18/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/18/00 | 0.00 | | | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 10/18/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze for full suite in reference methods. Additionally, include analyses per conversations with IT for low res. dioxins and furans.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 3 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

10181900 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

Formulas Verified 10/16/97

11/9/00 10:01 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101819HR



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/19/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00101819-PUF-2027 | AC, ED | PARCEL E, STATION A | 10/18/00 | 331.77 | Jar | ICE | TO-9 | | |
| 00101819-PUF-2028 | AC, ED | PARCEL E, STATION B | 10/18/00 | 333.70 | " | " | TO-9 | | |
| 00101819-PUF-2029 | AC, ED | PARCEL E, STATION C. | 10/18/00 | 298.57 | " | " | TO-9 | | |
| 00101819-PUF-2030 | AC, ED | PARCEL E, STATION D | 10/18/00 | 297.17 | " | " | TO-9 | | |
| 00101819-PUF-2031 | AC, ED | PARCEL E, STATION E | 10/18/00 | 331.91 | " | " | TO-9 | | |
| 00101819-PUF-2032 | AC, ED | PARCEL E, STATION F | 10/18/00 | 322.10 | " | " | TO-9 | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/18/00 | 0.00 | " | " | TO-9 | | |
| 00101819-PUF-2033 | AC, ED | PARCEL E, PUF-BLANK | 10/18/00 | NA | " | " | TO-9 | | |

Special Instructions: Analyze for high resolution dioxins and furans per conversations with IT.

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 5 day turnarour |
| QC Level: | See PAM | | | | |

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-101920E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/21/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00101920-PUF-2705 | AC, ED | PARCEL E, STATION A | 10/19/00 | 324.40 | Jar & Envelope | ICE | TO-4 | | |
| 00101920-PUF-2706 | AC, ED | PARCEL E, STATION B | 10/19/00 | 342.94 | " | " | TO-4 | | |
| 00101920-PUF-2707 | AC, ED | PARCEL E, STATION C. | 10/19/00 | 316.32 | " | " | TO-4 | | |
| 00101920-PUF-2708 | AC, ED | PARCEL E, STATION D | 10/19/00 | 375.58 | " | " | TO-4 | | |
| 00101920-PUF-2709 | AC, ED | PARCEL E, STATION E | 10/19/00 | 323.02 | " | " | TO-4 | | |
| 00101920-PUF-2710 | AC, ED | PARCEL E, STATION F | 10/19/00 | 331.21 | " | " | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/19/00 | 0.00 | " | " | TO-4 | | |
| 00101920-PUF-2711 | AC, ED | PARCEL E, PUF-BLANK | 10/19/00 | NA | " | " | TO-4 | | |
| 00101920-VOC-A915 | AC, ED | PARCEL E, STATION A | 10/19/00 | 6.50 psi | SUMMA | None | TO-14 | | |
| 00101920-VOC-A428 | AC, ED | PARCEL E, STATION B | 10/19/00 | 2.00 | " | " | TO-14 | | |
| 00101920-VOC-A810 | AC, ED | PARCEL E, STATION C | 10/19/00 | 5.00 | " | " | TO-14 | | |
| 00101920-VOC-A307 | AC, ED | PARCEL E, STATION D | 10/19/00 | 3.50 | " | " | TO-14 | | |
| 00101920-VOC-A806 | AC, ED | PARCEL E, STATION E | 10/19/00 | 3.50 | " | " | TO-14 | | |
| 00101920-VOC-A423 | AC, ED | PARCEL E, STATION F | 10/19/00 | 5.50 | " | " | TO-14 | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/19/00 | 0.00 | " | " | TO-14 | | |
| NOT COLLECTED | ;;;;;;; | PARCEL E, VOC-BLANK | 10/19/00 | NA | " | " | TO-14 | | |
| 00101920-TSP-7446 | AC, ED | PARCEL E, STATION A | 10/19/00 | 1767.69 | Envelope | " | See SOW | | |
| 00101920-TSP-7457 | AC, ED | PARCEL E, STATION B | 10/19/00 | 1783.36 | " | " | See SOW | | |
| 00101920-TSP-7458 | AC, ED | PARCEL E, STATION C | 10/19/00 | 1795.87 | " | " | See SOW | | |
| 00101920-TSP-7459 | AC, ED | PARCEL E, STATION D | 10/19/00 | 1811.59 | " | " | See SOW | | |
| 00101920-TSP-7460 | AC, ED | PARCEL E, STATION E | 10/19/00 | 1848.79 | " | " | See SOW | | |
| 00101920-TSP-7461 | AC, ED | PARCEL E, STATION F | 10/19/00 | 1848.59 | " | " | See SOW | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/19/00 | 0.00 | | | See SOW | | |
| 00101920-TSP-7462 | AC, ED | PARCEL E, TSP-BLANK | 10/19/00 | NA | " | " | See SOW | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-10-920-HCL



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/20/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (LITERS) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. | |
|---|---|---|---|---|---|---|---|---|---|---|
| 00101920-HCLAE-2131 | SMC | SAMPLE STATION A | 10/19/00 | 1533.60 | 3 vials | None | TO-0051m | | | |
| 00101920-HCLBE-2132 | SMC | SAMPLE STATION B | 10/19/00 | 1533.60 | 3 vials | None | TO-0051m | | | |
| 00101920-HCLCE-2133 | SMC | SAMPLE STATION C | 10/19/00 | 1540.80 | 3 vials | None | TO-0051m | | | |
| 00101920-HCLDE-2134 | SMC | SAMPLE STATION D | 10/19/00 | 1533.60 | 3 vials | None | TO-0051m | | | |
| 00101920-HCLEE-2135 | SMC | SAMPLE STATION E | 10/19/00 | 1576.80 | 3 vials | None | TO-0051m | | | |
| 00101920-HCLFE-2136 | SMC | SAMPLE STATION F | 10/19/00 | 1591.20 | 3 vials | None | TO-0051m | | | |
| Not Collected | | SAMPLE STATION G | 10/19/00 | 0.00 | 3 vials | None | TO-0051m | | | |
| Not Collected | | Blank | 10/19/00 | NA | 3 vials | None | TO-0051m | | | |
| 001019-PHAE-2235 | SMC | SAMPLE STATION A | 10/19/00 | 53.50 | 1 vial | Ice | TO-6m | | | |
| 001019-PHBE-2236 | SMC | SAMPLE STATION B | 10/19/00 | 54.00 | 1 vial | Ice | TO-6m | | | |
| 001019-PHCE-2237 | SMC | SAMPLE STATION C | 10/19/00 | 53.00 | 1 vial | Ice | TO-6m | | | |
| 001019-PHDE-2238 | SMC | SAMPLE STATION D | 10/19/00 | 55.00 | 1 vial | Ice | TO-6m | | | |
| 001019-PHEE-2239 | SMC | SAMPLE STATION E | 10/19/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| 001019-PHFE-2240 | SMC | SAMPLE STATION F | 10/19/00 | 52.50 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/19/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| 001019-PHAE-2241 | SMC | SAMPLE STATION A | 10/19/00 | 53.00 | 1 vial | Ice | TO-6m | | | |
| 001019-PHBE-2242 | SMC | SAMPLE STATION B | 10/19/00 | 53.00 | 1 vial | Ice | TO-6m | | | |
| 001019-PHCE-2243 | SMC | SAMPLE STATION C | 10/19/00 | 51.50 | 1 vial | Ice | TO-6m | | | |
| 001019-PHDE-2244 | SMC | SAMPLE STATION D | 10/19/00 | 50.50 | 1 vial | Ice | TO-6m | | | |
| 001019-PHEE-2245 | SMC | SAMPLE STATION E | 10/19/00 | 54.00 | 1 vial | Ice | TO-6m | | | |
| 001019-PHFE-2246 | SMC | SAMPLE STATION F | 10/19/00 | 57.00 | 1 vial | Ice | TO-6m | | | |
| Not collected | | SAMPLE STATION G | 10/19/00 | 0.00 | 1 vial | Ice | TO-6m | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Special Instructions: Returning unused aniline, acid, base, vials and chlorine filters. Also returning used sample impingers

| | | | | | |
|---|---|---|---|---|---|
| Possible Hazard ID: | none | Sample Disposal: | By Lab | Turnaround Time Required: | 3 day turnarour |
| QC Level: | See PAM | | | | |
| 1. Relinquished by (Signature/Affiliation) | | Date: Time: | | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | | Date: Time: | | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | | Date: Time: | | 3. Received by (Signature/Affiliation) | Date: Time: |
| Comments: | Fax Preliminary results to Cliff Foreman (1-415-671-2809) | | | | |

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102021



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/22/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00102021-PUF-2712 | AC, ED | PARCEL E, STATION A | 10/20/00 | 339.95 | Jar & Envelope | ICE | TO-4 | | |
| 00102021-PUF-2713 | AC, ED | PARCEL E, STATION B | 10/20/00 | 337.74 | " | " | TO-4 | | |
| 00102021-PUF-2714 | AC, ED | PARCEL E, STATION C. | 10/20/00 | 326.14 | " | " | TO-4 | | |
| 00102021-PUF-2715 | AC, ED | PARCEL E, STATION D | 10/20/00 | 317.47 | " | " | TO-4 | | |
| VOID | | PARCEL E, STATION E | 10/20/00 | 0.00 | " | " | TO-4 | | |
| 00102021-PUF-2717 | AC, ED | PARCEL E, STATION F | 10/20/00 | 334.03 | " | " | TO-4 | | |
| 00102021-PUF-2718 | AC, ED | PARCEL E, STATION G | 10/20/00 | 358.26 | " | " | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 10/20/00 | NA | " | " | TO-4 | | |
| 00102021-VOC-A425 | AC, ED | PARCEL E, STATION A | 10/20/00 | 6.00 psi | SUMMA | None | TO-14a See Note | | |
| 00102021-VOC-A637 | AC, ED | PARCEL E, STATION B | 10/20/00 | 0.00 | " | " | TO-14a | | |
| 00102021-VOC-A427 | AC, ED | PARCEL E, STATION C | 10/20/00 | 5.00 | " | " | TO-14a | | |
| 00102021-VOC-A604 | AC, ED | PARCEL E, STATION D | 10/20/00 | 3.50 | " | " | TO-14a | | |
| 00102021-VOC-A303 | AC, ED | PARCEL E, STATION E | 10/20/00 | 5.00 | " | " | TO-14a | | |
| 00102021-VOC-A503 | AC, ED | PARCEL E, STATION F | 10/20/00 | 6.50 | " | " | TO-14a | | |
| 00102021-VOC-A206 | AC, ED | PARCEL E, STATION G | 10/20/00 | 7.50 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 10/20/00 | NA | " | " | TO-14a | | |
| 00102021-TSP-7463 | AC, ED | PARCEL E, STATION A | 10/20/00 | 1847.90 | Envelope | " | Full Suite Metals | | |
| 00102021-TSP-7464 | AC, ED | PARCEL E, STATION B | 10/20/00 | 1835.47 | " | " | Full Suite Metals | | |
| 00102021-TSP-7465 | AC, ED | PARCEL E, STATION C | 10/20/00 | 1810.20 | " | " | Full Suite Metals | | |
| 00102021-TSP-7466 | AC, ED | PARCEL E, STATION D | 10/20/00 | 1804.50 | " | " | Full Suite Metals | | |
| VOID | | PARCEL E, STATION E | 10/20/00 | 0.00 | " | " | Full Suite Metals | | |
| 00102021-TSP-7468 | AC, ED | PARCEL E, STATION F | 10/20/00 | 1764.60 | " | " | Full Suite Metals | | |
| 00102021-TSP-7469 | AC, ED | PARCEL E, STATION G | 10/20/00 | 1792.96 | | | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 10/20/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only.

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

Formulas Verified 10/16/97

10202100 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

11/9/00 10:01 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102122



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/23/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00102122-PUF-2726 | AC, ED | PARCEL E, STATION A | 10/21/00 | 341.83 | Jar & Envelope | ICE | TO-4 | | |
| 00102122-PUF-2727 | AC, ED | PARCEL E, STATION B | 10/21/00 | 346.84 | " | " | TO-4 | | |
| 00102122-PUF-2728 | AC, ED | PARCEL E, STATION C. | 10/21/00 | 349.22 | " | " | TO-4 | | |
| 00102122-PUF-2729 | AC, ED | PARCEL E, STATION D | 10/21/00 | 344.97 | " | " | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION E | 10/21/00 | 0.00 | " | " | TO-4 | | |
| 00102122-PUF-2731 | AC, ED | PARCEL E, STATION F | 10/21/00 | 341.47 | " | " | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/21/00 | 0.00 | " | " | TO-4 | | |
| 00102122-PUF-2732 | AC, ED | PARCEL E, PUF-BLANK | 10/21/00 | NA | " | " | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | 10/21/00 | NA psi | SUMMA | None | TO-14a See Note | | |
| NOT COLLECTED | | PARCEL E, STATION B | 10/21/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | 10/21/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | 10/21/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | 10/21/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | 10/21/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/21/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 10/21/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | 10/21/00 | NA | Envelope | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION B | 10/21/00 | NA | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION C | 10/21/00 | NA | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION D | 10/21/00 | NA | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION E | 10/21/00 | NA | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION F | 10/21/00 | NA | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/21/00 | NA | | | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 10/21/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

| | | | |
|---|---|---|---|
| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarour | QC Level: See PAM |
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Cliff Foreman (1-415-671-2809)

Formulas Verified 10/16/97

10212200 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

11/9/00 10:01 AM

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102223



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 85554
Required Report Date: See PAM

Samples Shipment Date: 10/24/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Cliff Foreman
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Date Collected | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|
| 00102223-PUF-2733 | AC, ED | PARCEL E, STATION A | 10/22/00 | 325.90 | Jar & Envelope | ICE | TO-4 | | |
| 00102223-PUF-2734 | AC, ED | PARCEL E, STATION B | 10/22/00 | 329.19 | " | " | TO-4 | | |
| 00102223-PUF-2735 | AC, ED | PARCEL E, STATION C. | 10/22/00 | 330.08 | " | " | TO-4 | | |
| 00102223-PUF-2736 | AC, ED | PARCEL E, STATION D | 10/22/00 | 327.75 | " | " | TO-4 | | |
| 00102223-PUF-2737 | AC, ED | PARCEL E, STATION E | 10/22/00 | 323.65 | " | " | TO-4 | | |
| 00102223-PUF-2738 | AC, ED | PARCEL E, STATION F | 10/22/00 | 328.80 | " | " | TO-4 | | |
| 00102223-PUF-2739 | AC, ED | PARCEL E, STATION G | 10/22/00 | 304.93 | " | " | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 10/22/00 | NA | " | " | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | 10/22/00 | 0.00 psi | SUMMA | None | TO-14a See Note | | |
| NOT COLLECTED | | PARCEL E, STATION B | 10/22/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | 10/22/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | 10/22/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | 10/22/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | 10/22/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/22/00 | 0.00 | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 10/22/00 | NA | " | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | 10/22/00 | 0.00 | Envelope | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION B | 10/22/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION C | 10/22/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION D | 10/22/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION E | 10/22/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION F | 10/22/00 | 0.00 | " | " | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, STATION G | 10/22/00 | 0.00 | | | Full Suite Metals | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 10/22/00 | NA | " | " | Full Suite Metals | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

| Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarour | QC Level: See PAM |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

Formulas Verified 10/16/97

11/9/00 10:01 AM

10222300 COC
H. Bowles, Excel 5/7 Win 95
TSP and PM-10 Volume Calcs

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102324



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 10/25/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: 0

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00102324-PUF-2740 | AC, ED, BK | PARCEL E, STATION A | 10/23/00 | 0846AM | 10/24/00 | 0829AM | 327.77 | Jar & Envelope | | TO-4 | | |
| 00102324-PUF-2741 | AC, ED, BK | PARCEL E, STATION B | 10/23/00 | 0852AM | 10/24/00 | 0856AM | 333.85 | " | | TO-4 | | |
| 00102324-PUF-2742 | AC, ED, BK | PARCEL E, STATION C. | 10/23/00 | 0857AM | 10/24/00 | 0910AM | 335.97 | " | | TO-4 | | |
| 00102324-PUF-2743 | AC, ED, BK | PARCEL E, STATION D | 10/23/00 | 0905AM | 10/24/00 | 0925AM | 337.13 | " | | TO-4 | | |
| 00102324-PUF-2744 | AC, ED, BK | PARCEL E, STATION E | 10/23/00 | 0913AM | 10/24/00 | 0943AM | 343.17 | " | | TO-4 | | |
| 00102324-PUF-2745 | AC, ED, BK | PARCEL E, STATION F | 10/23/00 | 0920AM | 10/24/00 | 0958AM | 342.66 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| 00102324-PUF-2746 | AC, ED, BK | PARCEL E, PUF-BLANK | 10/23/00 | | 10/24/00 | | 0.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | NA | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | NA | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnarou

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102425E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 10/26/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00102425-PUF-2747 | AC, BK | PARCEL E, STATION A | 10/24/00 | 0837AM | 10/25/00 | 0837AM | 340.36 | Jar & Envelope | | TO-4 | | |
| 00102425-PUF-2748 | AC, BK | PARCEL E, STATION B | 10/24/00 | 0902AM | 10/25/00 | 0847AM | 338.30 | " | | TO-4 | | |
| 00102425-PUF-2749 | AC, BK | PARCEL E, STATION C. | 10/24/00 | 0915AM | 10/25/00 | 0855AM | 328.27 | " | | TO-4 | | |
| 00102425-PUF-2750 | AC, BK | PARCEL E, STATION D | 10/24/00 | 0930AM | 10/25/00 | 0906AM | 330.02 | " | | TO-4 | | |
| 00102425-PUF-2751 | AC, BK | PARCEL E, STATION E | 10/24/00 | 0949AM | 10/25/00 | 0917AM | 322.43 | " | | TO-4 | | |
| 00102425-PUF-2800 | AC, BK | PARCEL E, STATION F | 10/24/00 | 1003AM | 10/25/00 | 0927AM | 331.54 | " | | TO-4 | | |
| 00102425-PUF-2801 | AC, BK | PARCEL E, STATION G | 10/24/00 | 0937AM | 10/25/00 | 0912AM | 341.15 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| 00102425-VOC-A704 | AC, BK | PARCEL E, STATION A | 10/24/00 | 0838AM | 10/25/00 | 0836AM | 0.00 psi | SUMMA | | TO-14a | | |
| 00102425-VOC-A420 | AC, BK | PARCEL E, STATION B | 10/24/00 | 0904AM | 10/25/00 | 0844AM | 7.00 | " | | TO-14a | | |
| 00102425-VOC-A705 | AC, BK | PARCEL E, STATION C | 10/24/00 | 0915AM | 10/25/00 | 0850AM | 2.00 | " | | TO-14a | | |
| 00102425-VOC-A429 | AC, BK | PARCEL E, STATION D | 10/24/00 | 0938AM | 10/25/00 | 0905AM | 6.00 | " | | TO-14a | | |
| 00102425-VOC-A914 | AC, BK | PARCEL E, STATION E | 10/24/00 | 0946AM | 10/25/00 | 0916AM | 4.00 | " | | TO-14a | | |
| 00102425-VOC-A805 | AC, BK | PARCEL E, STATION F | 10/24/00 | 1001AM | 10/25/00 | 0927AM | 4.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| 00102425-VOC-A803 | AC, BK | PARCEL E, VOC-BLANK | 10/24/00 | | 10/25/00 | | NA | " | | TO-14a | | |
| 00102425-TSP-7477 | AC, BK | PARCEL E, STATION A | 10/24/00 | 0844AM | 10/25/00 | 0843AM | 1860.43 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00102425-TSP-7478 | AC, BK | PARCEL E, STATION B | 10/24/00 | 0907AM | 10/25/00 | 0851AM | 1844.02 | " | | IO 3.1 & IO 3.5 | | |
| 00102425-TSP-7479 | AC, BK | PARCEL E, STATION C | 10/24/00 | 0920AM | 10/25/00 | 0901AM | 1837.16 | " | | IO 3.1 & IO 3.5 | | |
| 00102425-TSP-7480 | AC, BK | PARCEL E, STATION D | 10/24/00 | 0933AM | 10/25/00 | 0910AM | 1834.95 | " | | IO 3.1 & IO 3.5 | | |
| 00102425-TSP-7481 | AC, BK | PARCEL E, STATION E | 10/24/00 | 0953AM | 10/25/00 | 0923AM | 1824.41 | " | | IO 3.1 & IO 3.5 | | |
| 00102425-TSP-7482 | AC, BK | PARCEL E, STATION F | 10/24/00 | 1007AM | 10/25/00 | 0933AM | 1813.34 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| 00102425-TSP-7483 | AC, BK | PARCEL E, TSP-BLANK | 10/24/00 | | 10/25/00 | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaroun | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102526



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 10/27/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VOID | | PARCEL E, STATION A | | | | | 0.00 | Jar & Envelope | | TO-4 | | |
| 00102526-PUF-2809 | AC, BK | PARCEL E, STATION B | 10/25/00 | 0850AM | 10/26/00 | 0901AM | 343.29 | " | | TO-4 | | |
| 00102526-PUF-2810 | AC, BK | PARCEL E, STATION C. | 10/25/00 | 0859AM | 10/26/00 | 0906AM | 341.12 | " | | TO-4 | | |
| VOID | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-4 | | |
| 00102526-PUF-2812 | AC, BK | PARCEL E, STATION E | 10/25/00 | 0923AM | 10/26/00 | 0917AM | 347.70 | " | | TO-4 | | |
| 00102526-PUF-2752 | AC, BK | PARCEL E, STATION F | 10/25/00 | 0933AM | 10/26/00 | 0927AM | 334.43 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| 00102526-PUF-2813 | AC, BK | PARCEL E, PUF-BLANK | 10/25/00 | NA | 10/26/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaroun

QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102627



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn, B. Womack
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 10/30/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Jar & Envelope | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION C. | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-4 | | |
| 00102627-PUF-2757 | AC, BK, BW | PARCEL E, STATION E | 10/26/00 | 0921AM | 10/27/00 | 0900AM | 336.32 | " | | TO-4 | | |
| 00102627-PUF-2758 | AC, BK, BW | PARCEL E, STATION F | 10/26/00 | 0929AM | 10/27/00 | 0914AM | 338.72 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaroun

QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102728



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Womack, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 10/30/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOT COLLECTED | | PARCEL E, STATION A | | | | | NA | Jar & Envelope | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION C. | | | | | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | NA | " | | TO-4 | | |
| 00102728-PUF-2765 | BW, BK | PARCEL E, STATION E | 10/27/00 | 0912AM | 10/28/00 | 0939AM | 352.20 | " | | TO-4 | | |
| 00102728-PUF-2769 | BW, BK | PARCEL E, STATION F | 10/27/00 | 0921AM | 10/28/00 | 0946AM | 345.34 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | NA psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | NA | " | | TO-14a | | |
| 00102728-VOC-A802 | BW, BK | PARCEL E, STATION E | 10/27/00 | 0907AM | 10/28/00 | 0937AM | 2.00 | " | | TO-14a | | |
| 00102728-VOC-A602 | BW, BK | PARCEL E, STATION F | 10/27/00 | 0921AM | 10/28/00 | 0943AM | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | NA | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| 00102728-TSP-7494 | BW, BK | PARCEL E, STATION E | 10/27/00 | 0912AM | 10/28/00 | 0938AM | 1896.31 | " | | IO 3.1 & IO 3.5 | | |
| 00102728-TSP-7495 | BW, BK | PARCEL E, STATION F | 10/27/00 | 0921AM | 10/28/00 | 0944AM | 1893.96 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnarou

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102829



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Womack, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 10/30/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOT COLLECTED | | PARCEL E, STATION A | | | | | NA | Jar & Envelope | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION C. | | | | | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | NA | " | | TO-4 | | |
| 00102728-PUF-2766 | BW,BK | PARCEL E, STATION E | 10/28/00 | 0941AM | 10/29/00 | 1010AM | 356.15 | " | | TO-4 | | |
| VOID | | PARCEL E, STATION F | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | NA psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | NA | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only. Returning 1 VOID PUF sample.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). Circuit breaker flipped on Station F generator after only ~5 hours of sample time; sample voided.

IT INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-102930



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Womack, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 10/31/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Jar & Envelope | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION C. | | | | | 0.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-4 | | |
| 00102930-PUF-2770 | BW,BK | PARCEL E, STATION E | 10/29/00 | 0912AM | 10/30/00 | 0904AM | 346.48 | " | | TO-4 | | |
| 00102930-PUF-2771 | BW,BK | PARCEL E, STATION F | 10/29/00 | 0920AM | 10/30/00 | 0927AM | 336.84 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| 00102930-PUF-2772 | BW,BK | PARCEL E, PUF-BLANK | 10/29/00 | | 10/30/00 | | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning 3 VOID PUF samples.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaroun | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-103031E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/1/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Jar & Envelope | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION C. | | | | | 0.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-4 | | |
| 00103031-PUF-2773 | AC, BK | PARCEL E, STATION E | 10/30/00 | 0919AM | 10/31/00 | 0946AM | 343.87 | " | | TO-4 | | |
| 00103031-PUF-2774 | AC, BK | PARCEL E, STATION F | 10/30/00 | 0925AM | 10/31/00 | 0954AM | 342.91 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| 00000 | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| 0000000 | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION C | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION E | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION F | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION A | | | | | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION B | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION D | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION E | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION F | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaround

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-1031111



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/2/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VOID | | PARCEL E, STATION A | | | | | 0.00 | Jar & Envelope | | TO-4 | | |
| 001031111-PUF-2754 | AC, BK | PARCEL E, STATION B | 10/31/00 | 11:59:00 | 11/1/00 | 11:06 | 327.51 | " | | TO-4 | | |
| 001031111-PUF-2755 | AC, BK | PARCEL E, STATION C. | 10/31/00 | 12:11:00 | 11/1/00 | 11:23 | 320.08 | " | | TO-4 | | |
| 001031111-PUF-2756 | AC, BK | PARCEL E, STATION D | 10/31/00 | 9:39:00 | 11/1/00 | 11:23 | 323.76 | " | | TO-4 | | |
| 001031111-PUF-2775 | AC, BK | PARCEL E, STATION E | 10/31/00 | 9:50:00 | 11/1/00 | 9:45 | 342.90 | " | | TO-4 | | |
| 001031111-PUF-2776 | AC, BK | PARCEL E, STATION F | 10/31/00 | 9:57:00 | 11/1/00 | 9:59 | 332.55 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| 001031111-PUF-2777 | AC, BK | PARCEL E, PUF-BLANK | 10/31/00 | NA | 11/1/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning void PUF sample.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaroun | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-110102



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/3/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Jar & Envelope | | TO-4 | | |
| 00110102-PUF-2779 | AC, BK | PARCEL E, STATION B | 11/1/00 | 11:13:00 | 11/2/00 | 10:19:00 | 325.66 | " | | TO-4 | | |
| 00110102-PUF-2780 | AC, BK | PARCEL E, STATION C. | 11/1/00 | 11:27:00 | 11/2/00 | 10:30:00 | 334.48 | " | | TO-4 | | |
| 00110102-PUF-2781 | AC, BK | PARCEL E, STATION D | 11/1/00 | 9:12:00 | 11/2/00 | 8:26:00 | 312.51 | " | | TO-4 | | |
| 00110102-PUF-2782 | AC, BK | PARCEL E, STATION E | 11/1/00 | 9:49:00 | 11/2/00 | 8:52:00 | 316.50 | " | | TO-4 | | |
| 00110102-PUF-2783 | AC, BK | PARCEL E, STATION F | 11/1/00 | 10:03:00 | 11/2/00 | 9:03:00 | 322.94 | " | | TO-4 | | |
| 00110102-PUF-2759 | AC, BK | PARCEL E, STATION G | 11/1/00 | 9:29:00 | 1/0/00 | 8:41:00 | 308.18 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| 00110102-VOC-A417 | AC, BK | PARCEL E, STATION A | 11/1/00 | 10:56 | 11/2/00 | 10:17 | 2.00 psi | SUMMA | | TO-14a | | |
| 00110102-VOC-A112 | AC, BK | PARCEL E, STATION B | 11/1/00 | 11:04 | 11/2/00 | 10:18 | 8.00 | " | | TO-14a | | |
| 00110102-VOC-A601 | AC, BK | PARCEL E, STATION C | 11/1/00 | 11:20 | 11/2/00 | 10:30 | 4.00 | " | | TO-14a | | |
| 00110102-VOC-A621 | AC, BK | PARCEL E, STATION D | 11/1/00 | 9:16 | 11/2/00 | 8:25 | 5.00 | " | | TO-14a | | |
| 00110102-VOC-A430 | AC, BK | PARCEL E, STATION E | 11/1/00 | 9:44 | 11/2/00 | 8:50 | 0.00 | " | | TO-14a | | |
| 00110102-VOC-A603 | AC, BK | PARCEL E, STATION F | 11/1/00 | 9:58 | 11/2/00 | 9:02 | 7.00 | " | | TO-14a | | |
| 00110102-VOC-A426 | AC, BK | PARCEL E, STATION G | 11/1/00 | 8:34 | 11/2/00 | 9:04 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| 00110102-TSP-7491 | AC, BK | PARCEL E, STATION B | 11/1/00 | 11:15 | 11/2/00 | 10:24 | 1802.19 | " | | IO 3.1 & IO 3.5 | | |
| 00110102-TSP-7492 | AC, BK | PARCEL E, STATION C | 11/1/00 | 11:31 | 11/2/00 | 10:36 | 1785.39 | " | | IO 3.1 & IO 3.5 | | |
| 00110102-TSP-7493 | AC, BK | PARCEL E, STATION D | 11/1/00 | 9:20 | 11/2/00 | 8:36 | 1808.35 | " | | IO 3.1 & IO 3.5 | | |
| 00110102-TSP-7504 | AC, BK | PARCEL E, STATION E | 11/1/00 | 9:53 | 11/2/00 | 8:56 | 1791.51 | " | | IO 3.1 & IO 3.5 | | |
| 00110102-TSP-7505 | AC, BK | PARCEL E, STATION F | 11/1/00 | 10:07 | 11/2/00 | 9:00 | 1774.23 | " | | IO 3.1 & IO 3.5 | | |
| 00110102-TSP-7496 | AC, BK | PARCEL E, STATION G | 11/2/00 | 9:38 | 1/0/00 | 8:43 | 1792.64 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) Date: Time: | 1. Received by (Signature/Affiliation) Date: Time: |
| 2. Relinquished by (Signature/Affiliation) Date: Time: | 2. Received by (Signature/Affiliation) Date: Time: |
| 3. Relinquished by (Signature/Affiliation) Date: Time: | 3. Received by (Signature/Affiliation) Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809) Sample 00110102-TSP-7505 ran slightly less than 23 hours.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-110203E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/6/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Jar & Envelope | | TO-4 | | |
| 00110203-PUF-2790 | AC, BK | PARCEL E, STATION B | 11/2/00 | 10:23:00 | 11/3/00 | 10:37:00 | 345.31 | " | | TO-4 | | |
| 00110203-PUF-2791 | AC, BK | PARCEL E, STATION C. | 11/2/00 | 10:35:00 | 11/3/00 | 10:48:00 | 347.67 | " | | TO-4 | | |
| 00110203-PUF-2792 | AC, BK | PARCEL E, STATION D | 11/2/00 | 8:31:00 | 11/3/00 | 9:35:00 | 344.00 | " | | TO-4 | | |
| 00110203-PUF-2793 | AC, BK | PARCEL E, STATION E | 11/2/00 | 8:56:00 | 11/3/00 | 9:50:00 | 371.69 | " | | TO-4 | | |
| 00110203-PUF-2794 | AC, BK | PARCEL E, STATION F | 11/2/00 | 9:08:00 | 11/3/00 | 10:04:00 | 353.38 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00110203-PUF-2795 | AC, BK | PARCEL E, PUF-BLANK | 11/2/00 | NA | 11/3/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-110304



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/6/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00110304-PUF-2778 | AC, BK | PARCEL E, STATION A | 11/3/00 | 11:05:00 | 11/4/00 | 11:05:00 | 326.99 | Jar & Envelope | | TO-4 | | |
| 00110304-PUF-2796 | AC, BK | PARCEL E, STATION B | 11/3/00 | 10:43:00 | 11/4/00 | 10:22:00 | 333.94 | " | | TO-4 | | |
| 00110304-PUF-2797 | AC, BK | PARCEL E, STATION C. | 11/3/00 | 10:55:00 | 11/4/00 | 10:31:00 | 341.21 | " | | TO-4 | | |
| 00110304-PUF-2798 | AC, BK | PARCEL E, STATION D | 11/3/00 | 9:43:00 | 11/4/00 | 9:14:00 | 312.07 | " | | TO-4 | | |
| 00110304-PUF-2799 | AC, BK | PARCEL E, STATION E | 11/3/00 | 9:58:00 | 11/4/00 | 9:29:00 | 329.81 | " | | TO-4 | | |
| 00110304-PUF-2814 | AC, BK | PARCEL E, STATION F | 11/3/00 | 10:09:00 | 11/4/00 | 9:38:00 | 328.57 | " | | TO-4 | | |
| 00110304-PUF-2815 | AC, BK | PARCEL E, STATION G | 11/3/00 | 9:47:00 | 11/4/00 | 9:24:00 | 330.57 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-110405



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/6/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00110405-PUF-2816 | AC, ED, BK | PARCEL E, STATION A | 11/4/00 | 10:17:00 | 11/5/00 | 10:17:00 | 331.38 | Jar & Envelope | | TO-4 | | |
| 00110405-PUF-2817 | AC, ED, BK | PARCEL E, STATION B | 11/4/00 | 10:25:00 | 11/5/00 | 9:24:00 | 323.05 | " | | TO-4 | | |
| 00110405-PUF-2818 | AC, ED, BK | PARCEL E, STATION C. | 11/4/00 | 10:34:00 | 11/5/00 | 9:31:00 | 331.16 | " | | TO-4 | | |
| 00110405-PUF-2819 | AC, ED, BK | PARCEL E, STATION D | 11/4/00 | 9:17:00 | 11/5/00 | 9:41:00 | 309.35 | " | | TO-4 | | |
| 00110405-PUF-2820 | AC, ED, BK | PARCEL E, STATION E | 11/4/00 | 9:32:00 | 11/5/00 | 9:54:00 | 331.35 | " | | TO-4 | | |
| 00110405-PUF-2821 | AC, ED, BK | PARCEL E, STATION F | 11/4/00 | 9:41:00 | 11/5/00 | 10:01:00 | 340.70 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00110405-PUF-2822 | AC, ED, BK | PARCEL E, PUF-BLANK | 11/4/00 | NA | 11/5/00 | NA | NA | " | | TO-4 | | |
| 00110405-VOC-A606 | AC, ED, BK | PARCEL E, STATION A | 11/4/00 | 0.42569 | 11/5/00 | 9:17 | 0.00 psi | SUMMA | | TO-14a | | |
| 00110405-VOC-A915 | AC, ED, BK | PARCEL E, STATION B | 11/4/00 | 0.43333 | 11/5/00 | 9:27 | 0.00 | " | | TO-14a | | |
| 00110405-VOC-A204 | AC, ED, BK | PARCEL E, STATION C | 11/4/00 | 0.44028 | 11/5/00 | 9:35 | 4.00 | " | | TO-14a | | |
| 00110405-VOC-A303 | AC, ED, BK | PARCEL E, STATION D | 11/4/00 | 0.38611 | 11/5/00 | 9:43 | 2.50 | " | | TO-14a | | |
| 00110405-VOC-A809 | AC, ED, BK | PARCEL E, STATION E | 11/4/00 | 0.39583 | 11/5/00 | 9:55 | 8.00 | " | | TO-14a | | |
| 00110405-VOC-A702 | AC, ED, BK | PARCEL E, STATION F | 11/4/00 | 0.40278 | 11/5/00 | 10:03 | 5.50 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| 00110405-VOC-A423 | AC, ED, BK | PARCEL E, VOC-BLANK | 11/4/00 | NA | 11/5/00 | NA | NA | " | | TO-14a | | |
| 00110405-TSP-7490 | AC, ED, BK | PARCEL E, STATION A | 11/4/00 | 0.42917 | 11/5/00 | 9:20 | 1785.80 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00110405-TSP-7512 | AC, ED, BK | PARCEL E, STATION B | 11/4/00 | 0.43542 | 11/5/00 | 9:29 | 1782.92 | " | | IO 3.1 & IO 3.5 | | |
| 00110405-TSP-7513 | AC, ED, BK | PARCEL E, STATION C | 11/4/00 | 0.44236 | 11/5/00 | 8:47 | 1711.67 | " | | IO 3.1 & IO 3.5 | | |
| 00110405-TSP-7514 | AC, ED, BK | PARCEL E, STATION D | 11/4/00 | 0.39028 | 11/5/00 | 9:50 | 1893.87 | " | | IO 3.1 & IO 3.5 | | |
| 00110405-TSP-7515 | AC, ED, BK | PARCEL E, STATION E | 11/4/00 | 0.39583 | 11/5/00 | 9:58 | 1888.71 | " | | IO 3.1 & IO 3.5 | | |
| 00110405-TSP-7516 | AC, ED, BK | PARCEL E, STATION F | 11/4/00 | 0.40556 | 11/5/00 | 10:05 | 1881.79 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| 00110405-TSP-7517 | AC, ED, BK | PARCEL E, TSP-BLANK | 11/4/00 | NA | 11/5/00 | | NA | " | | IO 3.1 & IO 3.5 | | |

Special Instructions: Analyze PUFs for PCBs only.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarour | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). Sample 00110405-TSP-7513 will be a representative sample only. Samples 00110405-PUF-2816, 00110405-PUF-2817 & 00110405-PUF-2818 ran slightly less than 23 hours.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-110506



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/7/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00110506-PUF-2823 | AC, ED, BK | PARCEL E, STATION A | 11/5/00 | 9:19:00 | 11/6/00 | 9:19:00 | 326.68 | Jar & Envelope | | TO-4 | | |
| 00110506-PUF-2824 | AC, ED, BK | PARCEL E, STATION B | 11/5/00 | 9:27:00 | 11/6/00 | 8:42:00 | 323.52 | " | | TO-4 | | |
| 00110506-PUF-2825 | AC, ED, BK | PARCEL E, STATION C. | 11/5/00 | 9:34:00 | 11/6/00 | 8:47:00 | 304.24 | " | | TO-4 | | |
| 00110506-PUF-2826 | AC, ED, BK | PARCEL E, STATION D | 11/5/00 | 9:44:00 | 11/6/00 | 8:56:00 | 293.76 | " | | TO-4 | | |
| 00110506-PUF-2827 | AC, ED, BK | PARCEL E, STATION E | 11/5/00 | 9:57:00 | 11/6/00 | 9:03:00 | 330.41 | " | | TO-4 | | |
| 00110506-PUF-2828 | AC, ED, BK | PARCEL E, STATION F | 11/5/00 | 10:03:00 | 11/6/00 | 9:09:00 | 321.99 | " | | TO-4 | | |
| 00110506-PUF-2829 | AC, ED, BK | PARCEL E, STATION G | 11/5/00 | 9:49:00 | 11/6/00 | 8:58:00 | 321.23 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaroun | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-110607



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/8/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00110607-PUF-2830 | AC,BK | PARCEL E, STATION A | 11/6/00 | 11:08:00 | 11/7/00 | 11:08:00 | 383.80 | Jar & Envelope | | TO-4 | | |
| 00110607-PUF-2831 | AC,BK | PARCEL E, STATION B | 11/6/00 | 11:15:00 | 11/7/00 | 11:40:00 | 349.79 | " | | TO-4 | | |
| 00110607-PUF-2832 | AC,BK | PARCEL E, STATION C. | 11/6/00 | 8:52:00 | 11/7/00 | 8:18:00 | 344.85 | " | | TO-4 | | |
| 00110607-PUF-2833 | AC,BK | PARCEL E, STATION D | 11/6/00 | 11:24:00 | 11/7/00 | 11:53:00 | 348.02 | " | | TO-4 | | |
| 00110607-PUF-2834 | AC,BK | PARCEL E, STATION E | 11/6/00 | 9:06:00 | 11/7/00 | 8:40:00 | 336.21 | " | | TO-4 | | |
| 00110607-PUF-2835 | AC,BK | PARCEL E, STATION F | 11/6/00 | 9:13:00 | 11/7/00 | 8:44:00 | 320.56 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| 00110607-PUF-2836 | AC,BK | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| 00000 | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| 0000000 | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION C | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION E | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION F | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| 0000000 | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| 0000000 | | PARCEL E, STATION A | | | | | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION B | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION D | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION E | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION F | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| 0000000 | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-110708



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/9/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00110708-PUF-2837 | AC,BK | PARCEL E, STATION A | 11/7/00 | 11:34:00 | 11/8/00 | 11:34:00 | 303.56 | Jar & Envelope | | TO-4 | | |
| 00110708-PUF-2838 | AC,BK | PARCEL E, STATION B | 11/7/00 | 11:44:00 | 11/8/00 | 10:47:00 | 323.67 | " | | TO-4 | | |
| VOID | | PARCEL E, STATION C. | | | | | | " | | TO-4 | | |
| 00110708-PUF-2840 | AC,BK | PARCEL E, STATION D | 11/7/00 | 11:58:00 | 11/8/00 | 11:17:00 | 322.51 | " | | TO-4 | | |
| 00110708-PUF-2841 | AC,BK | PARCEL E, STATION E | 11/7/00 | 12:24:00 | 11/8/00 | 11:38:00 | 309.59 | " | | TO-4 | | |
| 00110708-PUF-2842 | AC,BK | PARCEL E, STATION F | 11/7/00 | 12:33:00 | 11/8/00 | 11:48:00 | 342.43 | " | | TO-4 | | |
| 00110708-PUF-2843 | AC,BK | PARCEL E, STATION G | 11/7/00 | 12:05:00 | 1/0/00 | 11:20:00 | 316.24 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| 00110708-VOC-A-704 | AC,BK | PARCEL E, STATION A | 11/7/00 | 11:32 | 11/8/00 | 10:35 | 7.00 psi | SUMMA | | TO-14a | | |
| 00110708-VOC-A-429 | AC,BK | PARCEL E, STATION B | 11/7/00 | 11:42 | 11/8/00 | 10:45 | 4.00 | " | | TO-14a | | |
| 00110708-VOC-A-511 | AC,BK | PARCEL E, STATION C | 11/7/00 | 8:15 | 11/8/00 | 7:19 | 1.00 | " | | TO-14a | | |
| 00110708-VOC-A-420 | AC,BK | PARCEL E, STATION D | 11/7/00 | 11:54 | 11/8/00 | 11:13 | 9.00 | " | | TO-14a | | |
| 00110708-VOC-A-805 | AC,BK | PARCEL E, STATION E | 11/7/00 | 12:25 | 11/8/00 | 11:32 | 0.00 | " | | TO-14a | | |
| 00110708-VOC-A-803 | AC,BK | PARCEL E, STATION F | 11/7/00 | 12:32 | 11/8/00 | 11:41 | 2.00 | " | | TO-14a | | |
| 00110708-VOC-A-703 | AC,BK | PARCEL E, STATION G | 11/7/00 | 12:03 | 11/8/00 | 11:34 | 4.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| 00110708-TSP-7518 | AC,BK | PARCEL E, STATION A | 11/7/00 | 11:37 | 11/8/00 | 10:43 | 1787.54 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00110708-TSP-7519 | AC,BK | PARCEL E, STATION B | 11/7/00 | 11:47 | 11/8/00 | 10:48 | 1781.10 | " | | IO 3.1 & IO 3.5 | | |
| VOID | AC,BK | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| 00110708-TSP-7521 | AC,BK | PARCEL E, STATION D | 11/7/00 | 12:01 | 11/8/00 | 12:02 | 1858.48 | " | | IO 3.1 & IO 3.5 | | |
| 00110708-TSP-7522 | AC,BK | PARCEL E, STATION E | 11/7/00 | 12:27 | 11/8/00 | 11:38 | 1793.99 | " | | IO 3.1 & IO 3.5 | | |
| 00110708-TSP-7523 | AC,BK | PARCEL E, STATION F | 11/7/00 | 12:36 | 11/8/00 | 11:47 | 1795.44 | " | | IO 3.1 & IO 3.5 | | |
| 00110708-TSP-7524 | AC,BK | PARCEL E, STATION G | 11/7/00 | 12:11 | 11/8/00 | 11:22 | 1795.44 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |

Special Instructions: Analyze PUFs for PCBs only Returning one void PUF sample.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-110809E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Kuhn, S.McNerney, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/10/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00110809-PUFAE-2855 | BK, SM, ED | PARCEL E, STATION A | 11/8/00 | 10:41:00 | 11/9/00 | 10:02:00 | 329.95 | Jar & Envelope | | TO-4 | | |
| 00110809-PUFBE-2856 | BK, SM, ED | PARCEL E, STATION B | 11/8/00 | 10:51:00 | 11/9/00 | 10:10:00 | 330.24 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION C. | | | | | | " | | TO-4 | | |
| 00110809-PUFDE-2858 | BK, SM, ED | PARCEL E, STATION D | 11/8/00 | 11:20:00 | 11/9/00 | 10:24:00 | 327.53 | " | | TO-4 | | |
| 00110809-PUFEE-2859 | BK, SM, ED | PARCEL E, STATION E | 11/8/00 | 11:37:00 | 11/9/00 | 10:37:00 | 329.62 | " | | TO-4 | | |
| 00110809-PUFFE-2860 | BK, SM, ED | PARCEL E, STATION F | 11/8/00 | 11:46:00 | 11/9/00 | 10:46:00 | 313.28 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00110809-FBEPUF-2861 | BK, SM, ED | PARCEL E, PUF-BLANK | 11/8/00 | NA | 11/9/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaround

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-110910



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz, B. Kuhn, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/10/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00110910-PUFAE-2845 | AC, ED, BK, SM | PARCEL E, STATION A | 11/9/00 | 10:07:00 | 11/10/00 | 9:29:00 | 326.17 | Jar & Envelope | | TO-4 | | |
| 00110910-PUFBE-2846 | AC, ED, BK, SM | PARCEL E, STATION B | 11/9/00 | 10:14:00 | 11/10/00 | 9:45:00 | 330.60 | " | | TO-4 | | |
| VOID | | PARCEL E, STATION C | | | | | | " | | TO-4 | | |
| 00110910-PUFDE-2853 | AC, ED, BK, SM | PARCEL E, STATION D | 11/9/00 | 10:28:00 | 11/10/00 | 10:48:00 | 338.99 | " | | TO-4 | | |
| 00110910-PUFEE-2854 | AC, ED, BK, SM | PARCEL E, STATION E | 11/9/00 | 10:40:00 | 11/10/00 | 11:00:00 | 341.82 | " | | TO-4 | | |
| 00110910-PUFFE-2862 | AC, ED, BK, SM | PARCEL E, STATION F | 11/9/00 | 10:50:00 | 11/10/00 | 11:11:00 | 329.41 | " | | TO-4 | | |
| 00110910-PUFGE-2863 | AC, ED, BK, SM | PARCEL E, STATION G | 11/9/00 | 10:31:00 | 11/10/00 | 10:55:00 | 328.05 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning VOID PUF sample.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaroun | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). PUF sample in Parcel E, Station C was voided since it only ran for approximately 2 hours.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111011



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. Diaz, S. McNerney, A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/13/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00111011-PUFAE-2864 | SM, ED, AC, BK | PARCEL E, STATION A | 11/10/00 | 9:35 | 11/11/00 | 8:49 | 335.59 | Jar & Envelope | | TO-4 | | |
| 00111011-PUFBE-2865 | SM, ED, AC, BK | PARCEL E, STATION B | 11/10/00 | 9:51 | 11/11/00 | 9:00 | 332.08 | " | | TO-4 | | |
| 00111011-PUFCE-2866 | SM, ED, AC, BK | PARCEL E, STATION C. | 11/10/00 | 10:43 | 11/11/00 | 9:10 | 336.37 | " | | TO-4 | | |
| 00111011-PUFDE-2867 | SM, ED, AC, BK | PARCEL E, STATION D | 11/10/00 | 10:54 | 11/11/00 | 9:54 | 325.50 | " | | TO-4 | | |
| 00111011-PUFEE-2868 | SM, ED, AC, BK | PARCEL E, STATION E | 11/10/00 | 11:06 | 11/11/00 | 10:06 | 334.21 | " | | TO-4 | | |
| VOID | | PARCEL E, STATION F | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | " | | TO-4 | | |
| 00111011-FBEPUF-2870 | SM, ED, AC, BK | PARCEL E, PUF-BLANK | 11/10/00 | NA | 11/11/00 | NA | NA | " | | TO-4 | | |
| 00111011-VOCAE-A-426 | SM, ED, AC, BK | PARCEL E, STATION A | 11/10/00 | 9:28 | 11/11/00 | 8:47 | 0.00 psi | SUMMA | | TO-14a | | |
| 00111011-VOCBE-A-502 | SM, ED, AC, BK | PARCEL E, STATION B | 11/10/00 | 9:45 | 11/11/00 | 8:58 | 3.50 | " | | TO-14a | | |
| 00111011-VOCCE-A-605 | SM, ED, AC, BK | PARCEL E, STATION C | 11/10/00 | 9:54 | 11/11/00 | 9:07 | 0.00 | " | | TO-14a | | |
| 00111011-VOCDE-A-602 | SM, ED, AC, BK | PARCEL E, STATION D | 11/10/00 | 10:47 | 11/11/00 | 9:47 | 9.00 | " | | TO-14a | | |
| 00111011-VOCEE-A-512 | SM, ED, AC, BK | PARCEL E, STATION E | 11/10/00 | 11:01 | 11/11/00 | 10:01 | 0.00 | " | | TO-14a | | |
| 00111011-VOCFE-A-101 | SM, ED, AC, BK | PARCEL E, STATION F | 11/10/00 | 11:12 | 11/11/00 | 10:23 | 5.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | " | | TO-14a | | |
| 00111011-FBEVOC-A-806 | SM, ED, AC, BK | PARCEL E, VOC-BLANK | 11/10/00 | NA | 11/11/00 | NA | NA | " | | TO-14a | | |
| 00111011-TSPAE-7531 | SM, ED, AC, BK | PARCEL E, STATION A | 11/10/00 | 9:40 | 11/11/00 | 8:54 | 1795.02 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00111011-TSPBE-7532 | SM, ED, AC, BK | PARCEL E, STATION B | 11/10/00 | 9:50 | 11/11/00 | 9:04 | 1797.93 | " | | IO 3.1 & IO 3.5 | | |
| 00111011-TSPCE-7533 | SM, ED, AC, BK | PARCEL E, STATION C | 11/10/00 | 9:59 | 11/11/00 | 9:14 | 1796.30 | " | | IO 3.1 & IO 3.5 | | |
| 00111011-TSPDE-7534 | SM, ED, AC, BK | PARCEL E, STATION D | 11/10/00 | 10:54 | 11/11/00 | 9:54 | 1779.87 | " | | IO 3.1 & IO 3.5 | | |
| 00111011-TSPEE-7535 | SM, ED, AC, BK | PARCEL E, STATION E | 11/10/00 | 11:06 | 11/11/00 | 10:06 | 1781.31 | " | | IO 3.1 & IO 3.5 | | |
| VOID | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | NA | | | IO 3.1 & IO 3.5 | | |
| 00111011-FBETSP-7537 | SM, ED, AC, BK | PARCEL E, TSP-BLANK | 11/10/00 | NA | 11/11/00 | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning 1 VOID PUF sample.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). PUF & TSP samples for Station F were voided since they only ran approximately 10 hours. PUF sampler burned out motor tripped the generator. Sample 00111011-PUFCE-2866 ran slightly less than 23 hours.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111112



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. Diaz, S. McNerney, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/13/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00111112-PUFAE-2871 | SMC, ED, BK | PARCEL E, STATION A | 11/11/00 | 8:52 | 11/12/00 | 8:33 | 343.89 | Jar & Envelope | | TO-4 | | |
| 00111112-PUFBE-2872 | SMC, ED, BK | PARCEL E, STATION B | 11/11/00 | 9:03 | 11/12/00 | 8:37 | 341.76 | " | | TO-4 | | |
| 00111112-PUFCE-2873 | SMC, ED, BK | PARCEL E, STATION C. | 11/11/00 | 9:13 | 11/12/00 | 8:43 | 338.52 | " | | TO-4 | | |
| 00111112-PUFDE-2874 | SMC, ED, BK | PARCEL E, STATION D | 11/11/00 | 9:58 | 11/12/00 | 8:58 | 336.49 | " | | TO-4 | | |
| 00111112-PUFEE-2875 | SMC, ED, BK | PARCEL E, STATION E | 11/11/00 | 10:10 | 11/12/00 | 9:10 | 345.70 | " | | TO-4 | | |
| 00111112-PUFFE-2876 | SMC, ED, BK | PARCEL E, STATION F | 11/11/00 | 10:43 | 11/12/00 | 9:43 | 350.22 | " | | TO-4 | | |
| 00111112-PUFGE-2877 | SMC, ED, BK | PARCEL E, STATION G | 11/11/00 | 9:23 | 11/12/00 | 8:49 | 345.48 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 11/11/00 | NA | 11/12/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 11/11/00 | NA | 11/12/00 | NA | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | 11/11/00 | 0 | 11/12/00 | 0:00 | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 11/11/00 | NA | 11/12/00 | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaroun

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111213



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. Diaz, S. McNerney, B. Kuhn, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/14/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00111213-PUFAE-2884 | ED, SM, BK, AC | PARCEL E, STATION A | 11/12/00 | 8:36:00 | 11/13/00 | 8:27:00 | 338.55 | Jar & Envelope | | TO-4 | | |
| 00111213-PUFBE-2885 | ED, SM, BK, AC | PARCEL E, STATION B | 11/12/00 | 8:40:00 | 11/13/00 | 8:36:00 | 342.38 | " | | TO-4 | | |
| 00111213-PUFCE-2886 | ED, SM, BK, AC | PARCEL E, STATION C. | 11/12/00 | 8:46:00 | 11/13/00 | 8:45:00 | 340.97 | " | | TO-4 | | |
| 00111213-PUFDE-2887 | ED, SM, BK, AC | PARCEL E, STATION D | 11/12/00 | 9:00:00 | 11/13/00 | 8:59:00 | 342.24 | " | | TO-4 | | |
| 00111213-PUFEE-2888 | ED, SM, BK, AC | PARCEL E, STATION E | 11/12/00 | 9:12:00 | 11/13/00 | 9:16:00 | 350.69 | " | | TO-4 | | |
| 00111213-PUFFE-2889 | ED, SM, BK, AC | PARCEL E, STATION F | 11/12/00 | 9:52:00 | 11/13/00 | 9:26:00 | 310.15 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 0111213-FBEPUF-2890 | ED, SM, BK, AC | PARCEL E, PUF-BLANK | 11/12/00 | NA | 11/13/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning one SUMMA regulator for maintenance or repairment.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111314E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/15/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00111314-PUFAE-2847 | AC,BK | PARCEL E, STATION A | 11/13/00 | 8:32 | 11/14/00 | 8:16 | 302.55 | Jar & Envelope | | TO-4 | | |
| 00111314-PUFBE-2891 | AC,BK | PARCEL E, STATION B | 11/13/00 | 8:42 | 11/14/00 | 8:30 | 338.75 | " | | TO-4 | | |
| 00111314-PUFCE-2892 | AC,BK | PARCEL E, STATION C. | 11/13/00 | 8:51 | 11/14/00 | 8:38 | 339.91 | " | | TO-4 | | |
| 00111314-PUFDE-2893 | AC,BK | PARCEL E, STATION D | 11/13/00 | 9:04 | 11/14/00 | 8:47 | 344.06 | " | | TO-4 | | |
| 00111314-PUFEE-2894 | AC,BK | PARCEL E, STATION E | 11/13/00 | 9:21 | 11/14/00 | 9:06 | 344.13 | " | | TO-4 | | |
| 00111314-PUFFE-2895 | AC,BK | PARCEL E, STATION F | 11/13/00 | 9:30 | 11/14/00 | 9:17 | 337.73 | " | | TO-4 | | |
| 00111314-PUFGE-2896 | AC,BK | PARCEL E, STATION G | 11/13/00 | 9:11 | 11/14/00 | 8:57 | 351.24 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| 00111314-VOCAE-A702 | AC,BK | PARCEL E, STATION A | 11/13/00 | 8:26 | 11/14/00 | 8:19 | 6.00 psi | SUMMA | | TO-14a | | |
| 00111314-VOCBE-A811 | AC,BK | PARCEL E, STATION B | 11/13/00 | 8:37 | 11/14/00 | 8:32 | 0.00 | " | | TO-14a | | |
| 00111314-VOCCE-A112 | AC,BK | PARCEL E, STATION C | 11/13/00 | 8:46 | 11/14/00 | 8:43 | 0.00 | " | | TO-14a | | |
| 00111314-VOCDE-A601 | AC,BK | PARCEL E, STATION D | 11/13/00 | 8:58 | 11/14/00 | 8:59 | 3.00 | " | | TO-14a | | |
| 00111314-VOCEE-A802 | AC,BK | PARCEL E, STATION E | 11/13/00 | 9:15 | 11/14/00 | 9:08 | 2.00 | " | | TO-14a | | |
| 00111314-VOCFE-A423 | AC,BK | PARCEL E, STATION F | 11/13/00 | 9:26 | 11/14/00 | 8:57 | 9.00 | " | | TO-14a | | |
| 00111314-VOCGE-A621 | AC,BK | PARCEL E, STATION G | 11/13/00 | 8:59 | 11/14/00 | 9:16 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| 00111314-TSPAE-7544 | AC,BK | PARCEL E, STATION A | 11/13/00 | 8:36 | 11/14/00 | 8:16 | 1836.43 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00111314-TSPBE-7545 | AC,BK | PARCEL E, STATION B | 11/13/00 | 8:43 | 11/14/00 | 8:34 | 1853.66 | " | | IO 3.1 & IO 3.5 | | |
| 00111314-TSPCE-7546 | AC,BK | PARCEL E, STATION C | 11/13/00 | 8:57 | 11/14/00 | 8:37 | 1834.94 | " | | IO 3.1 & IO 3.5 | | |
| 00111314-TSPDE-7547 | AC,BK | PARCEL E, STATION D | 11/13/00 | 9:00 | 11/14/00 | 8:47 | 1848.48 | " | | IO 3.1 & IO 3.5 | | |
| 00111314-TSPEE-7548 | AC,BK | PARCEL E, STATION E | 11/13/00 | 9:19 | 11/14/00 | 9:05 | 1847.19 | " | | IO 3.1 & IO 3.5 | | |
| 00111314-TSPFE-7549 | AC,BK | PARCEL E, STATION F | 11/13/00 | 9:28 | 11/14/00 | 9:17 | 1848.07 | " | | IO 3.1 & IO 3.5 | | |
| 00111314-TSPGE-7550 | AC,BK | PARCEL E, STATION G | 11/13/00 | 9:07 | 11/14/00 | 8:52 | 1805.57 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111415



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/16/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VOID | | PARCEL E, STATION A | | | | | | Jar & Envelope | | TO-4 | | |
| 00111415-PUFBE-2898 | AC, BK | PARCEL E, STATION B | 11/14/00 | 8:35 | 11/15/00 | 8:25 | 340.73 | " | | TO-4 | | |
| 00111415-PUFCE-2899 | AC, BK | PARCEL E, STATION C. | 11/14/00 | 8:44 | 11/15/00 | 8:31 | 337.92 | " | | TO-4 | | |
| 00111415-PUFDE-2900 | AC, BK | PARCEL E, STATION D | 11/14/00 | 8:55 | 11/15/00 | 8:38 | 341.91 | " | | TO-4 | | |
| 00111415-PUFEE-2901 | AC, BK | PARCEL E, STATION E | 11/14/00 | 9:13 | 11/15/00 | 8:54 | 334.32 | " | | TO-4 | | |
| 00111415-PUFFE-2902 | AC, BK | PARCEL E, STATION F | 11/14/00 | 9:23 | 11/15/00 | 8:58 | 329.82 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00111415-FBEPUF-2903 | AC, BK | PARCEL E, PUF-BLANK | 11/14/00 | NA | 11/15/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning one void PUF sample.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111516



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Kuhn, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/17/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00111516-PUFAE-2904 | BK, AC | PARCEL E, STATION A | 11/15/00 | 8:23 | 11/16/00 | 8:34 | 277.94 | Jar & Envelope | | TO-4 | | |
| 00111516-PUFBE-2905 | BK, AC | PARCEL E, STATION B | 11/15/00 | 8:29 | 11/16/00 | 8:43 | 343.63 | " | | TO-4 | | |
| 00111516-PUFCE-2906 | BK, AC | PARCEL E, STATION C. | 11/15/00 | 8:35 | 11/16/00 | 8:57 | 346.99 | " | | TO-4 | | |
| 00111516-PUFDE-2907 | BK, AC | PARCEL E, STATION D | 11/15/00 | 8:42 | 11/16/00 | 9:07 | 349.04 | " | | TO-4 | | |
| 00111516-PUFEE-2908 | BK, AC | PARCEL E, STATION E | 11/15/00 | 8:55 | 11/16/00 | 9:22 | 358.93 | " | | TO-4 | | |
| 00111516-PUFFE-2909 | BK, AC | PARCEL E, STATION F | 11/15/00 | 9:02 | 11/16/00 | 9:32 | 356.37 | " | | TO-4 | | |
| 00111516-PUFGE-2910 | BK, AC | PARCEL E, STATION G | 11/15/00 | 8:47 | 11/16/00 | 9:15 | 352.39 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | | | | | | | |
| --- | --- | --- | | | | | | | | | | |
| --- | --- | --- | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). Sample 00111516-PUFAE-2904 will be used as a representative sample only.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111617E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. CORTEZ, B. KUHN
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/17/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00111617-PUFAE-2911 | AC, BK | PARCEL E, STATION A | 11/16/00 | 8:39 | 11/17/00 | 8:26 | 344.16 | Jar & Envelope | | TO-4 | | |
| 00111617-PUFBE-2912 | AC, BK | PARCEL E, STATION B | 11/16/00 | 8:48 | 11/17/00 | 8:34 | 341.99 | " | | TO-4 | | |
| 00111617-PUFCE-2913 | AC, BK | PARCEL E, STATION C. | 11/16/00 | 9:02 | 11/17/00 | 8:42 | 341.43 | " | | TO-4 | | |
| 00111617-PUFDE-2914 | AC, BK | PARCEL E, STATION D | 11/16/00 | 9:13 | 11/17/00 | 8:53 | 341.61 | " | | TO-4 | | |
| 00111617-PUFEE-2915 | AC, BK | PARCEL E, STATION E | 11/16/00 | 9:26 | 11/17/00 | 9:09 | 347.68 | " | | TO-4 | | |
| 00111617-PUFFE-2916 | AC, BK | PARCEL E, STATION F | 11/16/00 | 9:37 | 11/17/00 | 9:20 | 333.75 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00111617-FBEPUF-2917 | AC, BK | PARCEL E, PUF-BLANK | 11/16/00 | NA | 11/17/00 | NA | NA | " | | TO-4 | | |
| 00111617-VOCAE-A428 | AC, BK | PARCEL E, STATION A | 11/16/00 | 8:31 | 11/17/00 | 8:33 | 9.00 psi | SUMMA | | TO-14a | | |
| 00111617-VOCBE-A105 | AC, BK | PARCEL E, STATION B | 11/16/00 | 8:45 | 11/17/00 | 8:40 | 0.00 | " | | TO-14a | | |
| 00111617-VOCCE-A508 | AC, BK | PARCEL E, STATION C | 11/16/00 | 8:55 | 11/17/00 | 8:47 | 0.00 | " | | TO-14a | | |
| 00111617-VOCDE-A808 | AC, BK | PARCEL E, STATION D | 11/16/00 | 9:15 | 11/17/00 | 8:57 | 3.50 | " | | TO-14a | | |
| 00111617-VOCEE-A417 | AC, BK | PARCEL E, STATION E | 11/16/00 | 9:23 | 11/17/00 | 9:12 | 0.00 | " | | TO-14a | | |
| 00111617-VOCFE-A607 | AC, BK | PARCEL E, STATION F | 11/16/00 | 9:37 | 11/17/00 | 9:23 | 3.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| 00111617-FBEVOC-A807 | AC, BK | PARCEL E, VOC-BLANK | 11/16/00 | NA | 11/17/00 | NA | NA | " | | TO-14a | | |
| 00111617-TSPAE-7551 | AC, BK | PARCEL E, STATION A | 11/16/00 | 8:37 | 11/17/00 | 8:26 | 1860.22 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00111617-TSPBE-7552 | AC, BK | PARCEL E, STATION B | 11/16/00 | 8:48 | 11/17/00 | 8:36 | 1861.94 | " | | IO 3.1 & IO 3.5 | | |
| 00111617-TSPCE-7553 | AC, BK | PARCEL E, STATION C | 11/16/00 | 9:02 | 11/17/00 | 8:44 | 1851.10 | " | | IO 3.1 & IO 3.5 | | |
| 00111617-TSPDE-7554 | AC, BK | PARCEL E, STATION D | 11/16/00 | 9:10 | 11/17/00 | 8:50 | 1851.51 | " | | IO 3.1 & IO 3.5 | | |
| 00111617-TSPEE-7555 | AC, BK | PARCEL E, STATION E | 11/16/00 | 9:23 | 11/17/00 | 9:11 | 1858.03 | " | | IO 3.1 & IO 3.5 | | |
| 00111617-TSPFE-7556 | AC, BK | PARCEL E, STATION F | 11/16/00 | 9:35 | 11/17/00 | 9:22 | 1859.13 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| 00111617-FBETSP-7557 | AC, BK | PARCEL E, TSP-BLANK | 11/16/00 | NA | 11/17/00 | NA | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaround | QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) Date: Time: | 1. Received by (Signature/Affiliation) Date: Time: |
| 2. Relinquished by (Signature/Affiliation) Date: Time: | 2. Received by (Signature/Affiliation) Date: Time: |
| 3. Relinquished by (Signature/Affiliation) Date: Time: | 3. Received by (Signature/Affiliation) Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111718



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Kuhn, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/20/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00111718-PUFAE-2924 | BK, AC | PARCEL E, STATION A | 11/17/00 | 8:31 | 11/18/00 | 8:37 | 345.33 | Jar & Envelope | | TO-4 | | |
| 00111718-PUFBE-2925 | BK, AC | PARCEL E, STATION B | 11/17/00 | 8:38 | 11/18/00 | 8:45 | 345.32 | " | | TO-4 | | |
| 00111718-PUFCE-2926 | BK, AC | PARCEL E, STATION C. | 11/17/00 | 8:47 | 11/18/00 | 8:51 | 341.90 | " | | TO-4 | | |
| 00111718-PUFDE-2927 | BK, AC | PARCEL E, STATION D | 11/17/00 | 8:58 | 11/18/00 | 9:00 | 347.03 | " | | TO-4 | | |
| 00111718-PUFEE-2928 | BK, AC | PARCEL E, STATION E | 11/17/00 | 9:14 | 11/18/00 | 9:12 | 347.45 | " | | TO-4 | | |
| 00111718-PUFFE-2929 | BK, AC | PARCEL E, STATION F | 11/17/00 | 9:25 | 11/18/00 | 9:19 | 333.16 | " | | TO-4 | | |
| 00111718-PUFGE-2930 | BK, AC | PARCEL E, STATION G | 11/17/00 | 9:05 | 11/18/00 | 9:05 | 341.27 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 11/17/00 | NA | 11/18/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 11/17/00 | NA | 11/18/00 | NA | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | 11/17/00 | 0:00 | 11/18/00 | 0:00 | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 11/17/00 | NA | 11/18/00 | | NA | " | | IO 3.1 & IO 3.5 | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111819



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/20/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00111819-PUFAE-2931 | AC, BK | PARCEL E, STATION A | 11/18/00 | 8:42 | 11/19/00 | 8:24 | 306.41 | Jar & Envelope | | TO-4 | | |
| 00111819-PUFBE-2932 | AC, BK | PARCEL E, STATION B | 11/18/00 | 8:49 | 11/19/00 | 8:35 | 340.14 | " | | TO-4 | | |
| 00111819-PUFCE-2933 | AC, BK | PARCEL E, STATION C. | 11/18/00 | 8:54 | 11/19/00 | 8:45 | 334.60 | " | | TO-4 | | |
| 00111819-PUFDE-2934 | AC, BK | PARCEL E, STATION D | 11/18/00 | 9:04 | 11/19/00 | 8:59 | 345.16 | " | | TO-4 | | |
| 00111819-PUFEE-2935 | AC, BK | PARCEL E, STATION E | 11/18/00 | 9:16 | 11/19/00 | 9:19 | 310.03 | " | | TO-4 | | |
| 00111819-PUFFE-2936 | AC, BK | PARCEL E, STATION F | 11/18/00 | 9:23 | 11/19/00 | 9:29 | 337.44 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 0111819-FBEPUF-2937 | AC, BK | PARCEL E, PUF-BLANK | 11/18/00 | NA | 11/19/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarour | QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) Date: Time: | 1. Received by (Signature/Affiliation) Date: Time: |
| 2. Relinquished by (Signature/Affiliation) Date: Time: | 2. Received by (Signature/Affiliation) Date: Time: |
| 3. Relinquished by (Signature/Affiliation) Date: Time: | 3. Received by (Signature/Affiliation) Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-111920



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/21/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00111920-PUFAE-2938 | AC, BK | PARCEL E, STATION A | 11/19/00 | 8:29 | 11/20/00 | 8:41 | 346.20 | Jar & Envelope | | TO-4 | | |
| 00111920-PUFBE-2939 | AC, BK | PARCEL E, STATION B | 11/19/00 | 8:41 | 11/20/00 | 8:50 | 348.85 | " | | TO-4 | | |
| 00111920-PUFCE-2940 | AC, BK | PARCEL E, STATION C. | 11/19/00 | 8:51 | 11/20/00 | 8:59 | 334.02 | " | | TO-4 | | |
| 00111920-PUFDE-2941 | AC, BK | PARCEL E, STATION D | 11/19/00 | 9:05 | 11/20/00 | 9:20 | 349.53 | " | | TO-4 | | |
| 00111920-PUFEE-2942 | AC, BK | PARCEL E, STATION E | 11/19/00 | 9:25 | 11/20/00 | 9:40 | 350.91 | " | | TO-4 | | |
| 00111920-PUFFE-2943 | AC, BK | PARCEL E, STATION F | 11/19/00 | 9:37 | 11/20/00 | 9:51 | 338.92 | " | | TO-4 | | |
| 00111920-PUFGE-2944 | AC, BK | PARCEL E, STATION G | 11/19/00 | 9:14 | 11/20/00 | 9:29 | 348.21 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| 0111920-VOCAE-A307 | AC, BK | PARCEL E, STATION A | 11/19/00 | 8:28 | 11/20/00 | 8:43 | 0.00 psi | SUMMA | | TO-14a | | |
| 0111920-VOCBE-A420 | AC, BK | PARCEL E, STATION B | 11/19/00 | 8:36 | 11/20/00 | 8:54 | 0.00 | " | | TO-14a | | |
| 0111920-VOCCE-A507 | AC, BK | PARCEL E, STATION C | 11/19/00 | 8:47 | 11/20/00 | 9:04 | 11.00 | " | | TO-14a | | |
| 0111920-VOCDE-A511 | AC, BK | PARCEL E, STATION D | 11/19/00 | 8:59 | 11/20/00 | 9:18 | 3.00 | " | | TO-14a | | |
| 0111920-VOCEE-A605 | AC, BK | PARCEL E, STATION E | 11/19/00 | 9:20 | 11/20/00 | 9:43 | 6.00 | " | | TO-14a | | |
| 0111920-VOCFE-A704 | AC, BK | PARCEL E, STATION F | 11/19/00 | 9:36 | 11/20/00 | 9:51 | 3.00 | " | | TO-14a | | |
| 0111920-VOCGE-A803 | AC, BK | PARCEL E, STATION G | 11/19/00 | 9:07 | 11/20/00 | 9:24 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| 00111920-TSPAE-7565 | AC, BK | PARCEL E, STATION A | 11/19/00 | 8:37 | 11/20/00 | 8:38 | 1880.09 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00111920-TSPBE-7566 | AC, BK | PARCEL E, STATION B | 11/19/00 | 8:42 | 11/20/00 | 8:52 | 1894.90 | " | | IO 3.1 & IO 3.5 | | |
| 00111920-TSPCE-7567 | AC, BK | PARCEL E, STATION C | 11/19/00 | 8:49 | 11/20/00 | 9:01 | 1894.44 | " | | IO 3.1 & IO 3.5 | | |
| 00111920-TSPDE-7568 | AC, BK | PARCEL E, STATION D | 11/19/00 | 9:05 | 11/20/00 | 9:15 | 1894.90 | " | | IO 3.1 & IO 3.5 | | |
| 00111920-TSPEE-7569 | AC, BK | PARCEL E, STATION E | 11/19/00 | 9:20 | 11/20/00 | 9:41 | 1904.05 | " | | IO 3.1 & IO 3.5 | | |
| 00111920-TSPFE-7570 | AC, BK | PARCEL E, STATION F | 11/19/00 | 9:37 | 11/20/00 | 9:53 | 1899.66 | " | | IO 3.1 & IO 3.5 | | |
| 00111920-TSPGE-7571 | AC, BK | PARCEL E, STATION G | 11/19/00 | 9:11 | 11/20/00 | 9:37 | 1908.05 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaround

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-112021



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. KUHN, A. CORTEZ
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/22/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00112021-PUFAE-2945 | AC, BK | PARCEL E, STATION A | 11/20/00 | 8:47 | 11/21/00 | 8:30 | 338.41 | Jar & Envelope | | TO-4 | | 29537 |
| 00112021-PUFBE-2946 | AC, BK | PARCEL E, STATION B | 11/20/00 | 8:56 | 11/21/00 | 8:34 | 317.29 | " | | TO-4 | | 29538 |
| 00112021-PUFCE-2947 | AC, BK | PARCEL E, STATION C. | 11/20/00 | 9:08 | 11/21/00 | 8:42 | 333.34 | " | | TO-4 | | 29539 |
| 00112021-PUFDE-2948 | AC, BK | PARCEL E, STATION D | 11/20/00 | 9:28 | 11/21/00 | 8:50 | 334.88 | " | | TO-4 | | 29540 |
| 00112021-PUFEE-2949 | AC, BK | PARCEL E, STATION E | 11/20/00 | 9:46 | 11/21/00 | 9:05 | 336.42 | " | | TO-4 | | 29541 |
| 00112021-PUFFE-2950 | AC, BK | PARCEL E, STATION F | 11/20/00 | 9:57 | 11/21/00 | 9:15 | 328.19 | " | | TO-4 | | 29542 |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00112021-FBEPUF-2951 | AC, BK | PARCEL E, PUF-BLANK | 11/20/00 | NA | 11/21/00 | NA | NA | " | | TO-4 | | 29543 |
| NOT COLLECTED | | PARCEL E, STATION A | NA | NA | NA | NA | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | NA | NA | NA | NA | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | NA | NA | NA | NA | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | NA | NA | NA | NA | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | NA | NA | NA | NA | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | NA | NA | NA | NA | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | NA | NA | NA | NA | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | NA | NA | NA | NA | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | NA | NA | NA | NA | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | NA | NA | NA | NA | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | NA | NA | NA | NA | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | NA | NA | NA | NA | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | NA | NA | NA | NA | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | NA | NA | NA | NA | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | NA | NA | NA | NA | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | NA | NA | NA | NA | NA | " | | IO 3.1 & IO 3.5 | | |

Special Instructions: Analyze RUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaroun

QC Level: Per SOW

1. Relinquished by (Signature/Affiliation): Date: 11-22-00 Time: 1148
2. Relinquished by (Signature/Affiliation): Date: 11.22.00 Time: 2:15
3. Relinquished by (Signature/Affiliation): Date: Time:

1. Received by (Signature/Affiliation): Date: 11 22 00 Time: 12:48
2. Received by (Signature/Affiliation): Date: 11-22-00 Time: 2:15
3. Received by (Signature/Affiliation): Date: Time:

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-112122



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. CORTEZ, B. KUHN
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/22/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00112122-PUFAE-2958 | AC, BK | PARCEL E, STATION A | 11/21/00 | 8:31 | 11/22/00 | 8:30 | 342.56 | Jar & Envelope | | TO-4 | | |
| VOID | | PARCEL E, STATION B | | | | | | " | | TO-4 | | |
| VOID | | PARCEL E, STATION C. | | | | | | " | | TO-4 | | |
| 00112122-PUFDE-2961 | AC, BK | PARCEL E, STATION D | 11/21/00 | 8:54 | 11/22/00 | 8:44 | 342.93 | " | | TO-4 | | |
| 00112122-PUFEE-2962 | AC, BK | PARCEL E, STATION E | 11/21/00 | 9:10 | 11/22/00 | 8:56 | 343.31 | " | | TO-4 | | |
| 00112122-PUFFE-2963 | AC, BK | PARCEL E, STATION F | 11/21/00 | 9:19 | 11/22/00 | 8:52 | 335.23 | " | | TO-4 | | |
| 00112122-PUFGE-2964 | AC, BK | PARCEL E, STATION G | 11/21/00 | 8:59 | 11/22/00 | 8:46 | 337.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | 11/21/00 | NA | 11/22/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 11/21/00 | NA | 11/22/00 | NA | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | 11/21/00 | 0:00 | 11/22/00 | 0:00 | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | 11/21/00 | NA | 11/22/00 | | NA | " | | IO 3.1 & IO 3.5 | | |

Special Instructions: Analyze PUFs for PCBs only. Returning 2 VOID PUF samples #2959 & #2960.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). PUF samples in Stations BE & CE voided since they ran less than 4 hours due to heavy rains tripping the generator.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-112728E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. CORTEZ, B. KUHN
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/28/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00112728-PUFAE-2965 | AC, BK | PARCEL E, STATION A | 11/27/00 | 8:31 | 11/28/00 | 8:45 | 339.16 | Jar & Envelope | | TO-4 | | |
| 00112728-PUFBE-2966 | AC, BK | PARCEL E, STATION B | 11/27/00 | 9:22 | 11/28/00 | 8:53 | 331.11 | " | | TO-4 | | |
| 00112728-PUFCE-2967 | AC, BK | PARCEL E, STATION C. | 11/27/00 | 8:52 | 11/28/00 | 8:59 | 341.71 | " | | TO-4 | | |
| 00112728-PUFDE-2968 | AC, BK | PARCEL E, STATION D | 11/27/00 | 9:18 | 11/28/00 | 9:05 | 338.68 | " | | TO-4 | | |
| 00112728-PUFEE-2969 | AC, BK | PARCEL E, STATION E | 11/27/00 | 9:36 | 11/28/00 | 9:19 | 342.83 | " | | TO-4 | | |
| 00112728-PUFFE-2970 | AC, BK | PARCEL E, STATION F | 11/27/00 | 9:44 | 11/28/00 | 9:25 | 330.91 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00112728-FBEPUF-2971 | AC, BK | PARCEL E, PUF-BLANK | 11/27/00 | NA | 11/28/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaround | QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-112829



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/30/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00112829-PUFAE-2972 | AC, BK | PARCEL E, STATION A | 11/28/00 | 8:49 | 11/29/00 | 8:55 | 339.49 | Jar & Envelope | | TO-4 | | |
| 00112829-PUFBE-2973 | AC, BK | PARCEL E, STATION B | 11/28/00 | 8:56 | 11/29/00 | 3:00 | 255.93 | " | | TO-4 | | |
| 00112829-PUFCE-2974 | AC, BK | PARCEL E, STATION C | 11/28/00 | 9:02 | 11/29/00 | 9:07 | 339.78 | " | | TO-4 | | |
| 00112829-PUFDE-2975 | AC, BK | PARCEL E, STATION D | 11/28/00 | 9:08 | 11/29/00 | 9:16 | 342.09 | " | | TO-4 | | |
| 00112829-PUFEE-2976 | AC, BK | PARCEL E, STATION E | 11/28/00 | 9:22 | 11/29/00 | 9:30 | 343.16 | " | | TO-4 | | |
| 00112829-PUFFE-2977 | AC, BK | PARCEL E, STATION F | 11/28/00 | 9:30 | 11/29/00 | 9:36 | 336.97 | " | | TO-4 | | |
| 00112829-PUFGE-2985 | AC, BK | PARCEL E, STATION G | 11/28/00 | 9:53 | 11/29/00 | 9:21 | 335.07 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning VOID PUF sample #2978.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). Sample 00112829-PUFGE-2992 ran approx. 18 hours and will be analyzed as a representative sample only. Heavy rains tripped the generator.

TERNATIONAL
CHNOLOGY
CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-112930



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 11/30/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00112930-PUFAE-2979 | AC, BK | PARCEL E, STATION A | 11/29/00 | 8:58 | 11/30/00 | 8:41 | 341.60 | Jar & Envelope | | TO-4 | | |
| 00112930-PUFBE-2980 | AC, BK | PARCEL E, STATION B | 11/29/00 | 9:04 | 11/30/00 | 8:51 | 337.50 | " | | TO-4 | | |
| 00112930-PUFCE-2981 | AC, BK | PARCEL E, STATION C. | 11/29/00 | 9:10 | 11/30/00 | 9:02 | 337.31 | " | | TO-4 | | |
| 00112930-PUFDE-2982 | AC, BK | PARCEL E, STATION D | 11/29/00 | 9:20 | 11/30/00 | 9:19 | 336.77 | " | | TO-4 | | |
| 00112930-PUFEE-2983 | AC, BK | PARCEL E, STATION E | 11/29/00 | 9:33 | 11/30/00 | 9:43 | 348.37 | " | | TO-4 | | |
| 00112930-PUFFE-2984 | AC, BK | PARCEL E, STATION F | 11/29/00 | 9:40 | 11/30/00 | 9:53 | 340.83 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00112930-FBEPUF-2992 | AC, BK | PARCEL E, PUF-BLANK | 11/29/00 | NA | 11/30/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | psi | SUMMA | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | " | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | Envelope | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | " | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | " | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | " | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | " | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | " | IO 3.1 & IO 3.5 | | |
| ---------- | ---------- | ---------- | | | | | | | | IO 3.1 & IO 3.5 | | |
| ---------- | ---------- | ---------- | | | | | | | | IO 3.1 & IO 3.5 | | |
| ---------- | ---------- | ---------- | | | | | | | | ---------- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnarou

QC Level: Per SOW

1. Relinquished by (Signature/Affiliation) Date: Time:
2. Relinquished by (Signature/Affiliation) Date: Time:
3. Relinquished by (Signature/Affiliation) Date: Time:

1. Received by (Signature/Affiliation) Date: Time:
2. Received by (Signature/Affiliation) Date: Time:
3. Received by (Signature/Affiliation) Date: Time:

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-113001E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/1/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00113001-PUFAE-2993 | AC, BK | PARCEL E, STATION A | 11/30/00 | 8:47 | 12/1/00 | 8:17 | 336.29 | Jar & Envelope | | TO-4 | | |
| 00113001-PUFBE-2994 | AC, BK | PARCEL E, STATION B | 11/30/00 | 8:58 | 12/1/00 | 8:26 | 334.29 | " | | TO-4 | | |
| 00113001-PUFCE-2995 | AC, BK | PARCEL E, STATION C. | 11/30/00 | 9:09 | 12/1/00 | 8:37 | 332.93 | " | | TO-4 | | |
| 00113001-PUFDE-2996 | AC, BK | PARCEL E, STATION D | 11/30/00 | 9:26 | 12/1/00 | 8:51 | 337.64 | " | | TO-4 | | |
| 00113001-PUFEE-2997 | AC, BK | PARCEL E, STATION E | 11/30/00 | 9:50 | 12/1/00 | 9:21 | 340.42 | " | | TO-4 | | |
| 00113001-PUFFE-2998 | AC, BK | PARCEL E, STATION F | 11/30/00 | 9:59 | 12/1/00 | 9:09 | 327.27 | " | | TO-4 | | |
| 00113001-PUFGE-2999 | AC, BK | PARCEL E, STATION G | 11/30/00 | 9:32 | 12/1/00 | 9:02 | 338.08 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| 00113001-VOCAE-A206 | AC, BK | PARCEL E, STATION A | 11/30/00 | 8:45 | 12/1/00 | 9:15 | 2.00 psi | SUMMA | | TO-14a | | |
| 00113001-VOCBE-A503 | AC, BK | PARCEL E, STATION B | 11/30/00 | 8:55 | 12/1/00 | 8:28 | 6.50 | " | | TO-14a | | |
| 00113001-VOCCE-A637 | AC, BK | PARCEL E, STATION C | 11/30/00 | 9:06 | 12/1/00 | 8:39 | 0.00 | " | | TO-14a | | |
| 00113001-VOCDE-A703 | AC, BK | PARCEL E, STATION D | 11/30/00 | 9:23 | 12/1/00 | 8:54 | 0.00 | " | | TO-14a | | |
| 00113001-VOCEE-A806 | AC, BK | PARCEL E, STATION E | 11/30/00 | 9:47 | 12/1/00 | 9:23 | 0.00 | " | | TO-14a | | |
| 00113001-VOCFE-A604 | AC, BK | PARCEL E, STATION F | 11/30/00 | 9:58 | 12/1/00 | 9:11 | 12.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| 00113001-FBEVOC-A705 | AC, BK | PARCEL E, VOC-BLANK | 11/30/00 | NA | 12/1/00 | NA | NA | " | | TO-14a | | |
| 00113001-TSPAE-7586 | AC, BK | PARCEL E, STATION A | 11/30/00 | 8:43 | 12/1/00 | 8:12 | 1830.59 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00113001-TSPBE-7587 | AC, BK | PARCEL E, STATION B | 11/30/00 | 8:54 | 12/1/00 | 8:26 | 1838.98 | " | | IO 3.1 & IO 3.5 | | |
| 00113001-TSPCE-7588 | AC, BK | PARCEL E, STATION C | 11/30/00 | 9:04 | 12/1/00 | 8:37 | 1835.79 | " | | IO 3.1 & IO 3.5 | | |
| 00113001-TSPDE-7589 | AC, BK | PARCEL E, STATION D | 11/30/00 | 9:21 | 12/1/00 | 8:50 | 1835.07 | " | | IO 3.1 & IO 3.5 | | |
| 00113001-TSPEE-7590 | AC, BK | PARCEL E, STATION E | 11/30/00 | 9:47 | 12/1/00 | 9:21 | 1846.79 | " | | IO 3.1 & IO 3.5 | | |
| 00113001-TSPFE-7591 | AC, BK | PARCEL E, STATION F | 11/30/00 | 9:55 | 12/1/00 | 9:09 | 1812.58 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| 00113001-FBETSP-7592 | AC, BK | PARCEL E, TSP-BLANK | 11/30/00 | NA | 12/1/00 | NA | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaround | QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-120102E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: S, MCNERNEY, E, DIAZ
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/4/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 001201102-PUFAE-3000 | SMC, ED | PARCEL E, STATION A | 12/1/00 | 8:23 | 12/2/00 | 8:23 | 342.87 | Jar & Envelope | | TO-4 | | |
| 001201102-PUFBE-3001 | SMC, ED | PARCEL E, STATION B | 12/1/00 | 8:34 | 12/2/00 | 8:34 | 339.53 | " | | TO-4 | | |
| VOID | SMC, ED | PARCEL E, STATION C. | | | | | | | | | | |
| 001201102-PUFDE-3003 | SMC, ED | PARCEL E, STATION D | 12/1/00 | 9:01 | 12/2/00 | 9:01 | 345.41 | " | | TO-4 | | |
| 001201102-PUFEE-3004 | SMC, ED | PARCEL E, STATION E | 12/1/00 | 9:29 | 12/2/00 | 9:29 | 334.44 | " | | TO-4 | | |
| 001201102-PUFFE-3005 | SMC, ED | PARCEL E, STATION F | 12/1/00 | 9:18 | 12/2/00 | 9:33 | 335.35 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| 001201102-FBEPUF-3006 | SMC, ED | PARCEL E, PUF-BLANK | 12/1/00 | NA | 12/2/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | | | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only RETURN 3002

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809) Motor down on station C, Sample voided

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-120203



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. DIAZ, S. MCNERNEY
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/4/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00120203-PUFAE-3007 | ED, SM | PARCEL E, STATION A | 12/2/00 | 8:27 | 12/3/00 | 8:07 | 337.76 | Jar & Envelope | | TO-4 | | |
| 00120203-PUFBE-3008 | ED, SM | PARCEL E, STATION B | 12/2/00 | 8:42 | 12/3/00 | 8:22 | 336.19 | " | | TO-4 | | |
| 00120203-PUFCE-3009 | ED, SM | PARCEL E, STATION C. | 12/2/00 | 8:59 | 12/3/00 | 8:39 | 330.44 | " | | TO-4 | | |
| 00120203-PUFDE-3010 | ED, SM | PARCEL E, STATION D | 12/2/00 | 9:14 | 12/3/00 | 8:54 | 336.47 | " | | TO-4 | | |
| 00120203-PUFEE-3011 | ED, SM | PARCEL E, STATION E | 12/2/00 | 9:31 | 12/3/00 | 9:11 | 343.53 | " | | TO-4 | | |
| 00120203-PUFFE-3012 | ED, SM | PARCEL E, STATION F | 12/2/00 | 9:46 | 12/3/00 | 9:26 | 331.81 | " | | TO-4 | | |
| 00120203-PUFGE-3013 | ED, SM | PARCEL E, STATION G | 12/2/00 | 9:16 | 12/3/00 | 8:56 | 328.98 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | psi | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | | | | |
| --- | --- | --- | | | | | --- | --- | --- | --- | | |
| --- | --- | --- | | | | | --- | --- | --- | --- | | |
| --- | --- | --- | | | | | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-120304E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. DIAZ, S. MCNERNEY, B. KUHN
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/5/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00120304-PUFAE-3014 | ED, SM, BK | PARCEL E, STATION A | 12/3/00 | 8:15 | 12/4/00 | 7:42 | 329.73 | Jar & Envelope | | TO-4 | | |
| 00120304-PUFBE-3015 | ED, SM, BK | PARCEL E, STATION B | 12/3/00 | 8:31 | 12/4/00 | 7:47 | 327.36 | " | | TO-4 | | |
| 00120304-PUFCE-3016 | ED, SM, BK | PARCEL E, STATION C. | 12/3/00 | 8:46 | 12/4/00 | 7:52 | 322.79 | " | | TO-4 | | |
| 00120304-PUFDE-3017 | ED, SM, BK | PARCEL E, STATION D | 12/3/00 | 9:00 | 12/4/00 | 8:00 | 323.60 | " | | TO-4 | | |
| 00120304-PUFEE-3018 | ED, SM, BK | PARCEL E, STATION E | 12/3/00 | 9:16 | 12/4/00 | 8:25 | 330.47 | " | | TO-4 | | |
| 00120304-PUFFE-3019 | ED, SM, BK | PARCEL E, STATION F | 12/3/00 | 9:29 | 12/4/00 | 8:29 | 321.15 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00120304-FBEPUF-3020 | ED, SM, BK | PARCEL E, PUF-BLANK | 12/3/00 | NA | 12/4/00 | NA | NA | " | | TO-4 | | |
| 00120304-VOCAE-A810 | ED, SM, BK | PARCEL E, STATION A | 12/3/00 | 8:10 | 12/4/00 | 7:43 | 12.00 psi | SUMMA | | TO-14a | | |
| 00120304-VOCBE-A811 | ED, SM, BK | PARCEL E, STATION B | 12/3/00 | 8:26 | 12/4/00 | 7:46 | 0.00 | " | | TO-14a | | |
| 00120304-VOCCE-A204 | ED, SM, BK | PARCEL E, STATION C | 12/3/00 | 8:42 | 12/4/00 | 7:52 | 6.00 | " | | TO-14a | | |
| 00120304-VOCDE-A508 | ED, SM, BK | PARCEL E, STATION D | 12/3/00 | 8:58 | 12/4/00 | 8:00 | 0.00 | " | | TO-14a | | |
| 00120304-VOCEE-A601 | ED, SM, BK | PARCEL E, STATION E | 12/3/00 | 9:15 | 12/4/00 | 8:26 | 5.00 | " | | TO-14a | | |
| 00120304-VOCFE-A105 | ED, SM, BK | PARCEL E, STATION F | 12/3/00 | 9:30 | 12/4/00 | 8:30 | 5.00 | " | | TO-14a | | |
| 00120304-VOCGE-A807 | ED, SM, BK | PARCEL E, STATION G | 12/3/00 | 9:03 | 12/4/00 | 8:03 | 5.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| 00120304-TSPAE-7599 | ED, SM, BK | PARCEL E, STATION A | 12/3/00 | 8:16 | 12/4/00 | 7:40 | 1820.01 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00120304-TSPBE-7601 | ED, SM, BK | PARCEL E, STATION B | 12/3/00 | 8:32 | 12/4/00 | 7:46 | 1809.98 | " | | IO 3.1 & IO 3.5 | | |
| 00120304-TSPCE-7602 | ED, SM, BK | PARCEL E, STATION C | 12/3/00 | 8:48 | 12/4/00 | 7:50 | 1791.49 | " | | IO 3.1 & IO 3.5 | | |
| 00120304-TSPDE-7603 | ED, SM, BK | PARCEL E, STATION D | 12/3/00 | 9:02 | 12/4/00 | 8:02 | 1791.81 | " | | IO 3.1 & IO 3.5 | | |
| 00120304-TSPEE-7604 | ED, SM, BK | PARCEL E, STATION E | 12/3/00 | 9:15 | 12/4/00 | 8:22 | 1802.68 | " | | IO 3.1 & IO 3.5 | | |
| 00120304-TSPFE-7605 | ED, SM, BK | PARCEL E, STATION F | 12/3/00 | 9:31 | 12/4/00 | 8:31 | 1790.35 | " | | IO 3.1 & IO 3.5 | | |
| 00120304-TSPGE-7606 | ED, SM, BK | PARCEL E, STATION G | 12/3/00 | 9:04 | 12/4/00 | 8:04 | 1796.17 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaround

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-120405E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. Diaz, B. Kuhn S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/5/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00120405-PUFAE-3027 | BK, ED, SM | PARCEL E, STATION A | 12/4/00 | 10:34 | 12/5/00 | 9:37 | 335.93 | Jar & Envelope | | TO-4 | | |
| 00120405-PUFBE-3028 | BK, ED, SM | PARCEL E, STATION B | 12/4/00 | 10:37 | 12/5/00 | 9:45 | 325.05 | " | | TO-4 | | |
| 00120405-PUFCE-3029 | BK, ED, SM | PARCEL E, STATION C. | 12/4/00 | 10:43 | 12/5/00 | 9:53 | 319.47 | " | | TO-4 | | |
| 00120405-PUFDE-3030 | BK, ED, SM | PARCEL E, STATION D | 12/4/00 | 10:46 | 12/5/00 | 10:01 | 336.37 | " | | TO-4 | | |
| 00120405-PUFEE-3031 | BK, ED, SM | PARCEL E, STATION E | 12/4/00 | 10:55 | 12/5/00 | 10:20 | 323.49 | " | | TO-4 | | |
| 00120405-PUFFE-3032 | BK, ED, SM | PARCEL E, STATION F | 12/4/00 | 10:52 | 12/5/00 | 10:11 | 321.53 | " | | TO-4 | | |
| 00120405-PUFGE-3033 | BK, ED, SM | PARCEL E, STATION G | 12/4/00 | 10:48 | 12/5/00 | 10:08 | 325.95 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | NA | | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | 0:00 | | 0:00 | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | 0:00 | | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | 0:00 | | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | 0:00 | | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | 0:00 | | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | 0:00 | | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | 0:00 | | 0:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | NA | | NA | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | 0:00 | | 0:00 | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | 0:00 | | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | 0:00 | | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | 0:00 | | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | 0:00 | | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | 0:00 | | 0:00 | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | 0:00 | | 0:00 | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | NA | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-120506E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: S. McNemey, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/6/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00120506-PUFAE-3021 | SMC, BK | PARCEL E, STATION A | 12/5/00 | 9:42 | 12/6/00 | 9:03 | 310.38 | Jar & Envelope | | TO-4 | | |
| 00120506-PUFBE-3022 | SMC, BK | PARCEL E, STATION B | 12/5/00 | 9:50 | 12/6/00 | 9:07 | 331.02 | " | | TO-4 | | |
| 00120506-PUFCE-3023 | SMC, BK | PARCEL E, STATION C. | 12/5/00 | 9:53 | 12/6/00 | 9:11 | 321.73 | " | | TO-4 | | |
| 00120506-PUFDE-3024 | SMC, BK | PARCEL E, STATION D | 12/5/00 | 10:05 | 12/6/00 | 9:16 | 334.08 | " | | TO-4 | | |
| 00120506-PUFEE-3025 | SMC, BK | PARCEL E, STATION E | 12/5/00 | 10:25 | 12/6/00 | 9:31 | 336.15 | " | | TO-4 | | |
| 00120506-PUFFE-3026 | SMC, BK | PARCEL E, STATION F | 12/5/00 | 10:17 | 12/6/00 | 9:25 | 323.44 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 00120506-FBEPUF-3034 | SMC, BK | PARCEL E, PUF-BLANK | 12/5/00 | NA | 12/6/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | 0.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | 0.00 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| ---------- | ---------- | ---------- | | | | | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | | | | | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | | | | | ---------- | ---------- | ---------- | ---------- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaround

QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-120607E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: S. McNerney, B. Kuhn, A. Cortez
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/8/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00120607-PUFAE-3041 | SM, BK,AC | PARCEL E, STATION A | 12/6/00 | 9:06 | 12/7/00 | 8:24 | 339.67 | Jar & Envelope | | TO-4 | | |
| 00120607-PUFBE-3042 | SM, BK,AC | PARCEL E, STATION B | 12/6/00 | 9:09 | 12/7/00 | 8:33 | 332.33 | " | | TO-4 | | |
| 00120607-PUFCE-3043 | SM, BK,AC | PARCEL E, STATION C. | 12/6/00 | 9:13 | 12/7/00 | 8:40 | 323.47 | " | | TO-4 | | |
| 00120607-PUFDE-3044 | SM, BK,AC | PARCEL E, STATION D | 12/6/00 | 9:19 | 12/7/00 | 8:50 | 336.74 | " | | TO-4 | | |
| 00120607-PUFEE-3045 | SM, BK,AC | PARCEL E, STATION E | 12/6/00 | 9:33 | 12/7/00 | 9:13 | 342.86 | " | | TO-4 | | |
| 00120607-PUFFE-3046 | SM, BK,AC | PARCEL E, STATION F | 12/6/00 | 9:28 | 12/7/00 | 9:03 | 331.59 | " | | TO-4 | | |
| 00120607-PUFGE-3047 | SM, BK,AC | PARCEL E, STATION G | 12/6/00 | 9:23 | 12/7/00 | 8:58 | 329.53 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaround

QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-120708



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/8/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00120708-PUFAE-3048 | AC, BK, SM | PARCEL E, STATION A | 12/7/00 | 8:28 | 12/8/00 | 8:04 | 342.81 | Jar & Envelope | | TO-4 | | |
| 00120708-PUFBE-3049 | AC, BK, SM | PARCEL E, STATION B | 12/7/00 | 8:37 | 12/8/00 | 8:12 | 333.61 | " | | TO-4 | | |
| 00120708-PUFCE-3050 | AC, BK, SM | PARCEL E, STATION C. | 12/7/00 | 8:46 | 12/8/00 | 8:20 | 327.70 | " | | TO-4 | | |
| 00120708-PUFDE-3051 | AC, BK, SM | PARCEL E, STATION D | 12/7/00 | 8:56 | 12/8/00 | 8:32 | 329.33 | " | | TO-4 | | |
| 00120708-PUFEE-3052 | AC, BK, SM | PARCEL E, STATION E | 12/7/00 | 9:18 | 12/8/00 | 8:58 | 325.71 | " | | TO-4 | | |
| 00120708-PUFFE-3053 | AC, BK, SM | PARCEL E, STATION F | 12/7/00 | 9:09 | 12/8/00 | 8:45 | 321.13 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| 00120708-FBEPUF-3054 | AC, BK, SM | PARCEL E, PUF-BLANK | 12/7/00 | NA | 12/8/00 | NA | NA | " | | TO-4 | | |
| 00120708-VOCAE-A303 | AC, BK, SM | PARCEL E, STATION A | 12/7/00 | 8:24 | 12/8/00 | 8:01 | 5.00 psi | SUMMA | | TO-14a | | |
| 00120708-VOCBE-A417 | AC, BK, SM | PARCEL E, STATION B | 12/7/00 | 8:33 | 12/8/00 | 8:10 | 0.00 | " | | TO-14a | | |
| 0120708-VOCCE-A513 | AC, BK, SM | PARCEL E, STATION C | 12/7/00 | 8:41 | 12/8/00 | 8:19 | 0.00 | " | | TO-14a | | |
| 0120708-VOCDE-A607 | AC, BK, SM | PARCEL E, STATION D | 12/7/00 | 8:52 | 12/8/00 | 8:30 | 5.00 | " | | TO-14a | | |
| 00120708-VOCEE-A804 | AC, BK, SM | PARCEL E, STATION E | 12/7/00 | 9:13 | 12/8/00 | 8:56 | 4.00 | " | | TO-14a | | |
| 00120708-VOCFE-A431 | AC, BK, SM | PARCEL E, STATION F | 12/7/00 | 9:03 | 12/8/00 | 8:45 | 13.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| 00120708-FBEVOC-A511 | AC, BK, SM | PARCEL E, VOC-BLANK | 12/7/00 | NA | 12/8/00 | NA | NA | " | | TO-14a | | |
| 00120708-TSPAE-7607 | AC, BK, SM | PARCEL E, STATION A | 12/7/00 | 8:21 | 12/8/00 | 7:58 | 1833.15 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00120708-TSPBE-7608 | AC, BK, SM | PARCEL E, STATION B | 12/7/00 | 8:31 | 12/8/00 | 8:08 | 1833.89 | " | | IO 3.1 & IO 3.5 | | |
| 00120708-TSPCE-7609 | AC, BK, SM | PARCEL E, STATION C | 12/7/00 | 8:38 | 12/8/00 | 8:15 | 1830.93 | " | | IO 3.1 & IO 3.5 | | |
| 00120708-TSPDE-7610 | AC, BK, SM | PARCEL E, STATION D | 12/7/00 | 8:48 | 12/8/00 | 8:27 | 1846.85 | " | | IO 3.1 & IO 3.5 | | |
| 00120708-TSPEE-7615 | AC, BK, SM | PARCEL E, STATION E | 12/7/00 | 9:13 | 12/8/00 | 8:54 | 1840.72 | " | | IO 3.1 & IO 3.5 | | |
| 00120708-TSPFE-7616 | AC, BK, SM | PARCEL E, STATION F | 12/7/00 | 9:00 | 12/8/00 | 8:42 | 1834.42 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| 00120708-FBETSP-7617 | AC, BK, SM | PARCEL E, TSP-BLANK | 12/7/00 | NA | 12/8/00 | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning 2 SUMMA regulators for maintenance and/or repair (SN# 00397 & 00402)

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarour | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-120809



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn S. McNerney, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/11/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00120809-PUFAE-3055 | AC,BK,SM,ED | PARCEL E, STATION A | 12/8/00 | 8:09 | 12/9/00 | 8:09 | 347.10 | Jar & Envelope | | TO-4 | | |
| 00120809-PUFBE-3056 | AC,BK,SM,ED | PARCEL E, STATION B | 12/8/00 | 8:18 | 12/9/00 | 8:18 | 340.36 | " | | TO-4 | | |
| 00120809-PUFCE-3057 | AC,BK,SM,ED | PARCEL E, STATION C. | 12/8/00 | 8:28 | 12/9/00 | 8:28 | 335.05 | " | | TO-4 | | |
| 00120809-PUFDE-3058 | AC,BK,SM,ED | PARCEL E, STATION D | 12/8/00 | 8:38 | 12/9/00 | 8:38 | 346.87 | " | | TO-4 | | |
| 00120809-PUFEE-3059 | AC,BK,SM,ED | PARCEL E, STATION E | 12/8/00 | 9:03 | 12/9/00 | 9:03 | 337.74 | " | | TO-4 | | |
| 00120809-PUFFE-3060 | AC,BK,SM,ED | PARCEL E, STATION F | 12/8/00 | 8:54 | 12/9/00 | 8:56 | 337.75 | " | | TO-4 | | |
| 00120809-PUFEE-3060 | AC,BK,SM,ED | PARCEL E, STATION G | 12/8/00 | 8:42 | 12/9/00 | 8:42 | 327.53 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-120910



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: E. Diaz, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/11/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00120910-PUFAE-3062 | ED, SM | PARCEL E, STATION A | 12/9/00 | 8:13 | 12/10/00 | 8:13 | 347.31 | Jar & Envelope | | TO-4 | | |
| 00120910-PUFBE-3063 | ED, SM | PARCEL E, STATION B | 12/9/00 | 8:20 | 12/10/00 | 8:20 | 340.24 | " | | TO-4 | | |
| 00120910-PUFCE-3064 | ED, SM | PARCEL E, STATION C. | 12/9/00 | 8:31 | 12/10/00 | 8:31 | 344.16 | " | | TO-4 | | |
| 00120910-PUFDE-3065 | ED, SM | PARCEL E, STATION D | 12/9/00 | 8:40 | 12/10/00 | 8:40 | 345.64 | " | | TO-4 | | |
| 00120910-PUFEE-3066 | ED, SM | PARCEL E, STATION E | 12/9/00 | 9:06 | 12/10/00 | 9:06 | 337.17 | " | | TO-4 | | |
| 00120910-PUFFE-3067 | ED, SM | PARCEL E, STATION F | 12/9/00 | 8:59 | 12/10/00 | 8:59 | 337.49 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| 00120910-FBEPUF-3068 | ED, SM | PARCEL E, PUF-BLANK | 12/9/00 | NA | 12/10/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | | | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnarou

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-121011



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: S. McNERNEY, E. DIAZ
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/12/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00121011-PUFAE-3069 | SMC, ED | PARCEL E, STATION A | 12/10/00 | 8:16 | 12/11/00 | 8:16 | 348.40 | Jar & Envelope | | TO-4 | | |
| 00121011-PUFBE-3070 | SMC, ED | PARCEL E, STATION B | 12/10/00 | 8:23 | 12/11/00 | 8:23 | 344.55 | " | | TO-4 | | |
| 00121011-PUFCE-3071 | SMC, ED | PARCEL E, STATION C. | 12/10/00 | 8:33 | 12/11/00 | 8:33 | 343.03 | " | | TO-4 | | |
| 00121011-PUFDE-3072 | SMC, ED | PARCEL E, STATION D | 12/10/00 | 8:42 | 12/11/00 | 8:42 | 349.36 | " | | TO-4 | | |
| 00121011-PUFEE-3073 | SMC, ED | PARCEL E, STATION E | 12/10/00 | 9:09 | 12/11/00 | 9:09 | 340.38 | " | | TO-4 | | |
| 00121011-PUFFE-3074 | SMC, ED | PARCEL E, STATION F | 12/10/00 | 9:02 | 12/11/00 | 9:02 | 337.65 | " | | TO-4 | | |
| 00121011-PUFGE-3075 | SMC, ED | PARCEL E, STATION G | 12/10/00 | 8:38 | 12/11/00 | 8:38 | 333.58 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | psi | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | | | | |
| ---------- | ---------- | ---------- | | | | | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | | | | | ---------- | ---------- | ---------- | ---------- | | |
| ---------- | ---------- | ---------- | | | | | ---------- | ---------- | ---------- | ---------- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaroun

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-121112



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn, E. Diaz, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/13/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00121112-PUFAE-3076 | AC, BK, ED, SM | PARCEL E, STATION A | 12/11/00 | 8:19 | 12/12/00 | 8:24 | 350.35 | Jar & Envelope | | TO-4 | | |
| 00121112-PUFBE-3077 | AC, BK, ED, SM | PARCEL E, STATION B | 12/11/00 | 8:26 | 12/12/00 | 8:33 | 341.72 | " | | TO-4 | | |
| 00121112-PUFCE-3078 | AC, BK, ED, SM | PARCEL E, STATION C | 12/11/00 | 8:35 | 12/12/00 | 8:43 | 336.12 | " | | TO-4 | | |
| 00121112-PUFDE-3079 | AC, BK, ED, SM | PARCEL E, STATION D | 12/11/00 | 8:45 | 12/12/00 | 8:54 | 346.87 | " | | TO-4 | | |
| 00121112-PUFEE-3080 | AC, BK, ED, SM | PARCEL E, STATION E | 12/11/00 | 9:11 | 12/12/00 | 9:17 | 332.24 | " | | TO-4 | | |
| 00121112-PUFFE-3081 | AC, BK, ED, SM | PARCEL E, STATION F | 12/11/00 | 9:04 | 12/12/00 | 9:08 | 340.80 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| 00121112-FBEPUF-3082 | AC, BK, ED, SM | PARCEL E, PUF-BLANK | 12/11/00 | NA | 12/12/00 | NA | NA | " | | TO-4 | | |
| 0121112-VOCAE-A102 | AC, BK, ED, SM | PARCEL E, STATION A | 12/11/00 | 8:00 | 12/12/00 | 7:55 | 9.00 psi | SUMMA | | TO-14a | | |
| 0121112-VOCBE-A429 | AC, BK, ED, SM | PARCEL E, STATION B | 12/11/00 | 8:20 | 12/12/00 | 7:57 | 3.50 | " | | TO-14a | | |
| 0121112-VOCCE-A430 | AC, BK, ED, SM | PARCEL E, STATION C | 12/11/00 | 8:30 | 12/12/00 | 8:37 | 0.00 | " | | TO-14a | | |
| 0121112-VOCDE-A603 | AC, BK, ED, SM | PARCEL E, STATION D | 12/11/00 | 8:45 | 12/12/00 | 8:52 | 4.00 | " | | TO-14a | | |
| 0121112-VOCEE-A620 | AC, BK, ED, SM | PARCEL E, STATION E | 12/11/00 | 9:07 | 12/12/00 | 9:16 | 5.00 | " | | TO-14a | | |
| 0121112-VOCFE-A805 | AC, BK, ED, SM | PARCEL E, STATION F | 12/11/00 | 8:53 | 12/12/00 | 9:07 | 16.00 | " | | TO-14a | | |
| 0121112-VOCGE-A808 | AC, BK, ED, SM | PARCEL E, STATION G | 12/11/00 | 8:40 | 12/12/00 | 8:52 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | 12/11/00 | | | | | | | | | |
| 00121112-TSPAE-7611 | AC, BK, ED, SM | PARCEL E, STATION A | 12/11/00 | 8:03 | 12/12/00 | 8:20 | 1885.59 | Envelope | | IO 3.1 & IO 3.5 | | |
| 00121112-TSPBE-7612 | AC, BK, ED, SM | PARCEL E, STATION B | 12/11/00 | 8:27 | 12/12/00 | 8:29 | 1867.69 | " | | IO 3.1 & IO 3.5 | | |
| 00121112-TSPCE-7613 | AC, BK, ED, SM | PARCEL E, STATION C | 12/11/00 | 8:36 | 12/12/00 | 8:40 | 1867.26 | " | | IO 3.1 & IO 3.5 | | |
| 00121112-TSPDE-7614 | AC, BK, ED, SM | PARCEL E, STATION D | 12/11/00 | 8:47 | 12/12/00 | 8:50 | 1868.99 | " | | IO 3.1 & IO 3.5 | | |
| 00121112-TSPEE-7624 | AC, BK, ED, SM | PARCEL E, STATION E | 12/11/00 | 9:07 | 12/12/00 | 9:14 | 1863.59 | " | | IO 3.1 & IO 3.5 | | |
| 00121112-TSPFE-7625 | AC, BK, ED, SM | PARCEL E, STATION F | 12/11/00 | 8:57 | 12/12/00 | 9:05 | 1872.43 | " | | IO 3.1 & IO 3.5 | | |
| 00121112-TSPGE-7626 | AC, BK, ED, SM | PARCEL E, STATION G | 12/11/00 | 8:50 | 12/12/00 | 8:54 | 1867.26 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaroun

QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). Sample 00121112-VOCFE-A805 will be analyzed as a representative sample only.
Note: The calculation for the TSP flow only incorporates temperature data from 8:00-15:00 12/11/00 as the temp sensor on the MET tower failed

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-121213E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/14/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00121213-PUFAE-3089 | AC, BK | PARCEL E, STATION A | 12/12/00 | 8:28 | 12/13/00 | 8:22 | 344.81 | Jar & Envelope | | TO-4 | | |
| 00121213-PUFBE-3090 | AC, BK | PARCEL E, STATION B | 12/12/00 | 8:37 | 12/13/00 | 8:27 | 341.65 | " | | TO-4 | | |
| 00121213-PUFCE-3091 | AC, BK | PARCEL E, STATION C. | 12/12/00 | 8:49 | 12/13/00 | 8:32 | 346.01 | " | | TO-4 | | |
| 00121213-PUFDE-3092 | AC, BK | PARCEL E, STATION D | 12/12/00 | 8:59 | 12/13/00 | 8:40 | 342.46 | " | | TO-4 | | |
| 00121213-PUFEE-3093 | AC, BK | PARCEL E, STATION E | 12/12/00 | 9:24 | 12/13/00 | 8:58 | 344.94 | " | | TO-4 | | |
| 00121213-PUFFE-3094 | AC, BK | PARCEL E, STATION F | 12/12/00 | 9:14 | 12/13/00 | 8:51 | 331.79 | " | | TO-4 | | |
| 00121213-PUFGE-3095 | AC, BK | PARCEL E, STATION G | 12/12/00 | 9:05 | 12/13/00 | 8:45 | 338.10 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnaroun | QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

Note: average temperature for flow calculation is missing first three operational hours (0800-1000) on 12/12/00 due to MET tower temperature sensor malfunction.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-121314E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/15/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00121314-PUFAE-3098 | AC, BK | PARCEL E, STATION A | 12/13/00 | 8:25 | 12/14/00 | 8:00 | 339.42 | Jar & Envelope | | TO-4 | | |
| 00121314-PUFBE-3099 | AC, BK | PARCEL E, STATION B | 12/13/00 | 8:30 | 12/14/00 | 8:07 | 335.29 | " | | TO-4 | | |
| 00121314-PUFCE-3100 | AC, BK | PARCEL E, STATION C. | 12/13/00 | 8:36 | 12/14/00 | 8:11 | 345.00 | " | | TO-4 | | |
| 00121314-PUFDE-3101 | AC, BK | PARCEL E, STATION D | 12/13/00 | 8:44 | 12/14/00 | 8:16 | 341.18 | " | | TO-4 | | |
| 00121314-PUFEE-3102 | AC, BK | PARCEL E, STATION E | 12/13/00 | 9:01 | 12/14/00 | 8:28 | 339.63 | " | | TO-4 | | |
| 00121314-PUFFE-3103 | AC, BK | PARCEL E, STATION F | 12/13/00 | 8:55 | 12/14/00 | 8:23 | 329.52 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| 00121314-FBPUF-3104 | AC, BK | PARCEL E, PUF-BLANK | 12/13/00 | NA | 12/14/00 | NA | NA | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | psi | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | | | | |
| ---------- | ---------- | ---------- | | | | | | | | | | |
| ---------- | ---------- | ---------- | | | | | | | | | | |
| ---------- | ---------- | ---------- | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 5 day turnaroun

QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2000-121415



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn, S. McNerney
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 12/15/00
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 00121415-PUFAE-3096 | AC, BK, SM | PARCEL E, STATION A | 12/14/00 | 8:05 | 12/15/00 | 8:15 | 349.81 | Jar & Envelope | | TO-4 | | |
| 00121415-PUFBE-3097 | AC, BK, SM | PARCEL E, STATION B | 12/14/00 | 8:09 | 12/15/00 | 8:21 | 344.65 | " | | TO-4 | | |
| 00121415-PUFCE-3105 | AC, BK, SM | PARCEL E, STATION C | 12/14/00 | 8:13 | 12/15/00 | 8:28 | 355.06 | " | | TO-4 | | |
| 00121415-PUFDE-3106 | AC, BK, SM | PARCEL E, STATION D | 12/14/00 | 8:18 | 12/15/00 | 8:36 | 352.63 | " | | TO-4 | | |
| 00121415-PUFEE-3107 | AC, BK, SM | PARCEL E, STATION E | 12/14/00 | 8:30 | 12/15/00 | 8:51 | 333.26 | " | | TO-4 | | |
| 00121415-PUFFE-3108 | AC, BK, SM | PARCEL E, STATION F | 12/14/00 | 8:25 | 12/15/00 | 8:45 | 346.25 | " | | TO-4 | | |
| 00121415-PUFGE-3109 | AC, BK, SM | PARCEL E, STATION G | 12/14/00 | 8:20 | 12/15/00 | 8:40 | 340.90 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | psi | SUMMA | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION C | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION D | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 5 day turnarou | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2uu0-010506E



Project Name HPS Air Monitoring
Project Number 773247
SampleTeam/Members A. Cortez, B. Kuhn, E. Diaz
Profit Center No. 3701110
Project Manager Jim Robbins
Purchase Order No. 149120
Required Report Date Per Statement of Work (SOW)

Samples Shipment Date 1/5/01
Lab Destination K-Prime Analytical
Lab Contact Carla Kagel
Project Contact/Phone Brett Womack
Carrier/Waybill No. Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01010506-PUFAE-3124 | AC, BK, ED | PARCEL E, STATION A | 1/5/01 | 13:59 | 1/6/01 | 13:07 | 323.61 | Jar & Envelope | | TO-4 | | |
| 01010506-PUFBE-3135 | AC, BK, ED | PARCEL E, STATION B | 1/5/01 | 14:08 | 1/6/01 | 13:13 | 330.41 | " | | TO-4 | | |
| 01010506-PUFCE-3136 | AC, BK, ED | PARCEL E, STATION C | 1/5/01 | 14:18 | 1/6/01 | 13:27 | 313.20 | " | | TO-4 | | |
| 01010506-PUFDE-3137 | AC, BK, ED | PARCEL E, STATION D | 1/5/01 | 14:29 | 1/6/01 | 13:34 | 325.82 | " | | TO-4 | | |
| 01010506-PUFEE-3138 | AC, BK, ED | PARCEL E, STATION E | 1/5/01 | 14:44 | 1/6/01 | 13:50 | 321.26 | " | | TO-4 | | |
| 01010506-PUFFE-3139 | AC, BK, ED | PARCEL E, STATION F | 1/5/01 | 14:35 | 1/6/01 | 13:41 | 326.47 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | TO-4 | | |
| 01010506-FBEPUF-3146 | AC, BK, ED | PARCEL E, PUF-BLANK | 1/5/01 | NA | 1/6/01 | NA | NA | " | | TO-4 | | |
| 01010506-VOCAE-A430 | AC, BK, ED | PARCEL E, STATION A | 1/5/01 | 14:00 | 1/6/01 | 13:03 | 0.00 psi | SUMMA | | TO-14a | | |
| 01010506-VOCBE-A807 | AC, BK, ED | PARCEL E, STATION B | 1/5/01 | 14:06 | 1/6/01 | 13:09 | 0.00 | " | | TO-14a | | |
| 01010506-VOCCE-A636 | AC, BK, ED | PARCEL E, STATION C | 1/5/01 | 14:16 | 1/6/01 | 14:23 | 0.00 | " | | TO-14a | | |
| 01010506-VOCDE-A602 | AC, BK, ED | PARCEL E, STATION D | 1/5/01 | 14:26 | 1/6/01 | 14:31 | 0.00 | " | | TO-14a | | |
| 01010506-VOCEE-A431 | AC, BK, ED | PARCEL E, STATION E | 1/5/01 | 14:45 | 1/6/01 | 13:46 | 5.00 | " | | TO-14a | | |
| 01010506-VOCFE-A607 | AC, BK, ED | PARCEL E, STATION F | 1/5/01 | 14:30 | 1/6/01 | 13:39 | 2.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | TO-14a | | |
| 01010506-FBEVOC-A705 | AC, BK, ED | PARCEL E, VOC-BLANK | 1/5/01 | NA | 1/6/01 | NA | NA | " | | TO-14a | | |
| 01010506-TSPAE-7716 | AC, BK, ED | PARCEL E, STATION A | 1/5/01 | 14:03 | 1/6/01 | 13:03 | 1781.04 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01010506-TSPBE-7717 | AC, BK, ED | PARCEL E, STATION B | 1/5/01 | 14:11 | 1/6/01 | 13:11 | 1782.50 | " | | IO 3.1 & IO 3.5 | | |
| 01010506-TSPCE-7718 | AC, BK, ED | PARCEL E, STATION C | 1/5/01 | 14:27 | 1/6/01 | 13:27 | 1779.59 | " | | IO 3.1 & IO 3.5 | | |
| 01010506-TSPDE-7719 | AC, BK, ED | PARCEL E, STATION D | 1/5/01 | 14:31 | 1/6/01 | 13:33 | 1785.08 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION E | | | | | | | | IO 3.1 & IO 3.5 | | |
| 01010506-TSPFE-7721 | AC, BK, ED | PARCEL E, STATION F | 1/5/01 | 14:38 | 1/6/01 | 13:38 | 1779.59 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| 01010506-FBETSP-7722 | AC, BK, ED | PARCEL E, TSP-BLANK | 1/5/01 | NA | 1/6/01 | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 10 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2uu1-012930E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 1/31/01
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01012930-PUFAE-3153 | AC, ED | PARCEL E, STATION A | 1/29/01 | 8:30 | 1/30/01 | 8:27 | 345.35 | Jar & Envelope | | TO-4 | | |
| 01012930-PUFBE-3154 | AC, ED | PARCEL E, STATION B | 1/29/01 | 8:40 | 1/30/01 | 8:34 | 349.01 | " | | TO-4 | | |
| 01012930-PUFCE-3155 | AC, ED | PARCEL E, STATION C | 1/29/01 | 8:49 | 1/30/01 | 8:40 | 350.83 | " | | TO-4 | | |
| 01012930-PUFDE-3156 | AC, ED | PARCEL E, STATION D | 1/29/01 | 11:34 | 1/30/01 | 10:59 | 326.19 | " | | TO-4 | | |
| 01012930-PUFEE-3157 | AC, ED | PARCEL E, STATION E | 1/29/01 | 9:23 | 1/30/01 | 11:12 | 370.97 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| 01012930-PUFGE-3159 | AC, ED | PARCEL E, STATION G | 1/29/01 | 11:39 | 1/30/01 | 11:03 | 344.51 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | | | | | |
| 01012930-VOCAE-A429 | AC, ED | PARCEL E, STATION A | 1/29/01 | 8:25 | 1/30/01 | 8:29 | 4.00 psi | SUMMA | | TO-14a | | |
| 01012930-VOCBE-A603 | AC, ED | PARCEL E, STATION B | 1/29/01 | 8:35 | 1/30/01 | 8:35 | 6.00 | " | | TO-14a | | |
| 01012930-VOCCE-A606 | AC, ED | PARCEL E, STATION C | 1/29/01 | 8:46 | 1/30/01 | 8:40 | 0.00 | " | | TO-14a | | |
| 01012930-VOCDE-A637 | AC, ED | PARCEL E, STATION D | 1/29/01 | 9:00 | 1/30/01 | 8:49 | 0.00 | " | | TO-14a | | |
| 01012930-VOCEE-A702 | AC, ED | PARCEL E, STATION E | 1/29/01 | 9:20 | 1/30/01 | 8:58 | 1.00 | " | | TO-14a | | |
| 01012930-VOCFE-A802 | AC, ED | PARCEL E, STATION F | 1/29/01 | 9:12 | 1/30/01 | 8:55 | 0.00 | " | | TO-14a | | |
| 01012930-VOCGE-A805 | AC, ED | PARCEL E, STATION G | 1/29/01 | 9:05 | 1/30/01 | 8:50 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | | | | | |
| 01012930-TSPAE-7723 | AC, ED | PARCEL E, STATION A | 1/29/01 | 8:30 | 1/30/01 | 8:30 | 1890.15 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01012930-TSPBE-7724 | AC, ED | PARCEL E, STATION B | 1/29/01 | 8:40 | 1/30/01 | 8:37 | 1887.76 | " | | IO 3.1 & IO 3.5 | | |
| 01012930-TSPCE-7725 | AC, ED | PARCEL E, STATION C | 1/29/01 | 8:45 | 1/30/01 | 8:43 | 1887.53 | " | | IO 3.1 & IO 3.5 | | |
| 01012930-TSPDE-7726 | AC, ED | PARCEL E, STATION D | 1/29/01 | 11:32 | 1/30/01 | 11:01 | 1852.49 | " | | IO 3.1 & IO 3.5 | | |
| 01012930-TSPEE-7720 | AC, ED | PARCEL E, STATION E | 1/29/01 | 11:15 | 1/30/01 | 11:15 | 1893.24 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | | | | | |
| 01012930-TSPGE-7729 | AC, ED | PARCEL E, STATION G | 1/29/01 | 11:35 | 1/30/01 | 11:05 | 1852.29 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | | | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only. Returning 1 void PUF sample (# 3158).

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 10 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). Sample 01012930-PUFEE-3157 will be used as a representative sample only since it ran over 25 hours.
The Ambient Temp (Deg. C) and Barometric Pressure (BP) were obtained from the National Weather Service website. Average temp was 46 deg. Fahrenheit, or 7.8 deg. Celcius and the BP was 30.26 hg.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2001-020102E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 2/2/01
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1020102-PUFAE-318 | AC, BK, ED | PARCEL E, STATION A | 2/1/01 | 8:57 | 2/2/01 | 8:28 | 324.08 | Jar & Envelope | | TO-4 | | |
| 1020102-PUFBE-318 | AC, BK, ED | PARCEL E, STATION B | 2/1/01 | 9:10 | 2/2/01 | 8:34 | 322.39 | " | | TO-4 | | |
| 1020102-PUFCE-318 | AC, BK, ED | PARCEL E, STATION C | 2/1/01 | 9:17 | 2/2/01 | 8:39 | 332.35 | " | | TO-4 | | |
| 1020102-PUFDE-318 | AC, BK, ED | PARCEL E, STATION D | 2/1/01 | 9:25 | 2/2/01 | 8:45 | 320.33 | " | | TO-4 | | |
| 1020102-PUFEE-318 | AC, BK, ED | PARCEL E, STATION E | 2/1/01 | 9:47 | 2/2/01 | 8:56 | 320.17 | " | | TO-4 | | |
| 01020102-PUFFE-318 | AC, BK, ED | PARCEL E, STATION F | 2/1/01 | 9:37 | 2/2/01 | 8:50 | 315.42 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| 01020102-FBEPUF-3190 | AC, BK, ED | PARCEL E, PUF-BLANK | 2/1/01 | NA | 2/2/01 | NA | NA | " | | TO-4 | | |
| 1020102-VOCAE-A10 | AC, BK, ED | PARCEL E, STATION A | 2/1/01 | 8:56 | 2/2/01 | 8:29 | 13.00 psi | SUMMA | | TO-14a | | |
| 1020102-VOCBE-A30 | AC, BK, ED | PARCEL E, STATION B | 2/1/01 | 9:06 | 2/2/01 | 8:35 | 0.00 | " | | TO-14a | | |
| 1020102-VOCCE-A60 | AC, BK, ED | PARCEL E, STATION C | 2/1/01 | 9:15 | 2/2/01 | 8:40 | 0.00 | " | | TO-14a | | |
| 1020102-VOCDE-A80 | AC, BK, ED | PARCEL E, STATION D | 2/1/01 | 9:25 | 2/2/01 | 8:46 | 0.00 | " | | TO-14a | | |
| 1020102-VOCEE-A42 | AC, BK, ED | PARCEL E, STATION E | 2/1/01 | 9:45 | 2/2/01 | 8:57 | 3.00 | " | | TO-14a | | |
| 1020102-VOCFE-A42 | AC, BK, ED | PARCEL E, STATION F | 2/1/01 | 9:37 | 2/2/01 | 8:51 | 2.50 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| 01020102-FBEVOC-A427 | AC, BK, ED | PARCEL E, VOC-BLANK | 2/1/01 | NA | 2/2/01 | NA | NA | " | | TO-14a | | |
| 01020102-TSPAE-777 | AC, BK, ED | PARCEL E, STATION A | 2/1/01 | 9:00 | 2/2/01 | 8:28 | 1842.69 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01020102-TSPBE-777 | AC, BK, ED | PARCEL E, STATION B | 2/1/01 | 9:10 | 2/2/01 | 8:34 | 1840.46 | " | | IO 3.1 & IO 3.5 | | |
| 1020102-TSPCE-777 | AC, BK, ED | PARCEL E, STATION C | 2/1/01 | 9:15 | 2/2/01 | 8:39 | 1837.46 | " | | IO 3.1 & IO 3.5 | | |
| 1020102-TSPDE-777 | AC, BK, ED | PARCEL E, STATION D | 2/1/01 | 9:26 | 2/2/01 | 8:45 | 1835.39 | " | | IO 3.1 & IO 3.5 | | |
| 01020102-TSPEE-777 | AC, BK, ED | PARCEL E, STATION E | 2/1/01 | 9:46 | 2/2/01 | 8:56 | 1823.59 | " | | IO 3.1 & IO 3.5 | | |
| 01020102-TSPFE-777 | AC, BK, ED | PARCEL E, STATION F | 2/1/01 | 9:36 | 2/2/01 | 8:50 | 1825.86 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| 01020102-FBETSP-7776 | AC, BK, ED | PARCEL E, TSP-BLANK | 2/1/01 | NA | 2/2/01 | NA | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 10 day turnaround

QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 20u1-020405E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Kuhn, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 2/5/01
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01020405-PUFAE-3191 | BK, ED | PARCEL E, STATION A | 2/4/01 | 9:07 | 2/5/01 | 8:14 | 321.87 | Jar & Envelope | | TO-4 | | |
| 01020405-PUFBE-3192 | BK, ED | PARCEL E, STATION B | 2/4/01 | 9:15 | 2/5/01 | 8:22 | 329.39 | " | | TO-4 | | |
| 01020405-PUFCE-3193 | BK, ED | PARCEL E, STATION C | 2/4/01 | 9:20 | 2/5/01 | 8:26 | 314.75 | " | | TO-4 | | |
| 01020405-PUFDE-3194 | BK, ED | PARCEL E, STATION D | 2/4/01 | 9:28 | 2/5/01 | 8:36 | 317.95 | " | | TO-4 | | |
| 01020405-PUFEE-3195 | BK, ED | PARCEL E, STATION E | 2/4/01 | 9:56 | 2/5/01 | 8:56 | 314.62 | " | | TO-4 | | |
| 01020405-PUFFE-3196 | BK, ED | PARCEL E, STATION F | 2/4/01 | 9:44 | 2/5/01 | 8:46 | 313.06 | " | | TO-4 | | |
| VOID | | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| 01020405-VOCAE-A512 | BK, ED | PARCEL E, STATION A | 2/4/01 | 9:05 | 2/5/01 | 8:15 | 0.00 psi | SUMMA | | TO-14a | | |
| 01020405-VOCBE-A423 | BK, ED | PARCEL E, STATION B | 2/4/01 | 9:15 | 2/5/01 | 8:22 | 6.00 | " | | TO-14a | | |
| 01020405-VOCCE-A809 | BK, ED | PARCEL E, STATION C | 2/4/01 | 9:22 | 2/5/01 | 8:26 | 2.00 | " | | TO-14a | | |
| 01020405-VOCDE-A431 | BK, ED | PARCEL E, STATION D | 2/4/01 | 9:30 | 2/5/01 | 8:36 | 0.00 | " | | TO-14a | | |
| 01020405-VOCEE-A915 | BK, ED | PARCEL E, STATION E | 2/4/01 | 9:55 | 2/5/01 | 8:55 | 2.00 | " | | TO-14a | | |
| 01020405-VOCFE-A112 | BK, ED | PARCEL E, STATION F | 2/4/01 | 9:45 | 2/5/01 | 8:46 | 10.00 | " | | TO-14a | | |
| 01020405-VOCGE-A621 | BK, ED | PARCEL E, STATION G | 2/4/01 | 9:36 | 2/5/01 | 8:39 | 3.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| 01020405-TSPAE-7788 | BK, ED | PARCEL E, STATION A | 2/4/01 | 9:10 | 2/5/01 | 8:14 | 1786.33 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01020405-TSPBE-7789 | BK, ED | PARCEL E, STATION B | 2/4/01 | 9:16 | 2/5/01 | 8:22 | 1791.08 | " | | IO 3.1 & IO 3.5 | | |
| 01020405-TSPCE-7790 | BK, ED | PARCEL E, STATION C | 2/4/01 | 9:23 | 2/5/01 | 8:26 | 1783.59 | " | | IO 3.1 & IO 3.5 | | |
| 01020405-TSPDE-7791 | BK, ED | PARCEL E, STATION D | 2/4/01 | 9:31 | 2/5/01 | 8:36 | 1791.96 | " | | IO 3.1 & IO 3.5 | | |
| 01020405-TSPEE-7792 | BK, ED | PARCEL E, STATION E | 2/4/01 | 9:56 | 2/5/01 | 8:56 | 1785.49 | " | | IO 3.1 & IO 3.5 | | |
| 01020405-TSPFE-7793 | BK, ED | PARCEL E, STATION F | 2/4/01 | 9:46 | 2/5/01 | 8:47 | 1782.45 | " | | IO 3.1 & IO 3.5 | | |
| 01020405-TSPGE-7794 | BK, ED | PARCEL E, STATION G | 2/4/01 | 9:37 | 2/5/01 | 8:39 | 1784.47 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only Returning one void PUF sample 3197.

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 10 day turnaround

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) Date: Time: | 1. Received by (Signature/Affiliation) Date: Time: |
| 2. Relinquished by (Signature/Affiliation) Date: Time: | 2. Received by (Signature/Affiliation) Date: Time: |
| 3. Relinquished by (Signature/Affiliation) Date: Time: | 3. Received by (Signature/Affiliation) Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 20ut-020708E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 2/8/01
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01020708-PUFAE-3204 | AC, BK, ED | PARCEL E, STATION A | 2/7/01 | 10:35 | 2/8/01 | 9:42 | 315.93 | Jar & Envelope | | TO-4 | | |
| 01020708-PUFBE-3205 | AC, BK, ED | PARCEL E, STATION B | 2/7/01 | 10:45 | 2/8/01 | 9:53 | 316.15 | " | | TO-4 | | |
| 01020708-PUFCE-3206 | AC, BK, ED | PARCEL E, STATION C | 2/7/01 | 10:55 | 2/8/01 | 9:56 | 328.27 | " | | TO-4 | | |
| 01020708-PUFDE-3207 | AC, BK, ED | PARCEL E, STATION D | 2/7/01 | 11:05 | 2/8/01 | 10:14 | 322.63 | " | | TO-4 | | |
| 01020708-PUFEE-3208 | AC, BK, ED | PARCEL E, STATION E | 2/7/01 | 11:23 | 2/8/01 | 10:28 | 316.64 | " | | TO-4 | | |
| 01020708-PUFFE-3209 | AC, BK, ED | PARCEL E, STATION F | 2/7/01 | 11:15 | 2/8/01 | 10:21 | 314.88 | " | | TO-4 | | |
| NOT COLLECTED | AC, BK, ED | PARCEL E, STATION G | | | | | 0.00 | " | | TO-4 | | |
| 01020708-FBPUF-3210 | AC, BK, ED | PARCEL E, PUF-BLANK | 2/7/01 | NA | 2/8/01 | NA | NA | " | | TO-4 | | |
| VOID | AC, BK, ED | PARCEL E, STATION A | | | | | psi | SUMMA | | TO-14a | | |
| 01020708-VOCBE-A808 | AC, BK, ED | PARCEL E, STATION B | 2/7/01 | 10:45 | 2/8/01 | 9:55 | 3.00 | " | | TO-14a | | |
| 01020708-VOCCE-A703 | AC, BK, ED | PARCEL E, STATION C | 2/7/01 | 10:58 | 2/8/01 | 9:58 | 0.00 | " | | TO-14a | | |
| 01020708-VOCDE-A511 | AC, BK, ED | PARCEL E, STATION D | 2/7/01 | 11:05 | 2/8/01 | 10:15 | 5.00 | " | | TO-14a | | |
| 01020708-VOCEE-A502 | AC, BK, ED | PARCEL E, STATION E | 2/7/01 | 11:30 | 2/8/01 | 10:30 | 3.00 | " | | TO-14a | | |
| 01020708-VOCFE-A206 | AC, BK, ED | PARCEL E, STATION F | 2/7/01 | 11:20 | 2/8/01 | 10:35 | 2.00 | " | | TO-14a | | |
| NOT COLLECTED | AC, BK, ED | PARCEL E, STATION G | | | | | 0.00 | " | | TO-14a | | |
| 01020708-FBVOC-A914 | AC, BK, ED | PARCEL E, VOC-BLANK | 2/7/01 | NA | 2/8/01 | NA | NA | " | | TO-14a | | |
| 01020708-TSPAE-7795 | AC, BK, ED | PARCEL E, STATION A | 2/7/01 | 10:35 | 2/8/01 | 9:47 | 1792.44 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01020708-TSPBE-7796 | AC, BK, ED | PARCEL E, STATION B | 2/7/01 | 10:46 | 2/8/01 | 9:54 | 1789.47 | " | | IO 3.1 & IO 3.5 | | |
| 01020708-TSPCE-7797 | AC, BK, ED | PARCEL E, STATION C | 2/7/01 | 10:56 | 2/8/01 | 9:58 | 1781.74 | " | | IO 3.1 & IO 3.5 | | |
| 01020708-TSPDE-7798 | AC, BK, ED | PARCEL E, STATION D | 2/7/01 | 11:06 | 2/8/01 | 10:15 | 1793.68 | " | | IO 3.1 & IO 3.5 | | |
| 01020708-TSPEE-7799 | AC, BK, ED | PARCEL E, STATION E | 2/7/01 | 11:27 | 2/8/01 | 10:28 | 1782.62 | " | | IO 3.1 & IO 3.5 | | |
| 01020708-TSPFE-7800 | AC, BK, ED | PARCEL E, STATION F | 2/7/01 | 11:22 | 2/8/01 | 10:22 | 1780.61 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | AC, BK, ED | PARCEL E, STATION G | | | | | 0.00 | | | IO 3.1 & IO 3.5 | | |
| 01020708-FBTSP-7801 | AC, BK, ED | PARCEL E, TSP-BLANK | 2/7/01 | NA | 2/8/01 | NA | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Sending back one voided summa sample and five regulators for service.

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 10 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 20u1-021314E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 2/14/01
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VOID | | PARCEL E, STATION A | | | | | | Jar & Envelope | | TO-4 | | |
| 01021314-PUFBE-3218 | AC, BK, ED | PARCEL E, STATION B | 2/13/01 | 10:29 | 2/14/01 | 9:29 | 313.83 | " | | TO-4 | | |
| 01021314-PUFCE-3219 | AC, BK, ED | PARCEL E, STATION C | 2/13/01 | 10:37 | 2/14/01 | 10:37 | 313.73 | " | | TO-4 | | |
| 01021314-PUFDE-3220 | AC, BK, ED | PARCEL E, STATION D | 2/13/01 | 10:53 | 2/14/01 | 9:53 | 323.59 | " | | TO-4 | | |
| 01021314-PUFEE-3221 | AC, BK, ED | PARCEL E, STATION E | 2/13/01 | 11:14 | 2/14/01 | 10:16 | 322.98 | " | | TO-4 | | |
| 01021314-PUFFE-3222 | AC, BK, ED | PARCEL E, STATION F | 2/13/01 | 11:05 | 2/14/01 | 10:11 | 325.30 | " | | TO-4 | | |
| 01021314-PUFGE-3223 | AC, BK, ED | PARCEL E, STATION G | 2/13/01 | 10:57 | 2/14/01 | 9:57 | 310.72 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | NA | " | | TO-4 | | |
| VOID | | PARCEL E, STATION A | | | | | 0.00 psi | SUMMA | | TO-14a | | |
| 01021314-VOCBE-102 | AC, BK, ED | PARCEL E, STATION B | 2/13/01 | 10:30 | 2/14/01 | 9:30 | 7.00 | " | | TO-14a | | |
| 01021314-VOCCE-426 | AC, BK, ED | PARCEL E, STATION C | 2/13/01 | 10:44 | 2/14/01 | 9:44 | 1.00 | " | | TO-14a | | |
| 01021314-VOCDE-201 | AC, BK, ED | PARCEL E, STATION D | 2/13/01 | 10:55 | 2/14/01 | 9:55 | 5.00 | " | | TO-14a | | |
| 01021314-VOCEE-604 | AC, BK, ED | PARCEL E, STATION E | 2/13/01 | 11:15 | 2/14/01 | 10:15 | 4.00 | " | | TO-14a | | |
| 01021314-VOCFE-506 | AC, BK, ED | PARCEL E, STATION F | 2/13/01 | 11:05 | 2/14/01 | 10:05 | 1.00 | " | | TO-14a | | |
| 01021314-VOCGE-430 | AC, BK, ED | PARCEL E, STATION G | 2/13/01 | 11:00 | 2/14/01 | 10:00 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | NA | " | | TO-14a | | |
| 01021314-TSPAE-7808 | AC, BK, ED | PARCEL E, STATION A | 2/13/01 | 10:22 | 2/14/01 | 9:22 | 1772.17 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01021314-TSPBE-7809 | AC, BK, ED | PARCEL E, STATION B | 2/13/01 | 10:32 | 2/14/01 | 9:32 | 1775.06 | " | | IO 3.1 & IO 3.5 | | |
| 01021314-TSPCE-7810 | AC, BK, ED | PARCEL E, STATION C | 2/13/01 | 10:40 | 2/14/01 | 10:40 | 1772.17 | " | | IO 3.1 & IO 3.5 | | |
| 01021314-TSPDE-7811 | AC, BK, ED | PARCEL E, STATION D | 2/13/01 | 10:55 | 2/14/01 | 9:55 | 1776.50 | " | | IO 3.1 & IO 3.5 | | |
| 01021314-TSPEE-7812 | AC, BK, ED | PARCEL E, STATION E | 2/13/01 | 11:15 | 2/14/01 | 11:16 | 1776.35 | " | | IO 3.1 & IO 3.5 | | |
| 01021314-TSPFE-7813 | AC, BK, ED | PARCEL E, STATION F | 2/13/01 | 11:05 | 2/14/01 | 11:11 | 1779.88 | " | | IO 3.1 & IO 3.5 | | |
| 01021314-TSPGE-7814 | AC, BK, ED | PARCEL E, STATION G | 2/13/01 | 11:00 | 2/14/01 | 10:00 | 1773.62 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning 1 SUMMA regulator (#396).

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 10 day turnaround | QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). Station AE SUMMA canister voided due to regulator failure. Station AE PUF sample voided due to insufficient volume.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 20u1-021617E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: A. Cortez, B. Kuhn, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 2/20/01
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01021617-PUFAE-3230 | AC, BK, ED | PARCEL E, STATION A | 2/16/01 | 9:39 | 2/17/01 | 10:15 | 418.56 | Jar & Envelope | | TO-4 | | |
| 01021617-PUFBE-3231 | AC, BK, ED | PARCEL E, STATION B | 2/16/01 | 9:46 | 2/17/01 | 10:23 | 332.39 | " | | TO-4 | | |
| 01021617-PUFCE-3232 | AC, BK, ED | PARCEL E, STATION C | 2/16/01 | 9:55 | 2/17/01 | 10:27 | 335.06 | " | | TO-4 | | |
| 01021617-PUFDE-3233 | AC, BK, ED | PARCEL E, STATION D | 2/16/01 | 10:04 | 2/17/01 | 10:34 | 333.66 | " | | TO-4 | | |
| 01021617-PUFEE-3234 | AC, BK, ED | PARCEL E, STATION E | 2/16/01 | 10:20 | 2/17/01 | 10:44 | 350.41 | " | | TO-4 | | |
| 01021617-PUFFE-3235 | AC, BK, ED | PARCEL E, STATION F | 2/16/01 | 10:13 | 2/17/01 | 10:38 | 320.75 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 01021617-FBEPUF-3236 | AC, BK, ED | PARCEL E, PUF-BLANK | 2/16/01 | NA | 2/17/01 | NA | NA | " | | TO-4 | | |
| 01021617-VOCAE-A808 | AC, BK, ED | PARCEL E, STATION A | 2/16/01 | 9:40 | 2/17/01 | 10:18 | 1.00 psi | SUMMA | | TO-14a | | |
| 01021617-VOCBE-A507 | AC, BK, ED | PARCEL E, STATION B | 2/16/01 | 9:50 | 2/17/01 | 10:25 | 0.00 | " | | TO-14a | | |
| 01021617-VOCCE-A702 | AC, BK, ED | PARCEL E, STATION C | 2/16/01 | 9:55 | 2/17/01 | 10:30 | 1.00 | " | | TO-14a | | |
| 01021617-VOCDE-A502 | AC, BK, ED | PARCEL E, STATION D | 2/16/01 | 10:07 | 2/17/01 | 10:35 | 0.00 | " | | TO-14a | | |
| 01021617-VOCEE-A503 | AC, BK, ED | PARCEL E, STATION E | 2/16/01 | 10:25 | 2/17/01 | 10:45 | 0.00 | " | | TO-14a | | |
| 01021617-VOCFE-A704 | AC, BK, ED | PARCEL E, STATION F | 2/16/01 | 10:15 | 2/17/01 | 10:40 | 3.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| 01021617-FBEVOC-A105 | AC, BK, ED | PARCEL E, VOC-BLANK | 2/16/01 | NA | 2/17/01 | NA | NA | " | | TO-14a | | |
| 01021617-TSPAE-7821 | AC, BK, ED | PARCEL E, STATION A | 2/16/01 | 9:40 | 2/17/01 | 10:16 | 1908.00 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01021617-TSPBE-7822 | AC, BK, ED | PARCEL E, STATION B | 2/16/01 | 9:50 | 2/17/01 | 10:19 | 1900.49 | " | | IO 3.1 & IO 3.5 | | |
| 01021617-TSPCE-7823 | AC, BK, ED | PARCEL E, STATION C | 2/16/01 | 9:55 | 2/17/01 | 10:30 | 1905.16 | " | | IO 3.1 & IO 3.5 | | |
| 01021617-TSPDE-7824 | AC, BK, ED | PARCEL E, STATION D | 2/16/01 | 10:07 | 2/17/01 | 10:34 | 1897.90 | " | | IO 3.1 & IO 3.5 | | |
| 01021617-TSPEE-7825 | AC, BK, ED | PARCEL E, STATION E | 2/16/01 | 10:25 | 2/17/01 | 10:45 | 1888.85 | " | | IO 3.1 & IO 3.5 | | |
| 01021617-TSPFE-7826 | AC, BK, ED | PARCEL E, STATION F | 2/16/01 | 10:15 | 2/17/01 | 10:39 | 1890.95 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| 01021617-FBETSP-7827 | AC, BK, ED | PARCEL E, TSP-BLANK | 2/16/01 | NA | 2/17/01 | NA | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Sample 01021617-PUFAE-3230 has a high volume but is within the parameters of the method. **LEVEL 4 PACKAGE REQUESTED ON THIS COC.**

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 10 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 20u1-022324E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Kuhn, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 2/27/01
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01022324-PUFAE-3244 | BK, ED | PARCEL E, STATION A | 2/23/01 | 9:11 | 2/24/01 | 9:11 | 322.42 | Jar & Envelope | | TO-4 | | |
| 01022324-PUFBE-3245 | BK, ED | PARCEL E, STATION B | 2/23/01 | 9:20 | 2/24/01 | 9:20 | 333.57 | " | | TO-4 | | |
| 01022324-PUFCE-3243 | BK, ED | PARCEL E, STATION C | 2/23/01 | 9:26 | 2/24/01 | 9:25 | 333.50 | " | | TO-4 | | |
| 01022324-PUFDE-3246 | BK, ED | PARCEL E, STATION D | 2/23/01 | 9:32 | 2/24/01 | 9:36 | 335.12 | " | | TO-4 | | |
| 01022324-PUFEE-3247 | BK, ED | PARCEL E, STATION E | 2/23/01 | 10:02 | 2/24/01 | 10:00 | 340.34 | " | | TO-4 | | |
| 01022324-PUFFE-3248 | BK, ED | PARCEL E, STATION F | 2/23/01 | 9:50 | 2/24/01 | 9:51 | 315.66 | " | | TO-4 | | |
| 01022324-PUFGE-3249 | BK, ED | PARCEL E, STATION G | 2/23/01 | 9:58 | 2/24/01 | 9:45 | 324.00 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | | | | | |
| 010222324-VOCAE-A638 | BK, ED | PARCEL E, STATION A | 2/23/01 | 9:10 | 2/24/01 | 9:15 | 13.00 psi | SUMMA | | TO-14a | | |
| 01022324-VOCBE-A307 | BK, ED | PARCEL E, STATION B | 2/23/01 | 9:20 | 2/24/01 | 9:23 | 4.00 | " | | TO-14a | | |
| 01022324-VOCCE-A621 | BK, ED | PARCEL E, STATION C | 2/23/01 | 9:25 | 2/24/01 | 9:30 | 0.00 | " | | TO-14a | | |
| VOID | | PARCEL E, STATION D | | | | | | | | | | |
| 01022324-VOCEE-A705 | BK, ED | PARCEL E, STATION E | 2/23/01 | 10:00 | 2/24/01 | 10:00 | 0.00 | " | | TO-14a | | |
| 01022324-VOCFE-A504 | BK, ED | PARCEL E, STATION F | 2/23/01 | 9:46 | 2/24/01 | 9:51 | 0.00 | " | | TO-14a | | |
| 01022324-VOCGE-A101 | BK, ED | PARCEL E, STATION G | 2/23/01 | 9:38 | 2/24/01 | 9:40 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | | | | | |
| 01022324-TSPAE-7834 | BK, ED | PARCEL E, STATION A | 2/23/01 | 9:14 | 2/24/01 | 9:14 | 1853.34 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01022324-TSPBE-7835 | BK, ED | PARCEL E, STATION B | 2/23/01 | 9:23 | 2/24/01 | 9:21 | 1856.06 | " | | IO 3.1 & IO 3.5 | | |
| 01022324-TSPCE-7836 | BK, ED | PARCEL E, STATION C | 2/23/01 | 9:29 | 2/24/01 | 9:30 | 1856.14 | " | | IO 3.1 & IO 3.5 | | |
| 01022324-TSPDE-7837 | BK, ED | PARCEL E, STATION D | 2/23/01 | 9:36 | 2/24/01 | 9:35 | 1855.08 | " | | IO 3.1 & IO 3.5 | | |
| 01022324-TSPEE-7838 | BK, ED | PARCEL E, STATION E | 2/23/01 | 10:03 | 2/24/01 | 9:38 | 1849.92 | " | | IO 3.1 & IO 3.5 | | |
| 01022324-TSPFE-7841 | BK, ED | PARCEL E, STATION F | 2/23/01 | 9:50 | 2/24/01 | 9:50 | 1854.85 | " | | IO 3.1 & IO 3.5 | | |
| 01022324-TSPGE-7842 | BK, ED | PARCEL E, STATION G | 2/23/01 | 9:41 | 2/24/01 | 9:46 | 1861.29 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only Returning one void SUMMA (A301).

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 10 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). SUMMA sample at Parcel E, Station D was voided due to faulty regulator.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 20u1-030506E



Project Name HPS Air Monitoring
Project Number 773247
SampleTeam/Members B. Kuhn, E. Diaz
Profit Center No. 3701110
Project Manager Jim Robbins
Purchase Order No. 149120
Required Report Date Per Statement of Work (SOW)

Samples Shipment Date 3/6/01
Lab Destination K-Prime Analytical
Lab Contact Carla Kagel
Project Contact/Phone Brett Womack
Carrier/Waybill No. Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01030506-PUFAE-3304 | BK, ED | PARCEL E, STATION A | 3/5/01 | 9:52 | 3/6/01 | 9:31 | 330.48 | Jar & Envelope | | TO-4 | | |
| 01030506-PUFBE-3305 | BK, ED | PARCEL E, STATION B | 3/5/01 | 10:05 | 3/6/01 | 9:37 | 331.90 | " | | TO-4 | | |
| 01030506-PUFCE-3306 | BK, ED | PARCEL E, STATION C | 3/5/01 | 10:11 | 3/6/01 | 9:43 | 321.69 | " | | TO-4 | | |
| 01030506-PUFDE-3307 | BK, ED | PARCEL E, STATION D | 3/5/01 | 10:20 | 3/6/01 | 9:48 | 320.99 | " | | TO-4 | | |
| 01030506-PUFEE-3308 | BK, ED | PARCEL E, STATION E | 3/5/01 | 10:40 | 3/6/01 | 10:03 | 318.49 | " | | TO-4 | | |
| VOID | | PARCEL E, STATION F | | | | | | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-4 | | |
| 01030506-FBEPUF-3310 | BK, ED | PARCEL E, PUF-BLANK | 3/5/01 | NA | 3/6/01 | NA | NA | " | | TO-4 | | |
| 01030506-VOCAE-A-503 | BK, ED | PARCEL E, STATION A | 3/5/01 | 9:52 | 3/6/01 | 9:35 | 0.00 psi | SUMMA | | TO-14a | | |
| 01030506-VOCBE-A-423 | BK, ED | PARCEL E, STATION B | 3/5/01 | 10:00 | 3/6/01 | 9:40 | 4.00 | " | | TO-14a | | |
| 01030506-VOCCE-A-703 | BK, ED | PARCEL E, STATION C | 3/5/01 | 10:08 | 3/6/01 | 9:45 | 1.00 | " | | TO-14a | | |
| 01030506-VOCDE-A-506 | BK, ED | PARCEL E, STATION D | 3/5/01 | 10:16 | 3/6/01 | 9:50 | 1.00 | " | | TO-14a | | |
| 01030506-VOCEE-A-426 | BK, ED | PARCEL E, STATION E | 3/5/01 | 10:35 | 3/6/01 | 10:01 | 1.00 | " | | TO-14a | | |
| VOID | | PARCEL E, STATION F | | | | | | | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | " | | TO-14a | | |
| 01030506-FBEVOC-A-805 | BK, ED | PARCEL E, VOC-BLANK | 3/5/01 | NA | 3/6/01 | NA | NA | " | | TO-14a | | |
| 01030506-TSPAE-7858 | BK, ED | PARCEL E, STATION A | 3/5/01 | 9:55 | 3/6/01 | 9:33 | 1811.65 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01030506-TSPBE-7859 | BK, ED | PARCEL E, STATION B | 3/5/01 | 10:03 | 3/6/01 | 9:38 | 1813.69 | " | | IO 3.1 & IO 3.5 | | |
| 01030506-TSPCE-7860 | BK, ED | PARCEL E, STATION C | 3/5/01 | 10:10 | 3/6/01 | 9:43 | 1806.73 | " | | IO 3.1 & IO 3.5 | | |
| 01030506-TSPDE-7861 | BK, ED | PARCEL E, STATION D | 3/5/01 | 10:20 | 3/6/01 | 9:48 | 1803.26 | " | | IO 3.1 & IO 3.5 | | |
| 01030506-TSPEE-7862 | BK, ED | PARCEL E, STATION E | 3/5/01 | 10:38 | 3/6/01 | 10:00 | 1795.57 | " | | IO 3.1 & IO 3.5 | | |
| 01030506-TSPFE-7863 | BK, ED | PARCEL E, STATION F | 3/5/01 | 10:30 | 3/6/01 | 9:55 | 1795.77 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| 01030506-FBETSP-7864 | BK, ED | PARCEL E, TSP-BLANK | 3/5/01 | NA | 3/6/01 | NA | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning one void PUF sample (3309), and one void SUMMA (A-102).

Possible Hazard ID: none | Sample Disposal: By Lab | Turnaround Time Required: 10 day turnaround | QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809). PUF sample voided due to failed breaker. Void SUMMA sample due to faulty regulator.

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2001-030809E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Kuhn, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 3/9/01
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520

Report to: IT Corporation, 4005 Port Chicago Highway, Concord, CA. 94520, Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1030809-PUFAE-332 | BK, ED | PARCEL E, STATION A | 3/8/01 | 9:49 | 3/9/01 | 9:31 | 333.97 | Jar & Envelope | | TO-4 | | |
| 1030809-PUFBE-332 | BK, ED | PARCEL E, STATION B | 3/8/01 | 9:55 | 3/9/01 | 9:40 | 344.36 | " | | TO-4 | | |
| 1030809-PUFCE-332 | BK, ED | PARCEL E, STATION C | 3/8/01 | 10:04 | 3/9/01 | 9:48 | 330.34 | " | | TO-4 | | |
| 1030809-PUFDE-332 | BK, ED | PARCEL E, STATION D | 3/8/01 | 10:12 | 3/9/01 | 9:56 | 315.57 | " | | TO-4 | | |
| 1030809-PUFEE-332 | BK, ED | PARCEL E, STATION E | 3/8/01 | 10:44 | 3/9/01 | 10:14 | 334.05 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION F | | | | | | " | | TO-4 | | |
| 1030809-PUFGE-332 | BK, ED | PARCEL E, STATION G | 3/8/01 | 10:18 | 3/9/01 | 9:58 | 333.71 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, PUF-BLANK | | | | | | " | | TO-4 | | |
| 1030809-VOCAE-A20 | BK, ED | PARCEL E, STATION A | 3/8/01 | 9:51 | 3/9/01 | 9:36 | 0.00 psi | SUMMA | | TO-14a | | |
| 1030809-VOCBE-A60 | BK, ED | PARCEL E, STATION B | 3/8/01 | 9:56 | 3/9/01 | 9:44 | 0.00 | " | | TO-14a | | |
| 1030809-VOCCE-A42 | BK, ED | PARCEL E, STATION C | 3/8/01 | 10:01 | 3/9/01 | 9:51 | 0.00 | " | | TO-14a | | |
| 1030809-VOCDE-A60 | BK, ED | PARCEL E, STATION D | 3/8/01 | 10:12 | 3/9/01 | 10:00 | 0.00 | " | | TO-14a | | |
| 1030809-VOCEE-A80 | BK, ED | PARCEL E, STATION E | 3/8/01 | 10:45 | 3/9/01 | 10:13 | 0.00 | " | | TO-14a | | |
| 1030809-VOCFE-A63 | BK, ED | PARCEL E, STATION F | 3/8/01 | 10:25 | 3/9/01 | 10:04 | 0.00 | " | | TO-14a | | |
| 1030809-VOCGE-A43 | BK, ED | PARCEL E, STATION G | 3/8/01 | 10:17 | 3/9/01 | 9:58 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | | PARCEL E, VOC-BLANK | | | | | | " | | TO-14a | | |
| 01030809-TSPAE-786 | BK, ED | PARCEL E, STATION A | 3/8/01 | 9:50 | 3/9/01 | 9:35 | 1848.19 | Envelope | | IO 3.1 & IO 3.5 | | |
| 01030809-TSPBE-786 | BK, ED | PARCEL E, STATION B | 3/8/01 | 9:55 | 3/9/01 | 9:43 | 1852.09 | " | | IO 3.1 & IO 3.5 | | |
| 1030809-TSPCE-787 | BK, ED | PARCEL E, STATION C | 3/8/01 | 10:02 | 3/9/01 | 9:50 | 1852.09 | " | | IO 3.1 & IO 3.5 | | |
| 1030809-TSPDE-787 | BK, ED | PARCEL E, STATION D | 3/8/01 | 10:11 | 3/9/01 | 10:00 | 1851.88 | " | | IO 3.1 & IO 3.5 | | |
| 01030809-TSPEE-787 | BK, ED | PARCEL E, STATION E | 3/8/01 | 10:44 | 3/9/01 | 10:15 | 1828.55 | " | | IO 3.1 & IO 3.5 | | |
| 01030809-TSPFE-787 | BK, ED | PARCEL E, STATION F | 3/8/01 | 10:24 | 3/9/01 | 10:07 | 1841.11 | " | | IO 3.1 & IO 3.5 | | |
| 1030809-TSPGE-787 | BK, ED | PARCEL E, STATION G | 3/8/01 | 10:16 | 3/9/01 | 10:05 | 1848.87 | | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, TSP-BLANK | | | | | | " | | IO 3.1 & IO 3.5 | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |
| --- | --- | --- | | | | --- | --- | --- | --- | --- | | |

Special Instructions: Analyze PUFs for PCBs only

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 10 day turnaround

QC Level: Per SOW

| | | | |
|---|---|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: | 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: | 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: | 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809)

INTERNATIONAL TECHNOLOGY CORPORATION

# ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD

Reference Document No: 2uu1-031213E



Project Name: HPS Air Monitoring
Project Number: 773247
SampleTeam/Members: B. Kuhn, E. Diaz
Profit Center No.: 3701110
Project Manager: Jim Robbins
Purchase Order No.: 149120
Required Report Date: Per Statement of Work (SOW)

Samples Shipment Date: 3/13/01
Lab Destination: K-Prime Analytical
Lab Contact: Carla Kagel
Project Contact/Phone: Brett Womack
Carrier/Waybill No.: Courier

Bill to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520

Report to: IT Corporation
4005 Port Chicago Highway
Concord, CA. 94520
Attn: Pam Bauer

ONE CONTAINER PER LINE

| Sample Number | Sampler | Location | Sample Start Date | Sample Start Time | Sample End Date | Sample End Time | Sample Volume (Cubic meters) | Container Type | Preservative | Requested Testing Program | Condition on Receipt | Disposal Record No. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VOID | | PARCEL E, STATION A | | | | | | Jar & Envelope | | TO-4 | | |
| VOID | | PARCEL E, STATION B | | | | | | " | | TO-4 | | |
| 01031213-PUFCE-3338 | BK, ED | PARCEL E, STATION C | 3/12/01 | 11:05 | 3/13/01 | 10:05 | 319.67 | " | | TO-4 | | |
| 01031213-PUFDE-3339 | BK, ED | PARCEL E, STATION D | 3/12/01 | 10:55 | 3/13/01 | 9:55 | 312.82 | " | | TO-4 | | |
| 01031213-PUFEE-3340 | BK, ED | PARCEL E, STATION E | 3/12/01 | 11:29 | 3/13/01 | 10:29 | 330.11 | " | | TO-4 | | |
| 01031213-PUFFE-3328 | BK, ED | PARCEL E, STATION F | 3/12/01 | 10:42 | 3/13/01 | 9:44 | 324.52 | " | | TO-4 | | |
| NOT COLLECTED | | PARCEL E, STATION G | 3/12/01 | 0:00 | 3/13/01 | 0:00 | 0.00 | " | | TO-4 | | |
| 01031213-FBEPUF-3341 | BK, ED | PARCEL E, PUF-BLANK | 3/12/01 | NA | 3/13/01 | NA | NA | " | | TO-4 | | |
| 01031213-VOCAE-A-428 | BK, ED | PARCEL E, STATION A | 3/12/01 | 11:19 | 3/13/01 | 10:29 | 2.00 psi | SUMMA | | TO-14a | | |
| 01031213-VOCBE-A-512 | BK, ED | PARCEL E, STATION B | 3/12/13 | 11:11 | 3/13/01 | 10:15 | 12.00 | " | | TO-14a | | |
| 01031213-VOCCE-A-507 | BK, ED | PARCEL E, STATION C | 3/12/01 | 11:05 | 3/13/01 | 10:05 | 2.00 | " | | TO-14a | | |
| VOID | | PARCEL E, STATION D | | | | | | " | | TO-14a | | |
| 01031213-VOCEE-A-915 | BK, ED | PARCEL E, STATION E | 3/12/01 | 11:22 | 3/13/01 | 10:31 | 5.00 | " | | TO-14a | | |
| 01031213-VOCFE-A-603 | BK, ED | PARCEL E, STATION F | 3/12/01 | 10:46 | 3/13/01 | 9:46 | 0.00 | " | | TO-14a | | |
| NOT COLLECTED | BK, ED | PARCEL E, STATION G | 3/12/01 | 0:00 | 3/13/01 | 0:00 | 0.00 | " | | TO-14a | | |
| 01031213-FBEVOC-A-425 | BK, ED | PARCEL E, VOC-BLANK | 3/12/01 | NA | 3/13/01 | NA | NA | " | | TO-14a | | |
| VOID | | PARCEL E, STATION A | | | | | | Envelope | | IO 3.1 & IO 3.5 | | |
| VOID | | PARCEL E, STATION B | | | | | | " | | IO 3.1 & IO 3.5 | | |
| 01031213-TSPCE-7883 | BK, ED | PARCEL E, STATION C | 3/12/01 | 11:00 | 3/13/01 | 10:08 | 1812.25 | " | | IO 3.1 & IO 3.5 | | |
| 01031213-TSPDE-7884 | BK, ED | PARCEL E, STATION D | 3/12/01 | 10:52 | 3/13/01 | 9:55 | 1797.01 | " | | IO 3.1 & IO 3.5 | | |
| 01031213-TSPEE-7885 | BK, ED | PARCEL E, STATION E | 3/12/01 | 11:21 | 3/13/01 | 10:31 | 1805.38 | " | | IO 3.1 & IO 3.5 | | |
| 01031213-TSPFE-7886 | BK, ED | PARCEL E, STATION F | 3/12/01 | 10:44 | 3/13/01 | 9:45 | 1790.07 | " | | IO 3.1 & IO 3.5 | | |
| NOT COLLECTED | | PARCEL E, STATION G | | | | | | | | IO 3.1 & IO 3.5 | | |
| 01031213-FBETSP-7887 | BK, ED | PARCEL E, TSP-BLANK | 3/12/01 | NA | 3/13/01 | NA | NA | " | | IO 3.1 & IO 3.5 | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Special Instructions: Analyze PUFs for PCBs only. Returning ONE void SUMMA canisters (A-620) two faulty regulators (398,803) and two void PUF samples (3336,3337)

Possible Hazard ID: none

Sample Disposal: By Lab

Turnaround Time Required: 10 day turnaround

QC Level: Per SOW

| | |
|---|---|
| 1. Relinquished by (Signature/Affiliation) | Date: Time: |
| 1. Received by (Signature/Affiliation) | Date: Time: |
| 2. Relinquished by (Signature/Affiliation) | Date: Time: |
| 2. Received by (Signature/Affiliation) | Date: Time: |
| 3. Relinquished by (Signature/Affiliation) | Date: Time: |
| 3. Received by (Signature/Affiliation) | Date: Time: |

Comments: Fax Preliminary results to Brett Womack (1-415-671-2809).