
PA-KK3
PA-KK2
PA-KK1
PA-EE14
PA-UT14
PA-EE6
PA-EE18
PA-EE8
PA-DD6
PA-EE17
PA-UT53
PA-DD5
PA-FF1
PA-EE16
PA-DD4
PA-FF3
PA-DD12
PA-DD11
PA-O3
PA-O1
PA-O2
Explanation
Excavation Limits
PA-O1
ARC Soil Sample Location
Source:
Superfund Technical Assessment and Response Team (START) Report, August 15, 2008
Brown AND Caldwell
Date: July 2010
Atlantic Richfield Company
Project: 138554
N
W
E
S
75 0 75 150 FEET
Figure A-1
ARC Soil Samples
Jul 06, 2010 - 4:41pm rjohnson
P:\Arco-Yerington\Process Areas\138554 - Year 2010 Files\CAD\Drawings\June 2010\Figure A-1 - ARC Soil Samples.dwg