Nov 30, 2009 - 3:43pm rjohnson
P:\Arco-Yerington\Site-Wide Groundwater Remedial Investigation\136739 - Year 2009 Files\CAD\Drawings\Supp PWS Letter Report Dec 09\Figure 8 - PWS Intermediate Aquifer Wells.dwg



BROWN AND CALDWELL

Date: Nov 2009

Atlantic Richfield Company

Project: 136739

N
W E
S

250 0 250 500 FEET

Explanation

PW-10S Pumpback Well

W5AB-3I Monitor Well

Figure 8

Locations of Intermediate Aquifer Monitor Wells to be Monitored during Aquifer Test