Dec 01, 2009 - 12:51pm rhunt
P:\Arco-Yerington\Site-Wide Groundwater Remedial Investigation\136739 - Year 2009 Files\CAD\Drawings\Supp PWS Letter Report\Tech MeFigure 10 -PW-8S Water Level Recovery.dwg



BROWN AND CALDWELL

Date: Sept 2009

Atlantic Richfield Company

Project: 136739

Figure C-10

PW-8S Water Level Recovery Test Analysis