

Concentration Ranges for Aluminum in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-1

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Antimony in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-2

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Arsenic in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-3

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Barium in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-4

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Beryllium in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-5

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE




Concentration Ranges for Cadmium in Groundwater
Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-6

DRAWN WJF	JOB NUMBER 4088097619	CHECKED NAM	APPROVED WBC	DATE 1/2011	REVISED DATE
--------------	--------------------------	----------------	-----------------	----------------	--------------



Concentration Ranges for Calcium in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-7

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Chromium in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-8

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE




Concentration Ranges for Cobalt in Groundwater
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

Figure:

G3-9

DRAWN WJF	JOB NUMBER 4088097619	CHECKED NAM	APPROVED WBC	DATE 1/2011	REVISED DATE
--------------	--------------------------	----------------	-----------------	----------------	--------------



Concentration Ranges for Copper in Groundwater
Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-10

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Iron in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-11

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Lead in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-12

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Magnesium in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-13

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Manganese in Groundwater
Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-14

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Mercury in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-15

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Molybdenum in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-16

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Nickel in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-17

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Potassium in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-18

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Selenium in Groundwater
Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-19

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE




Concentration Ranges for Silver in Groundwater
Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-20

DRAWN WJF	JOB NUMBER 4088097619	CHECKED NAM	APPROVED WBC	DATE 1/2011	REVISED DATE
--------------	--------------------------	----------------	-----------------	----------------	--------------



Concentration Ranges for Sodium in Groundwater
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-21

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011


REVISED DATE



Concentration Ranges for Thallium in Groundwater
Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-22



Concentration Ranges for Tin in Groundwater
Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-23

DRAWN
WJF


JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE



Concentration Ranges for Zinc in Groundwater
Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

Figure:

G3-24

DRAWN
WJF

JOB NUMBER
4088097619

CHECKED
NAM

APPROVED
WBC

DATE
1/2011

REVISED DATE