



Concentrations under 0.5% not charted.

Gallery Well  
 LNAPL Composition - VOC Compounds  
 Final Remedial Investigation Report  
 Casmalia Resources Superfund Site  
 Casmalia, California

Figure:

**G-46**

DRAWN  
 NAM

JOB NUMBER  
 4088097619

CHECKED  
 WJF

APPROVED  
 WBC

DATE  
 1/2011