APPENDIX H – SITE PHOTOGRAPHS

This page intentionally left blank

Photo #1 – View north of the junction of the Western Depression area and the Upper Waste Consolidation Area at Site 1

Photo #2 – Groundwater monitoring well 12-R at Site 1 with stormwater retention pond in background

Photo #3 – Landfill gas monitoring well 1-4 at Site 1

Photo #4 – Landfill gas vent 12 at Site 1

Photo #5 – View south of the gas venting trench at Site 1

Photo #6 – Settlement marker at Site 1

Photo #7 – Raptor perch at Site 1 with stormwater retention pond in background

Photo #8 – Evidence of burrowing mammal activity at Site 1

Photo #9 – View southeast of the Site 2 Former landfill

Photo #10 – Building 191 pump station

Photo #11 – View east across Site 22 from southwest corner

Photo #12 – Groundwater monitoring well WGC2-4 at Site 22

Photo #13 – Landfill gas monitoring well 2 at Site 22

Photo #14 – Unlabeled monitoring well at Site 22, likely one of the recently replaced wells

Photo #15 – Perimeter methane monitoring point P-1 at Site 22

Photo #16 – Settlement Marker 2 at Site 22

Photo #17 – EATS treatment facility at Site 26

Photo #18 –Extraction well 2 at Site 26

Photo #19 – Groundwater monitoring well SW-6 at Site 26

Photo #20 – View southeast of WATS treatment facility at Site 28

Photo #21 – Advanced Oxidation Process (AOP) at WATS: Air compressor, oxygen generator, ozone generator, and oxidation tanks (from foreground to background)

Photo #22 – Liquid phase Granular Activated Carbon (GAC) units at WATS

Photo #23 – Storm drain action (SDA) Equalization Tank at WATS

Photo #24 – Flow Meter and Hydrogen Peroxide Storage Tank at WATS

Photo #25 – Effluent discharge into the stormwater drain at Site 28

Photo #26 – Deep extraction well EA2-2 at Site 28

Photo #27 – Upper portion of the A aquifer groundwater monitoring well W29-2 at Site 28

Photo #28 – Lower portion of the A aquifer groundwater monitoring well PZA2-2A at Site 28