



DRAWN GFA	JOB NUMBER 4088097619		Casmalia Resources Superfund Site Casmalia, California	Casmalia Site-Wide Water Balance Final Remedial Investigation Report	FIGURE F2-1
ENGINEER	SCALE				
CHECKED NAM	DATE 1/2011				
APPROVED WJF	DATE 1/2011				

Wednesday, December 22, 2010 10:43:06 AM
P:\4088\097619_Casmalia_RI_Revision\GIS\F2-1_waterbalance.mxd