


Explanation

- ◆ Extraction Well
- Drain
- Clay Barrier



FigureF2-3.mxd

**Extraction Wells
and Sumps/Drain Locations**
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

FIGURE

F2-3

DRAWN
TFC

JOB NUMBER
0020784 00.01

APPROVED
BB

CHECKED

DATE
01/2011

REVISED DATE