

Groundwater Elevations
RGPZ-7C and RGPZ-7D
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

Figure:

F4-2

DRAWN	JOB NUMBER	CHECKED	APPROVED	DATE
NAM	4088097619	WJF	WBC	1/2011