

Groundwater Elevations
RG-1B, RG-1C, and RGPZ-8D
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

Figure:

F4-3

DRAWN	JOB NUMBER	CHECKED	APPROVED	DATE
NAM	4088097619	WJF	WBC	1/2011