



FigureF3-1.mxd

Model Domain and Boundaries
 Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

FIGURE

F3-1

DRAWN
TFC

JOB NUMBER
0020784 00.01

APPROVED CHECKED
BB

DATE
01/2011

REVISED DATE