



FigureF3-13\_WL5\_2004.mxd

**Observed Water Levels for Layer 5  
March 2004**  
Final Remedial Investigation Report  
Casmalia Resources Superfund Site  
Casmalia, California

FIGURE

# F3-13

DRAWN  
TFC

JOB NUMBER  
0020784 00.01

APPROVED  
BB

CHECKED

DATE  
01/2011

REVISED DATE