

Recharge Rate from Precipitation
March 2004
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

FIGURE
F3-76

DRAWN	JOB NUMBER	APPROVED	CHECKED	DATE	REVISED DATE
TFC	0020784 00.01	BB		01/2011	