

On-site Freshwater Seeps

Runoff Sample in RCRA Canyon

Study Areas

Property Boundary

Roadways

0 250 500 1,000 Feet

Casmalia Resources Superfund Site

Final Remedial Investigation Report

January 2011

Figure U-1