



Figure 1: Site Location Map

Figure 2. Past Hexavalent Chromium Plume



Original hexavalent chromium contamination in groundwater  
January 1998

Figure 3. Present Hexavalent Chromium Plume



Remaining hexavalent chromium contamination in groundwater  
February 2006

Figure 4. Past Arsenic Plume (Upper Saturated Zone)




Figure 5. Present Arsenic Plume (Upper Saturated Zone)

