

T:\CASMALIA\GIS\deliverables\RI_Final_11\AppendixB\Administration_building.apr

Explanation

Soil Sample Locations

- Surface to Deep Soil (Type 5)
- ⊕ NAPL (Type 7)

Other Site Features

- Casmalia Site Boundary
- Administration Building Area Boundary
- Existing Sanitary Sewer Line
- ⊗ Liquids Extraction Well
- × × Fence
- Historical Features

All Values in mg/kg




Figure B-14a

Summary Analytical Results
Inorganics Detected Above Screening Levels
Administration Building Area

Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 January 2011

Source: Topographic base map provided by Pacific Engineering, Inc. from aerial survey dated March 4, 2004.