



T:\CASMALIA\GIS\deliverables\RI_Final_11\AppendixB\Treated_Liquid_Impoundments.apr

Explanation

Soil Sample Locations

▼ Sediment (Type 8a/8b)

Other Site Features

- - - Treated Liquid Impoundments Boundary

- - - Historical Natural Drainage (1956, 1974, 1988)

..... Historical Features

● ▲ Historical Soil Samples

Stormwater Pond

Treated Liquid Impoundment

1983 Spray Area

All Values in mg/kg



Scale in Feet

Figure B-20a

**Summary Analytical Results
Inorganics Detected Above Screening Levels
Treated Liquid Impoundments**

Final Remedial Investigation Report
Casmalia Resources Superfund Site

January 2011

Source: Topographic base map provided by Pacific Engineering, Inc. from aerial survey dated March 4, 2004.