

Figure 4-3
Maximum cis-1,2-Dichloroethene Concentrations Observed at Groundwater Wells
Remedial Investigation
San Gabriel Valley Area 3 Superfund Site

\\galt\proj\EPAF\ALOU\MapFiles\alou_cis12DCE_MaxValue.mxd