Photos Documenting Site Conditions

Attachment 5-1
Site Entrance

Attachment 5-2
Original Sump Area

Attachment 5-3
Pumping Well 101

Attachment 5-4
Monitoring Well 104

Attachment 5-5
Monitoring Well 104 Cap

Attachment 5-6
Monitoring Well 106

Attachment 5-7
Monitoring Well 107

Attachment 5-8
Monitoring Well 26



Attachment 5-9
Site Vegetation

Attachment 5-10
View toward Airport

Attachment 5-11
View toward Site Entrance

Attachment 5-12
Drainage Ditch

Attachment 5-13
Del Norte County Department of Agriculture Office

Attachment 5-14
Del Norte County Animal Quarantine Facility

Attachment 5-15
Adjacent McNamara Property

Attachment 5-16
Seawood Apartments

Attachment 5-17
Seawood Apartments