



Explanation

-  Survey Control Coordinate Location
-  Interpolated Clay Barrier Alignment
-  Gallery Well Location

Figure J-2

Detail of Interpolated Limits of Clay Barrier and Coordinate Locations

Remedial Investigation Report
Casmalia Site
January 2010

Source: Topographic base map provided by Pacific Engineering, Inc. from aerial survey dated March 4, 2004.