

BROWN AND CALDWELL

Date: August 2009

Atlantic Richfield Company

Project: 136739

Figure C-7

PW-4S Water Level Recovery Test Analysis