

LEGEND

- Burial Trench
- Landfill Boundaries
- Facility and Zone 1 Boundary
- Perimeter Source Control Trench (PSCT)
- Plume Capture Collection Trench (PCT)
- Clay Barrier
- Creek
- Pond Outline
- RGPZ-15B — Lower HSU Piezometer
- RP-63C — Lower HSU Monitoring Well
- MET — Meteorological Station
- Gauged Measurement of DNAPL
- Dissolved Concentrations of DNAPL Constituents greater than 1% of aqueous solubility
- Dissolved Concentrations of DNAPL Constituents greater than 10% of aqueous solubility
- Former Pond and Pad Subarea
- Historical Natural Drainage
- Dissolved Concentrations of Freon 113 greater than 1% and 10% of aqueous solubility

40088097001G1.DWG 40.0
2010/12/31 13:02

NO.	DATE	REVISIONS	BY	CHK

DRAWN: GFA	PROJECT NO: 4088097619	**Final Remedial Investigation Report**	FIGURE **G-71**
ENGINEER:	SCALE: 1"= 400'	**Casmalia Resources Superfund Site Casmalia, California**	SHEET: **1** OF **1**
CHECKED: NAM	APPROVED: WJF	**DNAPL in Upper HSU Observed or Inferred from Groudwater Concentrations Remedial Investigation Sampling**	REVISION NUMBER: 0
DATE: 1/2011	DATE: 1/2011		DATE: January 2011