

FigureF3-45.mxd

Model Cross Section Locations
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

FIGURE
F3-45

DRAWN	JOB NUMBER	APPROVED	CHECKED	DATE	REVISED DATE
TFC	0020784 00.01	BB		01/2011	